

ASS. REC. BY:

REF: CS/SPF/18013419/Ng d3ez Special Instruction:

Surveyor:

Na2

ASSIGNMENT (Office)

From (Person):

Abdul Rehman

of

SPF

Date/Time:

23/07/18

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJY 9292P

Insured:

QX 4894H

at Workshop m/s

TTS Euro Cars

Tel:

6757 2622

of

383 Bin Ming Drive

Policy No:

Claim No:

AEMD/105/009/2018/089

Sum Insured:

Excess:

Make of Veh:

D.O.A.

18/07/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

'up

H.O.D. Endorsement:

Date/Time:

24/7/18 @ 10:16am

Person Contacted:

wilson

Vehicle IN/OUT

(IN)

Date/Time

Action/Instruction

(✓)

Estimate

SJY 9292P - X

QX 4894H -

24/7/18

submit final Rg B 4684, 3 days.

Cred B 7617.30, 62%.

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STY 9292P Yr Regn: 30 JUN 2018Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: MERCEDES CLA 180 c.c. 1595Colour: WHITE A/C: Insured / Std / NI / NASp. Reading: 1246 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD1173422N652534Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A / Rim orTyre Size: F: 225/40 R18R: 11BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 18/7/18 D.O.I. 21/7/18Survey held at ITS EUROCARDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Do Not Finalize

P/P

Repair cost range \$4k - \$6k

2550 - 3700 adjust by bryan on 29/11/18

RECEIVED 21 SEP 2018

Date/Time, File Pass to?

☐

Preli. Report

1) 24/9/18 TP☐

Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 3Resurvey No. of Trip: 1

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: 4684 TPLump Sum / I.B.I. (\$) 4684

280

280



SINGAPORE POLICE FORCE

Your Ref : SJY9292P

Our Ref : AEMD/105/009/2018/089

Date : 23 July 2018

SPF Accidents Claims Section
Automotive Engg & Mgmt D
Police Logistics Department
No. 1 Mount Pleasant Road
Block 8 Old Police Academy
#02-12 Singapore 298333

Tel: 64784840

Fax: 64784848

M/s LKK Auto Consultants Pte Ltd
Paya Ubi Industrial Park
51 Ubi Avenue 1 #01/02-25
Singapore 408933

Via Fax only: 62564315

Dear Sir/Madam,

RTA ON 18 JULY 2018 INVOLVING GOVT VEH QX4894H AND OTHER VEH SJY9292P

We refer to the above matter.

- 2 Please arrange for a Pre Repair Inspection of vehicle no. SJY9292P at M/s TTS Eurocars Pte Ltd
383 Sin Ming Dr, TTS Centre, Singapore 575717.
- 3 For appointment please contact Ng Eng Kiat at Tel: 67572622.
- 4 Estimates were not provided by the workshop.
- 5 Thank you.

Yours sincerely,

Abdul Rahman
Accident Claims Officer
for Assistant Director

A FORCE FOR THE NATION



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

SINGAPORE POLICE FORCE

Ref : CS/SPF18013419/Nqd3

?? POLICE DIVISIONSINGAPORE

Date : 24-07-2018



Code : SPF1

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	QX 4894H	Veh. Inspected	SJY 9292P
Policy No.		Coverage (\$)	0.00
Claim No.	AEMD/105/1009/2018/089	Excess (\$)	0.00
Assign From	ABDUL RAHMAN	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	18/07/2018	Inspection Date	27/07/2018
Survey held at	TTS EUROCARS PTE LTD 383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2018 10:43
Date Of Accident	18/07/2018 16:10
Exact Location Of Accident	ALONG MEDICAL DRIVE IN FRONT OF MEDICINE MD 10
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJY9292P
Insured/Policyholder	
Name Of Registered Owner	LI JIN HONG
NRIC No	S8104788Z
Email Address	MAVERICKLI@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-90690053
Alternative Phone No	OFFICE-90690053

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	CLA180 AMG LINE
Exact Purpose for which vehicle was being used at time of accident	ON THE WAY HOME
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	HL ASSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	MP307702
Cover Note Number	

Driver

Name of Driver	LI JIN HONG
NRIC No	S8104788Z
Date Of Birth	19/02/1981
Occupation	INDOOR
Date Of Driving Pass	19/10/1999
Driving Experience	18 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90690053
Fax Number	
Contact Number	OFFICE-90690053
EMail Address	MAVERICKLI@HOTMAIL.COM

stacey.ing@axa.com.sg

Address	BLK 167B SIMEI LANE #11-16
Postcode	522167
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	PAYA LEBAR NPP
Police Station Address	ROAD: 114 HOUGANG AVE 1 #01-1270 , POSTCODE: 530114 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: - FAX NO:
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to Sketch plan and police report

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	QX4894H
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	GOVERNMENT
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre, Singapore 575717
Tel : 67572622 Fax : 67411626

To		DATE	19/7/2018
Attn	Claims Officer		TP CLAIM
CC	1595	VEH NO	SJY9292P
YEAR	2018	C/NO NO	WDD1173422N652534
MODEL	MERCEDES BENZ CLA180 AMG LINE AUTO	PAGE	1 OF 1

99

QUOTATION

S/NO	PARTS	QTY	PRICE
1	Rear Bumper	1	\$ 1,980.00
2	Rear Lower Bumper	1	\$ 540.00
3	LH Tail Lamp	1	\$ 980.00
4	RH Tail Lamp	1	\$ 980.00
5	Rear Bumper Retainer LH	1	\$ 48.00
6	Rear Bumper Retainer RH	1	\$ 48.00
7	Rear Bonnet	1	\$ 1,900.00
8	Rear Bonnet Mercedes Star Logo	1	\$ 66.00
9	Rear Bonnet "CLA 180" Chrome Ornament	1	\$ 115.00
10	Rear Bonnet Hinge LH	1	\$ 180.00
11	Rear Bonnet Hinge RH	1	\$ 180.00
SUB-TOTAL			\$ 7,017.00
DISCOUNT 10%			\$ 701.70
SUB-TOTAL			\$ 6,315.30

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Naz LKK

27/7/18 1730

P/P

3 days

BEFORE PAINT PHOTO 6741 8434
Naz @ lkkauto.com

✓ B&W
✓ W&P.
✓ SUC
✓ SUC
✓ SUC
✓ SUC
✓ R
✓ An
✓ An
✓ SUC
✓ SUC



TTS EUROCARS pte ltd

A member of the TTS Motor Group

383 Sin Ming Drive , TTS Centre . S'pore 575717
Tel : 67572622 Fax : 67411626

To		DATE	19/7/2018
Attn	Claims Officer		TP CLAIM
CC	1595	VEH NO	SJY9292P
YEAR	2018	C/NO NO	WDD1173422N652534
MODEL	MERCEDES BENZ CLA180 AMG LINE AUTO	PAGE	1 OF 1

QUOTATION

S/NO	NETT ITEMS	QTY	PRICE
1	CLIPS	8	\$ 76.00
2	Rear Parking Sensor	6	\$ 1,320.00
3	Parking sensor O-ring	6	\$ 57.00
SUB-TOTAL			\$ 1,453.00

✓ ALK
✗ SVL
✗ SVL



TTS EUROCARS pte ltd
A member of the TTS Motor Group

383 Sin Ming Drive, TTS Centre. S'pore 575717
Tel : 67572622 Fax : 67411626

QUOTATION

VEH NO SJY9292P

PAGE 2 OF 2

	<u>LABOUR</u>		
1	TO CUT, WELD, REPLACED ACCIDENT DAMAGE PARTS, ALIGNMENT AND CHECK ALSO TO KNOCKOUT & STRAIGHTEN - ACCIDENT DENTED PORTION SO AS TO REMOVE & REPLACE ACCIDENT AND REPLACED DAMAGED PARTS.	1	\$ 400 2,080.00
2	TO PUTTY, SAND DOWN & SPRAY PAINT ACCIDENT AFFECTED PORTION FACILITATE FOR THE REPAIR	1	\$ 400 700.00
3	TO REMOVE AND REFIT REVERSE SENSOR ASSY.	1	\$ 180.00
4	TO CHECK WIRING AND LIGHTING OPERATION.	1	\$ 120.00
	LABOUR-TOTAL		\$ 3,080.00
	GRAND TOTAL		\$ 10,848.30
	GST 7%		\$ 759.38
	GRAND TOTAL		\$ 11,607.68

REMARK THIS QUOTE IS ONLY AN ESTIMATE FOR REPAIR, SHOULD ANY ADDITIONAL PARTS OR
LABOUR INCURRED, WE WILL INFORM YOU ACCORDINGLY PRIOR BEFORE WE PROCEED.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 9292P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT	1,980.00	1,980.00
1	REAR LOWER BUMPER	WARPED	540.00	540.00
1	LH TAIL LAMP	SERVICEABLE	980.00	-
1	RH TAIL LAMP	SERVICEABLE	980.00	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	48.00	-
1	REAR BUMPER RETAINER RH	SERVICEABLE	48.00	-
1	REAR BONNET	TO REPAIR SEE LABOUR	1,900.00	-
1	REAR BONNET MERCEDES STAR LOGO	NOT NECESSARY	66.00	-
1	REAR BONNET "CLA 180" CHROME ORNAMENT	NOT NECESSARY	115.00	-
1	REAR BONNET HINGE LH	SERVICEABLE	180.00	-
1	REAR BONNET HINGE RH	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-701.70	-252.00
			6,315.30	2,268.00
<u>SPECIAL NETT ITEMS</u>				
8	CLIPS (SN)	NECESSARY	76.00	76.00
6	REAR PARKING SENSOR (SN)	SERVICEABLE	1,320.00	-
6	PARKING SENSOR O-RING (SN)	SERVICEABLE	57.00	-
			1,453.00	76.00
<u>LABOUR</u>				
	TO CUT, WELD, REPLACED ACCIDENT DAMAGE PARTS, ALIGNMENT AND CHECK ALSO TO KNOCKOUT & STRAIGHTEN - ACCIDENT DENTED PORTION SO AS TO REMOVE & REPLACE ACCIDENT AND REPLACED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BONNET.		2,080.00	1,560.00 400/-
	TO PUTTY, SAND DOWN & SPRAY PAINT ACCIDENT AFFECTED PORTION FACILITATE FOR THE REPAIR.		700.00	400/- 700.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		180.00	60.00
	TO CHECK WIRING AND LIGHTING OPERATION.		120.00	20.00
			-	880/-
			-	-
			3,080.00	2,340.00
GRAND TOTAL			10,848.30	4,684.00

Report Ref No. CS/SPF18013419/Nqd3e2

3224.00
4/s 2550/-



RECOMMENDED COST OF REPAIRS

4,684.00

Report Ref No. CS/SPF18013419/Nqd3e2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF ~~\$4,000-\$6,000~~

25301--

37001--

25301-- - 37001--

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

TAX INVOICE

SPF ACCIDENTS CLAIMS SECTION
NO.1 MOUNT PLEASANT ROAD
BLOCK 8 OLD POLICE ACADEMY
#02-12 SINGAPORE 298333

Document No: IN18-301656
Date : 24/09/2018

Vehicle No : SJY9292P
MERCEDES BENZ CLA180 AMG LINE
Mileage : 0

Staff ID : ANTHONY
Account No : SPF
Job No : T18-103817
Page 1

Description	Quantity	U Price	Disc%	Amount
REAR BUMPER	1	1,980.00	10.00	1,782.00
REAR LOWER BUMPER	1	540.00	10.00	486.00
BUMPER CLIPS	8	9.50		76.00
CONDUCTED WELDING, CUTTING, PENAL BEAT ACCIDENT DAMAGE PARTS ALIGNMENT AND CHECK ALSO TO KNOCKOUT AND STRAIGHTEN ACCIDENT DENTED PORTION SO AS TO REMOVED AND REPLACED ACCIDENT DAMAGE PARTS.	1	1,560.00		1,560.00
PERFORMED PUTTYING, SAND DOWN AND SPRAY PAINTING ON ACCIDENT AFFECTED PORTION SO AS TO FACILITATES THE REPAIR.	1	700.00		700.00
CONDUCTED REMOVAL AND REFITTING OF REVERSE SENSOR ASSY.	1	60.00		60.00
PERFORMED CHECKING OF WIRING HARNESS AND LIGHTING OPERATION.	1	20.00		20.00

Total 4,684.00
0.00

7.00% GST Pur 327.88
Nett Total 5,011.88
=====

*** Acknowledgement by Customer ***

I confirm that the goods stated in this invoice have
been received by me in good working order and condition.
I further confirm that all services and/or repair jobs
stated in this invoice are completed and done to my
satisfaction.

TTS EUROCARS PTE LTD



Name/Signature/WRIC No/Co Stamp (where applicable)

Authorised Signature



TTS EUROCARS pte ltd
A member of the TTS Motor Group

Company Reg. No: 200413930H GST No: 20-0413930-H

383 Sin Ming Drive, TTS Centre, Singapore 575717 • Sales: +65 6842 2222 • Admin: +65 6757 0122 • After Sales: +65 6757 2622 • Fax: +65 6741 1626
Branch: 15, Commonwealth Lane, Lot A1, Commonwealth Car Mall, Singapore 149554 • Tel: +65 6482 1111 • Fax: +65 6252 4834
24 Hours Emergency Assistance: +65 6475 2722

Website: www.tts.com.sg




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF18013419/Nqd3e2		
ACCIDENT CLAIM SECTION(SINGAPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMY SINGAPORE 298333		Date : 29-11-2018		
ATTN : ABDUL RAHMAN		Code : SPF		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	QX 4894H	Veh. Inspected	SJY 9292P	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/1009/2018/089	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	23/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ CLA180	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WDD1173422N652534	Colour	WHITE	
Odometer	1246	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/40 R18	DUNLOP	7 mm	
L/H Front Tyre	225/40 R18	DUNLOP	7 mm	
R/H Rear Tyre	225/40 R18	DUNLOP	7 mm	
L/H Rear Tyre	225/40 R18	DUNLOP	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/07/2018	Inspection Date	27/07/2018	
Survey held at	TTS EUROCARS PTE LTD 383 SIN MING DRIVE TTS CENTRE SINGAPORE 575717			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJY 9292P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	BENT	1,980.00	1,980.00
1	REAR LOWER BUMPER	WARPED	540.00	540.00
1	LH TAIL LAMP	SERVICEABLE	980.00	-
1	RH TAIL LAMP	SERVICEABLE	980.00	-
1	REAR BUMPER RETAINER LH	SERVICEABLE	48.00	-
1	REAR BUMPER RETAINER RH	SERVICEABLE	48.00	-
1	REAR BONNET	TO REPAIR SEE LABOUR	1,900.00	-
1	REAR BONNET MERCEDES STAR LOGO	NOT NECESSARY	66.00	-
1	REAR BONNET "CLA 180" CHROME ORNAMENT	NOT NECESSARY	115.00	-
1	REAR BONNET HINGE LH	SERVICEABLE	180.00	-
1	REAR BONNET HINGE RH	SERVICEABLE	180.00	-
	LESS 10% DISCOUNT		-701.70	-252.00
			6,315.30	2,268.00
<u>SPECIAL NETT ITEMS</u>				
8	CLIPS (SN)	NECESSARY	76.00	76.00
6	REAR PARKING SENSOR (SN)	SERVICEABLE	1,320.00	-
6	PARKING SENSOR O-RING (SN)	SERVICEABLE	57.00	-
			1,453.00	76.00
<u>LABOUR</u>				
	TO CUT, WELD, REPLACED ACCIDENT DAMAGE PARTS, ALIGNMENT AND CHECK ALSO TO KNOCKOUT & STRAIGHTEN - ACCIDENT DENTED PORTION SO AS TO REMOVE & REPLACE ACCIDENT AND REPLACED DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR BONNET.		2,080.00	400.00
	TO PUTTY, SAND DOWN & SPRAY PAINT ACCIDENT AFFECTED PORTION FACILITATE FOR THE REPAIR.		700.00	400.00
	TO REMOVE AND REFIT REVERSE SENSOR ASSY.		180.00	60.00
	TO CHECK WIRING AND LIGHTING OPERATION.		120.00	20.00
			-	-
			-	-
			3,080.00	880.00
GRAND TOTAL			10,848.30	3,224.00

Report Ref No. CS/SPF18013419/Nqd3e2



RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,550.00
---	--	--	----------

Report Ref No. CS/SPF18013419/Nqd3e2

NOTES : THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,550-\$3,700.00

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.