



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: 17.23342

Date: 07<sup>th</sup> Sep 2018

Our Ref: CS1/LAW18013424/Atbe2

**M/s Seah Ong & Partners LLP**

36 Robinson Road  
#12-03 City House  
Singapore 068877

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: YK 3690J**  
**INSURED VEHICLE: YM 8358B**  
**ACCIDENT DATE: 13/02/2017**

We thank you for your instruction on 27/06/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of YK 3690J from M/s Carlink Consultancy.
- b) Survey report by RT Appraisal Pte Ltd with colour photographs.
- c) Singapore Accident Statement of Vehicles YK 3690J and YM 8358B.
- d) Colour damaged vehicle photographs of YK 3690J.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: YK 3690J
Make & Model	: Mitsubishi FE639E6RDE
Year of Registration	: 2000
Chassis Number	: FE639EA40415
Engine Capacity	: 3907 cc

2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.