

**SPECIALISTS MOTOR PTE LTD**

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJM3409Z/1801005

23<sup>rd</sup> July 2018

The Manager  
Motor Claim Department  
Great American Insurance Company  
3 Temasek Avenue  
#16-01 Centennial Tower  
Singapore 039190

*Not Helioist  
hbr*

*EXCESS \$1500*

*26/7/18*

*4 day*

*Try 1/1/18*

*To keep photo taken painting*

Date of Accident : 22<sup>nd</sup> July 2018  
Location : Bishan Street 21  
Name of Policyholder : Lim Yew Jian  
Policy No : MOMVP000003421-00-000  
Vehicle No : SJM 3409 Z Mazda Roadster

Estimated Cost plus/ Supply of Parts & Labours

No.	Particulars	Qty	Price	Amounts
1	Front bumper fascia <i>DIS</i>	1	600.00	\$ 600.00 <i>—</i>
2	Front bumper clips <i>ren</i>	1set	30.00	\$ 30.00 <i>—</i>
3	Front bumper side retainer L&RH <i>MS sup</i>	2	45.00	\$ 90.00 <i>100</i>
4	Front bumper sponge <i>TO 11</i>	1	55.00	\$ 55.00 <i>—</i>
5	Front bumper towing cover <i>cut</i>	1	30.00	\$ 30.00 <i>—</i>
6	Front bumper fog lamp cover L&RH <i>MS grant</i>	2	30.00	\$ 60.00 <i>100</i>
7	Front bumper centre grille with chrome	1	600.00	\$ 600.00 <i>?</i>
8	Front bumper emblem (logo) <i>ren</i>	1	18.00	\$ 18.00 <i>—</i>
9	Headlamp assy L&RH <i>MS 310</i>	2	420.00	\$ 840.00 <i>100</i>
10	Front bumper reinforcement beam <i>bel</i>	1	290.00	\$ 290.00 <i>—</i>
11	Front fender cowling LH (front)	1	80.00	\$ 80.00 <i>→</i>
12	Front fender cowling LH (rear)	1	160.00	\$ 160.00 <i>→</i>
13	Front fender cowling clips	1set	25.00	\$ 25.00 <i>→</i>
14	Front support panel	1	350.00	\$ 350.00 <i>→</i>
15	Fuse box assy <i>11</i>	1	275.00	\$ 275.00 <i>X</i>
				\$ 3,503.00
Cost Plus			10%	\$ 350.30
				\$ 3,853.30

## SPECIALISTS MOTOR PTE LTD

Block 3018A, Ubi Road 1, #01-24-26, Singapore 408711

Tel: 67472112 (5 lines) Fax: 67438032

Email: cardoc@singnet.com.sg

Bus. Reg No: 199502604 E GST No: 19-9502604-E

SM/SJM3409Z/1801005

23<sup>rd</sup> July 2018

Balance b/f \$ 3,853.30

**Labour Charges :-**

	<u>Amounts</u>	
Cut out, renew, knocking & welding front bonnet, front fender LH, chassis pillar LH, remove & install all damage parts, straighten front chassis & re-align body	\$ 1,380.00	600
Remove & install air con system, vacuum & top up gas	\$ 120.00	?
Spray painting on damage parts	\$ 1,480.00	600
Check all lighting after repairs	\$ 40.00	20

Labour Charge \$ 3,020.00

Total Amount \$ 6,873.30

GST will be reflected in the final bills.

Notes : -Please inform us within 14 days, from the date of this letter, in the event that the owner/driver is in breach of its policy with your company, failing which we shall hold your company liable for all costs of repairs, loss of use and storage.

**LKK Auto Consultants** hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: