

Signature: *Paul*

REF:


NG/INC 18013445 / R1B22

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s: _____
 of: _____
 Insured: SLL 4889X
 Policy No: 50 88283153 - 01 71B16 - 16019
 Claims No: MT/1002999-003
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 16 days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB1307D Yr Regn: 216 / 66B
 Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ / Prime Mover /
 Truck / Trailer or

Make: Toyota Prous CC 1798
 Colour: Maroon A/C Insured / Std / NI / NA
 Sp. Reading: 26490 T/Radio: Insured / Std / NI / NA
 Eng/No: _____

C/No: STDKN36205767448

Gen. Cond: Good / ☒ / Poor / Burnt

Steering: ☒ / Jammed / Leaked / Burnt or

Brake: ☒ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/55R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Franken

Front	Rear
R/Bal. <u>5</u> mm	R/Bal. <u>5</u> mm
L/Bal. <u>5</u> mm	L/Bal. <u>5</u> mm
D.O.A. <u>14/7/2012</u>	D.O.I. <u>19/7/2012</u>

Survey held at SMRT

Des. of Damages: Frt / ☒ / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
12/9/2012	SHB 1307D - 173 / CTL16013446 / R1B22 CL 4889X - 173 / INC17011650 / 173 Confirmed final fig \$19,868.38 and 16 days. Red: \$18,348.58, 78% TAX / 07/12/2058 NTUE - SLL 4889X

RECEIVED 17 OCT 2012

Date/Time, File Pass to?

1) typist

Date/Time, File Return to?

2)

Report Format: TP

Lump Sum / ☒ : \$ 19,868.38

Days Of Repair: 16

Resurvey No. of Trip: _____

Add Fee: ☐ Site Insp (\$)
☐ Interview (\$)
☐ Tech Invs (\$)
☐ Weekend (\$)

Survey Fee

Transportation

\$ = P5, \$1

1) Show

1) Other

1)

TOTAL

160
160

Janice Lee (LKKAUTO)

From: mtreg <mtreg@income.com.sg>
Sent: Thursday, September 13, 2018 4:53 PM
To: Janice Lee (LKKAUTO)
Subject: FW: REQUEST CLAIMS NUMBER

Hi,

Claim created

With Regards

Samsia
Senior Admin Assistant,
Motor Insurance
www.income.com.sg



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.
Find out more at Income.com.sg/careers

in with you

'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504. Please forward all motor claims related correspondences to mtcl@income.com.sg so that we can attend to it accordingly.'

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Thursday, September 13, 2018 4:18 PM
To: mtreg <mtreg@income.com.sg>
Subject: REQUEST CLAIMS NUMBER

Dear Sir/ Madam,

Please refer to below.

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident
1	MT/1002999-003	SMRT TAXIS PTE LTD	SHB1307D	SLL 4889X	14/07/2018	15:00
						\$

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013445/R1rb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 24-07-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLL 4889X	Veh. Inspected	SHB 1307D
Policy No.	5088283153-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	14/07/2018	Inspection Date	19/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No. Date of Accident

Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☒	5088283153-01	ED LIMO	53352159M	GPC	drive CLASSIC	SL4889X	SL4889X	07/03/2018	16/02/2019

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	16/07/2018 09:08
Date Of Accident	14/07/2018 15:00
Exact Location Of Accident	PIE TOWARDS CHANGI BEFORE LORNIE ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB1307D
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	HASSAN BIN SUHAIMI
NRIC No	S1308896I
Date Of Birth	03/05/1958
Occupation	OUTDOOR
Date Of Driving Pass	30/10/2001
Driving Experience	16 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	638
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	TOA PAYOH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 93 TOA PAYOH CENTRAL TOA PAYOH COMMUNITY BUILDING ; POSTCODE: 319194 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-2519999 - FAX NO: 63548749
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT - T/20180714/2127 On 14/07/2018 at about 1500hrs, I was driving my taxi (SHB1307D) along PIE (Changi) lane number 1 just before Lornie Road when suddenly the traffic started slowing down due to congestion ahead as such I started to slow and eventually came to a stop. After which I felt an impact from my rear the impact was so great that my car moves forward but I did not hit the car in front of me. Subsequently I came down of my car and discovered that I was hit by an unknown car (SLL4889X) we then started to exchanged particulars and took photo of each other car damages. I wish to state that both car involved in the incident was unable to move and required towing service. My car bumper rear came off and the damages is quite big as such my car is unable to move. No police and ambulance came to the scene, however LTA officer came and make a check and affirm no ambulance is needed and advice both parties to seek medical attention if we are feeling unwell. After which EMAS was activated and tow my car to the nearest car park. After which I proceed to Intemedical 24HRS Clinic because I felt some pain on the back of my head and neck and was certify with a five days' medical certificate. I wish to state that I gave in-car front camera but is unsure whether it is able to capture the incident. I am lodging this report for insurance purposes.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLL4889X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	EDDIE KOH AI CHUAN

NRIC/Passport Number	S7225206C
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	2
Passenger 1	NAME: : GENDER: : FEMALE

DETAILS OF INJURED PERSON 1

Name	HASSAN BIN SUHAIMI
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB1307D
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

LORNE RD



A - PHB 13070
B - SLL 4889X

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

This image shows a single sheet of white paper with horizontal blue or grey ruling lines. The lines are evenly spaced and run across the width of the page. There is no handwriting or other markings on the paper.

DECLARATION
I/We declare the true

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name: _____
NRIC/Fin No.: _____



**SINGAPORE
POLICE FORCE**



T/20180714/2127

Police Station Of Origin:
Toa Payoh N.P.C
93 Toa Payoh Central #01-02 Toa Payoh
Community Building SINGAPORE 319194
Tel No: 1800-2519999

1 of 4

Report No. T/20180714/2127

REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 14/07/2018 17:17	Vide Report No.:	Station Diary No.: 136
--	------------------	---------------------------

Informant's Particulars

Name of Informant: HASSAN BIN SUHAIMI			Address: APT BLK 638 YISHUN STREET 61 #06-156 SINGAPORE 760638	
ID Type / ID No.: NRIC NO / S1308896I			Contact No.: Home/Office: Mobile: 98244722	
Nationality: SINGAPORE CITIZEN			Email:	
Sex: Male	Age: 60	Date of Birth: 03/05/1958	Type of Informant: Driver	
Race: Javanese			Language:	Institution / School Name:
Occupation: Taxi driver			Driving Licence Information: Class: 2B,3,4 Date of Expiry:	

General Information of the Accident

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident; 14/07/2018 15:00	Type of Location: Straight Road
Location: Along Road 1 LORNIE ROAD				
PIE(Changi) just before Lornie Road (first lane)				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow: Dual Carriage Way		Traffic Control: Not Controlled		Traffic Volume: Heavy
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

Details of Vehicle Involved

Vehicle No	Type	Make	Model	Color	Condition	No. of Passenger
SHB1307D	Car	TOYOTA	PRIUS	Maroon	Slightly Damaged	0
SLL4889X	Car	VOLVO	V40	Red	Slightly Damaged	1

Details of Person Involved

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE
POLICE FORCE**



T/20180714/2127

2 of 4

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

Report No. T/20180714/2127

CONTINUATION OF REPORT

Driver			
Name	HASSAN BIN SUHAIMI	ID No.	S1308896I
Related Vehicle	SHB1307D (Car)	Contact No.	98244722
Hospital/Clinic	INTEMEDICAL 24HR CLINIC	Class of Driving Licence & Expiry Date	Class: 2B,3,4 Date of Expiry: NIL
Date Treatment	14/07/2018	Date Discharge	NIL
No. of Days granted Medical Leave	05	Degree of Injury	Slight
Driver			
Name	EDDIE KOH AI CHUAN	ID No.	S7225206C
Related Vehicle	SLL4889X (Car)	Contact No.	90605206
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

Brief Details.

On 14/07/2018 at about 1500hrs, I was driving my taxi(SHB1307D) along PIE(changi) Lane number 1 just before Lornie road when suddenly the traffic started slowing down due to congestion ahead as such I started to slow down and eventually came to a stop.

After which I felt an impact from my rear the impact was so great that my car moves forward but I did not hit the car in front of me. Subsequently I came down of my car and discovered that I was hit by an unknown car(SLL4889X) we then started to exchanged particulars and took photo of each other car damages. I wish to state that both car involved in the incident was unable to move and required towing service.

My car bumper(Rear) came off and the damages is quite big as such my car is unable to move. No police and ambulance came to the scene, however LTA officer came and make a check and affirm no ambulance is needed and advice both parties to seek medical attention if we are feeling unwell. After which EMAS was activated and tow my car to the nearest car park.

After which I proceed to Intemedical 24Hrs Clinic because I felt some pain on the back of my head and neck and was certify with a five days' medical certificate. I wish to states than I have in-car front camera but is unsure whether it is able to capture the incident. I am lodging this report for insurance purposes.



**SINGAPORE
POLICE FORCE**



T/20180714/2127

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

3 of 4

Report No. T/20180714/2127

CONTINUATION OF REPORT



**SINGAPORE
POLICE FORCE**



T/20180714/2127

4 of 4

Report No. T/20180714/2127

Police Station Of Origin:

Toa Payoh N.P.C

93 Toa Payoh Central #01-02 Toa Payoh

Community Building SINGAPORE 319194

Tel No: 1800-2519999

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

E /

Sgt 2 CHUA JIN JUN

Signature Of Informant:

Signature Of Interpreter:

Not applicable

Date/Time:

14/07/2018 17:17

Officer In Charge Of Case:

TP / AE13

Staff Sgt WONG SIEU LUI

Contact No.: 65476151

SN 168

Classification Of Case:

Authentication Stamp

NP168

SIGNATURE

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1307D
 Ref. No : TAX/07/18/2058
 Reg. Date : 19/02/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : HASSAN BIN SUHAIMI
 Type of Accident : HEAD TO REAR
 Date / Time of Accident : 14/07/2018 03:00:00 PM
 Accident Reported Date / Time : 16/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : Yes
 Towed Back Date/Time : 14/07/2018
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097040
 Special Instruction to ARC, if any :
 TOWED \$120 / SLL4889X (NTUC) - LKK *(Resm b4 part)*
 Prepared Date : 16/07/2018 09:31:03 AM



LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Chassis No : JTDKN36U705767448

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	1,859.00	0.00
Total Spray Painting Charges	4,608.00	0.00
Total Material Charges	22,608.60 <i>28,618.22</i>	22,608.60
Other Charges	3,131.76	0.00
TOTAL	32,207.36 <i>38,216.98</i>	0.00
Lum Sum Total	0.00	0.00
No. of Repair Days	12.00	0.00 <i>12 days - P/P</i>
Prepared / Adjusted By		
Arc / Surveyor Sign Off Date	17/07/2018 03:06:42 PM	01/01/1900 12:00:00 AM

F

Rel 19/07/18
25/7/18
@1620

Prepared / Adjusted Date :

Remarks :

Prepared Date : 17/07/2018 03:02:44 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/17/2018 3:03:36 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	0.00 1200 1400
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200 /
TO RESPRAY TAIL GATE	378.00	0.00 200 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 100 /
TO RESPRAY SPOILER	180.00	0.00 X 11
TO RESPRAY RH RAIL ROOF SIDE	180.00	0.00 100 /
TO RESPRAY FRONT DOOR RH	378.00	0.00 200 X 11
TO RESPRAY REAR DOOR RH	378.00	0.00 200 /
TO RESPRAY REAR PANEL	180.00	0.00 100 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00 100 /
TO RESPRAY REAR MEMBER,LH	180.00	0.00 100 /
TO RESPRAY REAR MEMBER,RH	180.00	0.00 100 /
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00 80 /
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00 80 /
TO RESPRAY REAR RH WHEEL HOUSE	180.00	0.00 100 /
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00 X 11
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00 X 11
TO RESPRAY REAR FENDER LH	378.00	0.00 200 /
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 X 11
TO RESPRAY REAR FENDER RH	378.00	0.00 200 /
Total Spray Painting & Panel Beating	4,608.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	168.00	0.00 X 11
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 100 /
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 X 11
TO REMOVE / REFIT SEAT	120.00	0.00 60 /
TO REMOVE & REFIT EXHAUST	120.00	0.00 60 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	0.00 250 /
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00 X 11
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 60 /
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00 ? X 11
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60 /
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76	0.00 593.76 / net
TO ALIGN CHASSIS	350.00	0.00 200 /
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60 /
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60 /
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 30 /
TO REPLACE SUNDRY PARTS	100.00	0.00 X 11
TO WASH AND VACUUM	60.00	0.00 X 11
Total Other Costs	3,131.76	0.00

10128.76

31431.60

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95 ✓	Replace	Replace <i>DE</i>	No
52161-16010			BUMPER CLIPS	10	1.61 <i>(6.10)</i>	25.00	12.07 ✓	Replace	Replace <i>Am</i>	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27 ✓	Replace	Replace <i>RA</i>	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70 ✓	Replace	Replace <i>RA</i>	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70 ✓	Replace	Replace <i>RA</i>	No
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66 ✓	Replace	Replace <i>CR</i>	No
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15 ✓	Replace	Replace <i>DE</i>	No
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57 ✓	Replace	Replace <i>DE</i>	No
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67 ✓	Replace	Replace <i>DE</i>	No
			SENSOR REVERSE	1	180.00	0.00	180.00 ✓	Replace	Replace <i>DE</i>	No
			PIXEL STICKER	2	60.00 <i>(120)</i>	0.00	120.00 ✓	Replace	Replace <i>DE</i>	No
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67 ✓	Replace	Replace <i>DE</i>	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27 ✓	Replace	Replace <i>DE</i>	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10 ✓	Replace	Replace <i>DE</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10 ✓	Replace	Replace <i>DE</i>	No
8308-17011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.87 ✓	Replace	Replace <i>DE</i>	No
8327-17020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55 ✓	Replace	Replace <i>DE</i>	No
7430-17380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15 ✓	Replace	Replace <i>DE</i>	No
7565-12030			SUPPORT, EXHAUST REAR	2	33.60 <i>(67.20)</i>	25.00	50.40 ✓	Replace	Replace <i>DE</i>	No
17005-7241			TAILGATE ASY	1	1,007.90	25.00	755.92 ✓	Replace	Replace <i>DE</i>	No
5574-7020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05 ✓	Replace	Replace <i>DE</i>	No
5573-7080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05 ✓	Replace	Replace <i>DE</i>	No
5575-7030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05 ✓	Replace	Replace <i>DE</i>	No
8810-7010			TAILGATE DOOR HINGE LH/RH	2	58.30 <i>(116.60)</i>	25.00	87.45 ✓	Replace	Replace <i>DE</i>	No
9350-7030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07 ✓	Replace	Replace <i>DE</i>	No
8960-W532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.12 ✓	Replace	Replace <i>DE</i>	No
8950-W542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.12 ✓	Replace	Replace <i>DE</i>	No

66550

Number				Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
67381-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05 ✓	Replace	Replace <i>neu</i>	No
	COMMON		SEALANT W/SCREEN	3	37.00 <i>(111)</i>	0.00	111.00 ✓	Replace	Replace <i>neu</i>	No
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67 ✓ 378.60	Replace	Replace <i>DE</i>	No
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.67 ✓ 36.63	Replace	Replace ? <i>neu</i>	No
	REAR		NUMBER PLATE	1	30.00	0.00	30.00 ✓	Replace	Replace <i>neu</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00 ✓	Replace	Replace <i>DE</i>	No
81271-53011		6505463	LICENSE PLATE LAMP	2	35.70 <i>(2140)</i>	10.00	64.26 ✓	Replace	Replace ? <i>neu</i>	No
84840-28040	REAR		SWITCH ASSY, BACK DOOR OPENER	1	146.10	10.00	131.49 ✓	Replace	Replace ? <i>neu</i>	No
86790-47040			CAMERA ASSY, TELEVISION, RR	1	1,436.60	10.00	1,292.94 ✓	Replace	Replace ? <i>neu</i>	No
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92 ✓	Replace	Replace <i>neu</i>	No
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60 ✓	Replace	Replace <i>neu</i>	No
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92 ✓	Replace	Replace <i>neu</i>	No
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22 ✓	Replace	Replace <i>neu</i>	No
37938-47031C0			TAILGATE TRIM, LH	1	85.90	25.00	64.42 ✓	Replace	Replace ? <i>neu</i>	No
37751-47040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.52 ✓	Replace	Replace ? <i>neu</i>	No
37937-47031C0			TAILGATE TRIM, RH	1	88.30	25.00	66.22 ✓	Replace	Replace ? <i>neu</i>	No
34790-47030C0			TAILGATE TRIM, UPPER	1	49.60	25.00	37.20 ✓	Replace	Replace ? <i>neu</i>	No
37750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.17 ✓ 185.18	Replace	Replace ? <i>neu</i>	No
6085-47910		6505620	SPOILER REAR	1	953.70	25.00	715.27 ✓	Replace	Replace <i>X neu</i>	No
11006-47011		6505464	3RD BRAKE LAMP	1	231.30	10.00	208.17 ✓	Replace	Replace <i>X neu</i>	No
	COMMON		SMRT LOGO	1	7.80	0.00	7.80 ✓	Replace	Replace <i>neu</i>	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60 ✓	Replace	Replace <i>neu</i>	No
2184-7370			WIRE, BACK DOOR, NO.1	1	582.40	10.00	524.16 ✓	Replace	Replace ? <i>neu</i>	No
2161-7B22			WIRE, FLOOR	1	1,675.00	10.00	1,507.50 ✓	Replace	Replace ? <i>neu</i>	No
1217-7010			RAIL, ROOF SIDE	1	273.60	25.00	205.20 ✓	Replace	Replace ? <i>neu</i>	No
2470-7110B0			GARNISH ASSY, ROOF RH	1	256.40	25.00	192.30 ✓	Replace	Replace ? <i>neu</i>	No
2480-7050-B0			GARNISH SIDE UPPER, LHR	1	261.70	25.00	196.27 ✓	Replace	Replace <i>X neu</i>	No
8307-7060		6505522	END PANEL	1	602.10	25.00	451.57 ✓	Replace	Replace <i>neu</i>	No
4718-7031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57 ✓ 34.58	Replace	Replace ? <i>neu</i>	No
4716-7031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82 ✓ 90.83	Replace	Replace <i>neu</i>	No

2623.40

Number				Qty	Unit Price (\$)	Discount (%)	Final Price (\$)	Recommend	Surveyor Approved	Photos Attached
58336-12090			REINFORCEMENT, RR	2	34.60	69.30	25.00	51.90	Replace	Replace ? No
	COMMO N	4006314	SEALANT SIKAFLEX	1	37.00		0.00	37.00	Replace	Replace ? No
58311-47071		6505523	SPARE TYRE PANEL	1	667.70		25.00	500.77	Replace	Replace ? No
64777-47090			CUSHION, SPARE WHEEL	1	230.80		25.00	173.10	Replace	Replace ? No
51931-47020			CARRIER, SPARE	1	19.70		25.00	14.77	Replace	Replace ? No
64778-47050			PROTECTOR, SPARE	1	143.70		25.00	107.77	Replace	Replace ? No
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10		25.00	130.57	Replace	Replace ? No
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10		25.00	130.57	Replace	Replace ? No
58303-47301			FLOOR PANEL RR/LH	1	102.00		25.00	76.50	Replace	Replace ? No
58302-47030			FLOOR PANEL RR/RH	1	209.90		25.00	157.42	Replace	Replace ? No
31607-47060			PANEL SUB-ASSY, QTR	1	588.40		25.00	441.30	Replace	Replace ? No
31608-47061			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40		25.00	441.30	Replace	Replace ? No
58415-47030			BOARD, RR FLOOR	1	392.30		25.00	294.22	Replace	Replace ? No
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60		25.00	509.70	Replace	Replace ? No
34993-47020			BOX, DECK FLOOR, RR	1	649.70		25.00	487.27	Replace	Replace ? No
38418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10		25.00	172.57	Replace	Replace ? No
34997-47020			BOX, DECK FLOOR, LH	1	196.80		25.00	147.60	Replace	Replace ? No
38490-47140B0			BOARD ASSY, RR RH	1	379.20		25.00	284.40	Replace	Replace ? No
38427-47040			SPACER, RR FLOOR	1	130.60		25.00	97.95	Replace	Replace ? No
4440-47030			BATTERY TRAY	1	42.80		25.00	32.10	Replace	Replace ? No
4481-47050			BATTERY CLAMP	1	16.10		25.00	12.07	Replace	Replace ? No
			BATTERY	1	278.00		10.00	250.20	Replace	Replace ? No
2563-7010			TAIL LAMP BRACKET, LH	1	30.70		25.00	23.02	Replace	Replace ? No
1561-7170		6505461	TAIL LAMP LH	1	548.40		10.00	493.56	Replace	Replace ? No
1622-7030			TROUGH, BACK DOOR LH	1	110.90		10.00	99.81	Replace	Replace ? No
1602-7091		6505476	FENDER RR/LH	1	766.80		25.00	575.10	Replace	Replace ? No
	COMMO N		SMRT LOGO	1	7.80		0.00	7.80	Replace	Replace ? No
			STICKER DECAL 6555 8888	1	21.60		0.00	21.60	Replace	Replace ? No
2720-7031			QUARTER GLASS RR/LH	1	168.10		25.00	126.07	Replace	Replace ? No
	COMMO N		SEALANT W/SCREEN	1	37.00		0.00	37.00	Replace	Replace ? No

7691.50

Number			Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
85638-47021	6505477	FENDER LINER RR/LH	1	141.30	25.00	105.97	Replace	Replace <i>X</i>	No <i>suc</i>
64740-47031B2		PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Replace <i>?</i>	No <i>suc</i>
64730-47031B2		PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace <i>?</i>	No <i>suc</i>
52562-47010		TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace <i>?</i>	No <i>suc</i>
81551-47180	6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace <i>BRO</i>	No
61621-47030		TROUGH, BACK DOOR	1	110.90	25.00	83.17	Replace	Replace <i>X</i>	No <i>An</i>
61604-47090		FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>Re</i>	No
	COMMON	SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>Re</i>	No
		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>Re</i>	No
52710-47130		QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace <i>Re</i>	No
	COMMON	SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>Re</i>	No
35637-47021	6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace <i>?</i>	No <i>suc</i>
31625-47040		EXTENSION, QUARTER	1	55.70	25.00	41.77	Replace	Replace <i>?</i>	No <i>suc</i>
31623-47010		EXTENSION, QUARTER	1	83.50	25.00	62.62	Replace	Replace <i>?</i>	No <i>suc</i>
31743-47010		REINFORCEMENT, BACK	1	89.50	25.00	67.12	Replace	Replace <i>?</i>	No <i>suc</i>
31713-47020		REINFORCE, ROOF SIDE	1	91.90	25.00	68.92	Replace <i>?</i>	Replace <i>?</i>	No <i>suc</i>
3173747020		REINFORCEMENT, ROOF	1	60.30	25.00	45.22	Replace	Replace <i>?</i>	No <i>suc</i>
	6503707	TYRE	1	126.74	0.00	126.74	Replace	Replace <i>X</i>	No <i>suc</i>
17003-17080	6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>Repair</i>	No
19050-17080		DOOR LOCK RR/RH	1	709.30	25.00	531.97	Replace	Replace <i>?</i>	No <i>suc</i>
19410-13010		DOOR LOCK STRIKER	1	40.50	25.00	30.37	Replace	Replace <i>X</i>	No
18770-2031		HINGE LOWER RHR, DOOR	1	52.00	25.00	39.00	Replace	Replace <i>X</i>	No
8750-0121		HINGE UPPER RHR, DOOR	1	81.70	25.00	61.27	Replace	Replace <i>X</i>	No
8630-7031		CHECK ASSY, RR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>X</i>	No <i>suc</i>
7001-7070	6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>X</i>	No
		STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>X</i>	No
TOTAL MATERIALS							22,608.86	22,608.60	
TOTAL MATERIALS(Discounted)				6776.04		22,608.60	22,608.60		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

2-8-18 / 10:13

ADV - 2-8-18 / 14:13


3-8-18 / 09:13

SMRT Accident Vehicle Repair Estimates

20-7-18 / 09:13

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1307D
Ref. No : TAX/07/18/2058
Reg. Date : 19/02/2016
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : HASSAN BIN SUHAIMI
Type of Accident : HEAD TO REAR
Date / Time of Accident : 14/07/2018 03:00:00 PM
Accident Reported Date / Time : 16/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Rasul
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 14/07/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024097040
Special Instruction to ARC, if any :
TOWED \$120 / SLL4889X (NTUC) - LKK P/P
Before paint photo, After repair photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR RASUL
/ HP : 9001 0058, email: rasul@lkkauto.com
Prepared Date : 16/07/2018 09:31:03 AM



QC 8-8-18 14, & Project
Box Beck Floor RR Crack
16.37 VSSG

Supplementary
* Refer to the Supplementary form 11st ✓

Recording Camera ☒ ☐

Radio Antenna ☒ ☐

1st witness [Signature] Date 20-7-18

2nd witness _____ Date _____

264222 km

LEE SHENG AUTO PTE LTD

Vehicle Return Date: 08.8.18

Vehicle Return Time: Am 12:00

SMRT staff name: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705767448

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,859.00	1,400.00
Total Spray Painting Charges	: 4,608.00	1,860.00
Total Material Charges	: 22,881.35	14,784.66
Other Charges	: 3,493.76	1,823.76
TOTAL	: 32,842.11	19,868.42
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 17.00	16.00
Prepared / Adjusted By	:	RASUL (LKK)
Arc / Surveyor Sing Off Date	: 17/07/2018 03:06:42 PM	19/07/2018 04:46:40 PM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 17/07/2018 03:02:44 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No	: QN-1808-0273	Invoice No	:
Quotation Date	: 13/8	Invoice Date	:
Invoice Amount	: 0.00	Prepared Date	: 7/17/2018 3:03:36 PM

14784.62
1400
+ 3683.76

19868.38

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,859.00	1,400.00 /
Total Labour	1,859.00	1,400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 /
TO RESPRAY TAIL GATE	378.00	200.00 /
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100.00 /
TO RESPRAY SPOILER	180.00	0.00 x
TO RESPRAY RH RAIL ROOF SIDE	180.00	100.00 /
TO RESPRAY FRONT DOOR RH	378.00	0.00 x
TO RESPRAY REAR DOOR RH	378.00	200.00 /
TO RESPRAY REAR PANEL	180.00	100.00 /
TO RESPRAY REAR SPARE TYRE PANEL	180.00	100.00 /
TO RESPRAY REAR MEMBER,LH	180.00	100.00 /
TO RESPRAY REAR MEMBER,RH	180.00	100.00 /
TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	80.00 /
TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	80.00 /
TO RESPRAY REAR RH WHEEL HOUSE	180.00	100.00 /
TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00
TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00
TO RESPRAY REAR FENDER RH	378.00	200.00 /
Total Spray Painting & Panel Beating	4,608.00	1,860.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	100.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00
TO REMOVE / REFIT SEAT	120.00	60.00
TO REMOVE & REFIT EXHAUST	120.00	60.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	250.00	250.00
TO REMOVE & REFIT REAR QUARTER GLASS LH	120.00	0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	60.00
TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	60.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76	593.76
TO ALIGN CHASSIS	350.00	200.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	60.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00
TO REPLACE SUNDRY PARTS	100.00	0.00
TO WASH AND VACUUM	60.00	0.00
TO CHECK & RESET SYSTEM FUNCTION	350.00	100.00
TO REMOVE AND REFIT BATTERY ASSY HV	180.00	150.00
Total Other Costs	3,493.76	1,823.76

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No ✓
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace	No ✓
52023-12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace	No ✓
52016-47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace	No ✓
52015-47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace	No ✓
89997-30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace	No ✓
76088-47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No ✓
76087-47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace	No ✓
76891-47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No ✓
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No ✓
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No ✓
52592-47021			BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace	No ✓
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace	No ✓
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No ✓
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No ✓
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR	1	514.50	25.00	385.88	Replace	Replace	No ✓
58327-47020			EXHAUST HEAT SHIELD, REAR	1	107.40	25.00	80.55	Replace	Check	No X
17430-37380			EXHAUST TAIL PIPE	1	656.20	25.00	492.15	Replace	Replace	No ✓
17565-22030			SUPPORT, EXHAUST REAR	2	33.60	25.00	50.40	Replace	Replace	No ✓
67005-47241			TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace	No ✓
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace	No ✓
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace	No ✓
75575 - 47030			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace	No ✓
68810-47010			TAILGATE DOOR HINGE LH/RH	0	58.30	25.00	0.00	Replace	Not given	No X
69350-47030			TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace	No ✓
68960-0W532			TAILGATE DOOR STAY LH	1	241.50	25.00	181.13	Replace	Check	No X
68950-0W542			TAILGATE DOOR STAY RH	1	241.50	25.00	181.13	Replace	Check	No X

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67881-47022			TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace	No ✓
	COMMON		SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace	No ✓
76801-47070-B0			TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace	No ✓
69431-47010			STRIKER, BACK DOOR	1	48.90	25.00	36.68	Replace	Check	No X
	REAR		NUMBER PLATE	1	30.00	0.00	30.00	Replace	Replace	No ✓
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No ✓
81271-53011		6505463	LICENSE PLATE LAMP	1	35.70	10.00	32.13	Replace	Check	No X
84840-28040	REAR		SWITCH ASSY, BACK DOOR OPENER	1	146.10	10.00	131.49	Replace	Check	No X
86790-47040			CAMERA ASSY, TELEVISION, RR	1	1,436.60	10.00	1,292.94	Replace	Check	No X
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No ✓
75442-47030			NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace	No ✓
75443-47030			NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace	No ✓
75310-47020		6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace	No ✓
67938-47031C0			TAILGATE TRIM, LH	1	85.90	25.00	64.42	Replace	Check	No X
67751-47040C0			TAILGATE TRIM, LOWER	1	180.70	25.00	135.53	Replace	Check	No X
67937-47031C0			TAILGATE TRIM, RH	1	88.30	25.00	66.23	Replace	Check	No X
64790-47030C0			TAILGATE TRIM, UPPER	1	49.60	25.00	37.20	Replace	Check	No X
67750-47071C0			TAILGATE, BOARD ASSY	1	246.90	25.00	185.18	Replace	Replace	No ✓
76085-47910		6505620	SPOILER REAR	0	953.70	25.00	0.00	Replace	Not given	No X
81006-47011		6505464	3RD BRAKE LAMP	0	231.30	10.00	0.00	Replace	Not given	No X
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ✓
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ✓
82184-47370			WIRE, BACK DOOR, NO.1	1	582.40	10.00	524.16	Replace	Check	No X
82161-47B22			WIRE, FLOOR	1	1,675.00	10.00	1,507.50	Replace	Check	No X
81217-47010			RAIL, ROOF SIDE	1	273.60	25.00	205.20	Replace	Check	No X
62470-47110B0			GARNISH ASSY, ROOF RH	1	256.40	25.00	192.30	Replace	Check	No X
62480-47050-B0			GARNISH SIDE UPPER, LHR	0	261.70	25.00	0.00	Replace	Not given	No X
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace	No ✓
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.58	Replace	Replace	No ✓
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.83	Replace	Replace	No ✓

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
58336-12090			REINFORCEMENT, RR	1	34.60	25.00	25.95	Replace	Check	No ☒
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace	No ☒
58311-47071		6505523	SPARE TYRE PANEL	1	667.70	25.00	500.77	Replace	Replace	No ☒
64777-47090			CUSHION, SPARE WHEEL	1	230.80	25.00	173.10	Replace	Replace	No ☒
51931-47020			CARRIER, SPARE	1	19.70	25.00	14.78	Replace	Replace	No ☒
64778-47050			PROTECTOR, SPARE	1	143.70	25.00	107.78	Replace	Replace	No ☒
57604-47030			MEMBER SUB-ASSY, RR LH	1	174.10	100.00	0.00	Replace	Repair	No ☒
57603-47030			MEMBER SUB-ASSY, RR RH	1	174.10	25.00	130.58	Replace	Replace	No ☒
58303-47301			FLOOR PANEL RR/LH	1	102.00	25.00	76.50	Replace	Check	No ☒
58302-47030			FLOOR PANEL RR/RH	1	209.90	25.00	157.43	Replace	Replace	No ☒
61607-47060			PANEL SUB-ASSY, QTR	1	588.40	25.00	441.30	Replace	Check	No ☒
61608-47061			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	25.00	441.30	Replace	Check	No ☒
58415-47030			BOARD, RR FLOOR	1	392.30	25.00	294.22	Replace	Check	No ☒
58416-47030B3			BOX, RR FLOOR, BOARD	1	679.60	25.00	509.70	Replace	Check	No ☒
64993-47020			BOX, DECK FLOOR, RR	1	649.70	25.00	487.28	Replace	Replace	No ☒
58418-47070B0			BOX, DECK FLOOR, COVER LH	1	230.10	25.00	172.57	Replace	Check	No ☒
64997-47020			BOX, DECK FLOOR, LH	1	195.80	25.00	147.80	Replace	Check	No ☒
58490-47140B0			BOARD ASSY, RR RH	1	379.20	25.00	284.40	Replace	Replace	No ☒
58427-47040			SPACER, RR FLOOR	1	130.60	25.00	97.95	Replace	Check	No ☒
74440-47030			BATTERY TRAY	1	42.80	25.00	32.10	Replace	Check	No ☒
74481-47050			BATTERY CLAMP	1	16.10	25.00	12.07	Replace	Check	No ☒
			BATTERY	1	278.00	10.00	250.20	Replace	Replace	No ☒
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Check	No ☒
81561-47170		6505461	TAIL LAMP LH	0	548.40	10.00	0.00	Replace	Not given	No ☒
61622-47030			TROUGH, BACK DOOR LH	0	110.90	10.00	0.00	Replace	Not given	No ☒
61602-47091		6505476	FENDER RR/LH	1	766.80	100.00	0.00	Replace	Repair	No ☒
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ☒
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ☒
62720-47031			QUARTER GLASS RR/LH	0	168.10	25.00	0.00	Replace	Not given	No ☒
	COMMON		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No ☒

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
85636-47021		6505477	FENDER LINER RR/LH	0	141.30	25.00	0.00	Replace	Not given	No ☒
84740-47031B2			PANEL ASSY, DECK LH	1	307.00	25.00	230.25	Replace	Check	No ☒
84730-47031B2			PANEL ASSY, DECK RH	1	307.00	25.00	230.25	Replace	Replace	No ☒
52562-47010			TAIL LAMP BRACKET, RH	0	30.70	25.00	0.00	Replace	Not given	No ☒
81551-47180		6505462	TAIL LAMP RH	1	557.80	10.00	502.02	Replace	Replace	No ☒
81621-47030			TROUGH, BACK DOOR	0	110.90	25.00	0.00	Replace	Not given	No ☒
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace	No ☒
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace	No ☒
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No ☒
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace	No ☒
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No ☒
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.98	Replace	Check	No ☒
61625-47040			EXTENSION, QUARTER	1	55.70	25.00	41.77	Replace	Check	No ☒
61623-47010			EXTENSION, QUARTER	1	83.50	25.00	62.62	Replace	Check	No ☒
61743-47010			REINFORCEMENT, BACK	1	89.50	25.00	67.12	Replace	Check	No ☒
61713-47020			REINFORCE, ROOF SIDE	1	91.90	25.00	68.92	Replace	Check	No ☒
6173747020			REINFORCEMENT, ROOF	1	60.30	25.00	45.22	Replace	Check	No ☒
		6503707	TYRE	0	126.74	0.00	0.00	Replace	Not given	No ☒
67003-47080		6505486	DOOR RR/RH	1	954.50	100.00	0.00	Replace	Repair	No ☒
69050-47080			DOOR LOCK RR/RH	1	709.30	25.00	531.97	Replace	Check	No ☒
69410-33010			DOOR LOCK STRIKER	0	40.50	25.00	0.00	Replace	Not given	No ☒
68770-52031			HINGE LOWER RHR, DOOR	0	52.00	25.00	0.00	Replace	Not given	No ☒
68750-20121			HINGE UPPER RHR, DOOR	0	81.70	25.00	0.00	Replace	Not given	No ☒
68630-47031			CHECK ASSY, RR DOOR,	0	150.30	25.00	0.00	Replace	Not given	No ☒
67001-47070		6505528	DOOR FRT/RH	0	894.40	25.00	0.00	Replace	Not given	No ☒
			STICKER DECAL SMRT (DOOR)	0	60.00	0.00	0.00	Replace	Not given	No ☒
G3834-48010			GRIP, SERVICE PLUG	1	52.00	25.00	39.00	Replace	Replace	No ☒
G9510-47060			BATTERY ASSY, HV	1	5,544.40	10.00	4,989.96	Replace	Replace	No ☒
TOTAL MATERIALS							22,881.49	14,784.67		
TOTAL MATERIALS(Discounted)							22,881.35	14,784.66		

Added Spare Parts / Material Usage After Surveyor Signed off

Janice Lee (LKKAUTO)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Monday, August 13, 2018 4:00 PM
To: Rasul (LKKAUTO)
Cc: SUR; CS A Team; 'Ms Lee (Lee Sheng Auto)'
Subject: SHB1307D
Attachments: img-813160035-0001.pdf

Hi Rasul,

Attached herewith the repair estimate of SHB 1307D having Case No: TAX/07/18/2058.

There is no change to the approved amount of \$19,868.42 @ 16 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Ms Lee,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Monday, 13 August 2018 4:01 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013445/R1rbe2			
73 BRAS BASAH ROAD		Date: 03-10-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE			
189556		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLL 4889X	Veh. Inspected	SHB 1307D
Policy No.	5088283153-01	Coverage (\$)	0.00
Claim No.	MT/1002999-003	Excess (\$)	0.00
Assign From		Assign Date	19/07/2018
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	JTDKN36U705767448	Colour	MAROON
Odometer	264190	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	5 mm
L/H Front Tyre	195/65 R15	FALKEN	5 mm
R/H Rear Tyre	195/65 R15	FALKEN	5 mm
L/H Rear Tyre	195/65 R15	FALKEN	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/07/2018	Inspection Date	19/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR		16 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.: 1 of 5

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 1307D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	ADVERTISEMENT STICKER (SN)	NECESSARY	593.76	593.76
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.27
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	BENT	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER LIP COVER RR/LH (DISC 25%)	DEFORMED	72.20	54.15
1	BUMPER LIP COVER RR/RH (DISC 25%)	DEFORMED	118.10	88.57
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	BUMPER SEAL, RR LH (DISC 25%)	NECESSARY	88.90	66.67
1	BUMPER SEAL, RR RH (DISC 25%)	NECESSARY	65.70	49.27
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	NECESSARY	94.80	71.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
1	UNDER COVER SUB-ASSY, RR FLOOR (DISC 25%)	DEFORMED	514.50	385.88
1	EXHAUST TAIL PIPE (DISC 25%)	BENT	656.20	492.15
2	SUPPORT, EXHAUST REAR @\$33.60 (DISC 25%)	DISTORTED	67.20	50.40
1	TAILGATE ASY (DISC 25%)	BUCKLED	1,007.90	755.92
1	TAIL GATE DOOR GLASS MOULDING, LH (DISC 25%)	NECESSARY	29.40	22.05
1	TAIL GATE DOOR GLASS MOULDING, RH (DISC 25%)	NECESSARY	29.40	22.05
1	MOULDING BACK WINDOW, LOWER NO.1 (DISC 25%)	NECESSARY	29.40	22.05
1	TAILGATE DOOR LOCK (DISC 25%)	JAMMED	444.10	333.05
1	TAILGATE DOOR WEATHER STRIP (DISC 25%)	NECESSARY	353.40	265.05
1	TAILGATE OUTSIDE GARNISH (DISC 25%)	DEFORMED	504.90	378.60
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	NAME PLATE (PRIUS) (DISC 25%)	NECESSARY	60.80	45.60
1	NAME PLATE (TOYOTA) (DISC 25%)	NECESSARY	51.90	38.92
1	EMBLEM REAR (DISC 25%)	NECESSARY	60.30	45.22
1	TAILGATE, BOARD ASSY (DISC 25%)	DEFORMED	246.90	185.18

Report Ref No. NS/INC18013445/R1rbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.2 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	END PANEL (DISC 25%)	BENT	602.10	451.57
1	END PANEL COVER, DECK TRIM HOLE (DISC 25%)	DEFORMED	46.10	34.58
1	END PANEL COVER, DECK TRIM, RR (DISC 25%)	DEFORMED	121.10	90.83
1	SPARE TYRE PANEL (DISC 25%)	BUCKLED	667.70	500.77
1	CUSHION, SPARE WHEEL (DISC 25%)	NECESSARY	230.80	173.10
1	CARRIER, SPARE (DISC 25%)	BENT	19.70	14.78
1	PROTECTOR, SPARE (DISC 25%)	NECESSARY	143.70	107.78
1	MEMBER SUB-ASSY, RR RH (DISC 25%)	BENT	174.10	130.58
1	FLOOR PANEL RR/RH (DISC 25%)	BENT	209.90	157.43
1	BOX, DECK FLOOR, RR (DISC 25%)	DEFORMED	649.70	487.28
1	BOARD ASSY, RR RH (DISC 25%)	SERVICEABLE	379.20	284.40
1	PANEL ASSY, DECK RH (DISC 25%)	DEFORMED	307.00	230.25
1	FENDER RR/RH (DISC 25%)	BUCKLED	766.80	575.10
1	QUARTER GLASS RR/RH (DISC 25%)	NECESSARY	846.50	634.87
1	GRIP, SERVICE PLUG (DISC 25%)	CUT	52.00	39.00
1	ANTENNA, ELECTRICAL LOWER REAR (DISC 10%)	CRACKED	157.40	141.66
1	BATTERY (DISC 10%)	DEFORMED	278.00	250.20
1	TAIL LAMP RH (DISC 10%)	BROKEN	557.80	502.02
1	BATTERY ASSY, HV (DISC 10%)	BENT	5,544.40	4,989.96
1	SENSOR REVERSE (SN)	DISTORTED	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
3	SEALANT W/SCREEN @\$37.00 (SN)	NECESSARY	111.00	111.00
1	NUMBER PLATE (SN)	BENT	30.00	30.00
1	NUMBER PLATE FRAME (SN)	DEFORMED	12.00	12.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT SIKAFLEX (SN)	NECESSARY	37.00	37.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	EXHAUST HEAT SHIELD, REAR	SERVICEABLE	107.40	-
2	TAILGATE DOOR HINGE LH / RH @\$58.30	SERVICEABLE	116.60	-
1	TAILGATE DOOR STAY LH	SERVICEABLE	241.50	-

Report Ref No. NS/INC18013445/R1rbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No. 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	TAILGATE DOOR STAY RH	SERVICEABLE	241.50	-
1	STRIKER, BACK DOOR	SERVICEABLE	48.90	-
2	LICENSE PLATE LAMP @\$35.70	SERVICEABLE	71.40	-
1	SWITCH ASSY, BACK DOOR OPENER	SERVICEABLE	146.10	-
1	CAMERA ASSY, TELEVISION, RR	SERVICEABLE	1,436.60	-
1	TAILGATE TRIM, LH	SERVICEABLE	85.90	-
1	TAILGATE TRIM, LOWER	SERVICEABLE	180.70	-
1	TAILGATE TRIM, RH	SERVICEABLE	88.30	-
1	TAILGATE TRIM, UPPER	SERVICEABLE	49.60	-
1	SPOILER REAR	SERVICEABLE	953.70	-
1	3RD BRAKE LAMP	SERVICEABLE	231.30	-
1	WIRE, BACK DOOR, NO.1	SERVICEABLE	582.40	-
1	WIRE, FLOOR	SERVICEABLE	1,675.00	-
1	RAIL, ROOF SIDE	SERVICEABLE	273.60	-
1	GARNISH ASSY, ROOF RH	SERVICEABLE	256.40	-
1	GARNISH SIDE UPPER, LHR	SERVICEABLE	261.70	-
2	REINFORCEMENT, RR @\$34.60	SERVICEABLE	69.20	-
1	FLOOR PANEL RR/LH	SERVICEABLE	102.00	-
1	PANEL SUB-ASSY, QTR	SERVICEABLE	588.40	-
1	PANEL SUB-ASSY, QTR WHEEL HOUSE	SERVICEABLE	588.40	-
1	BOARD, RR FLOOR	SERVICEABLE	392.30	-
1	BOX, RR FLOOR BOARD	SERVICEABLE	679.60	-
1	BOX, DECK FLOOR, COVER LH	SERVICEABLE	230.10	-
1	BOX, DECK FLOOR, LH	SERVICEABLE	196.80	-
1	SPACER, RR FLOOR	SERVICEABLE	130.60	-
1	BATTERY TRAY	SERVICEABLE	42.80	-
1	BATTERY CLAMP	SERVICEABLE	16.10	-
1	TAIL LAMP BRACKET, LH	SERVICEABLE	30.70	-
1	TAIL LAMP LH	SERVICEABLE	548.40	-
1	TROUGH, BACK DOOR LH	SERVICEABLE	110.90	-
1	FENDER LINER RR/LH	SERVICEABLE	141.30	-
1	PANEL ASSY, DECK LH	SERVICEABLE	307.00	-
1	TAIL LAMP BRACKET, RH	SERVICEABLE	30.70	-

Report Ref No. NS/INC18013445/R1rbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983358E GST Reg. No. 20-0405911-H



Page No.:4 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FENDER LINER RR/RH	SERVICEABLE	141.30	-
1	EXTENSION, QUARTER	SERVICEABLE	55.70	-
1	EXTENSION, QUARTER	SERVICEABLE	83.50	-
1	REINFORCEMENT, BACK	SERVICEABLE	89.50	-
1	REINFORCE, ROOF SIDE	SERVICEABLE	91.90	-
1	REINFORCEMENT, ROOF	SERVICEABLE	60.30	-
1	TYRE	SERVICEABLE	126.74	-
1	DOOR LOCK RR/RH	SERVICEABLE	709.30	-
1	DOOR LOCK STRIKER	SERVICEABLE	40.50	-
1	HINGE LOWER RHR, DOOR	SERVICEABLE	52.00	-
1	HINGE UPPER RHR, DOOR	SERVICEABLE	81.70	-
1	CHECK ASSY, RR DOOR	SERVICEABLE	150.30	-
1	DOOR FRT / RH	SERVICEABLE	894.40	-
1	STICKER DECAL SMRT (DOOR)	SERVICEABLE	60.00	-
1	QUARTER GLASS RR/LH	NOT NECESSARY	168.10	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TROUGH, BACK DOOR	NOT NECESSARY	110.90	-
1	MEMBER SUB-ASSY, RR LH	TO REPAIR SEE LABOUR	174.10	-
1	FENDER RR/LH	TO REPAIR SEE LABOUR	766.80	-
1	DOOR RR/RH	TO REPAIR SEE LABOUR	954.50	-
			34,896.60	15,378.38
	LABOUR			
	TO REMOVE AND REFIT BATTERY ASSY HV.		180.00	150.00
	PANEL BEATING & BODY WORK, INCLUSIVE OF THE REPAIR OF MEMBER SUB-ASSY, RR LH, FENDER RR/LH AND DOOR RR/RH.		1,859.00	1,400.00
	SPRAY PAINT.		4,608.00	1,860.00
	TOWING CHARGE.	NOT NECESSARY	168.00	-
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	100.00
	TO DO WHEEL ALIGNMENT / TYRE BALANCING.	NOT NECESSARY	120.00	-

Report Ref No. NS/INC18013445/R1rbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:5 of 5

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE / REFIT SEAT.		120.00	60.00
	TO REMOVE & REFIT EXHAUST.		120.00	60.00
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.		250.00	250.00
	TO REMOVE & REFIT REAR QUARTER GLASS LH.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.		120.00	60.00
	TO REMOVE AND REFIT WIRE HARNESS.	NOT NECESSARY	250.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.		120.00	60.00
	TO ALIGN CHASSIS.		350.00	200.00
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	60.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	60.00
	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.		120.00	30.00
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO CHECK & RESET SYSTEM FUNCTION.		350.00	100.00
			9,535.00	4,490.00
GRAND TOTAL			44,431.60	19,868.38
RECOMMENDED COST OF REPAIRS (CONFIRMED)				19,868.38

Report Ref No. NS/INC18013445/R1rbe2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.