



**NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)**

**51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 68410055 FAX: 68416315**

Your Ref : MT/1003192-003

Date: 02<sup>nd</sup> January 2019

Our Ref : NS/INC18013446/R1vbs2

**M/s NTUC Income Insurance Co-Operative Ltd**

73 Bras Basah Road  
#05-01 NTUC Trade Union House  
Singapore 189556  
(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SHB 608S  
ACCIDENT ON 15/07/2018 INSURED VEHICLE GW 3502U**

Instruction was received to inspect the vehicle Reg. No. SHB 608S. The inspection was conducted on 19/07/2018 at the premises of M/s SMRT Automotive Services Pte Ltd, 60 Woodlands Industrial Park E4 Singapore 757705.

The following vehicle information was recorded:

Registration Number	: SHB 608S
Make/Model	: Toyota Prius 4
Year of Registration	: 2017
Body Colour	: Maroon
Chassis Number	: JTDKB3FU003576913
Engine Capacity	: 1798cc

The vehicle sustained damages at the front portion, o/s and n/s body and rear o/s portion. The Estimated repair cost of such vehicle is S\$83,171.66 (Sin Dollars: Eighty-Three Thousand One Hundred Seventy-One and Sixty-Six Cents only.) (Exclude check items S\$41,800.94Nett) (Details see photographs enclosed).



**NATIONAL ASSESSMENT CENTRE SERVICES  
(LKK GROUP)**

51 Ubi Ave 1, #01-25, Paya Ubi Industrial Park,  
Singapore 408933, TEL: 68410055 FAX: 68416315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Book Value

S\$ 87,596.00

Less: LTA Reimbursement Value (RV)

(S\$ 35,328.00)

Nett Liability

S\$ 52,268.00

S\$ 52,268.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 83,171.66

(Exclude check items S\$41,800.94Nett)

Nett Liability

S\$ 83,171.66

(a) - (b) =

(S\$ 30,903.66)

The amount of estimated saving of S\$30,903.66 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:

*MRB*

MOHD. RASUL BIN MOHD YUNUS

AMSOE, AMIRTE, AMSAE-A, M.MATAI  
Automotive Assessor

K.K.LAU

MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MHE(mech), MInstAEE, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NJAAR(USA),  
AM CATARICAN, M.MATA(USA), M.MATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.