

## CITY CAB PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHC 7028P

DATE 23/7/2018 11:56

MAKE :

MODEL : HYUNDAI i40

AXM

Chuang

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper / Re ?			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) X NN		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket X			\$ 49.00	
	Rear Bumper Clips / Re			\$ 22.00	
	Rear Bumper Sponge			\$ 143.40	
	Rear Bumper Under Cover X NN			\$ 225.00	
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>	
	<b>LESS 20%</b>			<b>\$ 381.47</b>	
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>	
	Rear Bumper Reverse Sensor X NN			\$ 135.70	Nett
	Rear Bumper Rubber Mat / Re			\$ 50.00	Nett
	Rear Bumper Advertisement Logo / Re			\$ 50.00	Nett
	Rear Fender Advertisement Logo (LH/RH) X NN		\$ 100.00	\$ 200.00	Nett
				<b>\$ 435.70</b>	
	<b>Labour Charge</b>				
	Panel Beating			\$ 350.00	200
	Spray Painting Charge			\$ 250.00	200
	Wiring Charge			\$ 50.00	X NN
	R/Refix Reverse Sensor			\$ 120.00	40
	<b>TOTAL LABOUR</b>			<b>\$ 770.00</b>	
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,731.58</b>	
<p>2 Days. part by part. before paint photos. Gino Qs ap - 82 88 0282 24/7/18 10Am</p>					
<div> <p>LKP Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> <li>• To resurvey before/after spray painting</li> <li>• To display damaged part(s) during resurvey</li> <li>• Parts prices are subject to confirmation</li> <li>• Third party survey is on a "Without Prejudice" basis</li> <li>• No illegal modification(s) is allowed</li> <li>• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company</li> </ul> <p>Acknowledged by Repairer Signature: Date:</p> </div>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					