

12/03/2001

ASS. REC. BY:

REF: CS/GA180/3460/THd302

Special Instruction:

Surveyor

Tay Hieh

ASSIGNMENT (Office)

From (Person):

Rachel Tan

of

GAI

Date/Time:

24/7/18 @ 4:31pm

Estimated Cost:

Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

FW 7510G

Insured:

GX 90134

at Workshop m/s

Yew Tee Automobile

Tel:

6765 3373

of

Blk 6, Woodlands Rd 349F - Yew Tee Ind. Est.

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01/07/18

CA / REV / REP. / REV 24 HRS

(up)

25/7/18

H.O.D. Endorsement:

Date/Time 5:50pm @ 24/7/18

Person Contacted:

Winnie

Vehicle ☒ IN / OUT

Date/Time

Action/Instruction (✓) Estimate

FW 7510G-X

GX 90134-X

31/7-

Revert via email preli

lump sum \$3050+ (Red: 1970.60 :39%)

Signature: *Tang*

REF:

G A I

ASSIGNMENT

OE-2023 May

From: \_\_\_\_\_ Date: \_\_\_\_\_  
Estimated Cost: \_\_\_\_\_  
OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No. \_\_\_\_\_  
at Workshop m/s: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: *FW 75106* Yr Regn: *2003 May*

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Honda CB400SF23* C.C. *399*

Colour: *Black* A/C: Insured / Std / NI / NA

Sp. Reading: \_\_\_\_\_ T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: \_\_\_\_\_

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: *120/60KR*  
R: *160/60KR*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. *5* mm R/Bal. *5* mm

L/Bal. \_\_\_\_\_ mm L/Bal. \_\_\_\_\_ mm

D.O.A. \_\_\_\_\_ D.O.I. *25/7/18 03pm*

Survey held at *Yew Tee Auto*

Des. of Damages: *Front* / Rear / *Left* / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

*BLK 6 399F Yew Tee 1st*

RECEIVED 23 AUG 2018

Date/Time, File Pass to?

*21/8 Typist*

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I. (\$)

☐ : Prel. Report  
☒ : Final Report

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Insp (\$)

☐ Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS. \$

) Photos

) Others

TOTAL

*250*

*250*



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: TBA

Date: 31/7/2018

Our Ref: CS/GAI18011879/Ktd3

The Motor Claims Department  
GREAT AMERICAN INSURANCE COMPANY

Dear Sirs/Mdm


**PRELIMINARY ADVICE OF VEHICLE NO. FW 7510G.**

Please be informed that we had conducted the inspection of the above-mentioned vehicle on 25/7/2018 at the premises of M/s Yew Tee and have the following to report: -

Workshop Estimate Amount	: <u>S\$ 5,020.60</u>
Revised Estimate Amount	: <u>S\$ 3,830.80</u>
Check" Items Amount	: <u>S\$ 846.40</u>
Market Value	: <u>S\$ -</u>
LTA Reimbursement Value	: <u>S\$ -</u>
Nett Value	: <u>S\$ -</u>

**Description of Damage:**

The vehicle sustained at the front and o/s portion.



**Comments/ Present Status:**

Damage consistent

Yours faithfully  
Taufikh  
Motor Surveyor

## Denise Tay (LKKAUTO)

---

**From:** Denise Tay (LKKAUTO)  
**Sent:** Tuesday, 31 July 2018 4:02 PM  
**To:** Admin-D (LKKAUTO); 'Tan, Rachel'; SUR  
**Cc:** assignments  
**Subject:** RE: RE: RE: Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018  
**Attachments:** PRELI ADVISED FW 7510G.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **FW 7510G**.

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Tuesday, 31 July 2018 2:50 PM  
**To:** 'Tan, Rachel' <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Cc:** assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: RE: RE: Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018

Dear Sir/Mdm,

Thank you for the email.

Dear Denise,

**Kindly assist.**

**FYNA Our Ref : CS/GAI18013460/T1td3**

BEST REGARDS,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]  
**Sent:** Tuesday, 31 July 2018 2:47 PM  
**To:** LKK Assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** FW: RE: RE: Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018

CLMOMVC000003384 - GX9013U (OI) - FW7510G (NTUC)

**Nivitha (LKK Auto)**

---

**From:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Sent:** Tuesday, 24 July 2018 4:31 PM  
**To:** LKK Assignments  
**Subject:** FW: RE: Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018  
**Attachments:** FW7510G Estimate.pdf; FW7510G\_01072018.pdf

Hi LKK

Please accept assignment to conduct TP survey.

Regards  
Rachel Tan  
Executive, Motor Claims, Great American Insurance Company  
Tel: 6804 7846

---

**From:** YT(MG) <info@yewteegroup.com>  
**Sent:** Tuesday, July 24, 2018 4:30 PM  
**To:** Tan, Rachel <Rachel.Tan@sg.gaig.com>  
**Cc:** info@yewteegroup.com  
**Subject:** [External] RE: Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018

Hi Rachel,

We choose LKK Auto Consultants.

Thanks.

Best Regards

*Sky Teh*

9747 1475

Website: [www.yewteegroup.com](http://www.yewteegroup.com)

Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)

Like Us On Facebook

Director of

YEW TEE AUTOMOBILE TECH PTE LTD



WEST HQ Office:

EAST Branch Office:

NORTH Branch Office:

Blk 6 Woodlands Road 399F  
Yew Tee Ind. Est  
Singapore 678006  
DID: 6762 2081 (3 Lines)  
Fax: 6760 4895  
Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Synergy@KB, 25 Kaki Bukit Road 4  
Unit No #01-60/61  
Singapore 417800  
DID: 6702 3113 (3 Lines)  
Fax: 6702 3773  
Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

Mega@Woodlands  
39 Woodlands Close #01-12  
Singapore 737856  
DID: 6256 2081 (3 Lines)  
Fax: 6256 2533  
Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)



*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

---

**From:** Tan, Rachel [<mailto:Rachel.Tan@sg.gaig.com>]

**Sent:** Tuesday, 24 July, 2018 4:17 PM

**To:** [info@yewteegroup.com](mailto:info@yewteegroup.com)

**Subject:** FW: Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018

Without Prejudice

Dear Yew Tee

Our client has not reported, we have informed them to report.

We append the following list of our panel surveyors:-

1. AJAX Adjusters & Surveyors Pte Ltd
2. A-PAC Investigation Solutions Pte Ltd
3. Priority Services
4. RT Appraisal Pte Ltd
5. LKK Auto Consultants
6. JP KNIGHTS PTE LTD

Kindly let us know which SJE is selected and furnish the estimates for the survey to be carried out.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

---

**From:** Ngian, Kelvyna

**Sent:** Tuesday, July 24, 2018 4:08 PM

**To:** Tan, Rachel <[Rachel.Tan@sg.gaig.com](mailto:Rachel.Tan@sg.gaig.com)>; [info@yewteegroup.com](mailto:info@yewteegroup.com)

**Subject:** FW: [External] Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018

---

**From:** YT(HQ) <[info@yewteegroup.com](mailto:info@yewteegroup.com)>

**Sent:** Tuesday, July 24, 2018 4:03 PM

**To:** Ngian, Kelvyna <[Kelvyna.Ngian@sg.gaig.com](mailto:Kelvyna.Ngian@sg.gaig.com)>

**Cc:** [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

**Subject:** [External] Accident involving FW7510G (NTUC) claiming against GX9013U (GA) on 01/07/2018

Hi Kelvyna,

Attached report, estimate and police investigation result.

Kindly arrange PRI at Yew Tee HQ.

Kindly let us have the list of surveyor to conduct pre-repair survey.

Best Regards

Ms Lai Yee Meng



**Yew Tee Automobile Tech Pte Ltd**

HQ:

Blk 6 Woodlands Road 399F

Yew Tee Ind. Est

Singapore 678006

DID: 6765 3373 / 6762 2081 / 6764 9042 Fax: 6760 4895

Email: [utauto@singnet.com.sg](mailto:utauto@singnet.com.sg)

Branch Office:

Synergy@KB, 25 Kaki Bukit Road

Unit No #01-60/61

Singapore 417800

DID: 6702 3113

Email: [utauto2@singnet.com.sg](mailto:utauto2@singnet.com.sg)

Branch Office:

39 Woodlands Close,

#01-12 Mega@Woodlands

Singapore 737856

DID: 62562081

Email: [info@yewteegroup.com](mailto:info@yewteegroup.com)



*please consider the environment before printing this email*

Notice : This mail (including all attachments) contains confidential information which may be privileged. It is intended solely for the identified recipient(s) to whom it is addressed. If you are not an intended recipient, please reply to us immediately and delete this message from your system. You may not copy or use it for any purpose, or otherwise disclose its contents to any person.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

---

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI18013470/Nqd3	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 24-07-2018  Code : AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLJ 1892R	Veh. Inspected	SHD 3542S	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10001803/JM	Excess (\$)	0.00	
Assign From	JULIE MANGUBAT	Assign Date	24/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	23/07/2018	Inspection Date	25/07/2018	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/07/2018 09:21
Date Of Accident	01/07/2018 20:40
Exact Location Of Accident	WOODLANDS AVE 5 > WOODLANDS AVE 2
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	FW7510G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	ZEFFLIN LOK YEE YANG
NRIC No	S95160851
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97509378
Alternative Phone No	OFFICE-97509378

### Vehicle Particulars

Manufacturer	HONDA
Model	CB400SF2J-399CC
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	MOTORCYCLE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5096215409
Cover Note Number	

### Driver

Name of Driver	ZEFFLIN LOK YEE YANG
NRIC No	S95160851
Date Of Birth	07/05/1995
Occupation	INDOOR
Date Of Driving Pass	28/11/2017
Driving Experience	0 YEAR AND 7 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-97509378
Fax Number	
Contact Number	OFFICE-97509378
Email Address	NOEMAIL

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name ZEFFLIN LOK YEE YANG

Approximate Age

Injuries Sustain

Injured person in which vehicle? FW7510G

Were seat belts worn?

Was this injured conveyed to hospital by ambulance? YES

Address

Postcode

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER

TO

POLICE

REPORT

The user must be able to log in to the system and be able to log out.

1. Signature  
 2. Full Name  
 3. Address  
 4. City  
 5. State  
 6. Zip  
 7. Phone  
 8. Age  
 9. Gender  
 10. Religion  
 11. Marital Status  
 12. Education  
 13. Occupation  
 14. Income  
 15. Assets  
 16. Liabilities  
 17. Net Worth  
 18. Other Information



# SINGAPORE POLICE FORCE



T/20180702/2131

1 of 3

Police Station Of Origin:  
Woodlands West N.P.C.  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

Report No. T/20180702/2131

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 02/07/2018 19:17	Vide Report No.:	Station Diary No.: 57
<b>Informant's Particulars</b>		
Name of Informant: ZEFFLIN LOK YEE YANG	Address: APT BLK 202 MARSILING DRIVE #03-140 SINGAPORE 730202	
ID Type / ID No.: NRIC NO / S9516085I	Contact No.: Home/Office:	Mobile: 97509378
Nationality: SINGAPORE CITIZEN	Email:	
Sex: Male	Age: 23	Date of Birth: 07/05/1995
Type of Informant: Rider		
Race: Chinese	Language: English	Institution / School Name:
Occupation: TRAINEE	Driving Licence Information: Class: 2B,2A,3      Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Conveyed By Ambulance	Drink Drive: No	Date/Time of Accident: 01/07/2018 20:40	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 WOODLANDS AVENUE 5 WOODLANDS AVENUE 2				
Weather: Drizzling		Road Surface: Wet		Road Speed Limit:
Traffic Flow: One Way		Traffic Control: Not Controlled		Traffic Volume:
Type of Collision: Moving Vehicle Against - Others				Anyone conveyed by ambulance: Yes

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
FW7510G	Motorcycle	HONDA	CB400SF2J	Black	Slightly Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
FW7510G	NTUC Income Insurance Co-Operative Limited	5096215409	24/11/2017	27/11/2018



**SINGAPORE  
POLICE FORCE**



T/20180702/2131

2 of 3

Report No. T/20180702/2131

Police Station Of Origin:  
Woodlands West N.P.C.  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

**CONTINUATION OF REPORT**

**Brief Details.**

On 01/07/2018 at about 2040hrs, I was riding my motorbike (FW7510G) along Woodlands Avenue 5 heading towards Woodlands Avenue 2. The traffic was clear at that time with no vehicles travelling on the straight road. It was however drizzling slightly causing the road surface to be wet. As I was travelling along the second lane, a van then turned out from my left. The van driver was driving along South Woodlands Way and merging into Woodlands Avenue 5.

While the van was merging, the van then cut from the fourth lane all the way into the second lane. Although the van did signal his intention to filter right, the van driver had failed to keep a proper lookout and was directly in front of me. I was travelling about 70km/hr at that point of time.

To avoid a collision, I then applied my horn and brakes at the same time. Despite doing so, the van continued to cut into my lane. I tried to avoid him by swerving to the right, into the first lane, which then caused me to lose control of my motorbike.

After I fell off my motorbike, the van driver did stop his vehicle and make an assessment of my injuries. As I was in pain, I called the police and a traffic police officer was dispatched to the scene. An ambulance was also dispatched to scene and I was conveyed to Khoo Teck Puat Hospital. I was also given 6 days of MC by the doctor from 01/07/2018 to 06/07/2018.

I would like to state that I could not remember the vehicle plate number of the van and no exchange of contacts were made between us.



SINGAPORE  
POLICE FORCE



T/20180702/2131

3 of 3

Police Station Of Origin:  
Woodlands West N.P.C.  
9 Marsiling Lane SINGAPORE 739146  
Tel No: 1800-363 9999

Report No. T/20180702/2131

CONTINUATION OF REPORT

### Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report:

J /

Staff Sgt TAN YU REN

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:

TP / GIT /

Sr Staff Sgt SHAHRUL NIZAM BIN SAMARRI

Contact No.: 65476904

Authentication Stamp

NP168

Signature Of Informant:

Date/Time:

02/07/2018 19:17

Classification Of Case:



SINGAPORE  
POLICE FORCE

Traffic Police  
10 Ubi Avenue 3  
Singapore 408865  
Tel +65 6547 6904  
Fax +65 6547 6259  
[www.police.gov.sg](http://www.police.gov.sg)

Your Ref :  
Our Ref : TP/IP/38103/2018

Date : 17 JULY 2018

ZEFFLIN LOK YEE YANG  
APT BLK 202 MARSILING DRIVE  
#03-140  
SINGAPORE 730202

Dear Sir/Mdm,

**TRAFFIC ACCIDENT INVOLVING MOTORCYCLE FW7510G AND MOTOR VAN GX9013U  
ALONG WOODLANDS AVENUE 5 ON 01.07.2018 AT ABOUT 8:51 P.M.**

I refer to the above accident.

- 2 We have completed our investigations. Our investigation shows that an offence of **Inconsiderate Driving under Section 65(b) of the Road Traffic Act Chapter 276** was disclosed against the driver of motor van **GX9013U** and action has been taken against the driver for the said offence.
- 3 You may wish to note that our decision does not preclude future prosecution should new evidence emerge at a later stage.
- 4 Please be informed that our decision does not preclude you from pursuing civil claims.

Yours faithfully,

**SHahrul NIZAM**  
for HEAD INVESTIGATION  
TRAFFIC POLICE  
SINGAPORE POLICE FORCE

NP 510

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : GREAT AMERICAN INSURANCE COMPANY, SINGAPORE BRANCH**

**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1807/006
Policy No:	5096215409	Date of Loss:	01/07/2018
Vehicle Reg. No.:	<b>FW7510G</b>	Driveable?	yes
Driver Age:	07/05/1995	Third Party Vehicle No.:	GX9013U
Any Injuries?	yes	Contact No:	97509378
Insured/Claimant:	ZEFFLIN LOK YEE YANG	Driver:	ZEFFLIN LOK YEE YANG

Make/Model:	Honda, CB400	Vehicle Reg. Date:	28/05/2003
Vehicle Colour:	BLACK	Engine Number:	NC23E2050652
Chassis No:	NC391041189	Odometer:	
Total Loss?	<b>NO</b>	Est. Duration of Repair(Day)	

Description of Accident/loss: MOVING VEHICLE AGAINST - OTHERS  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	4,190.60
Miscellaneous Items	230.00
Labour	390.00
Paintwork Labour	210.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>5,020.60</b>
<b>GST 7.00%(S\$):</b>	<b>351.44</b>
<b>Nett Amount(S\$):</b>	<b>5,372.04</b>

This claim is handled by: Sky Toh T C

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

office - 62563561/  
Tanjoh 97445749  
WP  
25/7/18 @ 3pm  
Resurvey after repair  
Lumpsum  
4 days  
sur @ lkk auto-won



**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT FENDER <i>at</i>	130.00	130.00	+15.00	149.50
2	1	FRONT FORK LH <i>Run</i>	210.00	210.00	+15.00	241.50
3	1	FRONT FORK RH <i>Run</i>	210.00	210.00	+15.00	241.50
4	1	FRONT HEADLAMP <i>cut</i>	258.00	258.00	+15.00	296.70
5	1	FRONT HEADLAMP CHROME RIM <i>cut</i>	95.00	95.00	+15.00	109.25
6	1	FRONT HEADLAMP BRACKET LH <i>Run</i>	36.00	36.00	+15.00	41.40
7	1	FRONT HEADLAMP BRACKET RH <i>Run</i>	36.00	36.00	+15.00	41.40
8	1	SPEEDOMETER <i>cut</i>	1,480.00	1,480.00	+15.00	1,702.00
9	1	FRONT SIGNAL LAMP LH <i>Run</i>	80.00	80.00	+15.00	92.00
10	1	FRONT SIGNAL LAMP RH <i>cut</i>	80.00	80.00	+15.00	92.00
11	1	FRONT HANDLE BAR <i>cut</i>	220.00	220.00	+15.00	253.00
12	1	STEERING CONE & BEARING <i>Run</i>	95.00	95.00	+15.00	109.25
13	1	STEERING STEM <i>Run</i>	185.00	185.00	+15.00	212.75
14	1	FRONT SIDE MIRROR RH <i>cut</i>	68.00	68.00	+15.00	78.20
15	1	BALANCER RH <i>cut</i>	28.00	28.00	+15.00	32.20
16	1	FRONT BRAKE LEVER RH <i>cut</i>	28.00	28.00	+15.00	32.20
17	1	FRONT BRAKE LEVER CABLE RH <i>cut</i>	255.00	255.00	+15.00	293.25
18	1	REAR FOOT BRAKE RH <i>cut</i>	90.00	90.00	+15.00	103.50
19	1	REAR SIGNAL LAMP RH <i>cut</i>	60.00	60.00	+15.00	69.00

Total Parts (S\$) 4,190.60

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	ENGINE CRASH BAR (SET) <i>at</i>	230.00	230.00	0.00	230.00

Sub Total (S\$) 230.00

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
2	1	To Conduct Wheel Balancing	60.00	60.00	0.00	60.00 30
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	300.00	300.00	0.00	300.00 200

Gross Labour Cost (S\$) 390.00

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 30
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	150.00	150.00	0.00	150.00 100

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
-----	-----	-------------	------	--------	-------	---------------

Waxing are also available.

Gross Labour Cost (S\$)	210.00
-------------------------	--------

< END OF ESTIMATES >

**Yew Tee Automobile Tech Pte Ltd** (Co.Reg.No.200311009C)

Block 6 Woodlands Road 399F, Yew Tee Industrial Estate  
Singapore 678006

Tel: 67653373 Fax: 67604895 Email: YTHQ

**INSURER : GREAT AMERICAN INSURANCE COMPANY, SINGAPORE BRANCH**

**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTMG/TP/1807/006
Policy No:	5096215409	Date of Loss:	01/07/2018
Vehicle Reg. No.:	<b>FW7510G</b>	Driveable?	yes
Driver Age:	07/05/1995	Third Party Vehicle No.:	GX9013U
Any Injuries?	yes	Contact No:	97509378
Insured/Claimant:	ZEFFLIN LOK YEE YANG	Driver:	ZEFFLIN LOK YEE YANG

Make/Model:	Honda, CB400	Vehicle Reg. Date:	28/05/2003
Vehicle Colour:	BLACK	Engine Number:	NC23E2050652
Chassis No:	NC391041189	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	

Description of Accident/loss: MOVING VEHICLE AGAINST - OTHERS  
Remarks:  
Present Location: Yew Tee Automobile Tech Pte Ltd (HQ)-YTHQ

**COST OF CLAIMS**

	Amount
Parts	3310.80 4,190.60
Miscellaneous Items	230.00 230.00
Labour	260.00 390.00
Paintwork Labour	130.00 210.00
Towing	0.00
<b>Gross Total(S\$):</b>	<b>3830.80 5,020.60</b>
<b>GST 7.00%(S\$):</b>	<b>351.44</b>
<b>Nett Amount(S\$):</b>	<b>5,372.04</b>

This claim is handled by: Sky Toh T C

\$ 3830.80  
-20% \$ 766.16  
\$ 3064.64  
  
L/S \$ 3,050.64  
(PLS CONFIRM)

affie - 62563561/  
Tanjoh 97445749  
-wp  
25/7/18 @ 3pm  
Resuming after repair  
Lumpsum  
4 days  
sure/kk auto-won

**REPAIR DETAILS****Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT FENDER <i>at</i>	130.00	130.00	+15.00	149.50
<del>2</del>	<del>1</del>	<del>FRONT FORK LH ?</del>	<del>210.00</del>	<del>210.00</del>	<del>+15.00</del>	<del>241.50</del>
<del>3</del>	<del>1</del>	<del>FRONT FORK RH ?</del>	<del>210.00</del>	<del>210.00</del>	<del>+15.00</del>	<del>241.50</del>
4	1	FRONT HEADLAMP <i>cut</i>	258.00	258.00	+15.00	296.70
5	1	FRONT HEADLAMP CHROME RIM <i>cut</i>	95.00	95.00	+15.00	109.25
<del>6</del>	<del>1</del>	<del>FRONT HEADLAMP BRACKET LH *</del>	<del>36.00</del>	<del>36.00</del>	<del>+15.00</del>	<del>41.40</del>
<del>7</del>	<del>1</del>	<del>FRONT HEADLAMP BRACKET RH ?</del>	<del>36.00</del>	<del>36.00</del>	<del>+15.00</del>	<del>41.40</del>
8	1	SPEEDOMETER <i>cut</i>	1,480.00	1,480.00	+15.00	1,702.00
<del>9</del>	<del>1</del>	<del>FRONT SIGNAL LAMP LH *</del>	<del>80.00</del>	<del>80.00</del>	<del>+15.00</del>	<del>92.00</del>
10	1	FRONT SIGNAL LAMP RH <i>cut</i>	80.00	80.00	+15.00	92.00
11	1	FRONT HANDLE BAR <i>bt</i>	220.00	220.00	+15.00	253.00
<del>12</del>	<del>1</del>	<del>STEERING CONE &amp; BEARING ?</del>	<del>95.00</del>	<del>95.00</del>	<del>+15.00</del>	<del>109.25</del>
<del>13</del>	<del>1</del>	<del>STEERING STEM ?</del>	<del>185.00</del>	<del>185.00</del>	<del>+15.00</del>	<del>212.75</del>
14	1	FRONT SIDE MIRROR RH <i>cut</i>	68.00	68.00	+15.00	78.20
15	1	BALANCER RH <i>cut</i>	28.00	28.00	+15.00	32.20
16	1	FRONT BRAKE LEVER RH <i>cut</i>	28.00	28.00	+15.00	32.20
17	1	FRONT BRAKE LEVER CABLE RH <i>cut</i>	255.00	255.00	+15.00	293.25
18	1	REAR FOOT BRAKE RH <i>cut</i>	90.00	90.00	+15.00	103.50
19	1	REAR SIGNAL LAMP RH <i>cut</i>	60.00	60.00	+15.00	69.00

Total Parts (\$\$) 3,910.80 4,190.60

**Estimates of Miscellaneous Items**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	ENGINE CRASH BAR (SET) <i>dd</i>	230.00	230.00	0.00	230.00

Sub Total (\$\$) 230.00 230.00

**Estimates On Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓
2	1	To Conduct Wheel Balancing	60.00	60.00	0.00	60.00 30
3	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	300.00	300.00	0.00	300.00 200

Gross Labour Cost (\$\$) 360.00 390.00

**Estimates On Paint Work Labour**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	60.00	60.00	0.00	60.00 30
2	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and	150.00	150.00	0.00	150.00 100

# Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
-----	-----	-------------	------	--------	-------	------------

Waxing are also available.

Gross Labour Cost (\$\$)	130.00	210.00
--------------------------	--------	--------

< END OF ESTIMATES >




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY		Ref : CS/GAI18013460/T1td3e2		
3 TEMASEK AVENUE #16-01 CENTENNIAL TOWER SINGAPORE 039190		Date : 06-09-2018		
		Code : GAI		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GX 9013U	Veh. Inspected	FW 7510G	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000003384	Excess (\$)	0.00	
Assign From	RACHEL TAN	Assign Date	24/07/2018	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	HONDA CB400SF2J	c.c	399	
Engine No.	HIDDEN	Year of Reg.	2003	
Chassis No.	NC391041189	Colour	BLACK	
Odometer	-	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	120/60 R17	MICHELIN	5 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	160/60 R17	MICHELIN	5 mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY AND FRONT PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/07/2018	Inspection Date	25/07/2018	
Survey held at	YEW TEE AUTOMOBILE TECH PL (HQ) BLK 6 WOODLANDS ROAD 399F YEW TEE IND. ESTATE SINGAPORE 678006			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>4 Working Days</b>		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FW 7510G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	FRONT FENDER (WCP)	CUT	130.00	130.00
1	FRONT FORK LH (WCP)	NOT NECESSARY	210.00	-
1	FRONT FORK RH (WCP)	NOT NECESSARY	210.00	-
1	FRONT HEADLAMP (WCP)	CUT	258.00	258.00
1	FRONT HEADLAMP CHROME RIM (WCP)	CUT	95.00	95.00
1	FRONT HEADLAMP BRACKET LH (WCP)	NOT NECESSARY	36.00	-
1	FRONT HEADLAMP BRACKET RH (WCP)	NOT NECESSARY	36.00	-
1	SPEEDOMETER (WCP)	CRACKED	1,480.00	1,480.00
1	FRONT SIGNAL LAMP LH (WCP)	NOT NECESSARY	80.00	-
1	FRONT SIGNAL LAMP RH (WCP)	CUT	80.00	80.00
1	FRONT HANDLE BAR (WCP)	BENT	220.00	220.00
1	STEERING CONE & BEARING (WCP)	NOT NECESSARY	95.00	-
1	STEERING STEM (WCP)	NOT NECESSARY	185.00	-
1	FRONT SIDE MIRROR RH (WCP)	CUT	68.00	68.00
1	BALANCER RH (WCP)	CUT	28.00	28.00
1	FRONT BRAKE LEVER RH (WCP)	CUT	28.00	28.00
1	FRONT BRAKE LEVER CABLE RH (WCP)	CUT	255.00	255.00
1	REAR FOOT BRAKE RH (WCP)	CUT	90.00	90.00
1	REAR SIGNAL LAMP RH (WCP)	CRACKED	60.00	60.00
	COST PLUS 15%		546.60	418.80
			4,190.60	3,210.80
<b>SPECIAL NETT ITEMS</b>				
1	SET ENGINE CRASH BAR (SN)	DENTED	230.00	230.00
			230.00	230.00
<b>LABOUR</b>				
	TO DISCONNECT AND RECONNECT, CHECK ELECTRICAL WIRING HARNESS WIRE, SOCKETS, REPLACE DAMAGED PARTS.		30.00	30.00
	TO CONDUCT WHEEL BEARING.		60.00	30.00

Report Ref No. CS/GAI18013460/T1td3e2





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REPLACE THE ABOVE DAMAGED PARTS, STRAIGHTEN, KNOCK OUT, REALIGN AND REPAIR INCLUDING CUT AND WELD BODY PANELS. TO RE-ADJUST TO THE ORIGINAL POSITION USING POWER TOOLS.		300.00	200.00
	TO CARRY-OUT BODY CAVITY PRESERVATION.			
	TO SPRAY PAINTING ON THE REPLACED AND REPAIR PARTS, PREPARE SPRAY SUCH AS MASKING TAPE THE UNAFFECTED AREAS WITH PAPER, CLEANING AND SANDING OF SURFACES, FINAL POLISHING AND WAXING ARE ALSO AVAILABLE.		60.00	30.00
			150.00	100.00
GRAND TOTAL			600.00	390.00
			5,020.60	3,830.80
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/GAI18013460/T1td3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.