

ASS. REC. BY:

REF: CS/EG118013461/Uwb3n2 Special Instruction:

Surveyor:

Marcus

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EGI

Date/Time:

24/7/18 @ 2:36pm

Estimated Cost:

Bill to:

GD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDN 8188T

Insured:

GBD 3305G

at Workshop m/s:

Fastech Auto

Tel:

6746 5405

of

1 Kaki Bkt Ave 6 # 01-46

Policy No:

Claim No:

GBD 3305G/SL/p1

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 18/07/2018

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

5:30pm @ 24/7/18

Person Contacted:

Nancy

Vehicle ☒ IN ☐ OUT

Date/Time:

Action/Instruction (☒) EstimateSDN 8188T - CCG/A1Q18066286/Uwb3s2 DOA: 5/4/18
GBD 3305G-X

27/7/18

Informed Pei Li pending workshop est by email

14/8/18

Email preli revised to Pei Li

(08/11/13) wef

ASS. REC BY: MDV 645

REF:

ER1/
ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / VS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SDN 81887at Workshop m/s 24.

of _____

Insured: 613033050

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 30

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

37370

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDN 81887 Yr Regn: 9 / 10Type: M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CA /Make: Toyota prius O.C. 1797Colour: blue A/C: Insured / Std / NI / NASp. Reading: 12/893 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: ZUV 301192308Gen. Cond: Good / Fair / Poor / BurntSteering: Order / Jammed / Leaked / Burnt orBrake: Order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/45-R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mmR/Bal. 7 mmL/Bal. 7 mmL/Bal. 7 mmD.O.A. 18/7/18D.O.I. 24/7/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

MS PL.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

here 6.4Note: new parts replaced.13/8/18 confirmed repair - sum \$6200 with Aln. (Red 9142.01, 6073)

(No LS)

RECEIVED 14 AUG 2018.

Date/Time, File Pass to?



: Preli. Report

Days Of Repair: 4

1)



: Final Report

Resurvey No. of Trip: 1

Date/Time, File Return to?

2)

14/8 - typist

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

\$ - RS, \$

Photos

Others

TOTAL

350

Report Format: TPLump Sum / I.B.I: (\$ RS \$6200/2)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18013461/Uvd3

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 24-07-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 3305G	Veh. Inspected	SDN 8188T
Policy No.		Coverage (\$)	0.00
Claim No.	GBD3305G/SL/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	18/07/2018	Inspection Date	24/07/2018
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GBD3305G/SL/pl
Our Ref: CS/EGI18013461/Uvd3

Date: 14/8/2018

The Motor Claims Department
M/s: ERGO INSURANCE PTE LTD

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SDN 8188T


We thank you for your instruction on 24/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 24/7/2018 at the premises of M/s FASTECH AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$15,342.01
Revised Estimate Amount	: S\$6,894.75
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the n/s front portion



Comments/Present Status:

Damages Consistent

Yours faithfully,

MARCUS CHUA
Licensed Appraiser

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Tuesday, 14 August 2018 9:21 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018
Attachments: SDN 8188T PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle SDN 8188T
Date of survey: 24/7/2018
Number of days : 4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 July 2018 8:21 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SDN 8188T on 24/7/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 24 July 2018 5:15 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]

Sent: Tuesday, 24 July 2018 2:36 PM

To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>

Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>

Subject: OI : GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,

Yee Pei Li

Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID.: +65 6829 9194
Tel.: +65 6829 9199
Fax: +65 6829 9247

www.ergo.com.sg

ERGO

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Friday, 27 July 2018 8:21 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018

Dear Pei Li,

Please be informed that we have inspected the vehicle SDN 8188T on 24/7/2018 .

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Tuesday, 24 July 2018 5:15 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>; assignments <assignments@lkkauto.com>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Tuesday, 24 July 2018 2:36 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Cc: 'ASSIGNMENTS@LKKAUTO.COM' <ASSIGNMENTS@LKKAUTO.COM>
Subject: OI : GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID: +65 6829 9194
Tel: +65 6829 9199
Fax: +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Nivitha (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Tuesday, 24 July 2018 2:36 PM
To: 'admin-d@lkkauto.com'
Cc: 'ASSIGNMENTS@LKKAUTO.COM'
Subject: OI : GBD3305G / TP : SDN8188T/LKK / DOA : 18.07.2018
Attachments: GBD3305G - SAS.pdf; SDN8188T - SAS.pdf; SDN8188T - PRS FORM.pdf; RE: Request for prs SDN8188T (61.1 KB)

Dear Catherine/Nivitha,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **FASTECH AUTO PTE LTD.**

ADDRESS : 1 KAKI BUKIT AVENUE 6
#01-46/48/50 AUTOBAY
SINGAPORE 417883

PERSON TO CONTACT : NANCY LAM @ 6746 5405

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Regards,
Yee Pei Li
Claims Assistant (Motor)

ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-01 Suntec Tower Five
Singapore 038985
DID : +65 6829 9194
Tel : +65 6829 9199
Fax : +65 6829 9247

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

ERGO

Date: 19.07.2018
Our Reference: GBD 3305G/SL/pl
Your Reference: SDN 8188T

To: FASTECH AUTO PTE LTD

Sent via Fax
or
Email nancy.lam@fastechauto.com.sg

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SDN 8188T
Insured's Vehicle: GBD 3305G
Date Of Accident: 18.07.2018


We acknowledge receipt of your request for PRS on: 18.07.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK Auto

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☒ Your request for inspection does not have your client's GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☒ Our Insured's driver has not reported the accident to us todate.
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 3733E

Vehicle Details

Vehicle No.: SDN8188T

Vehicle to be Exported: No

Intended De-registration Date: 24 Jul 2018

Vehicle Make: TOYOTA

Vehicle Model: PRIUS HYBRID 1.8S A

Primary Colour: Blue

Manufacturing Year: 2010

Engine No.: 2ZRR123832

Chassis No.: ZVW301192308

Maximum Power Output: 73.0 kW (97 bhp)

Open Market Value: \$30,210.00

Original Registration Date: 02 Sep 2010

First Registration Date: 02 Sep 2010

Transfer Count: 1

Actual ARF Paid: \$18,126.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 01 Sep 2020

PARF Rebate Amount: \$10,875.00

Intended COE Rebate Details

COE Expiry Date: 01 Sep 2020

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$42,901.00

COE Rebate Amount: \$9,030.00

Total Rebate Amount: \$19,905.00

The information contained herein is correct as at 24 Jul 2018

OK

Not Authorized
Repair - Sum \$6200-
24/7/18
4dy.

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6
#01-46,48,50 Autobay
SINGAPORE 417883

VEHICLE NO: SND 8188T

QTY	PARTICULAR		
1 PCS	FRONT BUMPER	Dis 945.11	\$1,250.10
1 PCS	FRONT BUMPER LOGO	nu	\$68.50
1 PCS	FRONT BUMPER CENTRE GRILLE	nu 188.20	\$242.30
1 PCS	FRONT BUMPER LOWER GRILLE	Torn/nu 288.50	\$366.20
2 PCS	FRONT BUMPER SIDE HOLDERS	@\$85.10 5ea	\$170.20
1 PCS	FRONT BUMPER TOW COVER	17	\$30.00 X
1 PCS	FRONT BUMPER SPONGE	17	\$122.60 X
1 PCS	FRONT BUMPER REINFORCEMENT	17	\$485.11 X
1 SET	FRONT BUMPER CLIPS	nu	\$50.00
1 PCS	FRONT BUMPER LOWER COVER	Torn 312.30	\$366.90
1 SET	FRONT BUMPER LOWER COVER CLIPS	nu	\$50.00
2 PCS	HEADLAMPS @\$1850.10	holder one 1450.10 x 2 = 2900.20	\$3,700.20
1 PCS	FRONT BUMPER TOP RUBBER	nu	\$122.50
1 PCS	FRONT FENDER N/S	3ea 866.50	\$991.10
1 PCS	FRONT FENDER 'HYBRID' EMBLEM	nu 101.00	\$165.50
2 PCS	FRONT FENDER INNER SHIELD @\$312.20	De/Torn 285.10 x 2 = 570.20	\$624.40
1 SET	FRONT FENDER INNER SHIELD CLIPS	nu	\$50.00
1 PCS	FRONT BUMPER INNER RETAINER	2ea	\$185.30
1 PCS	FRONT SUPPORT PANEL	2	\$1,145.20 X
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	17	\$350.10 X
1 PCS	HEADLAMP PANEL N/S	2	\$188.50 X
1 PCS	BONNET	2	\$945.10 X
1 PCS	FRONT FOG LAMP N/S	1ea 312.50	\$350.20
1 PCS	FRONT LICENCE PLATE W/HOLDER	5ea	\$52.00
			\$12,072.01

LABOUR CHARGES:

TOWING CHARGE	\$100.00 50
TO CHECK WIRING	\$80.00 30
TO SPRAY RUST PROOFING	\$120.00 50
TO CONDUCT WHEEL ALIGNMENT	17 \$120.00 X
TO REFILL AIR CON GAS	17 \$150.00 X
LABOUR FOR PANEL BEATING & REPLACING PARTS	\$1,200.00 540
TO PUTTY & SPRAY PAINTING	\$1,500.00 800
	\$15,342.01

LKK Auto Consultant TOTAL notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

7233.01
542475
6884




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18013461/Uvd3n2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 15-08-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBD 3305G	Veh. Inspected	SDN 8188T	
Policy No.		Coverage (\$)	0.00	
Claim No.	GBD3305G/SL/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS (A)	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	ZVW301192308	Colour	BLUE	
Odometer	121893	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R16	MICHELIN	7 mm	
L/H Front Tyre	205/55 R16	MICHELIN	7 mm	
R/H Rear Tyre	205/55 R16	MICHELIN	7 mm	
L/H Rear Tyre	205/55 R16	MICHELIN	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	18/07/2018	Inspection Date	24/07/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SDN 8188T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	DISTORTED	1,250.10	945.11
1	FRONT BUMPER LOGO	NECESSARY	68.50	68.50
1	FRONT BUMPER CENTRE GRILLE	MISSING	242.30	188.20
1	FRONT BUMPER LOWER GRILLE	TORN / MISSING	366.20	288.50
2	FRONT BUMPER SIDE HOLDERS @\$85.10	BENT	170.20	170.20
1	FRONT BUMPER TOW COVER	NOT NECESSARY	30.00	-
1	FRONT BUMPER SPONGE	NOT NECESSARY	122.60	-
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	485.11	-
1	SET FRONT BUMPER CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER LOWER COVER	TORN	366.90	312.30
1	SET FRONT BUMPER LOWER COVER CLIPS	NECESSARY	50.00	50.00
2	HEADLAMPS @\$1850.10	HOLDER CRACKED	3,700.20	2,900.20
1	FRONT BUMPER TOP RUBBER	NECESSARY	122.50	122.50
1	FRONT FENDER N/S	BADLY DENTED	991.10	866.50
1	FRONT FENDER "HYBRID" EMBLEM	NECESSARY	165.50	101.00
2	FRONT FENDER INNER SHIELD @\$312.20	DEFORMED / TORN	624.40	570.20
1	SET FRONT FENDER INNER SHIELD CLIPS	NECESSARY	50.00	50.00
1	FRONT BUMPER INNER RETAINER	CRACKED	185.30	185.30
1	FRONT SUPPORT PANEL	TO REPAIR SEE LABOUR	1,145.20	-
1	FRONT SUPPORT PANEL TOP GARNISH	NOT NECESSARY	350.10	-
1	HEADLAMP PANEL N/S	TO REPAIR SEE LABOUR	188.50	-
1	BONNET	TO REPAIR SEE LABOUR	945.10	-
1	FRONT FOG LAMP N/S	CRACKED	350.20	312.50
1	FRONT LICENCE PLATE W/HOLDER	SCRATCHED	52.00	52.00
	LESS 25% DISCOUNT		-	-1,808.26
			12,072.01	5,424.75
LABOUR				
	TOWING CHARGE.		100.00	50.00

Report Ref No. CS/EGI18013461/Uvd3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING.		80.00	30.00
	TO SPRAY RUST PROOFING.		120.00	50.00
	TO CONDUCT WHEEL ALIGNMENT.	NOT NECESSARY	120.00	-
	TO REFILL AIR CON GAS.	NOT NECESSARY	150.00	-
	LABOUR FOR PANEL BEATING & REPLACING PARTS.INCLUSIVE OF THE REPAIR OF FRONT SUPPORT PANEL,HEADLAMP PANEL N/S AND BONNET.		1,200.00	540.00
	TO PUTTY & SPRAY PAINTING.		1,500.00	800.00
			3,270.00	1,470.00
GRAND TOTAL			15,342.01	6,894.75
RECOMMENDED COST OF REPAIR SUM				6,200.00

Report Ref No. CS/EGI18013461/Uvd3n2

NOTE: NEW PARTS REPLACEMENT

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.