

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **AXA INSURANCE SINGAPORE PTE LTD**
8 SHENTON WAY #27-10
Singapore 068811

Date : 24.07.2018

Motor Claim Dept

Vehicle number : **SLC 662 G**
Make/Model : **MAZDA, MAZDA 2 SEDAN 1.5L SP.6EAT**
Date of accident : **23.07.2018**
Claim Type : **TP Claim**

Accident involving SLC 662 G & SLW 8034 L along (SLE) Highway on 23.07.2018.

Re: Estimate

1.	1 pc	Rear bumper	\$	909.00	de ✓
2.	2 pcs	Rear bumper bracket	\$	44.80	nei ✓
3.	2 pcs	Rear bumper side retainer LH,RH	\$	43.40	nei ✓
4.	2 pcs	Rear bumper reflexor LH,RH	\$	100.80	LH - one ✓, RH - ✓
5.	1 set	Rear reverse sensor	(S/Nett) \$	200.00	qu ✓
6.	1 pc	Rear end panel	\$	624.00	bt ✓
7.	1 pc	Rear boot weathershield	\$	107.00	twi ✓
8.	1 pc	Rear end garnish	\$	57.00	de ✓
9.	2 pcs	Rear end side garnish LH,RH	\$	346.00	?
10.	1 pc	Rear lock	\$	181.00	bt ✓
11.	2 pcs	Rear tail lamp	\$	752.00	one ✓
12.	1 pc	Rear boot	\$	820.60	bt ✓
13.	1 pc	Rear boot inner trim	\$	288.00	x
14.	2 pcs	Rear boot lamp LH,RH	\$	396.00	LH - ? RH - one ✓
15.	1 pc	Rear Mazda 2 emblem	\$	55.10	nei ✓
16.	1 pc	Rear Mazda 2 logo	\$	55.60	nei ✓
17.	1 pc	Rear skyactiv technology emblem	\$	64.30	nei ✓
18.	1 set	Rear number plate & casing	(S/Nett) \$	45.00	x

李光華 摩哆燒焊

LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

LEE KUAN HWA MOTOR SERVICE

Mailing Add: 39, Westwood Ave Singapore 648719
Workshop: 24, Sungei Kadut Street 4 Singapore 729050
Tel: 6269 9192 Fax: 6269 2239 H/P: 9631 1712
Business Reg. No: 36463500B

M/s: **AXA INSURANCE SINGAPORE PTE LTD**
8 SHENTON WAY #27-10
Singapore 068811

Date : 24.07.2018

Motor Claim Dept

Vehicle number : **SLC 662 G**
Make/Model : **MAZDA, MAZDA 2 SEDAN 1.5L SP.6EAT**
Date of accident : **23.07.2018**
Claim Type : **TP Claim**

Accident involving SLC 662 G & SLW 8034 L along (SLE) Highway on 23.07.2018.

Re: Estimate

19.	2 pcs	Rear boot bracket	\$	236.00	✓
20.	15 pcs	Rear clips	\$	67.50	✓
21.	1 pc	Rear fender LH	\$	944.30	✓
			\$	6,337.40	
To Towing Services			\$	80.00	60
To Wiring Services			\$	100.00	30
To Replace & Repair Labour Charge			\$	1,200.00	900
To Putty & Spray Painting			\$	1,200.00	1000
Total			\$	8,917.40	

Yours Faithfully,

李光華 摩 嘜 燒 焊
LEE KUAN HWA MOTOR SERVICE
39, Westwood Avenue, Singapore 648719
TEL: 6269 9192 FAX: 6269 2239 H/P: 9631 1712

LKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Truphik 97495749
WP
25/7/18 @ 1800
Resurvey before part
7 days.
surellkhuon