


SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB439M
 Ref. No : TAX/07/18/2086
 Reg. Date : 02/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : VICKLAND MOHAMED SIDEK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 19/07/2018 11:50:00 AM
 Accident Reported Date / Time : 19/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097106
 Special Instruction to ARC, if any :
 SLC4300A - NTUC - LKK
 Prepared Date : 19/07/2018 01:24:46 PM



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date:

Tanjil 97495744

WP'

20/7/18 @ 630

Lumpsum

Resurvey after repair.

6 days.

SUR @ lkkauto.com

26/7/18