

Taylor

REF:

INC NS/INC18013473/TL vber

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SLC 4300A
 Policy No. 5099 434237 070518 - 120519
 Claims No. MT / 1003668 -002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SMB439M Yr Regn: 2015 Feb
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Toyota Prius c.c. 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 31006 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: STDKN36M 905756550
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195 / 65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Fallen
 Front 6 Rear 6
 R/Bal. _____ mm R/Bal. _____ mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 19/7/18 D.O.I. 20/7/18 @ 1650
 Survey held at SMRT WL
 Des. of Damages: Frt / Rear / O/S / NIS / UIC / Rooftop or _____
 The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>SMB 439M - CG / ALB / 600173 / Klyb3q2</u>
	<u>SLC 4300A - x</u>

14X 07/18/2086
SLC 4300A

30/7/18 LS \$ 3050 confirmed by email (Recd 7541.60, 719)

RECEIVED 31 JUL 2018

Date/Time. File Pass to? : Preli. Report
 : Final Report

Days Of Repair: 6
 Resurvey No. of Trip: 1

1) _____
 Date/Time. File Return to?
 2) 30/7 - typist

Add Fee: Site Insp (S)
 Interview (S)
 Tech. Invs (S)
 Weekend (S)

Report Format: TP
 Lump Sum / I.B.I. (S) 3050/-

Survey Fee:	<u>160</u>
Transportation	
_____ S - RS _____ SI	
Photos	
Others	
TOTAL	<u>160</u>



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013473/T1vb			
73 BRAS BASAH ROAD		Date: 24-07-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE			
189556		Code: INC4	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLC 4300A	Veh. Inspected	SHB 439M
Policy No.	5099434237	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	19/07/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/07/2018	Inspection Date	20/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Hello, NAC_PAYA_UBI_800601

Change Language Change Password Log Out

My Desktop
Notice of Loss

Policy Query

Policy No. Date of Accident

Vehicle No.(For Motor)

Search

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5099434237	LEE BIN ANN	S1346624F	GPC	drive CLASSIC	SLC4300A	SLC4300A	07/05/2018	12/05/2019

Continue

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	SHB439M		
Vehicle Type :	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1 :	Air-Con (Taxi)		
Vehicle Scheme :	Taxi (Company)		
Vehicle Make :	TOYOTA		
Vehicle Model :	PRIUS TAXI (SMRT)		
Chassis No. :	JTDKN36U905756550		
Propellant :	Petrol-Electric		
Engine No. :	2ZR6275858		
Motor No. :	3JM6275858		
Engine Capacity :	1798 cc		
Power Rating :	60.0 kW		
Maximum Power Output :	100.0 kW (134 bhp)		
Maximum Laden Weight :	1805 kg		
Unladen Weight :	1370 kg		
Year Of Manufacture :	2014		
Original Registration Date :	02 Feb 2015		
Lifespan Expiry Date :	01 Feb 2023		
COE Category :	A - Car up to 1600cc & 97kW (130bhp)		
PQP Paid :	\$52,904.00		
COE Expiry Date :	01 Feb 2023		
Road Tax Expiry Date :	01 Feb 2019		
PARF Eligibility Expiry Date :	01 Feb 2023		
Inspection Due Date :	01 Feb 2019		
Intended Transfer Date :	25 Jul 2018		
CO2 Emission :	92.00 (g/km)		
CEV/VES Rebate Utilised Amount :	\$30,000.00		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (\$\$)	GST Amount (\$\$)	Amount After GST (\$\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.			

You may print this page for reference.

OK

Print

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	19/07/2018 13:05
Date Of Accident	19/07/2018 11:50
Exact Location Of Accident	EU TONG SEN STREET
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB439M
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	VICKLAND MOHAMED SIDEK
NRIC No	S1679035D
Date Of Birth	22/11/1964
Occupation	OUTDOOR
Date Of Driving Pass	24/10/1983
Driving Experience	34 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
EMail Address	NOEMAIL

Address	363
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	5
Passenger 1	NAME: : UNKNOWN GENDER: : MALE
Passenger 2	NAME: : UNKNOWN GENDER: : FEMALE
Passenger 3	NAME: : UNKNOWN GENDER: : MALE
Passenger 4	NAME: : UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes,Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes,against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG EU TONG SEN STREET WITH FOUR PASSENGERS ON BOARD. MY TAXI WAS TRAVELLING STRAIGHT AT THIRD LANE WHEN THE VEHICLE SLC4300A FROM THE SECOND LANE CUT INTO MY LANE AND COLLIDED ONTO THE RIGHT PORTION OF MY TAXI.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLC4300A
Vehicle Make/Model/Colour	
Details Of Properties	

Vehicle Category	PRIVATE HIRE
Name of Driver	LEE BIN ANN
NRIC/Passport Number	S1346624F
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow Insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

Handwritten signature

Driver's Signature
(If driver is not the policyholder)
Date & Time: 12/07/2018


Handwritten signature and date: ak 19/8/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB439M
 Ref. No : TAX/07/18/2086
 Reg. Date : 02/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : VICKLAND MOHAMED SIDEK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 19/07/2018 11:50:00 AM
 Accident Reported Date / Time : 19/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097106
 Special Instruction to ARC, if any :
 SLC4300A - NTUC - LKK
 Prepared Date : 19/07/2018 01:24:46 PM



Tanjiloh 97495744
- WP'

20/7/18 @ 1630

Lumpsum

Resuming after repair.

6 days.

SUR @ lkkanto.com

[Signature]
26/7/18

Chassis No : JTDKN36U905756550

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,872.00	0.00
Total Material Charges	: 4,018.51	4,018.51
Other Charges	: 1,185.00	0.00
TOTAL	: 8,089.51	0.00
Lum Sum Total	: 8,100.00	0.00
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 20/07/2018 08:28:57 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/07/2018 08:28:57 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,014.00	0.00
Total Labour	1,014.00	0.00 800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 100
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	1,872.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED REA	100.00	0.00 40.
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 80.
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO REMOVE / REFIT SEAT	120.00	0.00 80
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 80
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
Total Other Costs	1,185.00	0.00

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
17001-17070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>Rx</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>nel</i>	No
15851-17900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace <i>Rx</i>	No
17003-17080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>bt</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>nel</i>	No
11604-17090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>bu</i>	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace <i>nel</i>	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>nel</i>	No
12710-17130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace <i>?</i>	No
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>nel</i>	No
2611-17140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace <i>Rx</i>	No
2159-17905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>Rx</i>	No
2576-17020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>Rx</i>	No
2575-17020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>nel</i>	No
TOTAL MATERIALS								4,952.05	4,952.04	
TOTAL MATERIALS(Discounted)								4,018.51	4,018.51	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

27.7-18 / 12:35
27.7.18 / 16:35

20-7-18 / 16:35

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB439M
 Ref. No : TAX/07/18/2086
 Reg. Date : 02/02/2015
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : VICKLAND MOHAMED SIDEK
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 19/07/2018 11:50:00 AM
 Accident Reported Date / Time : 19/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by : Taufikh
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097106
 Special Instruction to ARC, if any :
 SLC4300A - NTUC - LKK 45
 Before paint photo and after paint photo ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR TAUFIKH , HP 9749 5749/ EMAIL: sur@lkkauto.com
 Prepared Date : 19/07/2018 01:24:46 PM



QC 26/7/18 9.00 pass

Recording Camera
 Radio Antenna
 1st witness ad Date 20.7.18
 2nd witness _____ Date _____

310073
 LEE SHENG AUTO PTE LTD

Vehicle Return Date: 25-7-2018
 Vehicle Return Time: 15:00
 SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U905756550 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	800.00
Total Spray Painting Charges	: 1,872.00	1,000.00
Total Material Charges	: 1,435.74	1,608.47
Other Charges	: 1,185.00	-358.47
TOTAL	: 5,506.74	3,050.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 6.00	6.00
Prepared / Adjusted By	:	TAUFIK (LKK)
Arc / Surveyor Sing Off Date	: 20/07/2018 08:28:57 AM	20/07/2018 04:35:32 PM

10,591.60

Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/07/2018 08:28:57 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1807-0700 Invoice No :
Quotation Date : 29/7 Invoice Date :
Invoice Amount : Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,014.00	800.00
Total Labour	1,014.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	200.00
TO RESPRAY ROCKER PANEL MOULDING	180.00	100.00
TO RESPRAY REAR DOOR RH	378.00	200.00
TO RESPRAY REAR FENDER RH	378.00	200.00
TO RESPRAY RIM	180.00	100.00
TO REPSRAY REAR BUMPER	378.00	200.00
Total Spray Painting & Panel Beating	1,872.00	1,000.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	40.00
TO TRANSFER DOOR MECHANISM	240.00	60.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	80.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	30.00
TO REMOVE / REFIT SEAT	120.00	80.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	80.00
TO REPLACE SUNDRY PARTS	100.00	30.00
TO WASH AND VACUUM	60.00	0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-788.47
Total Other Costs	1,185.00	-358.47

10591.60

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>NEC</i>	No <i>/</i>
75851-47900			MOULDING BODY, RH	1	673.60	100.00	0.00	Replace	Repair	No <i>R</i>
67003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>bt</i>	No <i>/</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>NEC</i>	No <i>/</i>
61604-47090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>Buc</i>	No <i>/</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace <i>NEC</i>	No <i>/</i>
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>NEC</i>	No <i>/</i>
62710-47130			QUARTER GLASS RR/RH	1	846.50	25.00	634.88	Replace	Check <i>nn</i>	No <i>X</i>
	COMMON		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>NEC</i>	No <i>/</i>
42611-47140		6505658	WHEEL, DISC	1	1,490.20	100.00	0.00	Replace	Repair	No <i>R</i>
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH	0	94.80	25.00	0.00	Replace	Not given <i>nn</i>	No <i>X</i>
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>NEC</i>	No <i>/</i>
TOTAL MATERIALS								2,243.35	1,608.47	
TOTAL MATERIALS(Discounted)								1,435.74	1,608.47	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1608.47
 + 800.00
 + 1430.00

3838.47
 - 20%

3070.78

415 \$3050/-

Veron Chen (LKKAuto)

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 30 July 2018 6:08 PM
To: Veron Chen (LKKAuto); Taufikh (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB439M

Hi

Amount confirmed as per your recommendation, thanks.

Regards
Poh Suan

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Monday, 30 July 2018 2:56 PM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC); Taufikh (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB439M

Dear Poh Suan,

Confirmed Lump Sum \$3050 @ 6 working days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 30 July 2018 1:48 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB439M

Hi Taufikh,

Attached herewith the repair estimate of SHB 439M having Case No: TAX/07/18/2086.

There is no change to the approved amount of \$3,050 @ 6 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Sent: Monday, 30 July 2018 9:13 AM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)

Subject: Scan Data from FX-D421D6

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Monday, 30 July 2018 2:56 PM
To: 'Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)'; Taufikh (LKKAuto)
Cc: SUR; CS A Team
Subject: RE: SHB439M

Dear Poh Suan,

Confirmed Lump Sum \$3050 @ 6 working days.

Best Regards,
Veron Chen | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC) <YeoPohsuan@smrt.com.sg>
Sent: Monday, 30 July 2018 1:48 PM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: SHB439M

Hi Taufikh,

Attached herewith the repair estimate of SHB 439M having Case No: TAX/07/18/2086.

There is no change to the approved amount of \$3,050 @ 6 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Sent: Monday, 30 July 2018 9:13 AM
To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC)
Subject: Scan Data from FX-D421D6



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD		Ref:	NS/INC18013473/T1vbe2	
73 BRAS BASAH ROAD		Date:	14-08-2018	
#05-01 NTUC TRADE UNION HOUSESINGAPORE				
189556				
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLC 4300A	Veh. Inspected	SHB 439M	
Policy No.	5099434237	Coverage (\$)	0.00	
Claim No.	MT/1003668-002	Excess (\$)	0.00	
Assign From		Assign Date	20/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JTDKN36U905756550	Colour	MAROON	
Odometer	310016	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	FALKEN	6 mm	
L/H Front Tyre	195/65 R15	FALKEN	6 mm	
R/H Rear Tyre	195/65 R15	FALKEN	6 mm	
L/H Rear Tyre	195/65 R15	FALKEN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	19/07/2018	Inspection Date	20/07/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 439M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR RR/RH (DISC 25%)	BENT	954.50	715.87
1	FENDER RR/RH (DISC 25%)	BUCKLED	766.80	575.10
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
1	STICKER DECAL SMRT (DOOR) (SN)	NECESSARY	60.00	60.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	SEALANT W/SCREEN (SN)	NECESSARY	37.00	37.00
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	DOOR FRT / RH	TO REPAIR SEE LABOUR	894.40	-
1	MOULDING BODY, RH	TO REPAIR SEE LABOUR	673.60	-
1	WHEEL, DISC	TO REPAIR SEE LABOUR	1,490.20	-
1	BUMPER REAR	TO REPAIR SEE LABOUR	458.60	-
			6,520.60	1,608.47
<u>LABOUR</u>				
PANEL BEAT & BODY WORK. INCLUSIVE OF THE REPAIR OF DOOR FRT / RH, MOULDING BODY, RH, WHEEL, DISC AND BUMPER REAR.			1,014.00	800.00
SPRAY PAINT.			1,872.00	1,000.00
TO CHECK WIRING AND SYSTEM FUNCTION.			80.00	30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA.			100.00	40.00
TO TRANSFER DOOR MECHANISM.			240.00	60.00
TO REMOVE & REFIT REAR QUARTER GLASS RH.			120.00	80.00
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE).			120.00	30.00
TO REMOVE / REFIT SEAT.			120.00	80.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING.			120.00	80.00

Report Ref No. NS/INC18013473/T1vbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE SUNDRY PARTS.		100.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.	NOT NECESSARY	125.00	-
			4,071.00	2,230.00
	GRAND TOTAL		10,591.60	3,838.47
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				3,050.00

Report Ref No. NS/INC18013473/T1vbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.