

INSURANCE

Taufm

REF:

INC


NS/INC(180)3474/111ber

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: SJA 2414R
 Policy No: 5089066012-01 250318
 Claims No: MT/1004057-002
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHE/011K- Yr Regn: 2014 Dec.
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Toyota Prius C.C. 1798
 Colour: Maroon A/C: Insured / Std / NI / NA
 Sp. Reading: 377640 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JTDKN36470375491
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or
 Brake: Inorder / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 195/65R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Kallan

Front: 6 mm Rear: 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 2/7/18 D.O.I. 2/7/18 05pm
 Survey held at SWAT
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	SHE/011K - NS/INC 7019078 / 111ber
	SJA 2414R - X
	Lump Sum \$6,100 (Red: 6359.29, 7, 712)

RECEIVED 16 AUG 2018

Date/Time, File Pass to? ☐ : Preli. Report

1) 16/8 Typist ☒ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: 9

Resurvey No. of Trip: 2

Survey Fee:

Transportation: _____

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)

Report Format: TP

Lump Sum / I.B.I: (\$ 6100)

160

160



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013474/T1tb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 24-07-2018

189556



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 2414R	Veh. Inspected	SHF 1011K
Policy No.	5089066012-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	20/07/2018	Inspection Date	20/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

GeneralClaim

Hello, NAC_PAYA_UBI_800601

[Change Language](#) [Change Password](#) [Log Out](#)[My Desktop](#)[Notice of Loss](#)

Policy Query

Policy No.		Date of Accident	20/07/2018 18:05						
Vehicle No. (For Motor)	SJH2414R								
Search									
Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
☐	5089066012-01	ASIA EXPRESS CAR RENTAL PTE LTD	201116882D	GFT	Third Party, Fire & Theft	SJH2414R	SJH2414R	25/03/2018	
Continue									

TP Claims against NTUC Income: Follow-Through Survey

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.
1	MT/1007447-001	COMFORT TRANSPORTATION PTE LTD	SH 7642J	SGW 6777Z
2	MT/1006907-002	COMFORT TRANSPORTATION PTE LTD	SHC 8126H	SJP 2296Y
3	MT/1007096-002	CITYCAB PTE LTD	SHB 3420X	SHC 6930R
4	MT/1007261-002	COMFORT TRANSPORTATION PTE LTD	SH 7441Y	SKM 6659L
5	MT/1006877-002	COMFORT TRANSPORTATION PTE LTD	SHD 3503E	SLW 9739E
6	MT/1007260-002	COMFORT TRANSPORTATION PTE LTD	SHD 6683Z	SLW 2952B
7	MT/1007452-001	COMFORT TRANSPORTATION PTE LTD	SHD 4255P	SKL 9885K
8	MT/1004057-002	SMRT TAXIS PTE LTD	SHF 1011K	SIH 2414R
9	MT/1004374-002	SMRT TAXIS PTE LTD	SHB 1621X	YN 5815M

Claim received from LKK Auto

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2018 10:49
Date Of Accident	20/07/2018 08:00
Exact Location Of Accident	CTE TOWARDS CITY
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHF1011K
Insured/Policyholder	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-80000000

Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

Driver

Name of Driver	TAN LENG YONG
NRIC No	S1379184H
Date Of Birth	08/05/1959
Occupation	OUTDOOR
Date Of Driving Pass	01/12/1978
Driving Experience	39 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-80000000
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	840
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	AFTER RAIN
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	
	NAME: : UNKNOWN
	GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG CTE AT THE RIGHT MOST LANE WITH A PASSENGER ON BOARD WHEN THE FRONT VEHICLE SLC5048Y SUDDENLY STOPPED. I APPLY MY BRAKE AND MANAGED TO STOP IN TIME. HOWEVER THE VEHICLE SJH2414R FROM BEHIND FAILED TO STOP AND HIT ONTO THE REAR PORTION OF MY TAXI. THE IMPACT PUSHED MY TAXI MOVE FORWARD AND CAUSING MY TAXI TO HIT ONTO THE REAR OF THE VEHICLE SLC5048Y.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJH2414R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SLC5048Y

Vehicle Make/Model/Colour

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature]

Driver's Signature
(If driver is not the policyholder)
Date & Time:

[Signature] 20/7/2018

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN

Diagram illustrating a three-lane highway cross-section with the following lane designations:

- C - SLC 5042Y
- A - SHF1011K
- B - SJH 2414R

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

[illegible]

DECLARATION

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature _____
Date & Time: _____

Driver's Signature
(If driver is not the policyholder)
Date & Time:

du 20/7/18

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No	:	SHF1011K
Ref. No	:	TAX/07/18/2089
Reg. Date	:	17/12/2014
Vehicle Type	:	TAXI
Make	:	TOYOTA PRIUS
Model	:	PRIUS
Name of Driver	:	TAN LENG YONG
Type of Accident	:	CHAIN COLLISION
Date / Time of Accident	:	20/07/2018 08:00:00 AM
Accident Reported Date / Time	:	20/07/2018 12:00:00 AM
Surveyor is Required?	:	Yes
Survey by	:	
Vehicle is Towed Back?	:	No
Towed Back Date/Time	:	
Replacement Vehicle issued?	:	No
Accident Repair Job Card No	:	000024097121
Special Instruction to ARC,if any	:	
SJH2414R		
Prepared Date	:	20/07/2018 11:14:29 AM



Taught 97495749
"wp"
20/7/18 @ 1700

Warping

Recovery after repair.

Suo @ 11kanto.com

7 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental item(s) must be resurveyed and
is subject to final approval from Insurance Company

Signed by Repairer

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U705754196

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,690.00	0.00
Total Spray Painting Charges :	3,168.00	0.00
Total Material Charges :	9,714.06	9,714.06
Other Charges :	1,040.00	0.00
TOTAL :	15,612.06	0.00
Lum Sum Total :	15,600.00	0.00
No. of Repair Days :	10.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	20/07/2018 04:47:32 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/07/2018 04:47:32 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount :	Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00	0.00 500
TO REPAIR REAR PORTION	845.00	0.00 300
Total Labour	1,690.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 X150
TO RESPRAY FRONT FENDER LH	378.00	0.00 200
TO RESPRAY FRONT FENDER RH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 100
TO RESPRAY TAIL GATE	378.00	0.00 X 117
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00 X 117
TO RESPRAY REAR SPOILER	180.00	0.00 100
TO RESPRAY REAR PANEL	180.00	0.00 100
Total Spray Painting & Panel Beating	3,168.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X 744
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X 117
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 40
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X 117
Total Other Costs	1,040.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace <i>de</i>	No
52161-16010			BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>new</i>	No
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace <i>new</i>	No
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace <i>bt</i>	No
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace <i>all</i>	No
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace <i>one</i>	No
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace <i>? X m</i>	No
53111-47040		6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95	Replace	Replace <i>de</i>	No
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace <i>out</i>	No
52116-47040		6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30	Replace	Replace <i>X</i>	No
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Replace <i>X</i>	No
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace <i>? X</i>	No
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Replace <i>?</i>	No
57014-47030			ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80	Replace	Replace <i>?</i>	No
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Replace <i>?</i>	No
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.07	Replace	Replace <i>R</i>	No
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace <i>X</i>	No
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.92	Replace	Replace <i>R</i>	No
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.92	Replace	Replace <i>R</i>	No
53510-47102			HOOD LOCK	1	128.90	25.00	96.67	Replace	Replace <i>X</i>	No
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Replace <i>R</i>	No
31170-47500		6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>?</i>	No
31130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>?</i>	No
33802-47050		6505558	FENDER FRT/LH	1	723.40	25.00	542.55	Replace	Replace <i>R</i>	No
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace	No
3876-7030		6505554	FENDER LINER FRT/LH	1	171.70	25.00	128.77	Replace	Replace <i>new</i>	No
3801-7050		6505557	FENDER FRT/RH	1	723.40	25.00	542.55	Replace	Replace <i>X</i>	No
5374-7051			NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace <i>R</i>	No
3875-7030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.77	Replace	Replace <i>new</i>	No

Number			Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905	6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>de</i>	No
52161-16010		BUMPER CLIPS	10	1.61	25.00	12.07	Replace	Replace <i>nu</i>	No
76088-47020	6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace ?	No
76087-47020	6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace ?	No
76891-47020	6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace <i>de</i>	No
52023-12240	6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace ?	No
52016-47030		ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace ?	No
52015-47050		ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace <i>nu</i>	No
		PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>nu</i>	No
52592-47021		BUMPER SEAL, RR LH	1	88.90	25.00	66.67	Replace	Replace ?	No
52591-47021		BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace ?	No
52576-47020	6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace <i>nu</i>	No
52575-47020	6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace ?	No
67005-47241		TAILGATE ASY	1	1,007.90	25.00	755.92	Replace	Replace x	No
75574-47020		TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	25.00	22.05	Replace	Replace x	No
75573-47080		TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	25.00	22.05	Replace	Replace x	No
75575 - 47030		MOULDING BACK WINDOW, LOWER NO.1	1	29.40	25.00	22.05	Replace	Replace x	No
	COMMO N	SEALANT W/SCREEN	3	37.00	0.00	111.00	Replace	Replace x	No
39350-47030		TAILGATE DOOR LOCK	1	444.10	25.00	333.07	Replace	Replace x	No
37881-47022		TAILGATE DOOR WEATHER STRIP	1	353.40	25.00	265.05	Replace	Replace x	No
39415-47020		TAILGATE LOCK, COVER	1	15.70	25.00	11.77	Replace	Replace x	No
76801-47070-B0		TAILGATE OUTSIDE GARNISH	1	504.90	25.00	378.67	Replace	Replace x	No
39431-47010		STRIKER, BACK DOOR	1	48.90	25.00	36.67	Replace	Replace x	No
5310-7020	6505639	EMBLEM REAR	1	60.30	25.00	45.22	Replace	Replace x	No
5374-7051		NAME PLATE (HYBRID)	1	51.90	25.00	38.92	Replace	Replace x	No
5442-7030		NAME PLATE (PRIUS)	1	60.80	25.00	45.60	Replace	Replace x	No
5443-7030		NAME PLATE (TOYOTA)	1	51.90	25.00	38.92	Replace	Replace x	No
3085-7910		6505620 SPOILER REAR	1	953.70	25.00	715.27	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMON		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace ☒	No
	COMMON		STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace ☒	No
58307-47060		6505522	END PANEL	1	602.10	25.00	451.57	Replace	Replace ☒	No
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	1	46.10	25.00	34.57	Replace	Replace ☒	No
64716-47031B0			END PANEL COVER, DECK TRIM, RR	1	121.10	25.00	90.82	Replace	Replace ☒	No
	COMMON	4006314	SEALANT SIKAFLEX	1	37.00	0.00	37.00	Replace	Replace ☒	No
52563-47010			TAIL LAMP BRACKET, LH	1	30.70	25.00	23.02	Replace	Replace ☒	No
52562-47010			TAIL LAMP BRACKET, RH	1	30.70	25.00	23.02	Replace	Replace ☒	No

TOTAL MATERIALS

12,142.74 12,142.57

TOTAL MATERIALS(Discounted)

9,714.06 9,714.06

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

28-7-18 / 12:35


28-7-18 / 16:35

SMRT Accident Vehicle Repair Estimates

20-7-18 / 16:35

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF1011K
Ref. No : TAX/07/18/2089
Reg. Date : 17/12/2014
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : TAN LENG YONG
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 20/07/2018 08:00:00 AM
Accident Reported Date / Time : 20/07/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Tan Fik H
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle Issued? : No
Accident Repair Job Card No : 000024097121
Special Instruction to ARC, if any :
SJH2414R NTUC 45
Before paint photo and after paint photo ,FOR CHECK ITEM and REPLACE ITEM.PLEASE CALL SURVEYOR
TAUFIKH , HP 9749 5749/ EMAIL: sur@lkkauto.com
lumpsum repair
Prepared Date : 20/07/2018 11:14:29 AM



QC 31/7/18 14:49 P 55



Recording Camera

☒ ☐

Radio Antenna

☒ ☐

1st witness

Date 20-7-18

2nd witness

Date

Supplementary
+ Radio to the Supplementary panel 11:50
3777/18

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

31-7-2018

Vehicle Return Time:

10:50 am

SMRT staff sign:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U705754196

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,690.00	800.00
Total Spray Painting Charges	: 3,168.00	1,450.00
Total Material Charges	: 4,026.39	5,031.17
Other Charges	: 1,310.00	-1,181.17
TOTAL	: 10,194.39	6,100.00
Lump Sum Total	: 0.00	0.00
No. of Repair Days	: 10.00	9.00
Prepared / Adjusted By	:	TAUFIK (LKK)
Arc / Surveyor Sing Off Date	: 20/07/2018 04:47:32 PM	20/07/2018 04:57:10 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 20/07/2018 04:47:32 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : QN-1808-0249
Quotation Date : 12/8
Invoice No :
Invoice Date :
Invoice Amount :
Prepared Date :

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	845.00	500.00
TO REPAIR REAR PORTION	845.00	300.00
Total Labour	1,690.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00
TO REPSRAY FRONT HOOD	378.00	200.00
TO RESPRAY FRONT SUPPORT PANEL	180.00	150.00
TO RESPRAY FRONT FENDER LH	378.00	200.00
TO RESPRAY FRONT FENDER RH	378.00	200.00
TO REPSRAY REAR BUMPER	378.00	200.00
TO RESPRAY BUMPER BEAM	180.00	100.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0.00
TO RESPRAY REAR SPOILER	180.00	100.00
TO RESPRAY REAR PANEL	180.00	100.00
Total Spray Painting & Panel Beating	3,168.00	1,450.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	40.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	30.00
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40.00
TO REPLACE SUNDRY PARTS	100.00	30.00
TO WASH AND VACUUM	60.00	0.00
TO TOP UP A/C GAS	120.00	100.00 / <i>nil</i>
TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER	150.00	80.00 / <i>nil</i>
Lump Sum Adjustment by Surveyor	0.00	-1,531.17
Total Other Costs	1,310.00	-1,181.17

6162

22920

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52119-47930	1	6505517	BUMPER FRT	1	482.00	25.00	361.50 <i>de</i>	Replace	Replace	No <i>/</i>
52161-16010	2		BUMPER CLIPS	10	1.61	25.00	12.07 <i>rec</i>	Replace	Replace	No <i>/</i>
52114-47140	3		BRACKET, FR BUMPER	1	110.40	25.00	82.80 <i>rec</i>	Replace	Replace <i>S</i>	No <i>/</i>
	51		NUMBER PLATE	1	15.00	0.00	15.00 <i>bt</i>	Replace	Replace	No <i>/</i>
	52		NUMBER PLATE FRAME	1	12.00	0.00	12.00 <i>de</i>	Replace	Replace	No <i>/</i>
53102-47020	4	6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32 <i>org</i>	Replace	Replace	No <i>/</i>
52618-47050	X	6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.78 <i>X</i>	Replace	Check	No <i>Xnn</i>
53111-47040	5	6505573	GRILLE, RADIATOR	1	310.60	25.00	232.95 <i>de</i>	Replace	Replace	No <i>/</i>
75310-47010	6	6505638	EMBLEM FRONT	1	86.50	25.00	64.87 <i>cut</i>	Replace	Replace	No <i>/</i>
52116-47040	X	6505516	BUMPER SUPPORT F/LH	1	76.40	25.00	57.30 <i>Xnn</i>	Replace	Check	No <i>Xnn</i>
52115-47040	X	6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30 <i>Xnn</i>	Replace	Check	No <i>Xnn</i>
52611-47080	X	6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10 <i>X</i>	Replace	Check	No <i>Xnn</i>
52021-47023	X	6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80 <i>X</i>	Replace	Check	No <i>Xnn</i>
57014-47030	X		ARM SUB-ASSY, FR BUMPER LH	1	250.40	25.00	187.80 <i>X</i>	Replace	Check	No <i>Xnn</i>
57013-47030	X		ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80 <i>X</i>	Replace	Check	No <i>Xnn</i>
53301-47060	R	6505555	HOOD PANEL	1	748.10	100.00	0.00 <i>f</i>	Replace	Repair	No <i>R</i>
53395-47020	X		HOOD END PANEL SEAL	0	35.50	25.00	0.00 <i>X</i>	Replace	Not given	No <i>Xnn</i>
53420-47070	R		HOOD HINGE LH	1	55.90	100.00	0.00 <i>X</i>	Replace	Repair	No <i>R</i>
53410-47070	R		HOOD HINGE RH	1	55.90	100.00	0.00 <i>X</i>	Replace	Repair	No <i>Rnn</i>
53510-47102	X		HOOD LOCK	0	128.90	25.00	0.00 <i>X</i>	Replace	Not given	No <i>Xnn</i>
53201-47902	R		SUPPORT SUB-ASSY	1	1,460.40	100.00	0.00 <i>X</i>	Replace	Repair	No <i>R</i>
81170-47500	(1)	6505436	HEAD LAMP LH	1	945.20	10.00	850.68	Replace	Replace <i>S</i>	No <i>ana</i>
81130-47500	(2)	6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace <i>S</i>	No <i>ana</i>
53802-47050	X	6505558	FENDER FRT/LH	1	723.40	100.00	0.00 <i>X</i>	Replace	Repair	No <i>R</i>
75374-47051	7		NAME PLATE (HYBRID)	1	51.90	25.00	38.92 <i>rec</i>	Replace	Replace	No <i>/</i>
53876-47030	X	6505554	FENDER LINER FRT/LH	0	171.70	25.00	0.00 <i>X</i>	Replace	Not given	No <i>Xnn</i>
53801-47050	R	6505557	FENDER FRT/RH	1	723.40	100.00	0.00 <i>X</i>	Replace	Repair	No <i>R</i>
75374-47051	8		NAME PLATE (HYBRID)	1	51.90	25.00	38.92 <i>rec</i>	Replace	Replace	No <i>/</i>
53875-47030	X	6505553	FENDER LINER FRT/RH	0	171.70	25.00	0.00 <i>X</i>	Replace	Not given	No <i>Xnn</i>

807130

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905	9	6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace <i>de</i>	Replace	No
52161-16010	10		BUMPER CLIPS	10	1.61	25.00	12.07	Replace <i>nel</i>	Replace	No
76088-47020	X	6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace <i>Xm</i>	Check	No X
76087-47020	11	6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.58	Replace	Replace <i>S</i>	No <i>de</i>
76891-47020	12	6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace <i>de</i>	Replace	No
52023-12240	13	6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.28	Replace	Replace <i>S</i>	No <i>bt</i>
52016-47030	14		ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace <i>nel</i>	Replace <i>S</i>	No <i>to</i>
52015-47050	15		ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace <i>nel</i>	Replace <i>S</i>	No <i>to</i>
	53		SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No <i>nw</i>
	54		PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>nel</i>
52592-47021	X		BUMPER SEAL, RR LH	1	88.90	25.00	66.68	Replace	Check	No <i>Xm</i>
52591-47021	X		BUMPER SEAL, RR RH	1	65.70	25.00	49.28	Replace	Check	No <i>Xm</i>
52576-47020	16	6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No <i>out</i>
52575-47020	X	6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Check	No <i>Xm</i>
67005-47241	X		TAILGATE ASY	0	1,007.90	25.00	0.00	Replace	Not given	No X
75574-47020	X		TAIL GATE DOOR GLASS MOULDING, LH	0	29.40	25.00	0.00	Replace	Not given	No X
75573-47080	X		TAIL GATE DOOR GLASS MOULDING, RH	0	29.40	25.00	0.00	Replace	Not given	No X
75575 - 47030	X		MOULDING BACK WINDOW, LOWER NO.1	0	29.40	25.00	0.00	Replace	Not given	No X
	COMMON X		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No X
69350-47030	X		TAILGATE DOOR LOCK	0	444.10	25.00	0.00	Replace	Not given	No X
67881-47022	X		TAILGATE DOOR WEATHER STRIP	0	353.40	25.00	0.00	Replace	Not given	No X
69415-47020	X		TAILGATE LOCK, COVER	0	15.70	25.00	0.00	Replace	Not given	No X
76801-47070-B0	X		TAILGATE OUTSIDE GARNISH	0	504.90	25.00	0.00	Replace	Not given	No X
69431-47010	X		STRIKER, BACK DOOR	0	48.90	25.00	0.00	Replace	Not given	No X
75310-47020	X	6505639	EMBLEM REAR	0	60.30	25.00	0.00	Replace	Not given	No X
75374-47051	X		NAME PLATE (HYBRID)	0	51.90	25.00	0.00	Replace	Not given	No X
75442-47030	X		NAME PLATE (PRIUS)	0	60.80	25.00	0.00	Replace	Not given	No X
75443-47030	X		NAME PLATE (TOYOTA)	0	51.90	25.00	0.00	Replace	Not given	No X
76085-47910	X	6505620	SPOILER REAR	0	953.70	25.00	0.00	Replace	Not given	No X
	COMMON		SMRT LOGO	0	7.80	0.00	0.00	Replace	Not given	No X

5709-50

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
	COMMO N		STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No <i>X</i>
58307-47060		6505522	END PANEL	1	602.10	100.00	0.00	Replace	Repair	No <i>X</i>
64718-47031B0			END PANEL COVER, DECK TRIM HOLE	0	46.10	25.00	0.00	Replace	Not given	No <i>X</i>
64718-47031B0			END PANEL COVER, DECK TRIM, RR	0	121.10	25.00	0.00	Replace	Not given	No <i>X</i>
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No <i>X</i>
52563-47010			TAIL LAMP BRACKET, LH	0	30.70	25.00	0.00	Replace	Not given	No <i>X</i>
52562-47010			TAIL LAMP BRACKET, RH	0	30.70	25.00	0.00	Replace	Not given	No <i>X</i>
88460-47150			A/C CONDENSER	1	1,181.90	25.00	886.42	Replace	Replace <i>S</i>	No <i>X</i>
TOTAL MATERIALS							2071.20	6,291.29	5,031.17	
TOTAL MATERIALS(Discounted)								4,026.39	5,031.17	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
88460-47150		A/C CONDENSER	1	1,181.90	25.00	886.42	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						886.42			

5031.17
 + 800.00
 + 1800.00

 7631.17
 - 202

 6104.93
 US \$6100/-



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013474/T1tbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

Date: 27-08-2018



Code: INC4

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SJH 2414R	Veh. Inspected	SHF 1011K
Policy No.	5089066012-01	Coverage (\$)	0.00
Claim No.	MT/1004057-002	Excess (\$)	0.00
Assign From		Assign Date	20/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	JTDKN36U705754196	Colour	MAROON
Odometer	377640	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	20/07/2018	Inspection Date	20/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	9 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 1011K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	BUMPER FRT (DISC 25%)	DEFORMED	482.00	361.50
10	BUMPER CLIPS @\$1.61(DISC 25%)	NECESSARY	16.10	12.07
1	BRACKET, FR BUMPER (DISC 25%)	NECESSARY	110.40	82.80
1	BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%)	CRACKED	311.10	233.32
1	GRILLE, RADIATOR (DISC 25%)	DEFORMED	310.60	232.95
1	EMBLEM FRONT (DISC 25%)	CUT	86.50	64.87
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	NAME PLATE (HYBRID) (DISC 25%)	NECESSARY	51.90	38.92
1	BUMPER REAR (DISC 25%)	DEFORMED	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.07
1	BUMPER LIP COVER RR/RH (DISC 25%)	DEFORMED	118.10	88.58
1	BUMPER LIP REAR (DISC 25%)	DEFORMED	228.90	171.67
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER LH (DISC 25%)	NECESSARY	139.60	104.70
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	NECESSARY	139.60	104.70
1	BUMPER SIDE RETAINER RR/LH (DISC 25%)	CUT	94.80	71.10
1	A/C CONDENSER (DISC 25%)	BENT	1,181.90	886.42
1	HEAD LAMP LH (DISC 10%)	CRACKED	945.20	850.68
1	HEAD LAMP RH (DISC 10%)	CRACKED	945.20	850.68
1	NUMBER PLATE (SN)	BENT	15.00	15.00
1	NUMBER PLATE FRAME (SN)	DEFORMED	12.00	12.00
1	SENSOR REVERSE (SN)	NOT WORKING	180.00	180.00
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	BUMPER FRT ABSORBER LOWER	NOT NECESSARY	127.70	-
1	BUMPER SUPPORT F/LH	NOT NECESSARY	76.40	-
1	BUMPER SUPPORT F/RH	NOT NECESSARY	76.40	-
1	BUMPER ENERGY ABSORBER FRT	NOT NECESSARY	78.80	-
1	BUMPER REINFORCEMENT FRT	NOT NECESSARY	498.40	-
1	ARM SUB-ASSY, FR BUMPER LH	NOT NECESSARY	250.40	-
1	ARM SUB-ASSY, FR BUMPER RH	NOT NECESSARY	250.40	-

Report Ref No. NS/INC18013474/T1tbe2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HOOD END PANEL SEAL	NOT NECESSARY	35.50	-
1	HOOD LOCK	NOT NECESSARY	128.90	-
1	FENDER LINER FRT / LH	NOT NECESSARY	171.70	-
1	FENDER LINER FRT / RH	NOT NECESSARY	171.70	-
1	BUMPER LIP COVER RR/LH	NOT NECESSARY	72.20	-
1	BUMPER SEAL, RR LH	NOT NECESSARY	88.90	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER SIDE RETAINER RR/RH	NOT NECESSARY	94.80	-
1	TAILGATE ASY	NOT NECESSARY	1,007.90	-
1	TAIL GATE DOOR GLASS MOULDING, LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH	NOT NECESSARY	29.40	-
1	MOULDING BACK WINDOW, LOWER NO.1	NOT NECESSARY	29.40	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	TAILGATE DOOR WEATHERSTRIP	NOT NECESSARY	353.40	-
1	TAILGATE LOCK, COVER	NOT NECESSARY	15.70	-
1	TAILGATE OUTSIDE GARNISH	NOT NECESSARY	504.90	-
1	STRIKER, BACK DOOR	NOT NECESSARY	48.90	-
1	EMBLEM REAR	NOT NECESSARY	60.30	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	NAME PLATE (PRIUS)	NOT NECESSARY	60.80	-
1	NAME PLATE (TOYOTA)	NOT NECESSARY	51.90	-
1	SPOILER REAR	NOT NECESSARY	953.70	-
1	SMRT LOGO	NOT NECESSARY	7.80	-
1	STICKER DECAL 6555 8888	NOT NECESSARY	21.60	-
1	END PANEL	NOT NECESSARY	602.10	-
1	END PANEL COVER, DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAIL LAMP BRACKET, LH	NOT NECESSARY	30.70	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	HOOD PANEL	TO REPAIR SEE LABOUR	748.10	-

Report Ref No. NS/INC18013474/T1tbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	HOOD HINGE LH	TO REPAIR SEE LABOUR	55.90	-
1	HOOD HINGE RH	TO REPAIR SEE LABOUR	55.90	-
1	SUPPORT SUB-ASSY	TO REPAIR SEE LABOUR	1,460.40	-
1	FENDER FRT / LH	TO REPAIR SEE LABOUR	723.40	-
1	FENDER FRT / RH	TO REPAIR SEE LABOUR	723.40	-
			16,752.00	5,031.18
	LABOUR			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF HOOD PANEL, HOOD HINGE LH, HOOD HINGE RH, SUPPORT SUB-ASSY, FENDER FRT / LH AND FENDER FRT / RH.		1,690.00	800.00
	SPRAY PAINT.		3,168.00	1,450.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	40.00
	TO APPLY RUST-PROOFING ON AFFECTED AREA.		200.00	30.00
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	240.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	30.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.		120.00	40.00
	TO REPLACE SUNDRY PARTS.		100.00	30.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
	TO TOP UP A/C GAS.		120.00	100.00
	TO REMOVE & REFIX FAN ENGINE & RADIATOR ASSY & INNER COOLER & AIR CON CONDENSER.		150.00	80.00
			-	-
			-	-
			6,168.00	2,600.00
GRAND TOTAL			22,920.00	7,631.18
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,100.00

Report Ref No. NS/INC18013474/T1tbe2

Report Ref No. NS/INC18013474/T1tbe2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.