

SMRT Accident Vehicle Repair Estimates

G17

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB1156Y
 Ref. No : TAX/07/18/2108
 Reg. Date : 19/12/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : SOW CHEE MONG
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 21/07/2018 07:16:00 PM
 Accident Reported Date / Time : 23/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097180
 Special Instruction to ARC, if any :
 SHC2542D (III)
 Prepared Date : 23/07/2018 05:21:58 PM



Sathya Sai

24/7/2018

2 days.

- Part by Part repair
- Question mark item photo
- Photo before paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU903577736

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

Total Labour Charges	:	845.00	0.00
Total Spray Painting Charges	:	1,674.00	0.00
Total Material Charges	:	3,858.80	3,858.80
Other Charges	:	1,193.76	0.00
TOTAL	:	7,571.56	0.00
Lum Sum Total	:	0.00	0.00
No. of Repair Days	:	5.00	0.00 2 days
Prepared / Adjusted By	:		
Arc / Surveyor Sign Off Date	:	24/07/2018 08:55:40 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 24/07/2018 08:55:30 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/24/2018 8:57:04 AM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH PORTION	845.00	0.00 400
Total Labour	845.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 X
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 X
TO RESPRAY RIM	180.00	0.00 180.00 X
Total Spray Painting & Panel Beating	1,674.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 40 40
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 50
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 60
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	593.76	0.00 445.32 (3 piece)
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 50
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,193.76	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
6700447210			PANEL SUB-ASSY, REAR DOOR, LH <i>R</i>	1	1,243.90	25.00	932.92	Replace	Replace	No
7586047900			MOULDING ASSY, BODY ROCKER PANEL, LH <i>X</i>	1	576.00	25.00	432.00	Replace	Replace	No
6160247160			PANEL SUB-ASSY, FENDER REAR LH <i>R</i>	1	824.80	25.00	618.60	Replace	Replace	No
4261147450			WHEEL, DISC <i>✓cut</i>	1	1,555.10	25.00	1,166.32	Replace	Replace	No
5215947913			COVER, RR BUMPER ASSY <i>R</i>	1	423.90	25.00	317.92	Replace	Replace	No
5256647900			FILLER, RR BUMPER, LH <i>X</i>	1	119.90	25.00	89.92	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH <i>?</i>	1	111.50	25.00	83.62	Replace	Replace	No
5259247040			SEAL, RR BUMPER, LH <i>?</i>	1	85.20	25.00	63.90	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 <i>?</i>	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 <i>?</i>	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 <i>?</i>	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH <i>?</i>	2	11.00	25.00	16.50	Replace	Replace	No
			PIXEL STICKER <i>NEL</i>	2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS								3,858.83	3,858.80	
TOTAL MATERIALS(Discounted)								3,858.80	3,858.80	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									