

10/2000
W/S: CAVE OWNER

Angie Gran

3, LCR 190 13483

A pass

Surveyor:

Adrian

DOI:

ASSIGNMENT

25/1/18

(week)

Date / Time:

24/1/18

Registered in Merimen:

24/1/18

Pre-sign / CCU / FTE

SLR 950X

Claim No.:

0799994782

Policy No.:

MA2DA3

Make / Model:

PIE

Place of Accident:

Insured Vehicle No.:

Left PL

Name of Insured:

Insured Tel No.:

HP:

D.O.A.:

23/1/18 (Mon)

Excess Sec II: S\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Heng Kian Siong

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

Driver Tel No.:

(V/L: YES / NO)

RD 6164L

SLR 950X

SLR 9108R

INSRS:

WSP:

Tel:

Liability:

RMKS:

INSRS:

WSP:

Tel:

Liability:

RMKS:

67

INSRS:

WSP:

Tel:

Liability:

RMKS:

Premium

TP

INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

25/1/18
CH1

SLR 9108R - X; SLR 950X - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

24/1/18 26/1/18
(28 years old)

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

Confirm by:

FINALIZATION

Date/Time:

Confirm with:

Repair Cost:

S\$

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

11/1/19

Confirm with: Nura

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

2PC 3CC - 0122

If NO or B 28, Ass. Lia:

OK

Repair Cost: w/16h

S\$

23362.77

Loss of Rental (LOR):

S\$

-

(- days)

Loss of Use (LOU):

S\$

1600.00

(S\$100 x 16 days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

7-45

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost:

S\$

-

Total:

S\$

24970.22

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Payee 1:

S\$

23370.22

Name 1:

Premium Automobiles Pte Ltd

Payee 2: (Strike if N.A.)

S\$

1600.00

Name 2:

Phee Saw Jay Lewis

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

Email

Call

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$ 320.00

ASS. NO. BY: Adrian King

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop n/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

13 1/2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SLC8108R.

Yr Regn:

2017, March

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Audi A6.

c.c 1738

Colour:

white.

A/C

Insured / Std / NI / NA

Sp. Reading

23677.

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WAU22246HN009761

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ Rim / STD A/Rim or

Tyre Size:

F: 225/55R17.

R: 225/55R17.

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU ☒ PTW / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

25/07/18.

Survey held at

Premium.

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP ALG.

PIP \$21834.36 (Red \$1107.64/344%).

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Report Format

Lump Sum / L.B.E. (\$)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Insp (\$)

☐

Weekend (\$)

Survey Fee:

Transportation:

1) \$ + RS. 20

2) Photo:

3) Other:

TOTAL

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khal@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0842/2018/PH
Date : 24-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SLR 950 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Phee Soo Jay Louis
Address : 33 Jalan Limau Bali
Singapore 468504
Telephone : HP +65 97968155
Type of Claim : Third Party Claims
Policy No. : 2100503552-01
Vehicle No : **SLL 8108 R**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Mar-17
Engine No : CYG 015125
Chassis No : WAUZZZ4G8HN009761
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-18
Place of Accident : PIE towards Changi before Thomson exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 8108 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00 ✓	
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00 ✓	
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00 ?	
4	To dismantle center console and renew both front seat belt and control unit for airbag.	S/N \$ 1,800.00 ✓	
5	To dismantle and renew rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel.	\$ 4,200.00	2500 hrs. 1000 exclude End Panel.
6	To respray rear bumper, rear lid, rhs rear fender and end paneling. To carry out joint sealer works and stone chip treatment.	\$ 3,200.00	1750.
7	To carry out diagnostic check	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		\$ 10,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	BUMPER COVER <i>Distorted</i>	\$	2,519.00 ✓	2015.20
2	FIXING PARTS FOR BUMPER <i>Not New</i>	\$	234.00 ✓	
3	FIXING PARTS FOR BUMPER <i>Not New</i>	\$	23.00 ✓	
4	SECURINMG STRIP <i>Not New</i>	\$	191.00 ✓	
5	SPOILER <i>Repld</i>	\$	416.00 ✓	322.80
6	CLOSING ELEMENT - LH/RH <i>Not New</i>	2 \$	138.00 ✓	
7	REBUMPER CARRIER <i>Bent</i>	\$	851.00 ✓	686.40
8	SEAL - LH/RH <i>Not New</i>	2 \$	24.00 ✓	18.56
9	GUIDE SECTION - LH/RH <i>Not New</i>	2 \$	56.00 ✓	
10	GUIDE SECTION - LH/RH <i>Not New</i>	2 \$	92.00 ✓	
11	CONNECTING PIECE <i>New</i>	2 \$	21.00 ✓	16.48
12	GUIDE PROFILE - LH/RH <i>Not New</i>	2 \$	114.00 ✓	
13	GUIDE SECTION - CENTRE <i>Repld</i>	\$	91.00 ✓	72.32
14	HOLDING STRIP - LH/RH <i>Repld</i>	2 \$	108.00 ✓	42.96
15	SENSOR <i>Repld</i>	2 \$	421.00 ✓	376.20
16	WIRING SET FOR BUMPER <i>Not New Snapped</i>	\$	603.00 ✓	482.40
17	TRIM FOR EXHAUST TAIL PIPE - RH <i>Not New</i>	\$	498.00 ✓	
18	REAR LID <i>Distorted</i>	\$	2,485.00 ✓	1988.00
19	BRACKET <i>New</i>	\$	30.00 ✓	22.28
20	ATTACHMENT PARTS FOR REAR LID <i>New</i>	\$	93.00 ✓	74.40
SUB - TOTAL SPARE PARTS CHARGES :		\$	9,008.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description		S/Nett	Damaged Parts & Prices	
				S/Nett	Remark
21	PUSH BUTTON FOR LID LOCK ACTUATOR	Net	\$	1,181.00	X X
22	GASKET FOR FLAP	Net at	\$	181.00	✓✓ 144.50
23	LID LOCK	Net	\$	170.00	X X
24	PACKING ADHESIVE	Net	\$	15.00	✓✓ 11.00
25	AUDI EMBLEM	Net	\$	108.00	✓✓ 86.00
26	A6' EMBLEM	Net	\$	83.00	✓✓ 66.16
27	TFSI' EMBLEM	Net	\$	83.00	✓✓ 66.16
28	DECORATIVE TRIM FOR LID CHROME	Net	\$	317.00	✓✓ 253.20
29	LED TAIL LIGHT - RH/LH	RH at	2 \$	2,188.00	1094. ✓ 875.20
30	TRIM FOR LED TAIL LIGHT - RH	at	2 \$	52.00	✓✓ 40.16
31	REAR CROSS PANEL	Revised.	\$	274.00	✓✓ 219.20
32	REINFORCEMENT FOR CROSS PANEL	Revised	\$	639.00	✓✓ 511.20
33	CONNECTING PLATE - RH LOWER	Revised.	\$	39.00	✓✓ 31.04
34	TRIM FOR REAR CROSS PANEL BLACK	Revised	\$	116.00	✓✓ 93.90
35	3 POINT AUTOMATIC SEAT BELT-LH	Adjusted	\$	1,215.00	✓✓ 972.00
36	3 POINT AUTOMATIC SEAT BELT-RH	Adjusted	\$	956.00	✓✓ 764.80
37	CONTROL UNIT FOR AIRBAG	Revised	\$	2,258.00	✓✓ 1806.40
38	ADJUSTMENT FITTING	Net	2 \$	311.00	✓✓ 248.80
39	ARCYLIC SEALANT	Net	S/N \$	180.00	✓✓ 144.00
40	CAVITY WAX	Net	S/N \$	140.00	✓✓ 112.00
SUB - TOTAL SPARE PARTS CHARGES :				\$ 10,506.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
41	STONE CHIP TREATMENT <i>2 new</i>	S/N	\$ 180.00 ?	
42	CAR PLATE <i>Best</i>	\$	25.00 ✓	
43	SUNDRIES <i>2 new</i>	\$	500.00 ?	87.44
TOTAL SPARE PARTS CHARGES		:	\$ 20,219.00	
TOTAL LABOUR CHARGES		:	\$ 10,512.00	
GRAND TOTAL		:	\$ 30,731.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

: Adrian King
: 26/07/18

:
: None Authorised 06 Days.
: Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Hsiao Tong

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0842/2018/PH 27-Jul-18 CHANG 1 of 1 SLL 8108 R Audi A6 SEDAN 1.8 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	REAR BUMPER GUIDE - RH UPPER	\$ 28.00	✓ 28
2	REAR BUMPER GUIDE PROFILE - RH INNER	\$ 57.00	✓ 114
3	REAR LID LOCK COVER	\$ 7.00	✓ 7
4	REAR LID HINGE - LH/RH	\$ 400.00	✓ 800
5	REAR LID STOP BUFFER	\$ 9.00	✓ 18
6	LED TAIL LIGHT - RH	\$ 1,094.00	✓ 1,094
7	BATTERY CETRAL PROTECTION	\$ 516.00	✓ 516
GRAND TOTAL :		\$ 2,111.00	

Adrian Ling
27/7/18

For Premium Automobiles Pte Ltd



Authorised Signature

32822

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	BUMPER COVER <i>Distorted</i>	\$	2,519.00	✓
2	FIXING PARTS FOR BUMPER ?	\$	234.00	?
3	FIXING PARTS FOR BUMPER ?	\$	23.00	?
4	SECURINMG STRIP ?	\$	191.00	?
5	SPOILER <i>Del</i>	\$	416.00	✓
6	CLOSING ELEMENT - LH/RH ?	2 \$	138.00	?
⑦	REBUMPER CARRIER ? <i>ht</i>	\$	851.00	?
8	SEAL - LH/RH <i>new</i>	2 \$	24.00	x
9	GUIDE SECTION - LH/RH <i>new</i>	2 \$	56.00	x
10	GUIDE SECTION - LH/RH <i>new</i>	2 \$	92.00	x
11	CONNECTING PIECE <i>new</i>	2 \$	21.00	✓
12	GUIDE PROFILE - LH/RH <i>new</i>	2 \$	114.00	x
⑬	GUIDE SECTION - CENTRE ? <i>del</i>	\$	91.00	?
14	HOLDING STRIP - LH/RH ?	2 \$	108.00	?
15	SENSOR ?	2 \$	421.00	?
16	WIRING SET FOR BUMPER <i>new</i>	\$	603.00	x
17	TRIM FOR EXHAUST TAIL PIPE - RH ?	\$	498.00	?
18	REAR LID <i>Del</i>	\$	2,485.00	✓
19	BRACKET <i>new</i>	\$	30.00	✓
20	ATTACHMENT PARTS FOR REAR LID <i>new</i>	\$	93.00	✓
SUB - TOTAL SPARE PARTS CHARGES :		\$	9,008.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Signature 22/7/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	PUSH BUTTON FOR LID LOCK ACTUATOR <i>Not in</i>	\$	1,181.00	X
22	GASKET FOR FLAP <i>not at</i>	\$	181.00	✓
23	LID LOCK <i>Not in</i>	\$	170.00	X
24	PACKING ADHESIVE <i>Not in</i>	\$	15.00	✓
25	AUDI EMBLEM <i>Not in</i>	\$	108.00	✓
26	A6' EMBLEM <i>Not in</i>	\$	83.00	✓
27	TFSTI' EMBLEM <i>Not in</i>	\$	83.00	✓
28	DECORATIVE TRIM FOR LID CHROME <i>Not in</i>	\$	317.00	-
29	LED TAIL LIGHT - RH/LH <i>RH at</i>	2 \$	2,188.00	1094.
30	TRIM FOR LED TAIL LIGHT - RH <i>at</i>	2 \$	52.00	-
31	REAR CROSS PANEL <i>?</i>	\$	274.00	?
32	REINFORCEMENT FOR CROSS PANEL <i>?</i>	\$	639.00	?
33	CONNECTING PLATE - RH LOWER <i>?</i>	\$	39.00	?
34	TRIM FOR REAR CROSS PANEL BLACK <i>Del</i>	\$	116.00	✓
35	3 POINT AUTOMATIC SEAT BELT-LH <i>Abolished</i>	\$	1,215.00	✓
36	3 POINT AUTOMATIC SEAT BELT-RH <i>?</i>	\$	956.00	?
37	CONTROL UNIT FOR AIRBAG <i>?</i>	\$	2,258.00	?
38	ADJUSTMENT FITTING <i>Not in</i>	2 \$	311.00	X
39	ARCYLIC SEALANT <i>?</i>	S/N \$	180.00	?
40	CAVITY WAX <i>?</i>	S/N \$	140.00	?
SUB - TOTAL SPARE PARTS CHARGES :			\$ 10,506.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
41	STONE CHIP TREATMENT ?	S/M \$	180.00 ?	
42	CAR PLATE <i>Set</i>	\$	25.00 ✓	
43	SUNDRIES ?	\$	500.00 ?	
TOTAL SPARE PARTS CHARGES		:	\$ 20,219.00	
TOTAL LABOUR CHARGES		:	\$ 10,512.00	
GRAND TOTAL		:	\$ 30,731.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 26 July 2018 1:04 PM
To: 'Claims'
Cc: 'Mastura'; Admin A; Joy Irene (LKKAuto); Vivian Lau (LKKAuto)
Subject: RE: ACCIDENT INVOLVING SLL 8108 R AND YOUR INSURED SLR950X DATED ON 23/07/2018 (VEHICLE IN) *** LKK REF: CC3/LCR18013483/pa3

Without Prejudice

Hi Sirs/ Mdm,

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Please note that all finalisation subject insurer's approval.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>
Sent: Thursday, 26 July 2018 11:41 AM
To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Cc: 'Mastura' <mastura@premiumauto.com.sg>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>; claims@premiumauto.com.sg

Subject: RE: ACCIDENT INVOLVING SLL 8108 R AND YOUR INSURED SLR950X DATED ON 23/07/2018 (VEHICLE IN)
***** LKK REF: CC3/LCR18013483/pa3**

Dear Hsiao Tong,

Kindly assist forward Adrian marked estimate and update us liability clearance status.

Vehicle is at our workshop since day 1 and owner demanding claiming losses from day 1.

Kindly assist expedite the process.

Best Regards,
Tony Foong
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)
55 Ubi Road 1 Road Singapore 408699
p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183
e. claims@premiumauto.com.sg w. www.audi.com.sg
Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]
Sent: Wednesday, 25 July, 2018 9:51 AM
To: Claims <claims@premiumauto.com.sg>
Cc: 'Mastura' <mastura@premiumauto.com.sg>; Admin A <admin-a@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; Vivian Lau (LKKAuto) <vivianlau@lkkauto.com>
Subject: RE: ACCIDENT INVOLVING SLL 8108 R AND YOUR INSURED SLR950X DATED ON 23/07/2018 (VEHICLE IN)
***** LKK REF: CC3/LCR18013483/pa3**

Dear Sir / Madam,

We refer to the below email.

Please be informed that we are currently **pending for our principal to release OI GIA report**.

Kindly note that for liability, claim negotiation and settlement, please contact Hsiao Tong at 6742 3197.

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims <claims@premiumauto.com.sg>

Sent: Tuesday, 24 July, 2018 8:13 PM

To: 'Claims' <claims@premiumauto.com.sg>; Admin A <admin-a@lkkauto.com>

Cc: 'Mastura' <mastura@premiumauto.com.sg>

Subject: RE: ACCIDENT INVOLVING SLL 8108 R AND YOUR INSURED SLR950X DATED ON 23/07/2018 (VEHICLE IN)

Good evening all,

Here is the attached estimate for your kind reference. Vehicle is in our premises. Kindly arrange for survey.

Thank you.

Best Regards,

Phua

Claims Advisor

Premium Automobiles Pte Ltd (Reg No. 199902759S)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sg/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Tuesday, 24 July 2018 9:43 AM

To: admin-a@lkkauto.com; claims@premiumauto.com.sg

Cc: 'Mastura'

Subject: ACCIDENT INVOLVING SLL 8108 R AND YOUR INSURED SLR950X DATED ON 23/07/2018 (VEHICLE IN)

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report for direct settlement for your reference.

We will forward you the estimate once is available.

TP insured with AIG.

Do take note, video were uploaded in Merimen. Vehicle is in our premises.

Thank you.

Best Regards,
Mastura
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. mastura@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.

Hsiao Tong (LKKAuto)

From: Boo seng yak <boojohnny@gmail.com>
Sent: Saturday, 22 September 2018 5:21 PM
To: Adrian Ling (LKKAuto); CS A Team; Admin A; Carrine Leong;
jiayee.yap@premiumauto.com.sg; Chang Chee Sing
Subject: FINAL REVISION - SLL8108R - TP AIG - SURVEYED 25 JUL 18
Attachments: PA08422018 - SLL 8108 R- Audi A6 Sedan 1.8 TFSI - Rear TP (AIG) + SUPP.xls

Hi Adrian and all,

Revised estimate is attached.

Please confirm repair cost of \$21,834.36 @ 13 days of repairs exclude 1 PH and 2 Sundays.

Taufik re-inspected vehicle on 27 Jul & 31 Jul 18.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0842/2018/PH
Date : 24-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SLR 950 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

You recommended 6 days

We took 13 days exclude 1 PH 2 Sundays

Checked items replaced - jb - 22 Sep 18

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Phee Soo Jay Louis
Address : 33 Jalan Limau Bali
Singapore 468504
Telephone : HP +65 97968155
Type of Claim : Third Party Claims
Policy No. : 2100503552-01
Vehicle No : **SLL 8108 R**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Mar-17
Engine No : CYG 015125
Chassis No : WAUZZZ4G8HN009761
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-18
Place of Accident : PIE towards Changi before Thomson exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6365 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 8108 R

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$	360.00	\$ 360.00
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$	280.00	\$ 280.00
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$	480.00	\$ 480.00
4	To dismantle center console and renew both front seat belt and control unit for airbag.	S/N \$	1,800.00	\$ 1,800.00
5	To dismantle and renew rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel. <i>(Added 3 days \$1500/- for checked items)</i>	\$	4,200.00	\$ 2,500.00
6	To respray rear bumper, rear lid, rhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$	3,200.00	\$ 1,650.00
7	To carry out diagnostic check	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 10,512.00	\$ 7,262.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	BUMPER COVER	\$ 2,519.00	\$ 2,015.20
2	FIXING PARTS FOR BUMPER	\$ 234.00	
3	FIXING PARTS FOR BUMPER	\$ 23.00	
4	SECURINMG STRIP	\$ 191.00	
5	SPOILER	\$ 416.00	\$ 332.80
6	CLOSING ELEMENT - LH/RH	2 \$ 138.00	
7	REBUMPER CARRIER	\$ 851.00	\$ 680.40
8	SEAL - LH/RH	2 \$ 24.00	\$ 18.56
9	GUIDE SECTION - LH/RH	2 \$ 56.00	
10	GUIDE SECTION - LH/RH	2 \$ 92.00	
11	CONNECTING PIECE	2 \$ 21.00	\$ 16.48
12	GUIDE PROFILE - LH/RH	2 \$ 114.00	
13	GUIDE SECTION - CENTRE	\$ 91.00	\$ 72.32
14	HOLDING STRIP - LH/RH	2 \$ 108.00	\$ 42.96
15	SENSOR	2 \$ 421.00	\$ 336.80
16	WIRING SET FOR BUMPER	\$ 603.00	\$ 482.00
17	TRIM FOR EXHAUST TAIL PIPE - RH	\$ 498.00	
18	REAR LID	\$ 2,485.00	\$ 1,988.00
19	BRACKET	\$ 30.00	\$ 23.28
20	ATTACHMENT PARTS FOR REAR LID	\$ 93.00	\$ 74.40
SUB - TOTAL SPARE PARTS CHARGES:		\$ 9,008.00	\$ 6,083.20

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nettt.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
	c/f		\$ 6,083.20
21	PUSH BUTTON FOR LID LOCK ACTUATOR	\$ 1,181.00	
22	GASKET FOR FLAP	\$ 181.00	\$ 144.80
23	LID LOCK	\$ 170.00	
24	PACKING ADHESIVE	\$ 15.00	\$ 11.60
25	AUDI EMBLEM	\$ 108.00	\$ 86.00
26	A6' EMBLEM	\$ 83.00	\$ 66.16
27	TFSI' EMBLEM	\$ 83.00	\$ 66.16
28	DECORATIVE TRIM FOR LID CHROME	\$ 317.00	\$ 253.20
29	LED TAIL LIGHT - RH/LH	2 \$ 2,188.00	\$ 875.20
30	TRIM FOR LED TAIL LIGHT - RH	2 \$ 52.00	\$ 40.16
31	REAR CROSS PANEL	\$ 274.00	\$ 219.20
32	REINFORCEMENT FOR CROSS PANEL	\$ 639.00	\$ 511.20
33	CONNECTING PLATE - RH LOWER	\$ 39.00	\$ 31.04
34	TRIM FOR REAR CROSS PANEL BLACK	\$ 116.00	\$ 92.80
35	3 POINT AUTOMATIC SEAT BELT-LH	\$ 1,215.00	\$ 972.00
36	3 POINT AUTOMATIC SEAT BELT-RH	\$ 956.00	\$ 764.80
37	CONTROL UNIT FOR AIRBAG	\$ 2,258.00	\$ 1,806.40
38	ADJUSTMENT FITTING	2 \$ 311.00	\$ 248.80
39	ARCYLIC SEALANT	S/N \$ 180.00	\$ 180.00
40	CAVITY WAX	S/N \$ 140.00	\$ 140.00
SUB - TOTAL SPARE PARTS CHARGES :		\$ 10,506.00	\$ 12,592.72

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
			\$12,592.72
41	STONE CHIP TREATMENT	S/N \$ 180.00	\$ 180.00
42	CAR PLATE	\$ 25.00	\$ 25.00
43	<i>Added parts - see attached</i>	\$ 2,111.00	\$ 1,687.20
45	SUNDRIES	\$ 500.00	\$ 87.44
	TOTAL SPARE PARTS CHARGES	\$ 22,330.00	\$14,572.36
	TOTAL LABOUR CHARGES	\$ 10,512.00	\$ 7,262.00
	GRAND TOTAL	\$ 32,842.00	\$ 21,834.36

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0842/2018/PH 27-Jul-18 CHANG 1 of 1 SLL 8108 R Audi A8 SEDAN 1.8 TFSI
Quantity	Description	Unit Price	Amount
Parts			
1	REAR BUMPER GUIDE - RH UPPER <i>3 and</i>	\$ 28.00	\$ 22.00
2	REAR BUMPER GUIDE PROFILE - RH INNER	\$ 57.00	\$ 45.28
3	REAR LID LOCK COVER <i>lt</i>	\$ 7.00	\$ 4.88
4	REAR LID HINGE - LH/RH <i>both</i> 2	\$ 400.00	\$ 320.00
5	REAR LID STOP BUFFER <i>per</i> 4	\$ 9.00	\$ 7.04
6	LED TAIL LIGHT - RH <i>lt</i>	\$ 1,094.00	\$ 875.20
7	BATTERY CETRAL PROTECTION <i>Activated</i>	\$ 516.00	\$ 412.80
GRAND :		\$ 2,111.00	\$ 1,687.20

For Premium Automobiles Pte Ltd

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0842/2018/PH 27-Jul-18 CHANG 1 of 1 SLL 8108 R Audi A5 SEDAN 1.8 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR BUMPER GUIDE - RH UPPER	\$ 28.00	✓
2	REAR BUMPER GUIDE PROFILE - RH INNER	\$ 57.00	✓
3	REAR LID LOCK COVER	\$ 7.00	✓
4	REAR LID HINGE - LH/RH 2	\$ 400.00	✓
5	REAR LID STOP BUFFER 4	\$ 9.00	✓
6	LED TAIL LIGHT - RH	\$ 1,094.00	✓
⑦	BATTERY CETRAL PROTECTION	\$ 516.00	✓
GRAND TOTAL :		\$ 2,111.00	

duh
22/7/18

For Premium Automobiles Pte Ltd



[Signature]

Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	BUMPER COVER <i>Distorted</i>	\$	2,519.00	✓
2	FIXING PARTS FOR BUMPER ?	\$	234.00	?
3	FIXING PARTS FOR BUMPER ?	\$	23.00	?
4	SECURINMG STRIP ?	\$	191.00	?
5	SPOILER <i>Del</i>	\$	416.00	✓
6	CLOSING ELEMENT - LH/RH ?	2 \$	138.00	?
⑦	REBUMPER CARRIER ? <i>bt</i>	\$	851.00	?
8	SEAL - LH/RH <i>new</i>	2 \$	24.00	x
9	GUIDE SECTION - LH/RH <i>new</i>	2 \$	56.00	f
10	GUIDE SECTION - LH/RH <i>new</i>	2 \$	92.00	x,
11	CONNECTING PIECE <i>new</i>	2 \$	21.00	✓
12	GUIDE PROFILE - LH/RH <i>new</i>	2 \$	114.00	x
⑬	GUIDE SECTION - CENTRE ? <i>del</i>	\$	91.00	?
14	HOLDING STRIP - LH/RH ? <i>new</i>	2 \$	108.00	?
15	SENSOR ? <i>new</i>	2 \$	421.00	?
16	WIRING SET FOR BUMPER <i>new</i>	\$	603.00	x
17	TRIM FOR EXHAUST TAIL PIPE - RH ?	\$	498.00	?
18	REAR LID <i>Distorted</i>	\$	2,485.00	✓
19	BRACKET <i>new</i>	\$	30.00	✓
20	ATTACHMENT PARTS FOR REAR LID <i>new</i>	\$	93.00	✓
SUB - TOTAL SPARE PARTS CHARGES :		\$	9,008.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Signature 22/7/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	PUSH BUTTON FOR LID LOCK ACTUATOR <i>Net</i>	\$	1,181.00	*
22	GASKET FOR FLAP <i>new at</i>	\$	181.00	✓
23	LID LOCK <i>Net</i>	\$	170.00	X
24	PACKING ADHESIVE <i>new</i>	\$	15.00	✓
25	AUDI EMBLEM	\$	108.00	✓
26	A6' EMBLEM	\$	83.00	✓
27	TFSTI' EMBLEM	\$	83.00	✓
28	DECORATIVE TRIM FOR LID CHROME <i>Net</i>	\$	317.00	-
29	LED TAIL LIGHT - RH/LH <i>RH at</i>	2 \$	2,188.00	1094.
30	TRIM FOR LED TAIL LIGHT - RH <i>at</i>	2 \$	52.00	-
31	REAR CROSS PANEL <i>? hit</i>	\$	274.00	?
32	REINFORCEMENT FOR CROSS PANEL <i>hit</i>	\$	639.00	?
33	CONNECTING PLATE - RH LOWER <i>?</i>	\$	39.00	?
34	TRIM FOR REAR CROSS PANEL BLACK <i>Re-lid</i>	\$	116.00	✓
35	3 POINT AUTOMATIC SEAT BELT-LH <i>Adjusted</i>	\$	1,215.00	✓
36	3 POINT AUTOMATIC SEAT BELT-RH <i>?</i>	\$	956.00	2
37	CONTROL UNIT FOR AIRBAG <i>?</i>	\$	2,258.00	?
38	ADJUSTMENT FITTING <i>Net</i>	2 \$	311.00	*
39	ARCYLIC SEALANT <i>?</i>	S/N \$	180.00	?
40	CAVITY WAX <i>?</i>	S/N \$	140.00	?
SUB - TOTAL SPARE PARTS CHARGES :			\$ 10,506.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: CC3/LCR18013483/pa3

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/IP/0842/2018/MAS

28 Jan 2019

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

total pages

Dear Sir,

RE: INSURANCE CLAIM FOR SLL 8108 R, Audi A6 1.8 TFSI S-Tro

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

With reference to the above-mentioned vehicle, no. **SLL 8108 R**, claimant, **Mr. Phee Soo Jay Louis**, please find the related document as per attached.

1. A copy of the Original invoice no. 85013334 – S\$23,362.77
2. A copy of Authorization to Act duly signed by client
3. A copy of the Release Voucher attached
4. A copy of Breakdown of Payment attached
5. Loss of Use – S\$1,600.00 (S\$100.00 x 13 working days + 1 PH + 2 Sunday)
6. LTA Search Fee – S\$7.45

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 11183

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SLL 8108 R

BREAKDOWN OF PAYMENT

Vehicle No: SLL8108R

Accident on 23/7/2018 at PIE towards Changi before Thomson exit

Involving vehicle/s SLR950X

1) Repair cost \$ 23,362.77 Payable to: Premium Automobiles Pte Ltd

2) GTA/LTA search fee \$ 7.45 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or ~~Rental Car~~ \$ 1,600.00 Payable to: Phee Soo Jay Louis

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : PHEE SOO JAY LOUIS
Period of Insurance : 10 Mar 2018 To 09 Mar 2019
Engine No. : CYG015125
Chassis No. : WAUZZZ4G8HN009761

Vehicle No. : SLL8108R
Policy No. : 2100503552-01
Endorsement No. :
Issued Date : 22 Jan 2018

ABOUT THE COVER

Make/Model : AUDI A6 1.8 TFSI ULTRA
Engine Capacity/Tonnage : 1,798.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2017
Insuring with COE/PAF : Yes

Person or Classes of Persons Entitled to Drive*

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
The Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" (IDEX) if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

PHEE SOO JAY LOUIS - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408688 63982323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

(We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189) Part (I) of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).)

0504125268

PREMIUM LEASING -YCL

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCASA

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s)
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centre or authorised insurers within 24 hours or the next working day of the accident

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centre or authorised insurers within 24 hours or the next working day of the accident

What should I do in the event of an accident?

- Keep calm and move your car to a safe place
- Do not admit or discuss fault or blame with the other party(ies)
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centre or authorised insurers within 24 hours or the next working day of the accident
- Submit Witness Statements/Confessions from third parties to AIG immediately

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Monday, 4 February 2019 8:34 AM
To: 'Gan, Angiegeokling'
Subject: <Seek Mandate> AIG Ref: 6149076955SG **LKK Ref: CC3/LCR18013483/Apa3
[ACCIDENT INVOLVING SLR 950X(OI) / SLL 8108R(TP)/ OTHERS ON 23/07/2018]

AIG Ref: **6149076955SG**
LKK Ref: CC3/LCR18013483/Apa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLR 950X(OI) / SLL 8108R(TP)/ OTHERS ON 23/07/2018

We refer to the above matter.

The said chain collision involved 3 vehicles whereby our insured was the 2nd vehicle.
In accordance to the MCF guideline for chain collision, we have to settle the front vehicle's claim at 100%.

We seek your approval to offer to Third Party repairer, "**Premium Automobiles Pte Ltd**" is as follows: -

	Claimed Amount	Revised Amount
1. Cost of Repair (w/GST)	\$ 34,687.47	\$ 23,362.77
2. Loss of Use (16days x \$100.00)	\$ 1,600.00	\$ 1,600.00 (16days x \$100.00)
3. LTA/ GIA Search Fee	\$ 7.45	\$ 7.45
Total	\$ 36,294.92	\$ 24,970.22

**13days recommendation for repair + 2Sunday + 1PH = 16days.

For your approval in Merimen please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Print Received Message

This mail is associated with :

***SLL8108R (6149076955SG)**
[SLR950X]
TP
PHEE SOO JAY LOUIS
Jul 23 2018 5:00PM
[LCRF Pte Ltd]
Premium Automobiles Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 04/02/2019 11:02 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$24970.22) - SLL8108R - Claim Handler: Gan, Angie-GL

Approved:24970.22.



Name of Policyholder : PHEE SOO JAY LOUIS
Period of Insurance : 10 Mar 2018 To 09 Mar 2019
Engine No. : CYG015125
Chassis No. : WAUZZZ4G8HN009761

Vehicle No. : SLL8108R
Policy No. : 2100503552-01
Endorsement No. :
Issued Date : 22 Jan 2018

Make/Model : AUDI A6 1.8 TFSI ULTRA

Engine Capacity/Tonnage : 1,798.00 CC

Sum Insured : Market Value

First Year of Registration : 2017

Driver Restriction : NA

Off Peak Car : No

Insuring with COE/PARE : Yes

Person or Classes of Persons Entitled to Drive*

a) The Polystyrene

b) Any other person who is driving on the Policyholder's order or with his/her permission

The Policy will indemnify the Policyholder or any authorized driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" (IDF) if You are or Your Authorized Driver (named or unnamed) has less than 2 years' driving experience.

Age Condition : 40 years old and above

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business. This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 6 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1967 (Malaysia); are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen: \$100

Named Driver and Excess (where applicable)

PHEE 500 JAY LOUIS - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center, Add: 55 Ubi Road 1 Singapore 408669 63962323

For other Approved Reporting Centres/AIG Authorised Repairs, please contact our 24-hour accident emergency hotline at +65 8338 8200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download 'AIG SG' from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504 1253F#

PREMIUM LEASING VOL.

281 ALEXANDRA ROAD AUTO CUSTOMER SERVICE CENTRE

SINGAPORE 1903A

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Manila

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

徐世昌

24-HOUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Immediate assistance after an accident
- Emergency breakdown service
- Towing service (accident or non-accident related)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s).
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run case:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and vehicle(s), if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.

What should I do in the event of an accident?

- Keep calm and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours or the next working day of the accident.
- Submit Writ/Summons/Correspondences from third party(ies) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number **(65) 6419-3000** for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within **5** working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the **original** insurance policy and schedule issued by AIG, a copy of the Accident Report from **Audi Customer Service Centre** must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.).

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is **IMPORTANT** and **MUST** be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

Hsiao Tong (LKKAuto)

From: Hsiao Tong (LKKAuto)
Sent: Thursday, 26 July 2018 2:31 PM
To: Eileen, May Hwee Yap
Subject: ACCIDENT INVOLVING SLR 950X(AIG) /SLL 8108R/ OTHERS ON 23/07/2018

Your Ref: **SLR 950X**
Our Ref: CC3/LCR18013483/pa3

Dear Sirs/Madam,

ACCIDENT INVOLVING SLR 950X(AIG) /SLL 8108R/ OTHERS ON 23/07/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

We have received a claim from SLL 8108R against your insurance policy.

Pursuant to the above said accident wherein you and/or your authorized driver had amongst other information given us your version of how the accident had occurred, we as the appointed agent of your insurers shall proceed to negotiate for an amicable settlement with third party claimant.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please call us if you have further queries.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, Phee Soo Jay Louis (the third party claimant) of 33 Jalan Limau Ball
Singapore 468504 (address), owner of SLL8108R (vehicle no.)
hereby authorize Premium Automobiles Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLL8108R that was damaged pursuant to the accident which occurred on 23/7/2018
(date) along PIE towards Changi before Thomson exit (location) involving vehicle no/s
SLR950X ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 11 (day) of AUG (month) 2018 (year)



Signed by "the third party claimant"
(with chop if applicable)



Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Premium Automobiles Pte Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$23362.77 (Repair Cost), S\$600.00 (Loss of rental/use), S\$7.45 (Disbursement), for vehicle no. SLL8108R that was damaged pursuant to the accident which occurred on 23/7/2018 (date) along PIE towards Changi before Thomson exit (location) involving vehicle no/s SLR950X. This is pursuant to the inspection conducted on 25/7/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Phee Soo Jay Louis ("the third party claimant") of vehicle no. SLL8108R make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLL8108R (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11 (day) of Feb (month) 2019 (year)



Lup.

Signed by appointed surveyor



Signed by "the workshop" (with chop)



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 119938
Main Telephone: 6346 2222
Main Telefax: 6371 3133
Page 1 10:05

Alexandra Service Centre
281 Alexandra Road
Singapore 119938
Telephone: 6346 2222
Telefax: 6475 1025

Ubi Service Centre
55 Ubi Road 1
Singapore 408724
Telephone: 6386 1122
Telefax: 6386 1122

Customer Service
Service Appointment:
6346 2222
6328 1233
Email: customer.sing@premiumauto.com.sg

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013334 Date : 02/01/2019 Order : SLL8108R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLL8108R (V 31280) Regn Date: 10/03/2017 Mileage: 28905 WIP No.: 18554
Model: A6 1.8 TFSI S tronic 40066 (N Chassis: WAUZZZ4G8HNN09761 Engine: CYB 015125 Dept: U
USB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	SUBLET	M: TO SUPPLY VEHICLE NUMBER PLATE	25.00	1.00	25.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR,CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	350.00	1.00	350.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT	280.00	1.00	280.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO COMPONENTS.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE CENTRE CONSOLE AND RENEW BOTH FRONT SEAT BELT AND CONTROL UNIT FOR AIRBAG	1800.00	1.00	1,800.00
S	BODYWORK	M: TO DISMANTLE CENTRE CONSOLE AND RENEW BOTH FRONT SEAT BELT AND CONTROL UNIT FOR AIRBAG	2500.00	1.00	2,500.00
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159088
Main Telephone: 6836 2223
Main Telefax: 6871 3733
Page 2 10:05

Alexandra Service Centre
281 Alexandra Road
Singapore 159088
Telephone: 6886 2223
Telefax: 6871 1033

Ubi Service Centre
55 Ubi Road 1
Singapore 408623
Telephone: 6385 4555
Telefax: 6841 1122

Customer Service
Service Appointment
Hour Breakdown Service
Email: customer.care@premiumautos.com.sg
6386 2323
9828 1233

INS TAX INVOICE

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013334 Date : 02/01/2019 Order : SLL8108R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLL8108R (V 31280) Regn Date: 10/03/2017 Mileage: 28905 WIP No.: 18554
Model: A6 1.8 TFSI S tronic 460866 (N Chassis: WAUZZZ468H0009761 Engine: CYG 015125 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID, CUT OUT AND REMELD REAR OUTER, INNER AND LOWER REAR CROSS PANEL M:	1650.00	1.00	1,650.00
S	BODYWORK	TO RESPRAY REAR BUMPER, REAR LID AND END PANELLING, TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	500.00	1.00	500.00
X	A468857705F V04	TO SUPPLY ACRYLIC SEALANT, CAVITY WAX AND STONE CHIP TREATMENT			
X	A468857706M V04	SEAT BELT (SK) (A) Less 820%	1.00	1215.00	972.00
X	A440959655H	SEAT BELT (SK) (A) Less 820%	1.00	956.00	764.80
X	A465971085AG	MODULE (SK) (A) Less 820%	1.00	2258.00	1,806.40
X	A465945096E	HARNESS Less 820%	1.00	602.50	482.00
X	A465945096E	TAIL LIGHT Less 820%	1.00	1094.00	875.20
X	A465945094E	TAIL LIGHT Less 820%	1.00	1094.00	875.20
Sub-Total					
7% GST					
Grand Total					



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6386 2223
Main Telefax: 6471 2732
Page 3 10:05

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6386 2223
Telefax: 6475 1033

Ubi Service Centre
95 Ubi Road 1
Singapore 408722
Telephone: 6750 3333
Telefax: 6751 1122

Customer Service
Service Appointment
24 Hour Breakdown Service
Email: customer.care@premiumaudi.com.sg
6386 2223
6386 1233

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013334 Date : 02/01/2019 Order : SLL8108R Term : 30	Accounts: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	---

Regn No.: SLL8108R (V 31280) Regn Date: 10/03/2017 Mileage: 28905 WIP No.: 18554
Model: A6 1.8 TFSI S tronic 4G066 IN Chassis: WAUZZZ4G8HNN09761 Engine: CY6 015125 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A465827023C	LID	Less 020%	1.00	2485.00	1,988.00
X	A465827705D	WTHRSTRIP	Less 020%	1.00	181.00	144.80
X	A468007521T 989	SPOILER	Less 020%	1.00	416.00	332.80
X	A465863471C 4PK	TRIM PANEL (SK) (A)	Less 020%	1.00	116.00	92.80
X	A465813331	REINFORCEM	Less 020%	1.00	639.00	511.20
X	A465813307	REAR APRON	Less 020%	1.00	274.00	219.20
X	A465807067X GRU	COVER	Less 020%	1.00	2519.00	2,015.20
X	A000979940	CONNECTOR (WHITE)	Less 020%	2.00	9.00	14.40
X	A000979940	CONNECTOR (WHITE)	Less 020%	2.00	9.00	14.40
X	A465807309	BRACKET	Less 020%	1.00	850.50	680.40
X	A4F0853741 212	INSCRIPTION 'A6'	Less 020%	1.00	62.70	66.16
X	A1T0919133C 704	WASHER	Less 020%	4.00	1.10	3.52
X	A465807890A	GUIDE	Less 020%	1.00	27.50	22.00
X	A468007330	STRAP	Less 020%	1.00	53.70	42.96
X	A8X0853737A 212	INSCRIPTION 'TFSI'	Less 020%	1.00	62.70	66.16
X	A465853742 212	AUDI SIGN	Less 020%	1.00	107.50	86.00
X	A465807975A	CONN PIECE (SK) (A)	Less 020%	2.00	10.30	16.48
X	A465813394	PLATE (SK) (V)	Less 020%	1.00	38.80	31.04
Sub-Total						
7% GST						
Grand Total						



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159908
Main Telephone: 6836 2223
Main Telefax: 6471 3733
Page 4 10:05

Alexandra Service Centre
281 Alexandra Road
Singapore 159908
Telephone: 6888 2223
Telefax: 6475 1023

UBi Service Centre
55 Ubi Road 1
Singapore 408683
Telephone: 6388 2888
Telefax: 6341 1877

Customer Service
Service Appointment
Hour Breakdown Service
Email: customerservice@premiumaudisg.com.sg
6386 2223
6828 1233

INS TAX INVOICE

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013334 Date : 02/01/2019 Order : SLL8108R Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLL8108R (V 31280) Regn Date: 10/03/2017 Mileage: 28905 WIP No.: 18554

Model: A6 1.8 TFSI S tronic 4G0N66 (N Chassis: WAUZZZ468H009761 Engine: CYB 015125 Dept: U

VS8 No.:

You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A4H0827520	COVER	Less 020%	1.00	6.10	4.88
X	A4G5827301B	HINGE (SK) (V)	Less 020%	1.00	200.00	160.00
X	A4G5827302B	HINGE (SK) (V)	Less 020%	1.00	200.00	160.00
X	A8D0853419F	PACKING	Less 020%	1.00	14.50	11.60
X	A4G5807458A	GUIDE (N/S-SK) (A)	Less 020%	1.00	90.40	72.32
X	A4G0827310	CLIP	Less 020%	2.00	2.10	3.36
X	A8R0827199	BACKET (SK) (A)	Less 020%	1.00	29.10	23.28
X	A4H0827589B	BUMPER (SK) (A)	Less 020%	4.00	2.20	7.04
X	A8T8857833	ADJUSTMECH (SK) (A)	Less 020%	2.00	155.50	248.80
X	A4H0827310	CLIP	Less 020%	2.00	2.10	3.36
X	A4G0807932	FASTENING	Less 020%	4.00	1.50	4.80
X	A4G0807669	GASKET	Less 020%	1.00	11.60	9.28
X	A4G0807670	GASKET	Less 020%	1.00	11.60	9.28
X	A4G5807394D	PIECE	Less 020%	1.00	56.60	45.28
X	A4G5945256A	TRIM	Less 020%	1.00	25.10	20.08
X	A4G5945254	TRIM	Less 020%	1.00	25.10	20.08
X	A180919275C GRU	SENSOR	Less 020%	2.00	210.50	336.80
X	A4H0973704	HOUSING	Less 020%	1.00	7.80	6.24

Sub-Total

7% GST

Grand Total



Premium Automobiles Pte Ltd

Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone: 6334 2223
Main Telefax: 6471 2723
Page 5 10:05

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Telephone: 6334 2223
Telefax: 6471 2723

UBI Service Centre
55 Ubi Road 1
Singapore 408853
Telephone: 6781 1122
Telefax: 6781 1122

Customer Service
Service Appointment
Labour Breakdown Service
Email: customer.care@premiumauto.com.sg
6366 2525
6628 1228

INS TAX INVOICE
Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice: 85013334 Date : 02/01/2019 Order : SLL8108R Term : 30	Account: 00006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No.: SLL8108R (V 31280) Regn Date: 10/03/2017 Mileage: 28905 WIP No.: 18554
Model: A6 1.8 TFSI S tronic 40066 IN Chassis: WAUZZZ4G8H0009761 Engine: CY6 015125 Dept: U
VSB No.:
You have been assisted by :- UB-Jiayee (33)

		Details		Qty	Unit Price	Amount
X	A000979034EA	WIRES (RED)	Less 020%	1.00	54.70	43.76
X	A000979034EA	WIRES (RED)	Less 020%	1.00	54.70	43.76
X	A8J0915459	FUSE UNIT	Less 020%	1.00	516.00	412.80
X	A465945253	TRIM	Less 020%	1.00	25.10	20.08
X	AN 90814601	NUT	Less 020%	4.00	1.30	4.16
X	A465853927 2ZZ	MOLDING	Less 020%	1.00	316.50	253.20

Parts 14,047.36
Labour 0.00
Sublet 7,787.00
Menus 0.00
Lubricant 0.00

Sub-Total 21,834.36
7% GST 1,528.41
Grand Total 23,362.77



Received by

For & on behalf of
Premium Automobiles Pte Ltd

Customer

> Back to OneMotoring



Land Transport Authority

10 Sin Ming Drive

Singapore 575701

GST Registration No. : M4-0006529-2

Print Date/Time : 23 Jul 2018 / 19:26:10

Receipt Date/Time : 23 Jul 2018 / 19:26:10

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180723-002064

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SLR950X				
As at 23 Jul 2018/16:56:00				
Insurance Co: AIG ASIA PACIFIC INSURANCE PTE. LTD.				
1	Insurance Enquiry - SLR950X Enquiry Fee 20180723192510728651	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	xxxxxxxxxxxx8891	Credit Card: Visa/MasterCard		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Print Receipt

OK

Save as PDF

REPUBLIC OF SINGAPORE

Licensee Registration: **S7104703B**

Holder:

PHEE SOO JAY LOUIS

Birth Date: 05 Feb 1971

Valid Date: 06 Jan 2004

001075225K




REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7104703B**



Holder:

PHEE SOO JAY LOUIS

彭树捷

Race:

CHINESE

Date of birth:

05-02-1971

Country/Place of birth:

SINGAPORE

Sex:

M

57104703B




YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms

PASS DATE

11 Mar 1991

NP 428A

License No: S7104703B



520582

Barcode

NRIC No: S7104703B

Date of issue:

16-08-2013

Address:

33 JALAN LIMAU BALI

SINGAPORE 468504



...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	24 Jul 2018 Edit Reg		25 Jul 2018 00:00 Edit Adj Rpt	\$521,834.36 Edit Estimates	\$521,834.36 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: LCRF Pte Ltd , Co. Reg. No.: 201624597K									
Main Claimant: PHEE SOO JAY LOUIS , ID: S7104703B									
Vehicle Reg. No.:	SLL8108R	Date of Loss:	23/07/2018 17:00 - :59 [16 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 6149076955SG	Policy/Cover Note No.:	0999994782 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLR950X	Policy No. (Claimant):	2100503552-01						
		Excess:							
Repairer: Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911									
Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Gan, Angie-GL] Angiegeokling.Gan@aig.com									
Claimant's Insurer: AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 02/08/2018]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (04/02/2019): Alert - Adj Mandate Approved (\$24970.22) - SLL8108R - Claim Handler: Gan, Angie...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLL8108R (6149076955SG)
[SLR950X]
TP
PHEE SOO JAY LOUIS
Jul 23 2018 5:00PM
[LCRF Pte Ltd]
Premium Automobiles Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page v ☒	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	1	Edit
Photos/Images			3 per page v ☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	18/12/18 18:22	General View	1	Load JPG ☒
2	18/12/18 18:22	General View	1	Load JPG ☒
3	18/12/18 18:22	General View	1	Load JPG ☒
4	18/12/18 18:22	General View	1	Load JPG ☒
5	18/12/18 18:22	General View	1	Load JPG ☒
6	18/12/18 18:22	General View	1	Load JPG ☒
7	18/12/18 18:22	General View	1	Load JPG ☒
8	18/12/18 18:22	General View	1	Load JPG ☒
9	18/12/18 18:22	General View	1	Load JPG ☒
10	18/12/18 18:22	General View	1	Load JPG ☒
11	18/12/18 18:22	General View	1	Load JPG ☒
12	18/12/18 18:22	General View	1	Load JPG ☒
13	18/12/18 18:22	General View	1	Load JPG ☒
14	18/12/18 18:22	General View	1	Load JPG ☒
15	18/12/18 18:22	General View	1	Load JPG ☒
16	18/12/18 18:22	General View	1	Load JPG ☒
17	18/12/18 18:22	General View	1	Load JPG ☒
18	18/12/18 18:22	General View	1	Load JPG ☒
19	18/12/18 18:22	General View	1	Load JPG ☒
20	18/12/18 18:22	General View	1	Load JPG ☒
21	18/12/18 18:22	General View	1	Load JPG ☒
22	18/12/18 18:22	General View	1	Load JPG ☒
23	18/12/18 18:22	General View	1	Load JPG ☒
24	18/12/18 18:22	General View	1	Load JPG ☒
25	18/12/18 18:22	General View	1	Load JPG ☒
26	18/12/18 18:22	General View	1	Load JPG ☒
27	18/12/18 18:22	General View	1	Load JPG ☒
28	18/12/18 18:22	General View	1	Load JPG ☒
29	18/12/18 18:22	General View	1	Load JPG ☒
30	18/12/18 18:22	General View	1	Load JPG ☒
31	18/12/18 18:22	General View	1	Load JPG ☒
32	18/12/18 18:22	General View	1	Load JPG ☒
33	18/12/18 18:22	General View	1	Load JPG ☒
34	18/12/18 18:22	General View	1	Load JPG ☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				☒
35	18/12/18 18:22	General View		☒
36	18/12/18 18:22	General View		☒
37	18/12/18 18:22	General View		☒
38	18/12/18 18:22	General View		☒
39	18/12/18 18:22	General View		☒
40	18/12/18 18:22	General View		☒
41	18/12/18 18:22	General View		☒
42	18/12/18 18:22	General View		☒
43	18/12/18 18:22	General View		☒
44	18/12/18 18:22	General View		☒
45	18/12/18 18:22	General View		☒
46	18/12/18 18:22	General View		☒
47	18/12/18 18:22	General View		☒
48	18/12/18 18:22	General View		☒
49	18/12/18 18:22	General View		☒
50	18/12/18 18:22	General View		☒
51	18/12/18 18:22	General View		☒
52	18/12/18 18:22	General View		☒
53	18/12/18 18:22	General View		☒
54	18/12/18 18:22	General View		☒
55	18/12/18 18:22	General View		☒
56	18/12/18 18:22	General View		☒
57	18/12/18 18:22	General View		☒
58	18/12/18 18:22	General View		☒
59	18/12/18 18:22	General View		☒
60	18/12/18 18:22	General View		☒
61	18/12/18 18:22	General View		☒
62	18/12/18 18:22	General View		☒
63	18/12/18 18:22	General View		☒
64	18/12/18 18:22	General View		☒
65	18/12/18 18:22	General View		☒
66	18/12/18 18:22	General View		☒
67	18/12/18 18:22	General View		☒
68	18/12/18 18:22	General View		☒
69	18/12/18 18:22	General View		☒
70	18/12/18 18:22	General View		☒
71	18/12/18 18:22	General View		☒
72	18/12/18 18:22	General View		☒
73	18/12/18 18:22	General View		☒
74	18/12/18 18:22	General View		☒
75	18/12/18 18:22	General View		☒
76	18/12/18 18:22	General View		☒
77	18/12/18 18:22	General View		☒
78	18/12/18 18:22	General View		☒
79	18/12/18 18:22	General View		☒
80	18/12/18 18:22	General View		☒
81	18/12/18 18:22	General View		☒
82	18/12/18 18:22	General View		☒
83	18/12/18 18:22	General View		☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
84	18/12/18 18:22	General View	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/07/18 20:49	TP ESTIMATE	 Load PDF	
2	24/07/18 20:49	TP GIA REPORT	 Load PDF	
3	26/07/18 21:10	TP ESTIMATE - MARKED	 Load PDF	
4	07/01/19 14:15	LETTER TO OI	 Load PDF	
5	04/02/19 08:28	LTA SEARCH FEE	 Load PDF	
6	04/02/19 08:28	TP OWNER NRIC	 Load PDF	
7	12/02/19 09:15	WORKSHOP INVOICE	 Load PDF	
8	12/02/19 09:15	AUTHORISATION TO ACT FORM	 Load PDF	
9	12/02/19 09:15	Release Voucher	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	25/07/18 08:30	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLR950X (Insd veh)	Model:	AUDI A6 1.8 TFSI ULTRA (PI)
	SLL8108R (TP veh)		(NAV) (A)
Date of Accident:	23/07/2018		

Global Sum Settlement	: [] Yes	: [X] No	
Repair Estimate	: \$	34,687.47	
Final Repair Cost	: \$	23,362.77	
Loss of Use	: \$	1,600.00	16.00 days at \$100.00 per day
Rental (if any)	: \$	0.00	days
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$	0.00	
	: \$		
Final Settlement Sum	: \$	24,970.22	

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

BOLA Liability: _____ 100 _____ (%) Assessed Liability (*): _____ 0 _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	: \$	23,370.22
2)	Phee Soo Jay Louis	: \$	1,600.00
3)		: \$	
4)		: \$	

HUEY YON

12 Feb
2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/LCR18013483/APA3N2

Date: 12/02/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 0999994782

Claimant Vehicle No: SLL8108R

Insured Vehicle No: SLR950X

Date of Loss: 23/07/2018

Nature of Claim: TP

Claim No: 6149076955SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLL8108R

Make & Model: AUDI A6, 1.8 TFSI Ultra (PI) (NAV) (A)

Engine No: CYG015125

Reg. Date: 10/03/2017 (Man. Year: 2016)

Chassis No: WAUZZZ4G8HN009761

Colour: White

Odometer: 23677 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55 R17

Rear Tyre Size: 225/55 R17

Front Left Side: Pirelli 6 mm

Rear Left Side: Pirelli 6 mm

Front Right Side: Pirelli 6 mm

Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,906.20	14,572.36	7,333.84	33.48
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,512.00	7,262.00	3,250.00	30.92
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	32,418.20	21,834.36	10,583.84	32.65
+ GST 7.00/7.00% (S\$)	2,269.27	1,528.41	740.86	32.65
Nett Amount (S\$)	34,687.47	23,362.77	11,324.70	32.65
+ Loss of Use (16.0 x S\$100.00/day) (S\$)		1,600.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		24,970.22		

INSPECTION

Date of Assignment: 25/07/2018

Date Inspected: 25/07/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1

Singapore 408699

Estimated Period of Repair: 13.0 days

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Distorted	2,519.00 FS	*2,015.20 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	234.00 FS	*- FS
3	1		*FIXING PARTS FOR BUMPER	Not Necessary	23.00 FS	*- FS
4	1		*SECURING STRIP	Not Necessary	191.00 FS	*- FS
5	1		*SPOILER	Deformed	416.00 FS	*332.80 FS
6	2		*CLOSING ELEMENT -LH/RH	Not Necessary	138.00 FS	*- FS
7	1		*REAR BUMPER CARRIER	Bent	851.00 FS	*680.40 FS
8	2		*SEAL -LH/RH	Necessary	24.00 FS	*18.56 FS
9	2		*GUIDE SECTION -LH/RH	Not Necessary	56.00 FS	*- FS
10	2		*GUIDE SECTION -LH/RH	Not Necessary	92.00 FS	*- FS
11	2		*CONNECTING PIECE	Necessary	21.00 FS	*16.48 FS
12	2		*GUIDE PROFILE-LH/RH	Not Necessary	114.00 FS	*- FS
13	1		*GUIDE SECTION -CENTRE	Damaged	91.00 FS	*72.32 FS
14	2		*HOLDING STRIP -LH/RH	Damaged	108.00 FS	*42.96 FS
15	2		*SENSOR	Damaged	421.00 FS	*336.80 FS
16	1		*WIRING SET FOR BUMPER	Snapped	603.00 FS	*482.00 FS
17	1		*TRIM FOR EXHAUST TAIL PIPE -RH	Not Necessary	498.00 FS	*- FS
18	1		*REAR LID	Dented	2,485.00 FS	*1,988.00 FS
19	1		*BRACKET	Necessary	30.00 FS	*23.28 FS
20	1		*ATTACHMENT PARTS FOR REAR LID	Necessary	93.00 FS	*74.40 FS
21	1		*PUSH BUTTON FOR LID LOCK ACTUATOR	Not Necessary	1,181.00 FS	*- FS
22	1		*GASKET FOR FLAP	Cut	181.00 FS	*144.80 FS
23	1		*LID LOCK	Not Necessary	170.00 FS	*- FS
24	1		*PACKING ADHESIVE	Necessary	15.00 FS	*11.60 FS
25	1		*AUDI EMBLEM	Necessary	108.00 FS	*86.00 FS
26	1		*A6 EMBLEM	Necessary	83.00 FS	*66.16 FS
27	1		*TFSI EMBLEM	Necessary	83.00 FS	*66.16 FS
28	1		*DECORATIVE TRIM FOR LID CHROME	Necessary	317.00 FS	*253.20 FS
29	1		*LED TAIL LIGHT -RH/LH	O/S Cut	2,188.00 FS	*875.20 FS
30	2		*TRIM FOR LED TAIL LIGHT -RH	Cut	52.00 FS	*40.16 FS
31	1		*REAR CROSS PANEL	Dented	274.00 FS	*219.20 FS
32	1		*REINFORCEMENT FOR CROSS PANEL	Dented	639.00 FS	*511.20 FS
33	1		*CONNECTING PLATE -RH LOWER	Damaged	39.00 FS	*31.04 FS
34	1		*TRIM FOR REAR CROSS PANEL BLACK	Deformed	116.00 FS	*92.80 FS
35	1		*3 POINT AUTOMATIC SEAT BELT -LH	Activated	1,215.00 FS	*972.00 FS
36	1		*3 POINT AUTOMATIC SEAT BELT -RH	Activated	956.00 FS	*764.80 FS
37	1		*CONTROL UNIT FOR AIRBAG	Activated	2,258.00 FS	*1,806.40 FS
38	2		*ADJUSTMENT FITTING	Damaged	311.00 FS	*248.80 FS
39	1		*ARCYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
40	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
41	1		*STONE CHIP TREATMENT	Necessary	180.00 FS	*180.00 FS
42	1		*CAR PLATE	Bent	25.00 FS	*25.00 FS
43	1		*SUNDRIES	Necessary	500.00 FS	*87.44 FS
44	1		*REAR BUMPER GUIDE -RH UPPER	Damaged	22.00 FS	*22.00 FS
45	1		*REAR BUMPER GUIDE PROFILE-RH INNER	Damaged	45.28 FS	*45.28 FS
46	1		*REAR LID LOCK COVER	Cut	4.88 FS	*4.88 FS
47	2		*REAR LID HINGE -LH/RH	Bent	320.00 FS	*320.00 FS
48	4		*REAR LID STOP BUFFER	Necessary	7.04 FS	*7.04 FS
49	1		*LED TAIL LIGHT -RH	Cut	875.20 FS	*875.20 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	1		*BATTERY CETRAL PROTECTION	Activated	412.80 FS	*412.80 FS
				Total Parts (S\$)	21,906.20	14,572.36

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR ,CHECK FUNCTION AND RENEW ACCODING TO DAMAGE	New	360.00	360.00
2	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
3	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR TAIL LIGHTS ,BATTERY MANAGER ,FUSE AND RELAY TRAYS ,ELECTRICAL QND AUDIO COMPONENTS	New	480.00	480.00
4	TO DISMANTLE CENTER CONSOLE AND RENEW BOTH FRONT SEAT BELT AND CONTROL UNIT FOR AIRBAG	New	1,800.00	1,800.00
5	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID .CUT OUT AND REWELD REAR OUTER ,INNER AND LOWER REAR CROSS PANEL	New	4,200.00	2,500.00
6	TO RESPRAY REAR BUMPER ,REAR LID ,RHS REAR FENDER AND END PANELLING .TO CARRY OUT JOINT SEALER WORKS AND STONE CHIP TREATMENT	New	3,200.00	1,650.00
7	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (S\$)			10,512.00	7,262.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >