

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/TP/0842/2018/PH 27-Jul-18 CHANG 1 of 1 SLL 8108 R Audi A6 SEDAN 1.8 TFSI
Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	REAR BUMPER GUIDE - RH UPPER	\$ 28.00	✓
2	REAR BUMPER GUIDE PROFILE - RH INNER	\$ 57.00	✓
3	REAR LID LOCK COVER	\$ 7.00	✓
4	REAR LID HINGE - LH/RH	\$ 400.00	✓
5	REAR LID STOP BUFFER	\$ 9.00	✓
6	LED TAIL LIGHT - RH	\$ 1,094.00	✓
⑦	BATTERY CETRAL PROTECTION	\$ 516.00	✓
GRAND TOTAL :		\$ 2,111.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
1	BUMPER COVER Distorted	\$	2,519.00	✓
2	FIXING PARTS FOR BUMPER ?	\$	234.00	?
3	FIXING PARTS FOR BUMPER ?	\$	23.00	?
4	SECURINMG STRIP ?	\$	191.00	?
5	SPOILER Dehnd	\$	416.00	✓
6	CLOSING ELEMENT - LH/RH ?	2 \$	138.00	?
⑦	REBUMPER CARRIER ? bt ✓	\$	851.00	?
8	SEAL - LH/RH neu	2 \$	24.00	x
9	GUIDE SECTION - LH/RH } neu	2 \$	56.00	x
10	GUIDE SECTION - LH/RH	2 \$	92.00	x.
11	CONNECTING PIECE Neu	2 \$	21.00	✓
12	GUIDE PROFILE - LH/RH neu	2 \$	114.00	x
⑬	GUIDE SECTION - CENTRE ? de ✓	\$	91.00	?
⑭	HOLDING STRIP - LH/RH ? ewa ✓	2 \$	108.00	?
15	SENSOR ?	2 \$	421.00	?
16	WIRING SET FOR BUMPER neu	\$	603.00	x
17	TRIM FOR EXHAUST TAIL PIPE - RH ?	\$	498.00	?
18	REAR LID Dented.	\$	2,485.00	✓
19	BRACKET neu	\$	30.00	✓
20	ATTACHMENT PARTS FOR REAR LID Neu	\$	93.00	✓
SUB - TOTAL SPARE PARTS CHARGES :		\$	9,008.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Signature 27/7/18

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	PUSH BUTTON FOR LID LOCK ACTUATOR <i>Net</i>	\$ 1,181.00	<i>x</i>
22	GASKET FOR FLAP <i>new at</i>	\$ 181.00	<i>✓</i>
23	LID LOCK <i>Net</i>	\$ 170.00	<i>x</i>
24	PACKING ADHESIVE <i>new</i>	\$ 15.00	<i>✓</i>
25	AUDI EMBLEM <i>2</i>	\$ 108.00	<i>✓</i>
26	A6' EMBLEM <i>Net</i>	\$ 83.00	<i>✓</i>
27	TFSI' EMBLEM	\$ 83.00	<i>✓</i>
28	DECORATIVE TRIM FOR LID CHROME <i>Net</i>	\$ 317.00	<i>-</i>
29	LED TAIL LIGHT - RH/LH <i>RH at</i>	2 \$ 2,188.00	<i>1094.</i>
30	TRIM FOR LED TAIL LIGHT - RH <i>at</i>	2 \$ 52.00	<i>-</i>
31	REAR CROSS PANEL <i>? bt -</i>	\$ 274.00	<i>?</i>
32	REINFORCEMENT FOR CROSS PANEL <i>bp -</i>	\$ 639.00	<i>?</i>
33	CONNECTING PLATE - RH LOWER <i>?</i>	\$ 39.00	<i>?</i>
34	TRIM FOR REAR CROSS PANEL BLACK <i>Red</i>	\$ 116.00	<i>✓</i>
35	3 POINT AUTOMATIC SEAT BELT-LH <i>Adjuster</i>	\$ 1,215.00	<i>✓</i>
36	3 POINT AUTOMATIC SEAT BELT-RH <i>?</i>	\$ 956.00	<i>2</i>
37	CONTROL UNIT FOR AIRBAG <i>?</i>	\$ 2,258.00	<i>?</i>
38	ADJUSTMENT FITTING <i>Net</i>	2 \$ 311.00	<i>x</i>
39	ARCYLIC SEALANT <i>?</i>	S/N \$ 180.00	<i>?</i>
40	CAVITY WAX <i>?</i>	S/N \$ 140.00	<i>?</i>
SUB - TOTAL SPARE PARTS CHARGES :		\$ 10,506.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.