

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0842/2018/PH
Date : 24-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

Your insured vehicle : SLR 950 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Phee Soo Jay Louis
Address : 33 Jalan Limau Bali
Singapore 468504
Telephone : HP +65 97968155
Type of Claim : Third Party Claims
Policy No. : 2100503552-01
Vehicle No : **SLL 8108 R**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Mar-17
Engine No : CYG 015125
Chassis No : WAUZZZ4G8HN009761
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 23-Jul-18
Place of Accident : PIE towards Changi before Thomson exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SLL 8108 R

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer rear parking aid and rear lid kick sensor. Check function and renew according to damage.	S/N \$ 360.00	✓
2	To remove and transfer rear lid's convenience lock system and wire harness for tail lights.	S/N \$ 280.00	✓
3	To dislodge and reinstall rear wire harness for tail lights, battery manager, fuse and relay trays, electrical and audio components.	S/N \$ 480.00	?
4	To dismantle center console and renew both front seat belt and control unit for airbag.	S/N \$ 1,800.00	✓
5	To dismantle and renew rear bumper and rear lid. Cut out and reweld rear outer, inner and lower rear cross panel.	\$ 4,200.00	1000 exclude End Panel.
6	To respray rear bumper, rear lid, rhs rear fender and end panelling. To carry out joint sealer works and stone chip treatment.	\$ 3,200.00	1750.
7	To carry out diagnostic check	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 10,512.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/	Nett	
1	BUMPER COVER <i>Distorted</i>	\$	2,519.00	✓
2	FIXING PARTS FOR BUMPER ?	\$	234.00	?
3	FIXING PARTS FOR BUMPER ?	\$	23.00	?
4	SECURINMG STRIP ?	\$	191.00	?
5	SPOILER <i>Deh</i>	\$	416.00	✓
6	CLOSING ELEMENT - LH/RH ?	2 \$	138.00	?
7	REBUMPER CARRIER ?	\$	851.00	?
8	SEAL - LH/RH <i>neu</i>	2 \$	24.00	x
9	GUIDE SECTION - LH/RH <i>neu</i>	2 \$	56.00	x
10	GUIDE SECTION - LH/RH <i>neu</i>	2 \$	92.00	x
11	CONNECTING PIECE <i>neu</i>	2 \$	21.00	✓
12	GUIDE PROFILE - LH/RH <i>neu</i>	2 \$	114.00	x
13	GUIDE SECTION - CENTRE ?	\$	91.00	?
14	HOLDING STRIP - LH/RH ?	2 \$	108.00	?
15	SENSOR ?	2 \$	421.00	?
16	WIRING SET FOR BUMPER <i>neu</i>	\$	603.00	x
17	TRIM FOR EXHAUST TAIL PIPE - RH ?	\$	498.00	?
18	REAR LID <i>Deh</i>	\$	2,485.00	✓
19	BRACKET <i>neu</i>	\$	30.00	✓
20	ATTACHMENT PARTS FOR REAR LID <i>neu</i>	\$	93.00	✓
SUB - TOTAL SPARE PARTS CHARGES :		\$	9,008.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
21	PUSH BUTTON FOR LID LOCK ACTUATOR <i>Not m</i>	\$	1,181.00	x
22	GASKET FOR FLAP <i>new ut</i>	\$	181.00	✓
23	LID LOCK <i>new</i>	\$	170.00	x
24	PACKING ADHESIVE <i>new</i>	\$	15.00	✓
25	AUDI EMBLEM <i>2</i>	\$	108.00	✓
26	A6' EMBLEM <i>new</i>	\$	83.00	✓
27	TFSI' EMBLEM	\$	83.00	✓
28	DECORATIVE TRIM FOR LID CHROME <i>new</i>	\$	317.00	-
29	LED TAIL LIGHT - RH/LH <i>RH ut</i>	2 \$	2,188.00 1094.	
30	TRIM FOR LED TAIL LIGHT - RH <i>ut</i>	2 \$	52.00	-
31	REAR CROSS PANEL ?	\$	274.00	?
32	REINFORCEMENT FOR CROSS PANEL ?	\$	639.00	?
33	CONNECTING PLATE - RH LOWER ?	\$	39.00	?
34	TRIM FOR REAR CROSS PANEL BLACK <i>Red</i>	\$	116.00	✓
35	3 POINT AUTOMATIC SEAT BELT-LH <i>Adjusted</i>	\$	1,215.00	✓
36	3 POINT AUTOMATIC SEAT BELT-RH ?	\$	956.00	2
37	CONTROL UNIT FOR AIRBAG ? <i>Adapted</i>	\$	2,258.00	?
38	ADJUSTMENT FITTING <i>new</i>	2 \$	311.00	A
39	ARCYLIC SEALANT ?	S/N \$	180.00	?
40	CAVITY WAX ?	S/N \$	140.00	?
SUB - TOTAL SPARE PARTS CHARGES :			\$ 10,506.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLL 8018 R.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	STONE CHIP TREATMENT ?	S/N \$ 180.00 ?	
42	CAR PLATE <i>But</i>	\$ 25.00 ✓	
43	SUNDRIES ?	\$ 500.00 ?	
TOTAL SPARE PARTS CHARGES		: \$ 20,219.00	
TOTAL LABOUR CHARGES		: \$ 10,512.00	
GRAND TOTAL		: \$ 30,731.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 26/07/18
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised 06 Days.

Please Note

- : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
- For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant