

ASS: REC. BY: Adrian King

REF:

CC3 / AU118013506 / Avbn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost:

☒ OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured:

Policy No. 1800019597

Claims No. _____

Sum Insured: _____ Excess: 400

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 265K.

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 6 8/8 Consistent? : Yes or No

Est. Repairs: 6 8/8 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGS20696 Yr Regn: 2018 March

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: And: AG C.C. 1798

Colour: Brown A/C: Insured / Std / NI / NA

Sp. Reading: 7721 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WAU222468H N081687

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55R17

R: 225/55R17

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. 24/7/18 D.O.I. 24/07/18

Survey held at Premium

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Front N/S.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	☒ ALG -
	SGS 20696 - CC / AU118013506 / TJ1
	DA: 0302018
<u>26/7/18</u>	Revert via merimen
<u>27/7/18</u>	Recd approved \$ 21,262 from Victor by merimen
<u>27/7/18</u>	Informed George CIA ex \$400 by email
<u>7/11/18</u>	Final fig \$ 19,269.84 (Recd 17,641.16, 4790) confirmed by email

RECEIVED 30 NOV 2018.

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2) 30/11 - typist

Report Format: merimen

Lump Sum / I.B.I. (\$) 19,269.84

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

Survey Fee:

Transportation:

\$ + RS. \$

Photos

Others

TOTAL

200
10

210

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building
78 Shenton Way #07-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Dally Amri, Mimi Zarina

Date: 26 Jul 2018

Preliminary Advice

Vehicle No	: SGS2069G	Accident Date	: 24/07/2018
Make	: AUDI A6	Policy No.	: 1800019597
Assignment Date	: 25/07/2018	Excess	: S\$400.00
Date of Inspection	: 24/07/2018	Est. Duration of Repair	: 6.00
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	36,911.00
Revised Amount	:S\$	21,262.00
Check Items (Estimated)	:S\$	5,120.00
Total	:S\$	26,382.00

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	205,000.00
COE / PARF Rebate	:S\$	73,859.00
Salvage Value	:S\$	
Margin for Repair	:S\$	131,141.00

Remarks

(X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

() Other comments :

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 July 2018 1:24 PM
To: SUR; claims@premiumauto.com.sg
Subject: RE: SGS 2069 G - OWN DAMAGE AIG - DOA: 24/07/2018

Dear George,

As instructed by our client , please proceed to repair the insured vehicle **SGS 2069G (Excess \$400/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Friday, 27 July 2018 7:40 AM
To: SUR <sur@lkkauto.com>; claims@premiumauto.com.sg
Subject: RE: SGS 2069 G - OWN DAMAGE AIG - DOA: 24/07/2018

Dear George,

We are still pending approval from AIG.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Thursday, 26 July 2018 6:19 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Subject: RE: SGS 2069 G - OWN DAMAGE AIG - DOA: 24/07/2018

CC3/AIG18013506/Avb

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claims Dept <claims@premiumauto.com.sg>

Sent: Thursday, 26 July 2018 5:48 PM

To: Admin A <admin-a@lkkauto.com>; Adrian Ling (LKKAuto) <adrianling@lkkauto.com>

Cc: 'Claims Dept' <claims@premiumauto.com.sg>

Subject: RE: SGS 2069 G - OWN DAMAGE AIG - DOA: 24/07/2018

Dear all,

Any update for the above mentioned case ?

Thank you.

Best Regards,

George Wong

Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Wednesday, 25 July 2018 4:49 PM

To: 'Claims'; admin-a@lkkauto.com; 'Adrian Ling (LKKAuto)'

Cc: 'Mastura'

Subject: RE: SGS 2069 G - OWN DAMAGE AIG - DOA: 24/07/2018

Good afternoon all,

Here is the attached estimate for your kind reference.

Thank you.

Best Regards,
Phua
Claims Advisor

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223



http://www.audi.com.sg/sea/brand/sq/audi_promotions/promotions/car_promotions/new-audi-q2-2017.html

Email Disclaimer

This email, including any attachment, is confidential and may also be privileged.

If you have received it in error, please notify us immediately by reply email and then delete this message from your system.

Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you

From: Claims [<mailto:claims@premiumauto.com.sg>]

Sent: Tuesday, 24 July 2018 1:02 PM

To: admin-a@lkkauto.com; 'Adrian Ling (LKKAuto)'; claims@premiumauto.com.sg

Cc: 'Mastura'

Subject: SGS 2069 G - OWN DAMAGE AIG - DOA: 24/07/2018

Dear Claims team,

Above attachment is for your perusal. Adrian has surveyed the vehicle today, 24/07/2018.

Thank you.

Best Regards,
Mastura
Claims Administrator

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9828 f. +65 6841 1183

e. mastura@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 2223

View Received Message

This mail is associated with :

***SGS2069G (5892428828SG)**

OD

Jul 24 2018 6:00AM

[JAAFAR BIN MOHAMED]

Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (AIG_SG), sent on **27/07/2018 12:34 PM.**

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$21262.00) - SGS2069G - Claim Handler: Dally Amri, Mimi Zarina

Approved:21262.00:Re-inspection to be done for damage check and supplementary items / labour.

DOCUMENTS SUMMARY

There are no documents.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9786Z
Vehicle Details	
Vehicle No.:	SGS2069G
Vehicle to be Exported:	No
Intended De-registration Date:	25 Jul 2018
Vehicle Make:	AUDI
Vehicle Model:	A6 1.8 TFSI ULTRA (PI) (NAV)
Primary Colour:	Brown
Manufacturing Year:	2016
Engine No.:	CYG018412
Chassis No.:	WAUZZZ4G8HN081687
Maximum Power Output:	140.0 kW (187 bhp)
Open Market Value:	\$40,419.00
Original Registration Date:	01 Mar 2018
First Registration Date:	01 Mar 2018
Transfer Count:	0
Actual ARF Paid:	\$48,587.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Feb 2028
PARF Rebate Amount:	\$36,440.00
Intended COE Rebate Details	
COE Expiry Date:	29 Feb 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$39,000.00
COE Rebate Amount:	\$37,419.00
Total Rebate Amount:	\$73,859.00

The information contained herein is correct as at 25 Jul 2018

OK

CERTIFICATE OF INSURANCE

DI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : JAAFAR BIN MOHAMED
Period of Insurance : 01 Mar 2018 To 28 Feb 2020
Policy No. : CYG018412
Plate No. : WAUZZZ4G8HN081687

Vehicle No. : SGS2069G
Policy No. : 1800019597
Endorsement No. :
Issued Date : 02 Mar 2018

OUT OF THE COVER

Model : AUDI A6 1.8 TFSI ULTRA
Engine Capacity/Tonnage : 1,798.00 CC
Driver Restriction : NA
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive*

The Policyholder
Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition:
I have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use*

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Class of Use 1800cc - 2000cc Optional

Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$800 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

JAAFAR BIN MOHAMED - \$800 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 67662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third-Party Risks) Rules, 1950 (Malaysia).

0504125211

PREMIUM LEASING - NC
281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE
SINGAPORE 159938
Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Jonile

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Cheng Guan Yee

OUR AIG AUTO HOTLINE: +65 6338 6200

IMPORTANT: KEEP THIS DOCUMENT IN YOUR CAR AT ALL TIMES.

What can the 24-hour AIG Auto Emergency Hotline provide for you?

- Emergency roadside assistance
- Emergency breakdown service
- Towing services (subject to third-party approval)
- Advice on Motor Claims procedures
- Medical Referral Assistance

If no one is injured in the accident:

- You are not required to make any police report.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and witnesses.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

If the accident involves injuries or damage to government property & vehicles, foreign registered vehicles or non-injury hit & run cases:

- Report the accident to the police, providing full details of the circumstances of the accident.
- Record vehicle number, name and address, insurance company and policy number of the other driver(s) and witnesses, if applicable.
- Collect details (name, address and contact number) of witnesses and/or try to take photographs of the scene of the accident.
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.

What should I do in the event of an accident?

- Stop safely and move your car to a safe place.
- Do not admit or discuss fault or blame with the other party(ies).
- Report the accident to us with your accident vehicle (whether damaged or not) via our approved reporting centres or authorised repairers within 24 hours of the next working day of the accident.
- Submit Your Settlement Documents (claims from third parties) to AIG immediately.

LOSS OF USE CAR REPLACEMENT BENEFIT

Applicable only if this benefit is included in your motor insurance. Please refer to your Policy Schedule for details. Policy terms and conditions apply. Please call our customer service hotline number (65) 6419-3000 for assistance.

The Certificate of Insurance (CI) should be produced without demand when collecting the Rental Car and the Rental Car Company reserves the right to verify the identity of the holder. The CI is the property of AIG and its use is subject to the terms and conditions contained in the Loss of Use Endorsement under the policy issued to the policyholder.

Steps to activate Loss of Use Car Replacement Benefit and Important Information

1. To activate your loss of use car replacement, please contact the Rental Car Company (listed below) after filing/reporting your accident claim.
2. Your rental car will be made available within 5 working hours of activation with the Rental Car Company.
3. At the time of collection of the Rental Car, the original insurance policy and schedule issued by AIG, a copy of the Accident Report from Audi Customer Service Centre must be produced.
4. The number of days is based on the period your vehicle is in the repair workshop unless the number of days of loss of use entitlement is stated in the Policy.
5. Rental cars are strictly for use in Singapore only.
6. Extension of rental beyond repair period approved by AIG surveyor will be chargeable by the Rental Car Company on per day basis.
7. Upgrade of Rental Car is available upon request subject to additional charges by the Rental Car Company.

Rental Car Company: Popular Rent A Car Pte. Ltd.

Activation Hotline: 67428888

501 Guillemard Road Singapore 399840

Operation Hours: Monday to Friday: 9am to 6pm Saturday (Half Day): 9am to 4pm

*The Rental Car Company's Terms & Conditions apply (i.e., refundable security deposit, excess liability for the Rental Car, Collision Damage Waiver, etc.)

IMPORTANT NOTICE

If you sell your motor vehicle, this Notice is IMPORTANT and MUST be complied with. Policyholders are hereby warned that under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.99), it shall be unlawful for any person to use or cause or permit any other person to use a motor vehicle without a valid policy of insurance under the Act.

The Policyholder is further warned that on the sale of a motor vehicle, they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a Statutory Declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third Party Risks and Compensation) Act (Cap.88).

This Policy will cease to be valid once the motor vehicle has been sold to another person unless the transfer of interest has been duly notified to and agreed to by the insurance company concerned. If the insurance company agrees to cover the new owner, they will issue a new Certificate of Insurance in the new owner's name. The premium chargeable may vary according to the new owner's profile.

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7309786Z



JAAFAR BIN MOHAMED

جعفر بن محمد

Place
MALAY

Date of Birth
09-03-1973 M

Country of Birth
SINGAPORE



REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number: S7620345H

Name
ZURIANEE ZAINAL

Birth Date: 07 Jul 1976

Issue Date: 14 Jul 2003



NRIC No. S7309786Z



651E S7309786Z
JAAFAR

Block Group: 07-05-1994

7 SEMBAWANG CRESCENT #03-13
SINGAPORE 757006

NRIC No: S7309786Z

Date: 30/11/2016


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

Class 3 Motor Cars and Motor Tractors the weight of
which untladen does not exceed 2500 kilograms

PASS DATE

19 Aug 1998

NP 426A



3993463



Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate	:	Accident Repairs
Workshop	:	Ubi Road 1
Contact No	:	6366 2323
Fax No	:	6841 1183
Reference	:	PA/OD/0845/2018/PH
Date	:	25-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name	:	Mr Jaafar Bin Mohamed
Address	:	7 Sembawang Crescent
	:	#03-13, Skypark Residences
	:	Singapore 757096
Telephone	:	HP +65 98520060
Type of Claim	:	Own Damage Claims
Policy No.	:	1800019597
Vehicle No	:	SGS 2069 G
Model Code	:	Audi A6 Sedan 1.8 TFSI
Model / Year	:	Mar-18
Engine No	:	CYG 018412
Chassis No	:	WAUZZZ4G8HN081687
Mileage	:	
Date In	:	
Liability	:	-
Excess Cost	:	-
Estimated By	:	Johnny Boo / Allan Wu
Accident Date	:	24-Jul-18
Place of Accident	:	Sembawang Avenue(Filter out from Sembawang Drive)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2069 G.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	✓ ✓
2	To remove and transfer air con condenser, radiator, additional radiator electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,100.00	? X
3	To dismantle and renew front bumper, lhs headlight, lhs front fender and bonnet. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	S/N \$ 5,250.00	1750 ✓
4	To rep-spray front bumper, lhs front fender and bonnet.	\$ 2,500.00	1650 ✓
5	To carry out diagnostic check	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 9,522.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SGS20696

Material List for Accident Vehicle Regn No. SLL 8018 R.

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remark
1	BUMPER COVER <i>deformed</i>	\$ 2,650.00 ✓	2120
2	FIXING PARTS FOR BUMPER <i>replace</i>	\$ 464.00 ✗	
3	BUMPER CLIP SET <i>new</i>	\$ 43.00 ✓	34.40
4	GRILLE - LOWER CENTRE <i>HE m</i>	\$ 112.00 ✗	
5	ADAPTER - LH/RH	2 \$ 64.00 ✗	
6	CLOSING ELEMENT	\$ 188.00 ✗	
7	SPOILER <i>HE m</i>	\$ 216.00 ✗	
8	SPOILER PRIMED	\$ 817.00 ✗	
9	RADIATOR GRILLE	\$ 1,697.00 ✗	
10	AIR GUIDE GRILLE SATIN BLACK <i>cut missing</i>	\$ 434.00 ?	347.50
11	WHEEL SPOILER - LH FRONT <i>HE m</i>	\$ 232.00 ?	✗
12	COVER CAP <i>HE m</i>	\$ 49.00 ✗	
13	GUIDE PIECE - LH/RH <i>LH damaged</i>	2 \$ 64.00	32 25.36
14	FOAM FILLER PIECE	\$ 203.00 ✗	
15	SIDE REINFORCEMENT	\$ 702.00 ✗	
16	BUMPER COVER <i>HE m</i>	\$ 105.00 ✗	
17	CAUTION' SIGN STICKER	\$ 12.00 ✗	
18	STICKER FOR AIR CONDITIONER <i>HE m</i>	\$ 17.00 ✗	
19	BRACE - LH/RH <i>LH Bent</i>	2 \$ 50.00	25. 19.92
20	SENSOR PRIMED <i>HE m</i>	2 \$ 392.00 ✗	
SUB - TOTAL SPARE PARTS CHARGES :		\$ 8,511.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER - LH <i>Disburled.</i>	\$ 1,220.00	✓ 976
22	ATTACHMENT PARTS FOR FENDER <i>The new</i>	\$ 88.00	? X
23	STONE GUARD FILM WING DOOR <i>the new</i>	\$ 105.00	X
24	BRACE WING - LH <i>Bent</i>	\$ 72.00	? 57.00
25	STONE CHIP GUARD <i>new</i>	\$ 63.00	✓ 49.92
26	ADHESIVE TAPE <i>The new</i>	\$ 49.00	? X
27	WHEEL HOUSING LINER - LH <i>the new</i>	\$ 246.00	X
28	ATTACHMENT PARTS FOR WHEEL LINER <i>not new</i>	\$ 62.00	^
29	BONNET <i>Disburled</i>	\$ 4,771.00	✓ 3816.80
30	ATTACHMENT PARTS FOR BONNET <i>The new</i>	\$ 153.00	? X
31	CATCH HOOK	\$ 122.00	X
32	LOCK BAR	\$ 44.00	X
33	CATCH HOOK	\$ 15.00	^
34	LID LOCK WITH MICRO-SWITCH <i>new</i>	\$ 188.00	+
35	STOP BUFFER	2 \$ 50.00	X
36	MOUNT FOR MAIN HEADLIGHT-LH <i>the new</i>	\$ 103.00	? X
37	LED HEADLIGHT - LH <i>cauld</i>	\$ 8,386.00	✓ 6708.80
38	POWER MODULE FOR DAY RUNNING LIGHT- <i>Disburled</i>	\$ 501.00	? 400.40
39	POWER MODULE FOR DIPPED BEAM <i>Disburled</i>	\$ 486.00	? 388.80
40	FAN FOR HEADLIGHT - LH <i>The new</i>	\$ 345.00	? X
SUB - TOTAL SPARE PARTS CHARGES :		\$ 17,069.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G.

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/Nett		
41	LIFT CYLINDER - LH <i>new Cracked</i>	\$	208.00	X 166
42	LOCK CARRIER FOR COOLANT RADIATOR <i>new</i>	\$	1,024.00	? X
43	COOLANT CONCENTRATE <i>new</i>	4 \$	133.00	? X
44	COVER <i>new</i>	\$	44.00	X
45	SUNDRIES <i>new</i>	\$	400.00	? 86-96
TOTAL SPARE PARTS CHARGES		:	\$ 27,389.00	
TOTAL LABOUR CHARGES		:	\$ 9,522.00	
GRAND TOTAL		:	\$ 36,911.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name

: Adrian Ling

Surveyed Date

: 24/07/18

Authorised Date

:

Excess Cost

:

Liability

:

Remarks

: Not Authorised, 06 Dyp

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SGS20696

Material List for Accident Vehicle Regn No. ~~SL 0018 R~~

		Damaged Parts & Prices	
S/N	Parts Description	S/Nett	Remark
1	BUMPER COVER <i>deformed</i>	\$ 2,650.00	✓
2	FIXING PARTS FOR BUMPER <i>Not used</i>	\$ 464.00	x
3	BUMPER CLIP SET <i>new</i>	\$ 43.00	✓
4	GRILLE - LOWER CENTRE <i>Not used</i>	\$ 112.00	x
5	ADAPTER - LH/RH	2 \$ 64.00	x
6	CLOSING ELEMENT	\$ 188.00	x
7	SPOILER <i>Not used</i>	\$ 216.00	x
8	SPOILER PRIMED	\$ 817.00	x
9	RADIATOR GRILLE	\$ 1,697.00	x
10	AIR GUIDE GRILLE SATIN BLACK <i>? new</i>	\$ 434.00	?
11	WHEEL SPOILER - LH FRONT <i>?</i>	\$ 232.00	?
12	COVER CAP <i>Not used</i>	\$ 49.00	x
13	GUIDE PIECE - LH/RH <i>LH damaged</i>	2 \$ 64.00	32
14	FOAM FILLER PIECE	\$ 203.00	x
15	SIDE REINFORCEMENT <i>Not used</i>	\$ 702.00	x
16	BUMPER COVER	\$ 105.00	x
17	CAUTION SIGN STICKER	\$ 12.00	x
18	STICKER FOR AIR CONDITIONER <i>Not used</i>	\$ 17.00	x
19	BRACE - LH/RH <i>LH bent</i>	2 \$ 50.00	25
20	SENSOR PRIMED <i>Not used</i>	2 \$ 392.00	x
SUB - TOTAL SPARE PARTS CHARGES :		\$ 8,511.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
21	FRONT FENDER - LH <i>Dislodged</i>	\$ 1,220.00	✓
22	ATTACHMENT PARTS FOR FENDER	\$ 88.00	?
23	STONE GUARD FILM WING DOOR <i>Not in</i>	\$ 105.00	x
24	BRACE WING - LH <i>Not in</i>	\$ 72.00	?
25	STONE CHIP GUARD <i>new</i>	\$ 63.00	✓
26	ADHESIVE TAPE	\$ 49.00	?
27	WHEEL HOUSING LINER - LH <i>new</i>	\$ 246.00	x
28	ATTACHMENT PARTS FOR WHEEL LINER <i>not in</i>	\$ 62.00	x
29	BONNET <i>Dislodged</i>	\$ 4,771.00	✓
30	ATTACHMENT PARTS FOR BONNET	\$ 153.00	?
31	CATCH HOOK	\$ 122.00	x
32	LOCK BAR	\$ 44.00	x
33	CATCH HOOK	\$ 15.00	^
34	LID LOCK WITH MICRO-SWITCH <i>new</i>	\$ 188.00	+
35	STOP BUFFER	2 \$ 50.00	+
36	MOUNT FOR MAIN HEADLIGHT-LH	\$ 103.00	?
37	LED HEADLIGHT - LH <i>cracked</i>	\$ 8,386.00	✓
38	POWER MODULE FOR DAY RUNNING LIGHT	\$ 501.00	?
39	POWER MODULE FOR DIPPED BEAM	\$ 486.00	?
40	FAN FOR HEADLIGHT - LH	\$ 345.00	?
SUB - TOTAL SPARE PARTS CHARGES		\$ 17,069.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	LIFT CYLINDER - LH <i>Here over</i>	\$ 208.00	X
42	LOCK CARRIER FOR COOLANT RADIATOR ?	\$ 1,024.00	?
43	COOLANT CONCENTRATE ?	4 \$ 133.00	?
44	COVER <i>He ~</i>	\$ 44.00	X
45	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 27,389.00	
TOTAL LABOUR CHARGES		: \$ 9,522.00	
GRAND TOTAL		: \$ 36,911.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0845/2018/PH
Date : 25-Jul-18

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

6 days of repairs - ok - jb - 8 Oct 18

Exclude 1 PH & 1 Sunday

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Jaafar Bin Mohamed
Address : 7 Sembawang Crescent
: #03-13, Skypark Residences
Singapore 757096
Telephone : HP +65 98520060
Type of Claim : Own Damage Claims
Policy No. : 1800019597
Vehicle No : **SGS 2069 G**
Model Code : Audi A6 Sedan 1.8 TFSI
Model / Year : Mar-18
Engine No : CYG 018412
Chassis No : WAUZZZ4G8HN081687
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 24-Jul-18
Place of Accident : Sembawang Avenue(Filter out from Sembawang Drive)

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SGS 2069 G.

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights, horns, fog lamps, outside temperature sensor, headlight washer assy and front parking aid.	S/N \$ 480.00	\$ 480.00
2	To remove and transfer air con condenser, radiator, additional radiator electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	S/N \$ 1,100.00	nn
3	To dismantle and renew front bumper, lhs headlight, lhs front fender and bonnet. Renew front lock carrier and align to position. Re-organise front crash management components. Reinstall all parts removed.	S/N \$ 5,250.00	\$ 1,750.00
4	To rep-spray front bumper, lhs front fender and bonnet.	\$ 2,500.00	\$ 1,650.00
5	To carry out diagnostic check	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 9,522.00	\$ 4,072.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

SGS 2069G

Material List for Accident Vehicle Regn No. SLL 8018 R.

		<u>Damaged Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/Nett</u>	<u>Remark</u>
1	BUMPER COVER	\$ 2,650.00	\$ 2,120.00
2	FIXING PARTS FOR BUMPER	\$ 464.00	
3	BUMPER CLIP SET	\$ 43.00	\$ 34.40
4	GRILLE - LOWER CENTRE	\$ 112.00	
5	ADAPTER - LH/RH	2 \$ 64.00	
6	CLOSING ELEMENT	\$ 188.00	
7	SPOILER	\$ 216.00	
8	SPOILER PRIMED	\$ 817.00	
9	RADIATOR GRILLE	\$ 1,697.00	
10	AIR GUIDE GRILLE SATIN BLACK	\$ 434.00	\$ 347.20
11	WHEEL SPOILER - LH FRONT	\$ 232.00	
12	COVER CAP	\$ 49.00	
13	GUIDE PIECE - LH/RH	2 \$ 64.00	\$ 25.36
14	FOAM FILLER PIECE	\$ 203.00	
15	SIDE REINFORCEMENT	\$ 702.00	
16	BUMPER COVER	\$ 105.00	
17	CAUTION' SIGN STICKER	\$ 12.00	
18	STICKER FOR AIR CONDITIONER	\$ 17.00	
19	BRACE - LH/RH	2 \$ 50.00	\$ 19.92
20	SENSOR PRIMED	2 \$ 392.00	
SUB - TOTAL SPARE PARTS CHARGES:		\$ 8,511.00	\$ 2,546.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G

S/N	Parts Description		Damaged Parts & Prices	
			S/Nett	Remark
		c/f		\$ 2,546.88
21	FRONT FENDER - LH		\$ 1,220.00	\$ 976.00
22	ATTACHMENT PARTS FOR FENDER		\$ 88.00	
23	STONE GUARD FILM WING DOOR		\$ 105.00	
24	BRACE WING - LH		\$ 72.00	\$ 57.28
25	STONE CHIP GUARD		\$ 63.00	\$ 49.92
26	ADHESIVE TAPE		\$ 49.00	
27	WHEEL HOUSING LINER - LH		\$ 246.00	
28	ATTACHMENT PARTS FOR WHEEL LINER		\$ 62.00	
29	BONNET		\$ 4,771.00	\$ 3,816.80
30	ATTACHMENT PARTS FOR BONNET		\$ 153.00	
31	CATCH HOOK		\$ 122.00	
32	LOCK BAR		\$ 44.00	
33	CATCH HOOK		\$ 15.00	
34	LID LOCK WITH MICRO-SWITCH		\$ 188.00	
35	STOP BUFFER	2	\$ 50.00	
36	MOUNT FOR MAIN HEADLIGHT-LH		\$ 103.00	
37	LED HEADLIGHT - LH		\$ 8,386.00	\$ 6,708.80
38	POWER MODULE FOR DAY RUNNING LIGHT-		\$ 501.00	\$ 400.40
39	POWER MODULE FOR DIPPED BEAM		\$ 486.00	\$ 388.80
40	FAN FOR HEADLIGHT - LH		\$ 345.00	
SUB - TOTAL SPARE PARTS CHARGES :			\$ 17,069.00	\$ 14,944.88

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
	c/f		\$14,944.88
41	LIFT CYLINDER - LH	\$ 208.00	\$ 166.00
42	LOCK CARRIER FOR COOLANT RADIATOR	\$ 1,024.00	
43	COOLANT CONCENTRATE	4 \$ 133.00	
44	COVER	\$ 44.00	
45	SUNDRIES	\$ 400.00	\$ 86.96
TOTAL SPARE PARTS CHARGES		: \$ 27,389.00	\$15,197.84
TOTAL LABOUR CHARGES		: \$ 9,522.00	\$ 4,072.00
GRAND TOTAL		: \$ 36,911.00	\$ 19,269.84

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

08/08 Taufik. Resurvey 12pm

Put in file pls.

AW.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

SGS20696

Material List for Accident Vehicle Regn No. ~~SL 0010 R~~

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
1	BUMPER COVER <i>deformed</i>	\$ 2,650.00	✓
2	FIXING PARTS FOR BUMPER <i>new</i>	\$ 464.00	x
3	BUMPER CLIP SET <i>new</i>	\$ 43.00	✓
4	GRILLE - LOWER CENTRE <i>new</i>	\$ 112.00	x
5	ADAPTER - LH/RH	2 \$ 64.00	x
6	CLOSING ELEMENT	\$ 188.00	x
7	SPOILER	\$ 216.00	x
8	SPOILER PRIMED	\$ 817.00	x
9	RADIATOR GRILLE	\$ 1,697.00	x
10	AIR GUIDE GRILLE SATIN BLACK <i>? new</i>	\$ 434.00	?
11	WHEEL SPOILER - LH FRONT <i>?</i>	\$ 232.00	?
12	COVER CAP <i>new</i>	\$ 49.00	x
13	GUIDE PIECE - LH/RH <i>LH damaged</i>	2 \$ 64.00	32
14	FOAM FILLER PIECE	\$ 203.00	x
15	SIDE REINFORCEMENT	\$ 702.00	x
16	BUMPER COVER	\$ 105.00	x
17	CAUTION' SIGN STICKER	\$ 12.00	x
18	STICKER FOR AIR CONDITIONER <i>new</i>	\$ 17.00	x
19	BRACE - (LH/RH) <i>LH Bent</i>	2 \$ 50.00	25,
20	SENSOR PRIMED <i>new</i>	2 \$ 392.00	x
SUB - TOTAL SPARE PARTS CHARGES :		\$ 8,511.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SGS 2069 G

S/N	Parts Description	Damaged Parts & Prices		Remark
		S/	Nett	
21	FRONT FENDER - LH <i>Distorted</i>	\$	1,220.00	✓
22	ATTACHMENT PARTS FOR FENDER ?	\$	88.00	?
23	STONE GUARD FILM WING DOOR <i>NE</i>	\$	105.00	x
24	BRACE WING - LH ? <i>bd</i>	\$	72.00	?
25	STONE CHIP GUARD <i>new</i>	\$	63.00	✓
26	ADHESIVE TAPE ?	\$	49.00	?
27	WHEEL HOUSING LINER - LH <i>new</i>	\$	246.00	x
28	ATTACHMENT PARTS FOR WHEEL LINER <i>new</i>	\$	62.00	^
29	BONNET <i>Distorted</i>	\$	4,771.00	✓
30	ATTACHMENT PARTS FOR BONNET ?	\$	153.00	?
31	CATCH HOOK ?	\$	122.00	x
32	LOCK BAR <i>new</i>	\$	44.00	x
33	CATCH HOOK <i>new</i>	\$	15.00	^
34	LID LOCK WITH MICRO-SWITCH <i>new</i>	\$	188.00	+
35	STOP BUFFER	2 \$	50.00	+
36	MOUNT FOR MAIN HEADLIGHT-LH ?	\$	103.00	?
37	LED HEADLIGHT - LH <i>cauld</i>	\$	8,386.00	✓
38	POWER MODULE FOR DAY RUNNING LIGHT <i>new</i>	\$	501.00	?
39	POWER MODULE FOR DIPPED BEAM ? <i>new</i>	\$	486.00	?
40	FAN FOR HEADLIGHT - LH ?	\$	345.00	?
SUB - TOTAL SPARE PARTS CHARGES :			<u>\$ 17,069.00</u>	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SG5 2069 G.

S/N	Parts Description	Damaged Parts & Prices	
		S/Nett	Remark
41	LIFT CYLINDER - LH <i>HEHE</i> <i>am</i>	\$ 208.00	R.
42	LOCK CARRIER FOR COOLANT RADIATOR ?	\$ 1,024.00	?
43	COOLANT CONCENTRATE ?	4 \$ 133.00	?
44	COVER <i>HEHE</i>	\$ 44.00	X
45	SUNDRIES ?	\$ 400.00	?
TOTAL SPARE PARTS CHARGES		: \$ 27,389.00	
TOTAL LABOUR CHARGES		: \$ 9,522.00	
GRAND TOTAL		: \$ 36,911.00	

All charges are not inclusive of GST.

Legend: Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 7 November 2018 3:41 PM
To: 'Boo seng yak'; Carrine Leong; jiayee.yap@premiumauto.com.sg; Chang Chee Sing; SUR
Subject: RE: FINAL REVISION - SGS2069G - OD - SURVEYED 24 JUL 18

Dear Mr Boo,

Confirm repair cost of \$19,269.84 before excess \$400 and GST @ 6 days of repairs.

Kindly send us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Boo seng yak <boojohnny@gmail.com>

Sent: Monday, 8 October 2018 12:14 PM

To: Adrian Ling (LKKAUTO) <adrianling@lkkauto.com>; Veron Chen (LKKAUTO) <veronchen@lkkauto.com>; SUR <sur@lkkauto.com>; Carrine Leong <carrine.leong@premiumauto.com.sg>; jiayee.yap@premiumauto.com.sg; Chang Chee Sing <claims@premiumauto.com.sg>

Subject: FINAL REVISION - SGS2069G - OD - SURVEYED 24 JUL 18

Hi Adrian and all,

Revised estimate and re-survey docs attached.

Please confirm repair cost of \$19,269.84 @ 6 days of repairs exclude 1 PH and 1 Sunday.

Your early closure is well appreciated.

Best regards - jb

Premium Automobiles

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Motor Claims Dept
Yr Ref: SGS 2069 G

Norah Khai
6768 9911
6841 1183
Nora.khai@premiumauto.com.sg
Body & Paint Dept
PA/OD/0845/2018/MAS

29 Nov 2018

from
Telephone +65-
Telefax +65-
EMail
Our department
Our Ref
Your Ref
Date

Dear Sir,

RE: INSURANCE CLAIM FOR SGS 2069 G, Audi A6 1.8 TFSI S-tro

With reference to the above-mentioned vehicle, no. **SGS 2069 G**, claimant, **Mr. Jaafar Bin Mohamed**, please find the related document per attached.

1. A copy of the Original invoice no. 85013164 – S\$20,190.73
2. A copy of the Discharge Voucher duly signed by client.

Based on the above document, we would appreciate you could expedite the payment soonest possible.

If you require any further clarification, please do not hesitate to contact me at 6768 9911.

Regards

This is a computer-generated document. No signature is required.

Norah Khai
Claims Dept

Encls

AIG – SGS 2069 G

total pages

Premium Automobiles Pte Ltd
Showroom
9 Leng Kee Road
Singapore 159090
Telephone (65) 6566 1111
Telefax (65) 6471 3733

Service & Parts Centres
55 Ubi Rd 1
Singapore 408699
Telephone (65) 6336 2323
Telefax (65) 684 1183

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	25 Jul 2018 14:20		25 Jul 2018 12:12 Edit Adj Rpt	S\$19,269.84 Edit Estimates	S\$19,269.84 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	JAAFAR BIN MOHAMED, ID: S7309786Z, Tel: +6598520060								
Vehicle Reg. No.:	SGS2069G	Date of Loss:	24/07/2018 06:00 - :59 [4 Months and 23 Days From LTA Reg Date (Man Yr)]						
Claim Type:	OD / 5892428828SG	Policy/Cover Note No.:	1800019597 (Comprehensive)						
		Excess:	S\$400.00						
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000 ... [Handled by Dally Amri, Mimi Zarina] MimiZarina,DallyAmri@aig.com								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 03/08/2018]								
Driver/Custodian:	ZURIANEE ZAINAL (42 / Female), NRIC: S7620345H, Tel: +6598520060								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- AIG_SG (27/07/2018): Alert - Adj Mandate Approved (S\$21262.00) - SGS2069G - Claim Handler: Dally Amri... - AIG_SG (26/07/2018): SGS2069G / OD / 24/07/2018 / Coverage & Excess update									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGS2069G (5892428828SG)
OD**

**Jul 24 2018 6:00AM
[JAAFAR BIN MOHAMED]
Premium Automobiles Pte Ltd**

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View Use Viewer		
Video															1 per page		☒
No	Finalized On	Premium Automobiles Pte Ltd (UBI)													Thumbnail	Print	
1	24/07/18 12:49	Video - Accident [Linked Accident Report Documents]												1	Load MP4		
Assessment Reports															1 per page		☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print	
1	26/07/18 15:51	Adjuster Immediate Advice												1	Load HTM		
Photos/Images															3 per page		☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)													Thumbnail	Print	
1	25/07/18 14:22	General View												1	Load JPG	☒	
2	25/07/18 14:22	General View												1	Load JPG	☒	
3	25/07/18 14:22	General View												1	Load JPG	☒	
4	25/07/18 14:22	General View												1	Load JPG	☒	
5	25/07/18 14:22	General View												1	Load JPG	☒	
6	25/07/18 14:22	General View												1	Load JPG	☒	
7	25/07/18 14:22	General View												1	Load JPG	☒	
8	25/07/18 14:22	General View												1	Load JPG	☒	
9	25/07/18 14:22	General View												1	Load JPG	☒	
10	25/07/18 14:22	General View												1	Load JPG	☒	
11	25/07/18 14:22	General View												1	Load JPG	☒	
12	25/07/18 14:22	General View												1	Load JPG	☒	
13	25/07/18 14:22	General View												1	Load JPG	☒	
14	25/07/18 14:22	General View												1	Load JPG	☒	
15	25/07/18 14:22	General View												1	Load JPG	☒	
16	25/07/18 14:22	General View												1	Load JPG	☒	
17	25/07/18 14:22	General View												1	Load JPG	☒	
18	25/07/18 14:22	General View												1	Load JPG	☒	
19	25/07/18 14:22	General View												1	Load JPG	☒	
20	25/07/18 14:22	General View												1	Load JPG	☒	
21	25/07/18 14:22	General View												1	Load JPG	☒	
22	25/07/18 14:22	General View												1	Load JPG	☒	
23	25/07/18 14:22	General View												1	Load JPG	☒	
24	25/07/18 14:22	General View												1	Load JPG	☒	
25	25/07/18 14:22	General View												1	Load JPG	☒	
26	25/07/18 14:22	General View												1	Load JPG	☒	
27	25/07/18 14:22	General View												1	Load JPG	☒	
28	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
29	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
30	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
31	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
32	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
33	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
34	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
35	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	
36	07/11/18 14:28	Reinspection Photo												1	Load JPG	☒	

37	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
38	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
39	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
40	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
41	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
42	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
43	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
44	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
45	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
46	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
47	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
48	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
49	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
50	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
51	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
52	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
53	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
54	07/11/18 14:28	Reinspection Photo	1	Load JPG	☒
Documentation			1 per page	☒	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	25/07/18 14:21	Singapore Accident Statement	1	Load PDF	
2	25/07/18 14:21	Certificate of Insurance	1	Load PDF	
3	25/07/18 14:21	Driver's Driving License	1	Load PDF	
4	26/07/18 14:52	MARK ESTIMATE	1	Load PDF	
5	04/12/18 09:55	WORKSHOP INVOICE	1	Load PDF	
6	04/12/18 09:55	DISCHARGE VOUCHER	1	Load PDF	

Linked Accident Report Documents

			View	Use Viewer	
Video			1 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	24/07/18 12:49	Video - Accident	1	Load MP4	
Assessment Reports			1 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	24/07/18 12:55	Accident Statement	1	Load HTM	
Photos/Images			3 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	24/07/18 12:45	Accident Photo	1	Load JPG	☒
2	24/07/18 12:45	Accident Photo	1	Load JPG	☒
3	24/07/18 12:45	Accident Photo	1	Load JPG	☒
4	24/07/18 12:45	Accident Photo	1	Load JPG	☒
5	24/07/18 12:45	Accident Photo	1	Load JPG	☒
6	24/07/18 12:45	Accident Photo	1	Load JPG	☒
7	24/07/18 12:45	Accident Photo	1	Load JPG	☒
8	24/07/18 12:45	Accident Photo	1	Load JPG	☒
9	24/07/18 12:45	Accident Photo	1	Load JPG	☒
10	24/07/18 12:45	Accident Photo	1	Load JPG	☒
Documentation			1 per page	☒	
No	Finalized On	Premium Automobiles Pte Ltd (UBI)		Thumbnail	Print
1	24/07/18 12:38	Sketch Plan	1	Load JPG	☒
2	24/07/18 12:38	Sketch Plan #2	1	Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co Reg No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18013506/AVBN2

Date: 04/12/2018

REFERENCE

Insured/Claimant: JAAFAR BIN MOHAMED Policy No: 1800019597
Date of Loss: 24/07/2018 Nature of Claim: OD Claim No: 5892428828SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGS2069G
Make & Model: AUDI A6, 1.8 TFSI S-tronic (A)
Reg. Date: 01/03/2018 (Man. Year: 2016)
Colour: Brown
Engine Capacity: 1798 cc
Market Value/New Car Price: S\$205,000.00
Sum Insured (S\$): Market Value/New Car Price

Engine No: CYG018412
Chassis No: WAUZZZ4G8HN081687
Odometer: 7721 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R17 Rear Tyre Size: 225/55R17
Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	27,389.00	15,197.84	12,191.16	44.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	9,522.00	4,072.00	5,450.00	57.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	36,911.00	19,269.84	17,641.16	47.79
- Excess (S\$)	400.00	400.00	0.00	0.00
(S\$)	36,511.00	18,869.84	17,641.16	48.32
+ GST 7.00/7.00% (S\$)	2,555.77	1,320.89	1,234.88	48.32
Nett Amount (S\$)	39,066.77	20,190.73	18,876.04	48.32

INSPECTION

Date of Assignment: 25/07/2018

Date Inspected: 24/07/2018 Inspected At:

Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Deformed	2,650.00 FS	*2,120.00 FS
2	1		*FIXING PARTS FOR BUMPER	Not Necessary	464.00 FS	*- FS
3	1		*BUMPER CLIP SET	Necessary	43.00 FS	*34.40 FS
4	1		*GRILLE-LOWER CENTRE	Not Necessary	112.00 FS	*- FS
5	2		*ADAPTER-LH/RH	Not Necessary	64.00 FS	*- FS
6	1		*CLOSING ELEMENT	Not Necessary	188.00 FS	*- FS
7	1		*SPOILER	Not Necessary	216.00 FS	*- FS
8	1		*SPOILER PRIMED	Not Necessary	817.00 FS	*- FS
9	1		*RADIATOR GRILLE	Not Necessary	1,697.00 FS	*- FS
10	1		*AIR GUIDE GRILLE SATIN BLACK	Cut	434.00 FS	*347.20 FS
11	1		*WHEEL SPOILER-LH FRONT	Not Necessary	232.00 FS	*- FS
12	1		*COVER CAP	Not Necessary	49.00 FS	*- FS
13	1		*GUIDE PIECE-LH/RH	N/s Damaged	64.00 FS	*25.36 FS
14	1		*FOAM FILLER PIECE	Not Necessary	203.00 FS	*- FS
15	1		*SIDE REINFORCEMENT	Not Necessary	702.00 FS	*- FS
16	1		*BUMPER COVER	Not Necessary	105.00 FS	*- FS
17	1		*CAUTION SIGN STICKER	Not Necessary	12.00 FS	*- FS
18	1		*STICKER FOR AIR CONDITIONER	Not Necessary	17.00 FS	*- FS
19	1		*BRACE-LH/RH	N/s Bent	50.00 FS	*19.92 FS
20	2		*SENSOR PRIMED	Not Necessary	392.00 FS	*- FS
21	1		*FRONT FENDER-LH	Distorted	1,220.00 FS	*976.00 FS
22	1		*ATTACHMENT PARTS FOR FENDER	Not Necessary	88.00 FS	*- FS
23	1		*STONE GUARD FILM WING DOOR	Not Necessary	105.00 FS	*- FS
24	1		*BRACE WING-LH	Bent	72.00 FS	*57.28 FS
25	1		*STONE CHIP GUARD	Necessary	63.00 FS	*49.92 FS
26	1		*ADHESIVE TAPE	Not Necessary	49.00 FS	*- FS
27	1		*WHEEL HOUSING LINER-LH	Not Necessary	246.00 FS	*- FS
28	1		*ATTACHMENT PARTS FOR WHEEL LINER	Not Necessary	62.00 FS	*- FS
29	1		*BONNET	Dented	4,771.00 FS	*3,816.80 FS
30	1		*ATTACHMENT PARTS FOR BONNET	Not Necessary	153.00 FS	*- FS
31	1		*CATCH HOOK	Not Necessary	122.00 FS	*- FS
32	1		*LOCK BAR	Not Necessary	44.00 FS	*- FS
33	1		*CATCH HOOK	Not Necessary	15.00 FS	*- FS
34	1		*LID LOCK WITH MICRO-SWITCH	Not Necessary	188.00 FS	*- FS
35	2		*STOP BUFFER	Not Necessary	50.00 FS	*- FS
36	1		*MOUNT FOR MAIN HEADLIGHT-LH	Not Necessary	103.00 FS	*- FS
37	1		*LED HEADLIGHT-LH	Cracked	8,386.00 FS	*6,708.80 FS
38	1		*POWER MODULE FOR DAY RUNNING-LIGHT	Damaged	501.00 FS	*400.40 FS
39	1		*POWER MODULE FOR DIPPED BEAM	Damaged	486.00 FS	*388.80 FS
40	1		*FAN FOR HEADLIGHT-LH	Not Necessary	345.00 FS	*- FS
41	1		*LIFT CYLINDER-LH	Cracked	208.00 FS	*166.00 FS
42	1		*LOCK CARRIER FOR COOLANT RADIATOR	Not Necessary	1,024.00 FS	*- FS
43	4		*COOLANT CONCENTRATE	Not Necessary	133.00 FS	*- FS
44	1		*COVER	Not Necessary	44.00 FS	*- FS
45	1		*SUNDRIES	Necessary	400.00 FS	*86.96 FS
					Total Parts (\$\$)	27,389.00 15,197.84

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS,OUTSIDE TEMPERATURE SENSOR,HEADLIGHT WASHER ASSY AND FRONT PARKING AID	New	480.00	480.00
2	TO REMOVE AND TRANSFER AIR CON CONDENSER,RADIATOR,ADDITIONAL RADIATOR ELECTRICAL FANS AND CONTROL UNIT.TO CARRY OUT VACUUM/REGAS AND TO PRESSURISE COOLING SYSTEM	New	1,100.00	-
3	TO DISMANTLE AND RENEW FRONT BUMPER,LHS HEADLIGHT,LHS FRONT FENDER AND BONNET.RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	5,250.00	1,750.00
4	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER AND BONNET	New	2,500.00	1,650.00
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
Gross Labour Cost (\$\$)			9,522.00	4,072.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >