

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Janice Goh

Date: 30 Jul 2018

Preliminary Advice

Vehicle No	: SKW6175M	Accident Date	: 23/07/2018
Make	: VOLKSWAGEN TIGUAN	Policy No.	: MPC17A00481501
Assignment Date	: 24/07/2018	Excess	: S\$500.00
Date of Inspection	: 26/07/2018	Est. Duration of Repair	: 3 days
Inspection At	: Falcon-Air Auto Services Pte Ltd (Pandan) No 8 Pandan Loop Singapore		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,744.30
Revised Amount	:S\$	1,818.80
Check Items (Estimated)	:S\$	665.50
Total	:S\$	2,484.30
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	20,000.00
COE / PARF Rebate	:S\$	13,581.00
Salvage Value	:S\$	
Margin for Repair	:S\$	6,419.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :