Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 21 August 2018 5:07 PM

To:

'Daniel Jude'; SUR; Admin-D (LKKAuto); Admin A

Cc:

TPY Insurance Team

Subject:

RE: SBA9128C - OD RECOVERY - AIG INSURED - (TP) - (SLX6092B) - (AIG

INSURED) - (COMMON INSURED) - FINALIZED

Dear Daniel,

Confirmed amount \$1170 before excess \$500 and GST @ 3 working days.

Kindly forward us invoice and discharge voucher for us to close file.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Daniel Jude <danieljude@motorimage.net>

Sent: Tuesday, 21 August 2018 4:36 PM

To: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: SBA9128C - OD RECOVERY - AIG INSURED - (TP) - (SLX6092B) - (AIG INSURED) - (COMMON INSURED) -

FINALIZED

Importance: High

Hi Guo Qiang,

Attached for your reference and follow up.

Kindly reply to all for easier follow up action

Thank You.

Best Regards Daniel A Jude

Service Executive

Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com: www.motorimage.net















Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

Veron Chen (LKKAuto)

From:

Veron Chen (LKKAuto)

Sent:

Tuesday, 28 August 2018 11:53 AM

To:

'Katherine Chong'; Guo Qiang (LKKAuto); Admin-D (LKKAuto); Admin A

Cc:

TPY Insurance Team

Subject:

RE: SBA9128C - OD RECOVERY - AIG INSURED - (TP) - (SLX6092B) - (AIG

INSURED) - (COMMON INSURED) - INVOICED

Dear Katherine,

Noted with thanks.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Katherine Chong <katherinechong@motorimage.net>

Sent: Tuesday, 28 August 2018 10:45 AM

To: Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: TPY Insurance Team <tpyinsteam@tanchong.org>

Subject: RE: SBA9128C - OD RECOVERY - AIG INSURED - (TP) - (SLX6092B) - (AIG INSURED) - (COMMON INSURED) - INVOICED

Hi Teams,

Please find the attached file for your reference.

Thank You.

Best regards, Katherine Chong

Senior Admin Assistant

Motor Image Enterprises Pte Ltd

19 Toa Payoh Lorong 8, Singapore 319255 Tel: +65-6703 8333 DID: +65-6703 8115

Fax: +65-6253 5535

Email: katherinechong@motorimage.net

Website: www.tanchong.com: www.motorimage.net

From: Daniel Jude

Sent: Tuesday, August 21, 2018 4:36 PM

To: SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Cc: TPY Insurance Team < tpyinsteam@tanchong.org>

Subject: SBA9128C - OD RECOVERY - AIG INSURED - (TP) - (SLX6092B) - (AIG INSURED) - (COMMON INSURED) -

FINALIZED

Importance: High

Hi Guo Qiang,

Attached for your reference and follow up.

Kindly reply to all for easier follow up action

Thank You.

Best Regards

Daniel A Jude

Service Executive


Motor Image Enterprises Pte Ltd

19 Lorong 8 Toa Payoh Singapore 319255

HP: 8611 3195

Email: danieljude@motorimage.net

Website: www.tanchong.com: www.motorimage.net





Disclaimer: This e-mail is confidential. It may also be legally privileged. If you are not the addressee you may not copy, forward, disclose or use any part of this message. If you have received this message in error, please delete it and all copies from your system and notify the sender immediately by return e-mail. Internet communications cannot be guaranteed to be timely, secure, error-free or virus-free. The sender does not accept liability for any errors or omissions.

To stop receiving messages from TPY Insurance Team group, stop following it.



19 Lorong 8 Toa Payoh Singapore 319255

Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535 25 Leng Kee Road Singapore 159097

Service Centre Tel: (65) 6703 8163 Fax: (65) 6479 1137

Website: www.motorimage.net

SUBARU

TAX INVOICE

GST Reg No. M2-0076975-9 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L481946 For cash sales, payment will be

endorsed on this invoice and no separate receipt will be issued.

DATE REC'D: 30-Jul-2018 SERVICE ADVISOR: KUAN

JOB No.: L484915 MILEAGE: 3357

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD

ADDRESS: 78 SHENTON WAY

#07-16 AIG BUILDING. S(079120)

TELEPHONE: 91007211

MODEL: FORESTER 2.0I-L AWD CVT ENGINE No.: FB20YD87262 CHASSIS No.: JF1SJ5KC5JG110029 **REGISTRATION No.: SBA9128C**

ITEN	4S CODE	DESCRIPTION OF REPAIRS	AMOUNT
1	ODRECO	TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY)	
2	REMARK	CONDUCT OD CLAIM AIG LOCATION: GEYLANG LORONG 1	
		DATE:14/07/2018 TIME:1855HRS	
3	INS01	FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN	
		ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
4	INS02	IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO	
		STANDARD RATE CHART (REF. 0338).	
5	INS03	STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM	
		THE DATE OF CONFIRMATION OF AUTHORISATION BY THE	
6	INS04	SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT	
		THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD.	
7	INS05	INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF	
		IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM	
8	INS06	THE OWNER IS REQUIRED.	
9	INS07	CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF	
		DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING:	
10	INS08	NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO.	
		APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED	
11	INS09	CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE	
		WILL HAVE TO BE REFER TO FIDREC DIRECTLY.	
12	REMARK	REPAIR/REPLACE REAR BUMPER AND PANEL	250.00
13	REMARK	RESPRAY REAR BUMPER AND PANEL	200.00
14	REMARK	SUNDRIES	20.00
		TOTAL(LABOUR)	470.00
1		BUMPER FACE REAR FORESTER IL	378.00
		57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%))	
2		CARGO STEP PANEL S/S	322.00
		E7710SG000(Qty: 1 @ 460.00 each(Discount 30.00%))	



19 Lorong 8 Toa Payoh Singapore 319255 Service Centre Tel (65) 64170100/101 Fax (65) 62535535 25 Leng Kee Road Singapore 159097 Service Centre Tel (65) 64764776 Fax (65) 64791137

Website: www.motorimage.net

SUBARU

TAX INVOICE

GST Reg No. M2-0076975-9 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L481946
For cash sales, payment will be endorsed on this invoice and no separate receipt will be issued.

DATE REC'D: 30-Jul-2018 SERVICE ADVISOR: KUAN

JOB No.: L484915 MILEAGE: 3357

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD

ADDRESS: 78 SHENTON WAY

#07-16 AIG BUILDING. S(079120)

TELEPHONE: 91007211

MODEL: FORESTER 2.0I-L AWD CVT ENGINE No.: FB20YD87262

CHASSIS No.: JF1SJ5KC5JG110029 REGISTRATION No.: SBA9128C

ITEMS CODE

DESCRIPTION OF REPAIRS

TOTAL(SPARE PARTS)

700.00

less INSURANCE EXCESS

500.00

Subtotal GST(7%)

670.00 46.90

TOTAL

\$716.90

DATE: 23-Aug-2018

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Cor,



19 Lorong 8 Toa Payoh Singapore 319255 T (65) 6417 0333 F (65) 6252 5655 W www.motorimage.net

Co Reg No: 198702032R

DISCHARGE VOUCHER

Name of Insured:	SNG MENG LIANG		
Address of Insured:	35 JALAN MANIS SI	NGAPORE 329270	
Name of Repairs:	MOTOR IMAGE ENTE	RPRISES PTE LTD / WO	RKSHOP
Address of Repairs:	NO. 19 LORONG 8 TO	DA PAYOH SINGAPORE 3	319225
Place of Accident:	JUNCTION OF GEY	LANG LRG 1 AND SIMS	SAVENUE
Date of Accident:	14/07/2018	Vehicle No:	SBA9128C
Policy No:18000	73375	Claim No:	
I/We agree that by virtue Vehicle are subrogated I/We hereby grant the sall or any of such rights I/We further agree to fur exercising such rights a	abovementioned date and place of such payment, all my/outo the said Insurers in accordand insurers the authority to and remedies including the insish the said Insurers with a not remedies whilst on their parising in connection with an	ace. It rights and remedies in respect dance with the laws governing use my/our name to the extent right to give discharge and rece	necessary to effectively exercise eipts therefore. easonably require of me/us when ne/us against liability for costs
REPAIRERS:	(c)	INSURED:	S1125615E
Company's Chop &	Signature	IC No. & Signa	ture/Company's Chop
KATHER	RINE CHONG	SN Name	IG MENG LIANG
01/08/	2018	Date	01/08/2018







19 Lorong 8 Toa Payoh Singapore 319255

Service Centre Tel: (65) 6703 8101 / 102 Fax: (65) 6253 5535

GWb (S)

25 Leng Kee Road Singapore 159097

Service Centre Tel: (65) 6703 8163 Fax: (65) 6479 1137

Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L481946 For cash sales, payment will be endorsed on this invoice and no separate receipt will be issued.

DATE REC'D: 30-Jul-2018 SERVICE ADVISOR: KUAN

JOB No.: L484915 MILEAGE: 3357

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD

ADDRESS: 78 SHENTON WAY

#07-16 AIG BUILDING. S(079120)

TELEPHONE: 91007211

MODEL: FORESTER 2.0I-L AWD CVT ENGINE No.: FB20YD87262 CHASSIS No.: JF1SJ5KC5JG110029

REGISTRATION No.: SBA9128C

ODRECO	ITEM	IS CODE	DESCRIPTION OF REPAIRS	AMOUNT
DATE:14/07/2018 TIME:1855HRS	1	ODRECO	TO CONDUCT BODYWORK REPAIR (OWN DAMAGE RECOVERY)	
DATE: 14/07/2018 TIME: 1855HRS FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE INS02 IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338). INS03 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INS06 THE OWNER IS REQUIRED. INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL REMARK RESPRAY REAR BUMPER AND PANEL SUNDRIES TOTAL(LABOUR) BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S 322.00	2	REMARK	CONDUCT OD CLAIM AIG LOCATION: GEYLANG LORONG 1	
INSO1 FOR ACCIDENT CAR OR REPAIR JOB QUOTATION, AN ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338). INSO3 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE STANDARD RATE CHART (REF. 0338). INSO4 SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INSO5 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INSO6 THE OWNER IS REQUIRED. CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL REMARK SUNDRIES TOTAL(LABOUR) BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S 322.00			DATE:14/07/2018 TIME:1855HRS	
ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE INSO2 IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO STANDARD RATE CHART (REF. 0338). INSO3 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INSO5 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INSO6 THE OWNER IS REQUIRED. INSO7 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED INSO9 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 250.00 REMARK RESPRAY REAR BUMPER AND PANEL 200.00 REMARK SUNDRIES TOTAL (LABOUR) 470.00 BUMPER FACE REAR FORESTER IL 378.00 TOTAL(LABOUR) 322.00 ARGO STEP PANEL S/S 322.00	3	INS01		
STANDARD RATE CHART (REF. 0338). INS03 STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INS06 THE OWNER IS REQUIRED. INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL REMARK RESPRAY REAR BUMPER AND PANEL REMARK SUNDRIES TOTAL(LABOUR) BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S 322.00	20.550		ADMINISTRATIVE CHARGE WILL BE IMPOSED IF VEHICLE	
STORAGE CHARGES OF \$30/DAY WILL BE IMPOSED FROM THE DATE OF CONFIRMATION OF AUTHORISATION BY THE SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INSO5 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INSO6 THE OWNER IS REQUIRED. INSO7 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED UST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL REMARK RESPRAY REAR BUMPER AND PANEL TOTAL(LABOUR) BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S 322.00	4	INS02	IS WITHDRAW AND TOWED OUT FOR REPAIR. REFER TO	
THE DATE OF CONFIRMATION OF AUTHORISATION BY THE INSO4 SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INSO5 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INSO6 THE OWNER IS REQUIRED. INSO7 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: INSO8 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED INSO9 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL REMARK RESPRAY REAR BUMPER AND PANEL TOTAL(LABOUR) BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S 322.00				
THE DATE OF CONFIRMATION OF AUTHORISATION BY THE SURVEYOR SHOULD THE OWNER DECIDE NOT TO CARRY OUT THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. INSO5 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM INSO6 THE OWNER IS REQUIRED. INSO7 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: NO.0F DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. REMARK REPAIR/REPLACE REAR BUMPER AND PANEL REMARK RESPRAY REAR BUMPER AND PANEL TOTAL(LABOUR) BUMPER FACE REAR FORESTER IL 57704SG012(Qty : 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S	5	INS03		
THE REPAIR IN MOTORIMAGE ENTERPRISES PTE LTD. 7 INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM 8 INS06 THE OWNER IS REQUIRED. 9 INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: 10 INS08 NO.0F DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED 11 INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 13 REMARK RESPRAY REAR BUMPER AND PANEL 250.00 14 REMARK SUNDRIES TOTAL(LABOUR) 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00				
7 INS05 INSTRUCTIONS WILL BE TAKEN FROM THE OWNER ONLY. IF IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM 8 INS06 THE OWNER IS REQUIRED. 9 INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: 10 INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED 11 INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 250.00 13 REMARK RESPRAY REAR BUMPER AND PANEL 200.00 14 REMARK SUNDRIES 20.00 14 REMARK SUNDRIES 378.00 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty : 1 @ 540.00 each(Discount 30.00%)) 378.00 2 CARGO STEP PANEL S/S 322.00	6	INS04	이 가는 그리는 아이들이 가는 것이 되었다. 그는 그는 그리는 것이 되었다면 하는 것이 되었다. 그리고 있다면 하는 것이 되었다면 하는 것이 없는 것이 없는 것이다.	
IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM				
IT IS NOT POSSIBLE, AN AUTHORISATION LETTER FROM 8 INS06 THE OWNER IS REQUIRED. 9 INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: 10 INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED 11 INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 13 REMARK RESPRAY REAR BUMPER AND PANEL 14 REMARK SUNDRIES TOTAL(LABOUR) 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00	7	INS05		
9 INS07 CUSTOMER ARE INFORMED AND ACCEPT THAT NUMBER OF DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: 10 INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO. APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED 11 INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 13 REMARK RESPRAY REAR BUMPER AND PANEL 14 REMARK SUNDRIES TOTAL(LABOUR) 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00				
DAYS FOR LOSS OF USE IS BASE ON THE FOLLOWING: 10 INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO.	8	INS06		
10 INS08 NO.OF DAYS FOR LOSS OF USE RECOMMENDED BY INS.CO.	9	INS07	(
APPOINTED SURVEYOR NO FURTHER CLAIM CAN BE ALLOWED 11 INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 13 REMARK RESPRAY REAR BUMPER AND PANEL 14 REMARK SUNDRIES TOTAL(LABOUR) 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00				
11 INS09 CUST ACK THAT CLAIMS NOT EXCEEDING \$3,000 & ABOVE WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 250.00 13 REMARK RESPRAY REAR BUMPER AND PANEL 200.00 14 REMARK SUNDRIES TOTAL(LABOUR) 470.00 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty : 1 @ 540.00 each(Discount 30.00%)) 378.00 2 CARGO STEP PANEL S/S 322.00	10	INS08		
WILL HAVE TO BE REFER TO FIDREC DIRECTLY. 12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 250.00 13 REMARK RESPRAY REAR BUMPER AND PANEL 200.00 14 REMARK SUNDRIES TOTAL(LABOUR) 470.00 1 BUMPER FACE REAR FORESTER IL 378.00 157704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00				
12 REMARK REPAIR/REPLACE REAR BUMPER AND PANEL 250.00 13 REMARK RESPRAY REAR BUMPER AND PANEL 200.00 14 REMARK SUNDRIES TOTAL(LABOUR) 470.00 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 378.00 2 CARGO STEP PANEL S/S 322.00	11	INS09		
12 REMARK RESPRAY REAR BUMPER AND PANEL 200.00 14 REMARK SUNDRIES TOTAL(LABOUR) 20.00 157704SG012(Qty : 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00				250.00
14 REMARK SUNDRIES TOTAL(LABOUR) 20.00 470.00 1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty : 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00			5 B () () () () () () () () () (
1 BUMPER FACE REAR FORESTER IL 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 378.00	0.000		[- 5.47; The BOOK 1 1 1 1 1 1 1 1 1	57,577
1 BUMPER FACE REAR FORESTER IL 378.00 57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00	14	REMARK		
57704SG012(Qty : 1 @ 540.00 each(Discount 30.00%)) CARGO STEP PANEL S/S 322.00			TOTAL(LABOUR)	470.00
57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%)) 2 CARGO STEP PANEL S/S 322.00	1		BUMPER FACE REAR FORESTER IL	378.00
2 CARGO STEP PANEL S/S 322.00	ACC.		57704SG012(Qty: 1 @ 540.00 each(Discount 30.00%))	
	2		19 M PROBLEM AND MANAGEMENT AND	322.00
			E7710SG000(Qty: 1 @ 460.00 each(Discount 30.00%))	



19 Lorong 8 Toa Payoh Singapore 319255 Service Centre Tel (65) 64170100/101 Fax (65) 62535535 25 Leng Kee Road Singapore 159097 Service Centre Tel (65) 64764776 Fax (65) 64791137

Website: www.motorimage.net



TAX INVOICE

GST Reg No. M2-0076975-9 Co. Reg No. 198702032R

Sales: INSURANCE CUSTOMER

Invoice No: L481946 For cash sales, payment will be endorsed on this invoice and no separate receipt will be issued.

> **DATE REC'D: 30-Jul-2018** SERVICE ADVISOR: KUAN

JOB No.: L484915 MILEAGE: 3357

ID:

NAME: AIG ASIA PACIFIC INSURANCE PTE LTD

ADDRESS: 78 SHENTON WAY

#07-16 AIG BUILDING, S(079120)

TELEPHONE: 91007211

ITEMS CODE

MODEL: FORESTER 2.0I-L AWD CVT

ENGINE No.: FB20YD87262

CHASSIS No.: JF1SJ5KC5JG110029 REGISTRATION No.: SBA9128C

DESCRIPTION OF REPAIRS

TOTAL(SPARE PARTS)

AMOUNT 700.00

less INSURANCE EXCESS

500.00

Subtotal GST(7%) 670.00 46.90

TOTAL

\$716.90

DATE: 23-Aug-2018

CUSTOMER

MANAGER

The customer acknowledges and confirms by taking delivery of the vehicle and/or upon receipt of this invoice, either personally or by an agent that his/her complaints relating to the vehicle have been rectified to his/her satisfaction and that the Company's liability for defective work and/or materials will be limited to rectification works and/or replacement of parts without charge or at discounted charge, at the Company's option. The customer further acknowledges that any discrepancy in this invoice (with the exception of errors and omissions) must be brought to the Company's attention in writing within three(3) days from the date of this invoice failing which it will be deemed correct.

CUSTOMER

Not yet a DUO Member? Join us now at www.DUO.com.sg and start accumulating your points for your invoice today!

Certified True Copy



19 Lorong 8 Toa Payoh Singapore 319255 T (65) 6417 0333 F (65) 6252 5655

W www.motorimage.net

Co Reg No: 198702032R

DISCHARGE VOL	JCHER		
Name of Insured:	SNG MENG LIANG		
Address of Insured	35 JALAN MANIS SIN	IGAPORE 329270	
Name of Repairs:	MOTOR IMAGE ENTER	RPRISES PTE LTD / WO	RKSHOP
Address of Repair	s: NO. 19 LORONG 8 TO	A PAYOH SINGAPORE	319225
Place of Accident:	JUNCTION OF GEYL	ANG LRG 1 AND SIM	S AVENUE
Date of Accident:	14/07/2018	Vehicle No: _	SBA9128C
Policy No:1806	0073375	Claim No:	
all further obligations vehicle on or about the I/We agree that by vin Vehicle are subrogate I/We hereby grant the all or any of such right I/We further agree to fexercising such rights	and liabilities under the aforesaid e abovementioned date and place tue of such payment, all my/our and to the said Insurers in accordance said insurers the authority to us the said insurers the authority to us the said insurers with any furnish the said Insurers with any and remedies whilst on their pats a sarising in connection with any the said insurers with any and remedies whilst on their pats and sarising in connection with any the said insurers with any	d policy in respect on and acce. rights and remedies in respendence with the laws governing the my/our name to the extent that to give discharge and received assistance that they may rest they agree to indemnify meters.	necessary to effectively exercise eipts therefore. easonably require of me/us when ne/us against liability for costs
Company's Chop 8	& Signature	IC No. & Signa	S1125615E ature/Company's Chop
KATHE	CRINE CHONG	SN	NG MENG LIANG
Name		Name	
	8/2018		01/08/2018
Date		Date	



...CLAIM SUBFOLDER...(Pending for Survey Report)

Case	Notified	Est Submitted	Adi Assigned	Adj Rpt		Adj Subi	mitted 1	ins Auth'ed	Status	
	21 Jul 2018		26 Jul 2018 12:10 Edit Adj Rpt	S\$1,170.0 0 Edit Estima	ACCRECATION AND ADDRESS OF THE PARTY OF THE	S\$1,170 View Rp	Section 1997		Pending for Sur Report Cancel Case	
P	lain	Re	ference	T (Claim	Details		Document	s	Show All
CLAIM SUI	BFOLDER D	ETAILS			NAME OF TAXABLE PARTY.		[Created	by insurer]		
Insured:	SNG MEN	G LIANG, ID: S:	1125615E, Tel:	+65932801	38					
Vehicle Reg. No.:	SBA912	18C			Dat	e of Loss:		8 18:00 - :59 From LTA Reg Dat	te (Man Yr)]	
Claim Type:	OD / 5946011252SG				0.000,000,000	licy/Cover	18000733	1800073375 (Comprehensive)		
						ess:	S\$500.00			
Repairer:	Motor In	nage Enterprises	Pte Ltd (Toa Pa	ayoh) 19 Lor	ong 8	Toa Payor	n, 319255 To	oa Payoh - Tel: 67	7038104	
Handling Insurer:	# 100 Mar 10 - Mar 10 M	Pacific Insuranc								(00/2010)
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel:	6256-3561	[Ha	ndled by)	KING GUO	QIANG] [Fin	al Rpt due 06	/08/2018]
Driver/Cust dian:	JULIA SN	G HUINA (24 / Fem	nale), NRIC: S	9345772В,	Tel: +	65828805	49			
ASSOCIAT	ED MAIL R	ECEIVED						_	/iew All Comp	ose Case Mai
 AIG_SG 	(26/07/2018)	: SBA9128C / OI	0 / 14/07/201	8 / Coverag	e & E	xcess up	date			
ALL ASSO	CIATED TA	sks⊡					View All	Search Tasks	Create New Tas	Complete
Due Date	e Priority	Type Task	Group Sub	ject Han	dler	Assign	ned By	Completed On	Created C	n Done
No results.										

Claim Documents

*SBA9128C (5946011252SG)
OD
Jul 14 2018 6:55PM
[SNG MENG LIANG]
Motor Image Enterprises Pte Ltd

Pho	tos/Images		3 per pa	age v	•
10000	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1	Thumbnail	Print
No 1	27/07/18 08:42	General View	0	Load JPG	•
2	27/07/18 08:42	General View	0	Load JPG	•
3	27/07/18 08:42	General View	0	Load JPG	•
4	27/07/18 08:42	General View	0	Load JPG	•
	2000	General View	0	Load JPG	•
5	27/07/18 08:42	- Chale of the College of the Colleg	0	Load JPG	•
6	27/07/18 08:42	General View	0	Load JPG	•
7	27/07/18 08:42	General View	0	Load JPG	•
8	27/07/18 08:42	General View	0	Load JPG	•
9	27/07/18 08:42	General View		The same of the sa	•
10	27/07/18 08:42	General View	0	Load JPG	1000
11	27/07/18 08:42	General View	0	Load JPG	•
12	27/07/18 08:42	General View	0	Load JPG	•
13	27/07/18 08:42	General View	0	Load JPG	•
14	27/07/18 08:42	General View	0	Load JPG	€
15	21/08/18 16:58	Reinspection Photo	0	Load JPG	•
16	21/08/18 16:58	Reinspection Photo	0	Load JPG	•
17	21/08/18 16:58	Reinspection Photo	0	Load JPG	•
	umentation		1 per p	age V	•
		LKK Auto Consultants Pte Ltd (HQ)	Landara de la contracta de la	Thumbnail	-
No	Relabel/Reorder 27/07/18 08:52	Singapore Accident Statement	0	Load PDF	
2	27/07/18 08:52	Certificate of Insurance	0	Load PDF	
3	27/07/18 08:52	MARK ESTIMATE	0	Load PDF	
4	11/09/18 09:00	DISCHARGE VOUCHER	0	Load PDF	
5	11/09/18 09:00	WORKSHOP INVOICE	0	Load PDF	

Linked Accident Report Documents

		View View	in Brow	rser 🔻
essment Reports		1 per page ▼		•
Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		nbnail	Print
16/07/18 18:17	Accident Statement	① Load	MTH t	
24/07/18 19:02	Addendum Sheet	€ Loa	d JPG	•
	Accident Statement Addm. #1	① Load	MTH t	
	Addendum Sheet	€ Loa	d JPG	•
25/07/18 10:54	Accident Statement Addm. #2	1 Loan	MTH t	
otos/Images		3 per page		•
-	Motor Image Enterprises Pte Ltd (Toa Payoh)	Thur	nbnail	Print
	Finalized On 16/07/18 18:17 24/07/18 19:02 24/07/18 19:02 25/07/18 10:53 25/07/18 10:54	Finalized On	1 per page	Finalized On Motor Image Enterprises Pte Ltd (Toa Payoh) 16/07/18 18:17 Accident Statement 24/07/18 19:02 Addendum Sheet 24/07/18 19:02 Accident Statement Addm. #1 25/07/18 10:53 Addendum Sheet 25/07/18 10:54 Accident Statement Addm. #2 3 per page Thumbnail Load HTM 3 per page

	essment Reports		1 per	1	•
No	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh)		Thumbnail	-
1	16/07/18 18:14	Accident Photo	0	Load JPG	•
2	16/07/18 18:14	Accident Photo	0	Load JPG	•
3	16/07/18 18:14	Accident Photo	0	Load JPG	•
4	16/07/18 18:14	Accident Photo	0	Load JPG	•
5	16/07/18 18:14	Accident Photo	0	Load JPG	•
6	16/07/18 18:14	Accident Photo	0	Load JPG	•
7	16/07/18 18:14	Accident Photo	0	Load JPG	•
8	16/07/18 18:14	Accident Photo	0	Load JPG	•
9	16/07/18 18:14	Accident Photo	0	Load JPG	•
10	16/07/18 18:14	Accident Photo	0	Load JPG	•
11	16/07/18 18:14	Accident Photo	0	Load JPG	•
12	16/07/18 18:14	Accident Photo	0	Load JPG	•
13	16/07/18 18:14	Accident Photo	0	Load JPG	•
14	16/07/18 18:14	Accident Photo	0	Load JPG	•
15	16/07/18 18:14	Accident Photo	0	Load JPG	•
16	16/07/18 18:14	Accident Photo	0	Load JPG	•
17	16/07/18 18:14	Accident Photo	0	Load JPG	•
18	16/07/18 18:14	Accident Photo	0	Load JPG	•
19	16/07/18 18:14	Accident Photo	0	Load JPG	•
20	16/07/18 18:14	Accident Photo	0	Load JPG	•
21	16/07/18 18:14	Accident Photo	0	Load JPG	•
22	16/07/18 18:14	Accident Photo	0	Load JPG	•
23	16/07/18 18:14	Accident Photo	0	Load JPG	•
24	16/07/18 18:14	Accident Photo	0	Load JPG	•
25	16/07/18 18:14	Accident Photo	0	Load JPG	•
26	16/07/18 18:14	Accident Photo	0	Load JPG	•
27	16/07/18 18:14	Accident Photo	0	Load JPG	•
28	16/07/18 18:14	Accident Photo	0	Load JPG	•
29	16/07/18 18:14	Accident Photo	0	Load JPG	•
30	16/07/18 18:14	Accident Photo	0	Load JPG	•
31	16/07/18 18:14	Accident Photo	0	Load JPG	•
32	16/07/18 18:14	Accident Photo	0	Load JPG	•
33	16/07/18 18:14	Accident Photo	0	Load JPG	•
34	16/07/18 18:14	DRIVER LICENSE	0	Load JPG	•
35	16/07/18 18:14	DRIVER LICENSE	0	Load JPG	•
36	16/07/18 18:14	DRIVER NRIC	0	Load JPG	•
37	16/07/18 18:14	DRIVER NRIC	0	Load JPG	•
38	16/07/18 18:14	Accident Photo	0	Load JPG	•
39	16/07/18 18:14	Accident Photo	0	Load JPG	•
40	16/07/18 18:14	Accident Photo	0	Load JPG	•
					1 50
200	cumentation		1 per	page ▼	l Print
No.	Finalized On	Motor Image Enterprises Pte Ltd (Toa Payoh) Accident Sketch Plan	0	Load JPG	Print
1	16/07/18 18:17		0	Load JPG	•
3	16/07/18 18:17	Accident Sketch Plan	o	Load JPG	•
	16/07/18 18:17	OWNER LICENSE AND NRIC		2000 21 0	120

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	116
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd. AIG Building, 78 Shenton Way #07-16

14/07/2018

Singapore 079120

Our File No:

CS/AIG18013520/GVBS2

Date:

11/09/2018

REFERENCE

Date of Loss:

Insured/Claimant:

SNG MENG LIANG

Policy No:

1800073375

Nature of Claim:

OD

Claim No:

5946011252SG

JF1SJ5KC5JG110029

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SBA9128C

Make & Model:

SUBARU FORESTER, 2.0 XT AWD CVT (A) 25/06/2018 (Man. Year: 2018)

Engine No: Chassis No: Odometer:

FB20YD87262

2913 km

Reg. Date: Colour:

White

Engine Capacity: Market Value/New Car Price: 1995 cc \$\$95,000.00

Sum Insured (S\$):

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Good Steering (Serviceable): Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: Front Left Side:

225/60R17

Yokohama 9 mm

Rear Tyre Size: Rear Left Side: Rear Right Side: 225/60R17

Yokohama 9 mm Yokohama 9 mm

Yokohama 9 mm Front Right Side: The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		1,203.20	720.00	483.20	40.16
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,650.00	450.00	1,200.00	72.73
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	483.20 0.00 1,200.00	
1	Calculated Gross Total (S\$)	2,853.20	1,170.00	1,683.20	58.99
	- Excess (S\$)	500.00	500.00	483.20 0.00 1,200.00 0.00 0.00 1,683.20 0.00 1,683.20 117.82	0.00
	(S\$)	2,353.20	670.00	1,683.20	71.53
	+ GST 7.00/7.00% (S\$)	164.72	46.90	1,200.00 0.00 0.00 1,683.20 0.00 1,683.20 117.82	71.53
	Nett Amount (S\$)	2,517.92	716.90	1,801.02	71.53

INSPECTION

Date Inspected:

Date of Assignment:

26/07/2018

Motor Image Enterprises Pte Ltd (Toa Payoh)

25/07/2018 Inspected At:

19 Lorong 8 Toa Payoh

Singapore 319255

Estimated Period of Repair:

3.0 days

XING GUO QIANG Adjuster:

Manager:

VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SKIRT COMPL R	Repair	288.00 FL	*-FL
2	1		*BUMPER FACE REAR FORESTER IL	Scratched	540.00 FL	*540.00 FL
3	1		*BEAM COMPL R EU	Not Necessary	288.00 FL	*- FL
4	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
5	1		*CARGO STEP PANEL	Necessary	460.00 FL	*460.00 Fl
=Fra	nchise	part, S=SpcNe	ett. L=ListItemDisc.	-		1,11,11,11,11,11,11
				Sub Total (S\$)	1,676.00	1,020.00
			- List Item Discount	on L Items 30.00/30.00% (S\$)	472.80	300.00
				Total Parts (S\$)	1,203.20	720.00
			Report was unsubmitted	during this print-out.		

Recommended Miscellaneous Items

y Particulars		Repairer's	Amount
*OD/TP Case (Insurer)		888	0.00
	Sub Total (S\$)	0.00	0.00
	y Particulars aneous Items	y Particulars aneous Items *OD/TP Case (Insurer)	y Particulars Repairer's aneous Items *OD/TP Case (Insurer)

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	REPAIR / REPLACE REAR BUMPER AND PANEL.	New	750.00	250.00
2	RESPRAY REAR BUMPER AND PANEL.	New	600.00	200.00
3	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES.	New	300.00	0.00
		Gross Labour Cost (S\$)	1,650.00	450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >