

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

25/7/2018

M/S AIG

ESTIMATE REPAIR COST FOR SDR5885M

S/N	QTY	DESCRIPTION			
1	1 PC	REAR BUMPER <i>DS</i>	\$	1,460.00	✓
2	1 PCS	REAR BUMPER CLIPS <i>see</i>	\$	60.00	✓
3	1 PC	REAR BUMPER TOW COVER <i>Tom</i>	\$	47.00	✓
4	1 PC	REAR BUMPER REINFORCEMENT <i>see</i>	\$	715.00	✓
5	1 PC	REAR BUMPER <i>inner retainers one</i>	\$	69.00	✓
6	2 PC	REAR BUMPER REFLECTOR <i>an</i>	\$	72.00	X
7	1 PC	BOOTLID <i>DS/see</i>	\$	1,603.00	✓
8	1 PC	BOOTLID LOGO <i>see</i>	\$	69.00	✓
9	1 PC	BOOTLID 520i Emblem <i>see</i>	\$	63.00	✓
10	1 PC	REAR END PANEL <i>see</i>	\$	540.00	X
11	1 PC	BOOTLID REFLECTOR <i>an</i>	\$	340.00	X
			\$	5,038.00	
			LESS 10%	\$ (503.80)	
			\$	4,534.20	
12	2 PC	REVERSE SENSOR <i>shut</i>	\$	760.00	✓
13		To spray paint.	\$	1,250.00	600
14		labour charge to renew damage parts	\$	1,100.00	520
15		To remove and refit rear electrical wiring, renew sensor	\$	100.00	30
16		To apply undercoating.	\$	120.00	50
17		To remove and refit garnishes, carpets, etc	\$	100.00	80
			\$	7,964.20	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: