

CC 4, LPL 180 13536, RI 180374

Surveyor:

Kasmu

DOI:

3/7/18

Date / Time:

24/8/2018

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKF 2258 Z

Name of Insured:

LOO HIAN-U (LU JIANYOU)

Insured Tel No.:

HP:

98347337

Excess Sec II :SS

D.O.A.:

2/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

18/18/18/18/05/020777

Policy No.:

218VPO808510

Make / Model:

M-BENZ C180

Place of Accident:

After function Buream Rd
& Chanery Ln

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKF 2258 Z

SJF8118 Y

SJH 9770 R



INSRS:

WSP:

Tel:

Liability:

RMKS:

07



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pm

78



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

27/7/18
M/VIONSJF8118 Y
SKF 2258 ZNA/LPL 18013304/1/4 : 2/7/18
NA/LPL 18008457/2/4 : 2/7/18

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time: 05.03.19

Confirm with: Rasmu

Confirm by: MEB

Repair Cost:

P/P S\$24,847.94

(10 days)

Reduction:

24 %

Email

Call

FINAL SETTLEMENT

Date/Time: 27/7/19

Confirm with: Caroline

Email

Call

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

28

If NO or B 28, Ass. Lia: 100%

Repair Cost:

W/RAS7 S\$26,587.30

OCD involved in 3rd

OCD is the last ver

Loss of Rental (LOR):

S\$ -

(days)

Loss of Use (LOU):

S\$ 4,500.00

(\$100 x 15 days)

Loss of Income (LOI):

S\$ -

(\$ x days)

LOR only ☐ LOU only ☒LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 2.00

Medical:

S\$ 232.25

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost

S\$ -

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$430

Total:

S\$ 28,321.55

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 28321.55

Name 1:

Performance Motors Limited

Payee 2: (Strike if N.A.)

S\$ -

Name 2:

Payee 3: (Strike if N.A.)

S\$ -

Name 3:

W/R 16/8/19



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 18/18/18/VP05/020777
Our ref: CC4/LPC18013536/R1wa3

Date: 03.08.2018

The Motor Claims Department
M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJE 8118Y


We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 31.07.2018 at the premises of M/s Performance Motors Limited have the following to report:-

Workshop Estimate Amount	: S\$	27,574.90
Revised Estimate Amount	: S\$	17,577.65
"Check" Items Amount	: S\$	5,487.75
Total (Including Check Items)	: S\$	23,065.40
Market Value	: S\$	- (est.)
LTA Reimbursement Value	: S\$	- (est.)
Nett Value	: S\$	- (est.)

Description of Damage:

The vehicle sustained damages at the
Front & Rear Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 9~10 days

Yours faithfully,

MOHD. RASUL
Licensed Appraiser

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623
Tel: 6461 6555 | Fax: 6221 3302 | Website: www.sompo.com.sg
Co. Reg. No.: 198905490E | GST Reg. No.: M200903196

Certificate of Insurance

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

Cert No./Policy No. : D17MTPV01017149
Insured : CHONG AI CHOO
Motor Car (Registration No.) : SJE8118Y
Cover : Comprehensive - ExcelDrive PRESTIGE
Policy Commencement Date : 08 DECEMBER 2017 00:00
Policy Expiry Date : 07 DECEMBER 2018 23:59
Maximum Liability (Section I) : Market value at time of loss
Excess* : \$600 - Section I
(Waived up to S\$1,000 if accident repair is done at ExcelDrive Workshops for the first claim per policy year)
Voluntary Excess* : N.A
Windscreen Excess* : S\$100.00 - Waived if Repair at ExcelDrive Workshop
Loss of Use : Per Policy Schedule
* Subject to GST wherever applicable

Persons or Classes of Persons entitled to drive*

1. The Insured.
2. Any other person who is driving on the Insured's order or with his permission.
3. In the event of the death of the insured,
 - a. any member of the insured's family, or a paid driver who has been driving the Motor Car during the life of the insured and permission to drive had not been withdrawn prior to the death of the insured; and
 - b. any other person who has been given permission to drive the Motor Car prior to the death and such permission had not been withdrawn by the Insured.

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Car or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Car. And provided further that the Motor Car is registered under the Road Traffic Act (Chapter 276) and its registration under the Road Traffic Act (Chapter 276) has not been cancelled at the time of the accident, loss or damage.

Limitations As To Use

Use only for social, domestic and pleasure purpose and for the Insured's business. The Policy does not cover use for hire or reward, racing, pace-making, speed testing, reliability trial, the carriage of goods other than samples in connection with any trade or business or use for any purposes in connection with the Motor Trade.

ExcelDrive Workshops and Accident Reporting

It is a condition precedent to liability that the Insured shall call at the Company's Accident Reporting Center with the Motor Car within 24 hours of the accident or by the next working day thereof.

All accident repairs to the Motor Car must be carried out at ExcelDrive Workshops, otherwise the claim is not payable under the Policy. For ExcelDrive Prestige Plan, accident repairs to the Motor Car can be carried out at any workshop other than ExcelDrive Workshops.

For the list of Accident Reporting Centres and ExcelDrive Workshops, please visit our website at www.sompo.com.sg or call our Emergency Hotline: (65) 6226 3323.

WE HEREBY CERTIFY that the policy to which this Certificate relates is issued in accordance with (1) the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia); and (2) the Policy terms, conditions and exceptions of the Private Car Policy ref MTP.27

Sompo Insurance Singapore Pte. Ltd.

Authorised Signatory

Date/Time of Issue : 22 NOVEMBER 2017 11:59

IMPORTANT NOTICE

- o Keep the Certificate in your Motor Car;
- o Under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189), it shall be unlawful for any person to use or cause to permit any other person to use a motor vehicle without a valid policy of insurance under the Act;
- o On the sale of the Motor Car or if for any reason the Insurance is terminated during its currency, the Insured must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed, a statutory declaration to that effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189);
- o This Policy will cease to be valid once the Motor Car has been sold to another person. The Policy is not transferable to the new owner of the Motor Car.

Intermediary Code & Name : 11G03608 & GOH MUI SING @ GOH HUI SING CI Code: 22A L46DBZ02ILIYKAA

REPUBLIC OF SINGAPORE DRIVING LICENCE

License No: **S7341791J**

CHONG AI CHOO (ZHANG AIZHU)

Birth Date: **20 Nov 1973**

Issue Date: **07 Feb 2003**

1000178109E

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. **S7341791J**

Name: **CHONG AI CHOO (ZHANG AIZHU)**

張艾蓁

Race: **CHINESE**

Date of Birth: **20-11-1973** Sex: **F**

Country of Birth: **SINGAPORE**

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

	PASS DATE
Class 3 Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	04 Oct 1993

NP 428A



231465

NRIC No: **S7341791J**

Blood Group: **B+** Date of issue: **26-08-1994**

18 HOOPER ROAD
SINGAPORE 229195

NRIC No: **S7341791J** Date: **06/06/2010** No: **6494765**

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

24 JUL 2018

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47797
 Date Estimated : 24/07/2018
 Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -
 Chong Ai Choo (Zhang AiZhu)
 18 Hooper Road

Singapore 229195

- ACCOUNT - 158
 Lonpac Insurance Bhd
 300 Beach Road
 #17-04/07 The Concourse
 Singapore 199555

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE8118Y	OJ00183	08/12/2015	X3 sDrive20	0

DESCRIPTION

To replace rear tailgate, rear bumper upp, rear bumper lower, end panel, frt bumper, kidney frill & all attachment cause by accident.

Painting on rear tailgate, rear bumper, frt bumper, end panel & trunk floor

? - 531

To replace rear exhaust silencer including alignment system and conduct checks for leak.

To replace rear windscreen glass

To conduct water leak tests.

To supply and install rear windscreen solar film.

To check electrical wiring systems for proper function.

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

To carry out body cavity preservation.
 (Per panel).

To carry out body cavity preservation.
 (For cut panel).

To install car I cam recorder

To supply front and rear emboss number plate. 81

Sundries.

VALUE

4250 5,950.00
 5,100

3333 4,235.00
 3,408

451 531.00

487 574.00

63 75.00

Xan 531.00

250 150 177.00

451 531.00

100 118.00

451? 531.00

Xan 722? 850.00

83 165.00

150.00

Total Labour 1:

14,418.00



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47797
Date Estimated : 24/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE8118Y	OJ00183	08/12/2015	X3 sDrive20	0

DESCRIPTION

QTY

PRIC

VALUE

Installation kit for silencer
REAR MUFFLER
BOOTLID
OUTER PANEL TAIL TRIM
Set of mount
GRILLE MIDDLE BOTTOM PARTIALLY CLOS
GRILLE MIDDLE TOP OPEN
FRT LH GRILLE (CHROM/SCHWARZ)
FRT RH GRILLE (CHROM/SCHWARZ)
CLADDING BUMPER FRT (PDC/SCHWARZ)
FRT BUMPER PANEL PRIMED
REAR BUMPER SET MOUNTING PARTS (VAL
RR BUMPER CARRIER ECE
FLAP TOWING EYE REAR
RR LH BUMPER MIDDLE MOUNTING
RR RH BUMPER MIDDLE MOUNTING
RR BUMPER LH MOUNT
RR BUMPER RH MOUNT
COVER MIDDLE BOTTOM
CLADDING BUMPER REAR (PDC/SCHWARZ)
REAR BUMPER PANEL PRIMED (PDC)
EMBLEM GROMMET
MODEL LETTERING X3
BMW EMBLEM
RR W/SCREEN
BOOTLID GASKET
LH REFLECTOR
RH REFLECTOR
DECOUPLING RING PDC TORQUE CONVERTE
BUMPER PDC SENSOR (300 ALPINWEISS)
BUMPER PDC SENSOR (SCHWARZ)
BMW ADVANCED CAR EYE
BLIND RIVET AVIBVLB
SCREW (SF PLUS M5X15)
(DG/SL) BODY ADHESIVE K5B (195ML)
(DG) BODYWORK ADHESIVE K5A (50ML)
(DG) CLEANER R1 (100ML)
(DG) CLEANER R1 (100ML)
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)
PUNCH RIVET N4
(DG/SL) GLASS PRIMER 30ML (VP206)

Total Parts :

13,156.90

129.95
1,220.90
1,807.20
497.45
49.40
120.00
99.15
110.85
110.85
246.20
1,277.55
38.55
738.05
35.95
142.55
142.55
198.30
198.30
68.70
197.35
1,409.45
0.80
62.55
69.50
1,279.80
128.90
35.20
35.20
5.05
368.80
236.85
687.95
0.55
0.55
281.55
118.35
23.85
23.85
131.55
0.55
27.85

129.95
1,220.90
1,807.20
497.45
49.40
120.00
99.15
110.85
110.85
246.20
1,277.55
38.55
738.05
35.95
142.55
142.55
198.30
198.30
68.70
197.35
1,409.45
0.80
62.55
69.50
1,279.80
128.90
35.20
35.20
40.40
737.60
473.70
687.95
13.20
1.10
281.55
118.35
23.85
23.85
263.10
13.20
27.85

129.95
1,220.90
1,807.20
497.45
49.40
120.00
99.15
110.85
110.85
246.20
1,277.55
38.55
738.05
35.95
142.55
142.55
198.30
198.30
68.70
197.35
1,409.45
0.80
62.55
69.50
1,279.80
128.90
35.20
35.20
40.40
737.60
473.70
687.95
13.20
1.10
281.55
118.35
23.85
23.85
263.10
13.20
27.85

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax: 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47797
Date Estimated : 24/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SJE8118Y	0J00183	08/12/2015	X3 sDrive20	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / Third Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 31/07/18 @ 1200 Excess S\$ _____Surveyor's Name Rahul Sign _____Surveyor's Tel 90010068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 9-10 days

32585.44

Labour 1	:	14,418.00
Parts	:	13,156.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	1,930.24
Grand Total	:	<u>29,505.14</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47797
Date Estimated : 24/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Chong Ai Choo (Zhang AiZhu)
18 Hooper Road

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 229195

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SJE8118Y	0J00183	08/12/2015	X3 sDrive20	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
# To tow accident vehicle to PML workshop	195.00		195.00	✓
To replace front seat crash-active head restraint air bag include resetting and conducting checks for function	451.00		451.00	✓
# To replace rear PDC sensor wiring set include resetting and conducting checks for proper function	226.00		226.00	✓
# To replace boot lid smart opener control unit, sensor lead smart opener, sensor wire for bottom smart opener include programming and conducting checks for function	562.00		562.00	✓
# To remove and install rear compartment carpet and garnish to facilitate repairs	231.00		231.00	✓
# To install BMW advance eye cam recorder	722.00		722.00	✓

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT	
# RUBBER MOUNTING *	33.65	1.00		33.65	✓
# RR SILENCER CLAMPING BUSH *	60.60	1.00		60.60	✓
# REAR SILENCER BRACKET *	55.80	1.00		55.80	✓
# TAILPIPE TIP CHROME *	124.85	1.00		124.85	✓
# EXPANDING NUT *	1.00	8.00		8.00	✓
# TRUNK LID BADGE *	69.50	1.00		69.50	✓
# STRIKER BOOT LID *	55.75	1.00		55.75	✓
# BUMP STOP *	3.25	10.00		32.50	✓
# AIR DUCT *	308.95	1.00		308.95	✓
# EXPANDING RIVET *	1.35	20.00		27.00	✓
# (DG) REP. KIT CRASH ACTIVE HEAD RES *	112.55	2.00		225.10	✓
# RR PDC WIRING SET *	188.70	1.00		188.70	✓
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50	✓
# SENSOR LEAD SMART OPENER *	44.45	1.00		44.45	✓
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85	✓
# REAR RH LIGHT IN TRUNK LID *	308.60	1.00		308.60	✓
# THIRD STOPLAMP *	233.60	1.00		233.60	✓
# 3M S/F PREMIUM REAR WINDSCREEN	252.34			252.34	✓

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Total Labour :	2,387.00
Total Parts :	2,286.40
Total Labour & Parts :	4,673.40

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47797
Date Estimated : 24/07/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Chong Ai Choo (Zhang AiZhu)
18 Hooper Road

- ACCOUNT - 158
Lonpac Insurance Bhd
300 Beach Road
#17-04/07 The Concourse
Singapore 199555

Singapore 229195

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE	
SJE8118Y	0J00183	08/12/2015	X3 sDrive20	0	
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT		
* To replace rear bumper and attachments, tail end panel, boot lid and attachments, front bumper cladding, middle bottom cover, front air duct include making good front bumper and knocking out dents caused by the accident	5100.00		5,100.00		
* To spray paint boot lid, rear bumper, front bumper and tail end panel	3408.00		3,408.00		
To replace rear exhaust silencer and attachments include alignment of system and conducting checks for leak	451.00		451.00		
* To replace rear windscreen glass	574.00		574.00		
* To conduct water leak tests	75.00		75.00		
* To check electrical wiring systems and lightings at the front and rear section for proper function	250.00		250.00		
To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00		
To carry out body cavity preservation (Per panel)	100.00		100.00		
* To carry out body cavity preservation (For cut panel)	451.00		451.00		
To supply front emboss number plate	83.00		83.00		
# To tow accident vehicle to PML workshop	195.00		195.00		
To replace front seat crash-active head restraint air bag include resetting and conducting checks for function	451.00		451.00		
# To replace rear PDC sensor wiring set include resetting and conducting checks for proper function	226.00		226.00		
# To replace boot lid smart opener control unit, sensor lead smart opener, sensor wire for bottom smart opener	562.00		562.00		

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

include programming and conducting checks for function

# To remove and install rear compartment carpet and garnish to facilitate repairs	231.00	231.00
# To install BMW advance eye cam recorder	722.00	722.00
Sundries	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RUBBER MOUNTING *	33.65	1.00		33.65
# RR SILENCER CLAMPING BUSH *	60.60	1.00		60.60
# REAR SILENCER BRACKET *	55.80	1.00		55.80
REAR MUFFLER	1,220.90	1.00		1,220.90
# TAILPIPE TIP CHROME *	124.85	1.00		124.85
# 3M S/F PREMIUM REAF WINDSCREEN	252.34	1.00		252.34
BOOTLID	1,807.20	1.00		1,807.20
OUTER PANEL TAIL TRIM	497.45	1.00		497.45
GRILLE MIDDLE TOP OPEN	99.15	1.00		99.15
CLADDING BUMPER FRT (PDC/SCHWARZ)	246.20	1.00		246.20
# EXPANDING NUT *	1.00	8.00		8.00
COVER MIDDLE BOTTOM	68.70	1.00		68.70
CLADDING BUMPER REAR (PDC/SCHWARZ)	197.35	1.00		197.35
REAR BUMPER PANEL PRIMED (PDC)	1,409.45	1.00		1,409.45
EMBLEM GROMMET	0.80	2.00		1.60
MODEL LETTERING X3	62.55	1.00		62.55
# TRUNK LID BADGE *	69.50	1.00		69.50
# STRIKER BOOT LID *	55.75	1.00		55.75
# BUMP STOP *	3.25	10.00		32.50
RR W/SCREEN	1,279.80	1.00		1,279.80
# AIR DUCT *	308.95	1.00		308.95
BOOTLID GASKET	128.90	1.00		128.90
# EXPANDING RIVET *	1.35	20.00		27.00
# (DG) REP. KIT CRASH ACTIVE HEAD RES *	112.55	2.00		225.10
# RR PDC WIRING SET *	188.70	1.00		188.70
# SENSOR WIRE FOR SMART OPENER BOTTOM *	40.50	1.00		40.50
# SENSOR LEAD SMART OPENER *	44.45	1.00		44.45
# CONTROL UNIT SMART OPENER *	468.85	1.00		468.85
# REAR RH LIGHT IN TRUNK LID *	308.60	1.00		308.60
# THIRD STOPLAMP *	233.60	1.00		233.60
BUMPER PDC SENSOR (300 ALPINWEISS)	368.80	1.00		368.80
BMW ADVANCED CAR EYE	687.95	1.00		687.95
BLIND RIVET AVIBVLB	0.55	30.00		16.50
SCREW (SF PLUS M5X15)	0.55	10.00		5.50
(DG/SL) BODY ADHESIVE K5B (195ML)	281.55	1.00		281.55
PUNCH RIVET N4	0.55	30.00		16.50
(DG) BODYWORK ADHESIVE K5A (50ML)	118.35	1.00		118.35
(DG) CLEANER R1 (100ML)	23.85	1.00		23.85
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	131.55	2.00		263.10
(DG/SL) GLASS PRIMER 30ML (VP206)	27.85	1.00		27.85

SUPPLEMENTARY ITEMS

Total Labour : 13,480.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Total Parts :	11,367.94
Total Labour & Parts :	24,847.94
Deduction for Excess :	
Total Repair Costs less Excess:	24,847.94
GST @7%:	1,739.36
Grand Total :	26,587.30

Nivitha (LKK Auto)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>
Sent: Tuesday, 24 July 2018 2:16 PM
To: admin-d@lkkauto.com
Cc: MT_Claim_SG; PBSP
Subject: FW: REQUEST FOR DIRECT SETTLEMENT - SJE8118Y & SKF2258Z ON 21 JULY 2018
Attachments: SKM_558e18072412560.pdf; IMG_5133.JPG; IMG_5135.JPG; IMG_5136.JPG; IMG_5139.JPG; IMG_5140.JPG; IMG_5143.JPG

2.33pm @ 24/7/18
person @ caroline
vehicle not in

Our Ref : 18/18/18/VP05/020777

Dear Nivitha,

Kindly proceed to conduct the survey and revert to them on direct settlement.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]

Sent: Tuesday, 24 July, 2018 1:47 PM

To: MT_Claim_SG; GERALD POH WEE BIN

Subject: REQUEST FOR DIRECT SETTLEMENT - SJE8118Y & SKF2258Z ON 21 JULY 2018

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete

all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CC4/LPC18013536/R1da3n2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 23-08-2019	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKF 2258Z	Veh. Inspected	SJE 8118Y	
Policy No.	Z18VP05018510	Coverage (\$)	0.00	
Claim No.	18/18/18/VP05/020777	Excess (\$)	0.00	
Assign From	GERALD	Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	B.M.W. X3 SDRIVE	c.c	1997	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	WBAWY920400J00183	Colour	WHITE	
Odometer	38722	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/60 R17	PIRELLI	6 mm	
L/H Front Tyre	225/60 R17	PIRELLI	6 mm	
R/H Rear Tyre	225/60 R17	PIRELLI	6 mm	
L/H Rear Tyre	225/60 R17	PIRELLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/07/2018	Inspection Date	31/07/2018	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		10 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJE 8118Y

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT AND REAR EMBOSS NUMBER PLATE (SN)	BENT	165.00	83.00
1	SUNDRIES (SN)	NECESSARY	150.00	150.00
1	INSTALLATION KIT FOR SILENCER (SN)	NOT NECESSARY	129.95	-
1	REAR MUFFLER (SN)	BENT	1,220.90	1,220.90
1	BOOTLID (SN)	BENT	1,807.20	1,807.20
1	OUTER PANEL TAIL TRIM (SN)	CRACKED	497.45	497.45
1	SET OF MOUNT (SN)	SERVICEABLE	49.40	-
1	GRILLE MIDDLE BOTTOM PARTIALLY CLOS (SN)	SERVICEABLE	120.00	-
1	GRILLE MIDDLE TOP OPEN (SN)	CRACKED	99.15	99.15
1	FRT LH GRILLE (CHROM/SCHWARZ) (SN)	SERVICEABLE	110.85	-
1	FRT RH GRILLE (CHROM/SCHWARZ) (SN)	SERVICEABLE	110.85	-
1	CLADDING BUMPER FRT (PDC /SCHWARZ) (SN)	DEFORMED	246.20	246.20
1	FRT BUMPER PANEL PRIMED (SN)	SERVICEABLE	1,277.55	-
1	RR BUMPER CARRIER ECE (SN)	SERVICEABLE	738.05	-
1	FLAP TOWING EYE REAR (SN)	SERVICEABLE	35.95	-
1	RR LH BUMPER MIDDLE MOUNTING (SN)	SERVICEABLE	142.55	-
1	RR RH BUMPER MIDDLE MOUNTING (SN)	SERVICEABLE	142.55	-
1	RR BUMPER LH MOUNT (SN)	SERVICEABLE	198.30	-
1	RR BUMPER RH MOUNT (SN)	SERVICEABLE	198.30	-
1	COVER MIDDLE BOTTOM (SN)	CRACKED	68.70	68.70
1	CLADDING BUMPER REAR (PDC/SCHWARZ) (SN)	DEFORMED	197.35	197.35
1	REAR BUMPER PANEL PRIMED (PDC) (SN)	DEFORMED	1,409.45	1,409.45
2	EMBLEM GROMMET (SN)	NECESSARY	1.60	1.60
1	MODEL LETTERING X3 (SN)	NECESSARY	62.55	62.55
1	BMW EMBLEM (SN)	NOT NECESSARY	69.50	-
1	RR W/SCREEN (SN)	NECESSARY	1,279.80	1,279.80
1	BOOTLID GASKET (SN)	NECESSARY	128.90	128.90
1	LH REFLECTOR (SN)	SERVICEABLE	35.20	-
1	RH REFLECTOR (SN)	SERVICEABLE	35.20	-
8	DECOUPLING RING PDC TORQUE CONVERTER (SN)	SERVICEABLE	40.40	-

Report Ref No. CC4/LPC18013536/R1da3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	BUMPER PDC SENSOR (300 ALPINWEISS)(SN)	NOT WORKING (1 PC ONLY)	737.60	368.80
2	BUMPER PDC SENSOR (SCHWARZ)(SN)	NOT NECESSARY	473.70	-
1	BMW ADVANCED CAR EYE (SN)	NOT WORKING	687.95	687.95
30	BLIND RIVET AVIBVLB (SN)	NECESSARY	16.50	16.50
10	SCREW (SF PLUS M5X15)(SN)	NECESSARY	5.50	5.50
1	(DG/SL) BODY ADHESIVE K5B (195ML) (SN)	NECESSARY	281.55	281.55
1	(DG) BODYWORK ADHESIVE K5A (50ML) (SN)	NECESSARY	118.35	118.35
1	(DG) CLEANER R1 (100ML) (SN)	NECESSARY	23.85	23.85
1	(DG) CLEANER R1 (100ML) (SN)	NOT NECESSARY	23.85	-
2	(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) (SN)	NOT WORKING	263.10	263.10
30	PUNCH RIVET N4 (SN)	NECESSARY	16.50	16.50
1	(DG/SL) GLASS PRIMER 30ML (VP206) (SN)	NECESSARY	27.85	27.85
1	RUBBER MOUNTING (SN) (ADDITIONAL)	NECESSARY	33.65	33.65
1	RR SILENCER CLAMPING BUSH (SN) (ADDITIONAL)	NECESSARY	60.60	60.60
1	REAR SILENCER BRACKET (SN) (ADDITIONAL)	NECESSARY	55.80	55.80
1	TAILPIPE TIP CHROME (SN) (ADDITIONAL)	BENT	124.85	124.85
8	EXPANDING NUT (SN)(ADDITIONAL)	NECESSARY	8.00	8.00
1	TRUNK LID BADGE (SN)(ADDITIONAL)	NECESSARY	69.50	69.50
1	STRIKER BOOT LID (SN)(ADDITIONAL)	NECESSARY	55.75	55.75
10	BUMP STOP (SN)(ADDITIONAL)	NECESSARY	32.50	32.50
1	AIR DUCT (SN)(ADDITIONAL)	CRACKED	308.95	308.95
20	EXPANDING RIVET (SN)(ADDITIONAL)	NECESSARY	27.00	27.00
2	(DG) REP.KIT CRASH ACTIVE HEAD RES (SN) (ADDITIONAL)	ACTIVATED	225.10	225.10
1	SET RR PDC WIRING (SN)(ADDITIONAL)	CUT	188.70	188.70
1	SENSOR WIRE FOR SMART OPENER BOTTOM (SN) (ADDITIONAL)	NECESSARY	40.50	40.50
1	SENSOR LEAD SMART OPENER (SN) (ADDITIONAL)	NECESSARY	44.45	44.45
1	CONTROL UNIT SMART OPENER (SN) (ADDITIONAL)	NECESSARY	468.85	468.85
1	REAR RH LIGHT IN TRUNK LID (SN) (ADDITIONAL)	CRACKED	308.60	308.60
1	THIRD STOPLAMP (SN)(ADDITIONAL)	NECESSARY	233.60	233.60
1	3M S/F PREMIUM REAR WINDSCREEN (SN) (ADDITIONAL)	NECESSARY	252.34	252.34

Report Ref No. CC4/LPC18013536/R1da3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER SET MOUNTING PARTS (VAL)(SN)	SERVICEABLE	38.55	-
			16,022.44	11,600.94
	LABOUR			
	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP. (ADDITIONAL)		195.00	195.00
	TO REPLACE FRONT SEAT CRASH-ACTIVE HEAD RESTRAINT AIR BAG INCLUDE RESETTING AND CONDUCTING CHECKS FOR FUNCTION.(ADDITIONAL)		451.00	451.00
	TO REPLACE REAR PDC SENSOR WIRING SET INCLUDE RESETTING AND CONDUCTING CHECKS FOR PROPER FUNCTION.(ADDITIONAL)		226.00	226.00
	TO REPLACE BOOT LID SMART OPENER CONTROL UNIT ,SENSOR LEAD SMART OPENER ,SENSOR WIRE FOR BOTTOM SMART OPENER INCLUDE PROGRAMMING AND CONDUCTING CHECKS FOR FUNCTION.(ADDITIONAL)		562.00	562.00
	TO REMOVE AND INSTALL REAR COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS. (ADDITIONAL)		231.00	231.00
	TO INSTALL BMW ADVANCE EYE CAM RECORDER. (ADDITIONAL)		722.00	722.00
	TO REPLACE REAR TAILGATE ,REAR BUMPER UPP,REAR BUMPER LOWER,END PANEL,FRT BUMPER ,KIDNEY FRILL & ALL ATTACHMENT CAUSE BY ACCIDENT.		5,950.00	5,100.00
	PAINTING ON REAR TAILGATE ,REAR BUMPER ,FRT BUMPER ,END PANEL & TRUNK FLOOR.		4,235.00	3,408.00
	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK.		531.00	451.00
	TO REPLACE REAR WINDSCREEN GLASS.		574.00	574.00
	TO CONDUCT WATER LEAK TESTS.		75.00	75.00
	TO SUPPLY AND INSTALL REAR WINDSCREEN SOLAR FILM.	NOT NECESSARY	531.00	-
	TO CHECK ELECTRICAL WIRING SYSTEMS FOR PROPER FUNCTION.		250.00	250.00
	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.		531.00	451.00

Report Ref No. CC4/LPC18013536/R1da3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL).		531.00	451.00
	TO INSTALL CAR I CAM RECORDER.	NOT NECESSARY	850.00	-
			16,563.00	13,247.00
GRAND TOTAL			32,585.44	24,847.94
RECOMMENDED COST OF REPAIRS				24,847.94

Report Ref No. CC4/LPC18013536/R1da3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.