

ASS. REC. BY:

REF: CS/FCI18013539/Kvb02 Special Instruction:

SURVAYOR

Kenneth

ASSIGNMENT (Office)

From (Person): (WS) Luene Jun of FCI Date/Time: 25/03/018 6536m

Estimated Cost: Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHK 9828D Insured: SHB 45889

at Workshop m/s City Auto Tel: 6453 1235

of Bk 3 Bin ming And rst #01-58

Policy No: Claim No: D18005621MESH

Sum Insured: Excess:

Make of Veh: D.O.A. 21072018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement:

Date/Time: 25/03/2016 939am Person Contacted: Viorita Vehicle: IN/OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHK 9828D - CCL / ALG14014574 / Acc 2	DA: 110714
	SHB 45889 - CCL / ASE18001047 / Tlb 3112	DA: 110118
26/11/18	Email preli revised to FCI	
6/18	11 Lm 8305A Confirm (Red) 2311.36, 437m	

Garryanor

ASSIGNMENT

From:

Date:

25/07/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SGK 9828D

at Workshop m/s

City Auto

of

160 Sim Ming Drive

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

814K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SGK 9828D

Yr Regn:

11 / 09

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Avanza 1591

Colour:

M. Silver

A/C: Insured / Std / NI / NA

Sp. Reading

199195

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KMH1DU41BMA4900013

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

Hyundai 185/65R15
Austan

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

mm

Rear

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/7/18

D.O.I.

25/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/7 PM 1951 to Carhume

Note:

MV: \$14K (EST) LTA: \$8467 NV: \$5533

Date/Time, File Pass to?



: Preli. Report

1)



: Final Report

Date/Time, File Return to?

2) 6/8 - typist

Days Of Repair:

5

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

) S + RS. SI

) Photos

) Others:

TOTAL

Report Format :

CWS

Lump Sum / I.B.I. (\$

3050 /-

Add Fee:



: Site Insp (\$



Interview (\$



Tech. Invs (\$



Weekend (\$

140

50

50+50

26

316



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18005621MFSH

Our ref: CS/FCI18013539/Kvb

Date : 26/7/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

INITIAL INSPECTION REPORT OF VEHICLE NO. SGK 9828D


We thank for your instruction on 25/7/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 25/7/2018 at the premises of M/s CITY AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$5,361.36
Revised Estimate Amount	: S\$3,380.08
"Check" Items Amount	: S\$516.56
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the rear portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

Kenneth Kong
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	24-07-2018	Our Ref No. D18005621MFSH
Accident Date	21-07-2018	Claim Type. Third Party
Insured Vehicle	SHB4588P	Third Party Vehicle. SGK9828D
Survey Location	BLK 8 SIN MING ROAD #01-58/60/62 SIN MING IND EST	
Contact Person.	VRONICA LAW	
Contact No.	64531235/ 0	Fax No. 64537944
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CITY AUTO PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
 This is a computer generated letter, no signature required.

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 26 July 2018 5:19 PM
To: 'Claim Workflow System'
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18005621MFSH/1, SGK 9828D
Attachments: SGK 9828D PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle SGK 9828D
Date of survey: 25/7/2018
Number of days : 5 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 25 July 2018 9:38 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18005621MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 25 July, 2018 8:53 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; LURENEJAW@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18005621MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	7506A
Vehicle Details	
Vehicle No.:	SGK9828D
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jul 2018
Vehicle Make:	HYUNDAI
Vehicle Model:	AVANTE 1.6 AT ABS D/AB 2WD 4DR
Primary Colour:	Silver
Manufacturing Year:	2009
Engine No.:	G4FC9U752216
Chassis No.:	KMHJU41BMAU900013
Maximum Power Output:	89.7 kW (120 bhp)
Open Market Value:	\$11,465.00
Original Registration Date:	11 Nov 2009
First Registration Date:	11 Nov 2009
Transfer Count:	1
Actual ARF Paid:	\$11,465.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	10 Nov 2019
PARF Rebate Amount:	\$6,305.00
Intended COE Rebate Details	
COE Expiry Date:	10 Nov 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$16,747.00
COE Rebate Amount:	\$2,162.00
Total Rebate Amount:	\$8,467.00

The information contained herein is correct as at 26 Jul 2018

OK



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000389(00)

Date : 24/07/2018

Vehicle No. : SGK9828D

Make/Model : HYUNDAI AVANTE 1.6 AT ABS D/AB
2WD 4DR

Mileage (km) : 0

Chassis No. : KMHDU41BMAU900013

Accident Date : 21/07/2018 00:00:00

Claim No. : SHB4588P

Reference : SGK9828D

Policy No. : 5083218049-01

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Contact : -

Fax No. : 6507 3849

*Not Notified
C/Sing @ 3050L
Resurvey After Paint*

S/No	Particular	Quantity	Unit Price	Amount S\$
------	------------	----------	------------	------------

LIST ITEMS :

1	Rear bumper	1.0	489.10	CM 489.10 ✓
2	Rear bumper clip	8.0	2.00	RM 16.00 ✓
3	Rear bumper sponge	1.0	109.90	CM 109.90 ✓
4	Rear bumper reinforcement	1.0	270.00	CM 270.00 ✓
5	Rear bumper reinforcement damper	2.0	67.30	BY 134.60 ✓
6	Rear bumper reinforcement bracket - upper	2.0	24.00	R 48.00 X
7	Rear bumper reinforcement bracket - lower	3.0	21.60	R 64.80 X
8	Rear end panel	1.0	493.80	BY 493.80 ✓
9	Rear end panel top garnish	1.0	34.40	RM 34.40 X
10	Rear boot	1.0	985.90	RM 985.90 ✓
11	Rear boot lock	1.0	118.30	R 118.30 X
12	Rear boot weatherstrip	1.0	79.30	SL 79.30 X
13	Rear boot logo	1.0	23.30	RM 23.30 ✓
14	Rear boot emblem - Avante	1.0	31.20	RM 31.20 ✓
15	Rear boot emblem - S	1.0	28.30	RM 28.30 ✓
16	RH taillamp	1.0	288.40	CM 288.40 ✓
17	Rear exhaust silencer	1.0	711.20	R 711.20 X
18	Rear exhaust mounting	1.0	50.20	SL 50.20 X

List Total :

20% Discount S\$

SPECIAL NET :

1	Reverse sensor	1.0	250.00	CM 250.00
2	Number plate	1.0	25.00	RM 25.00 X
3	Number plate casing	1.0	35.00	RM 35.00 X
SPECIAL NET Total S\$:				310.00

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

LABOUR :

*To supply panel sealant and to seal all weld seam and gaps	1.0	90.00	90.00	30L
*To check wiring and lighting	1.0	60.00	60.00	20L
*To spray under coating	1.0	120.00	120.00	60L
-To knock jackout damaged parts, panel beating, welding, align, refix and to renew accident parts	1.0	800.00	800.00	600L
- Spray painting on affected & replace parts	1.0	800.00	800.00	600L

CONTINUE NEXT PAGE



CITY AUTO PTE LTD

One Stop Automotive Solution

BLK 8, SIN MING IND. ESTATE, #01-60/62, SIN MING ROAD, SINGAPORE 575643

TEL: 6453 1235, 6452 0850 FAX: 6453 7944

24hrs Towing Services Tel: 9823 9898

Co. Reg. No.: 199503435C GST Reg. No.: M2-8920979-4

Estimate : QUOT201807-000389(00)

Date : 24/07/2018

Vehicle No. : SGK9828D

Make/Model : HYUNDAI AVANTE 1.6 AT ABS D/AB
2WD 4DR

Mileage (km) : 0

Chassis No. : KMH DU41BMAU900013

Accident Date : 21/07/2018 00:00:00

Claim No. : SHB4588P

Reference : SGK9828D

Policy No. : 5083218049-01

MS FIRST CAPITAL INSURANCE LTD

NO. 36

ROBINSON RD

CITY HOUSE

SINGAPORE 068877

Contact : -

Fax No. : 6507 3849


S/No	Particular	Quantity	Unit Price	Amount S\$
				1,870.00

E. & O.E.

Total S\$: 5,361.36

GST 7% S\$: 375.30

Amount Due S\$: 5,736.66


for CITY AUTO PTE LTD



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18013539/Kvbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 13-08-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 4588P	Veh. Inspected	SGK 9828D	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18005621MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	25/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	HYUNDAI AVANTE S (A)	c.c	1591	
Engine No.	HIDDEN	Year of Reg.	2009	
Chassis No.	KMH DU41BMAU900013	Colour	METALLIC SILVER	
Odometer	194195	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	HAIDA	8 mm	
L/H Front Tyre	185/65 R15	HAIDA	8 mm	
R/H Rear Tyre	185/65 R15	AUSTONE	7 mm	
L/H Rear Tyre	185/65 R15	AUSTONE	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	21/07/2018	Inspection Date	25/07/2018	
Survey held at	CITY AUTO PTE LTD BLK 8, SIN MING IND. ESTATE #01-60/62 SIN MING ROAD SINGAPORE 575643.			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGK 9828D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER	CRACKED	489.10	489.10
8	REAR BUMPER CLIP @\$2.00	NECESSARY	16.00	16.00
1	REAR BUMPER SPONGE	CRACKED	109.90	109.90
1	REAR BUMPER REINFORCEMENT	CRACKED	270.00	270.00
2	REAR BUMPER REINFORCEMENT DAMPER @\$67.30	BENT	134.60	134.60
2	REAR BUMPER REINFORCEMENT BRACKET-UPPER @\$24.00	TO REPAIR SEE LABOUR	48.00	-
3	REAR BUMPER REINFORCEMENT BRACKET-LOWER @\$21.60	TO REPAIR SEE LABOUR	64.80	-
1	REAR END PANEL	BENT	493.80	493.80
1	REAR END PANEL TOP GARNISH	SERVICEABLE	34.40	-
1	REAR BOOT	BENT	985.90	985.90
1	REAR BOOT LOCK	TO REPAIR SEE LABOUR	118.30	-
1	REAR BOOT WEATHERSTRIP	SERVICEABLE	79.30	-
1	REAR BOOT LOGO	NECESSARY	23.30	23.30
1	REAR BOOT EMBLEM-AVANTE	NECESSARY	31.20	31.20
1	REAR BOOT EMBLEM-S	NECESSARY	28.30	28.30
1	RH TAILLAMP	CRACKED	288.40	288.40
1	REAR EXHAUST SILENCER	TO REPAIR SEE LABOUR	711.20	-
1	REAR EXHAUST MOUNTING	SERVICEABLE	50.20	-
	LESS 20% DISCOUNT		-795.34	-574.10
			3,181.36	2,296.40
SPECIAL NETT ITEMS				
1	REVERSE SENSOR (SN)	CRACKED	250.00	200.00
1	NUMBER PLATE (SN)	SERVICEABLE	25.00	-
1	NUMBER PLATE CASING (SN)	SERVICEABLE	35.00	-
			310.00	200.00
LABOUR				
	TO SUPPLY PANEL SEALANT AND TO SEAL ALL WELD SEAM AND GAPS.		90.00	30.00

Report Ref No. CS/FCI18013539/Kvbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO CHECK WIRING AND LIGHTING.		60.00	20.00
	TO SPRAY UNDER COATING.		120.00	60.00
	TO KNOCK,JACKOUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ACCIDENT PARTS.INCLUSIVE OF THE REPAIR OF REAR BUMPER REINFORCEMENT BRACKET-UPPER,REAR BUMPER REINFORCEMENT BRACKET-LOWER,REAR BOOT LOCK AND REAR EXHAUST SILENCER.		800.00	600.00
	SPRAY PAINTING ON AFFECTED & REPLACE PARTS.		800.00	600.00
			1,870.00	1,310.00
GRAND TOTAL			5,361.36	3,806.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				3,050.00

Report Ref No. CS/FCI18013539/Kvbn2

MARKET VALUE: \$14,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$8,467.00=NETT VALUE: \$5,533.00

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.