

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : TOA PAYOH
CONTACT NO : 64730333
REFERENCE : INS/IC/CHI/0701/2018
DATE : 23-MAR-2018

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
S(079120)
TEL : 91007211
FAX :

OWNER'S NAME : HERD MATTHEW ALAN
ADDRESS : 38 LORONG 30 GEYLANG
#08-10
S(398371)
TELEPHONE NO : 8686 1807

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : 2100506672
VEHICLE NO : SLB590K
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A873410
CHASSIS NO : JF1SJGK85GG067717
MILEAGE : 1 KM
DATE IN : 23/03/2018
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : KUAN WEI LOONG**
ACCIDENT DATE : 23/03/2018

Print Date : 24/03/2018
Print Time : 12:32:31

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLB590K

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AIG LOCATION:STILL RD EXIT ECP DATE:23/08/2018 TIME:0830 HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	500.00	125/-
4	ZZ/003	RESPRAY REAR BUMPER AND REAR PANEL	400.00	200/-
5	ZZ/004	TO CONDUCT REAR LIGHTING TEST	nn 50.00	X
6	ZZ/005	TO CONDUCT REAR PROTECTANT COATING	500.00	250/-
7	ZZ/006	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	nn 300.00	X
8	ZZ/007	SUNDRIES	na 100.00	* 20/-
TOTAL LABOUR CHARGES			1850.00	

MOTORIMAGE ENTERPRISES PTE. LTD.
 19 LORONG 8, TOA PAYOH
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLB590K

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	SKIRT COMPL R END PANEL	52401SG0109P			<i>R</i>	288.00 <i>X</i>
2	BUMPER FACE R	57704SG012			<i>Not in</i>	540.00 <i>✓</i>
3	BRKT CORNER R RH	57707SG060			<i>R</i>	18.00 <i>X</i>
4	BRKT CORNER R LH	57707SG070			<i>Dir</i>	18.00 <i>✓</i>
5	BRKT SD R RH	57707SG080			<i>R</i>	14.40 <i>X</i>
6	BRKT SD R LH	57707SG090			<i>R</i>	14.40 <i>X</i>
7	BEAM COMPL R EU	(SUPP) 57711SG0219P			<i>R</i>	288.00 <i>X</i>
8	COVER HOOK R	57731SG010NN			<i>R</i>	12.60 <i>X</i>
9	REFLEC AY RH	84281SC000			<i>R</i>	20.40 <i>X</i>
10	REFLEX AY LH	84281SC010			<i>R</i>	20.40 <i>X</i>
SUB TOTAL			0.00	0.00	0.00	1234.20
LESS DISCOUNT (S/LIST-30 %)			0.00	0.00	0.00	370.26
GRAND TOTAL			0.00	0.00	0.00	863.94
OVERALL TOTAL			863.94			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SLB590K

TOTAL LABOUR CHARGES	1850.00
TOTAL SPARE PARTS CHARGES	863.94
GRAND TOTAL	2713.94 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

*Not wither
1: B.1
Resurvey 34 paint
2 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: