

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0838/2018/KS
Date : 24-Jul-18

Vehicle not IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Ms Lim Ah Gek
Address : 1 Tuo Kong Walk
Singapore 455299
Telephone : HP +65 94529916
Type of Claim : Own Damage Claim
Policy No. : 2100470596-02
Vehicle No : **SLD 5359 U**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Jun-16
Engine No : CZC 562577
Chassis No : WAUZZZ8V2G1104055
Mileage : -
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 21-Jul-18
Place of Accident : PARKWAY PARADE

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle.SLD 5359 U

S/N	Nature of Jobs	Estimated Charges	Surveyor's Recommendation
1	To remove and transfer front wire harness for headlights,horns,fog lamps,outside temperature sensor,headlight washer assy.	S/N \$ 360.00	✓
2	To dismantle and renew front bumper and lhs headlight. Re-organise front crash management components.Reinstall all parts removed.	\$ 1,200.00	500.
3	To respray front bumper and lhs front fender.	\$ 1,400.00	550
5	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ <u>3,152.00</u>	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SLD 5359 U.

		<u>Damage Parts & Prices</u>	
<u>S/N</u>	<u>Parts Description</u>	<u>S/NETT</u>	<u>REMARKS</u>
1	FRONT BUMPER <i>torn</i>	\$ 1,739.00	✓
2	FRONT BUMPER FIXING PARTS ?	\$ 161.00	?
3	FRONT BUMPER TRIM COVER LH / RH ?	2 \$ 280.00	?
4	FRONT BUMPER CLOSING ELEMENT LOWER CENTER <i>torn</i>	\$ 140.00	✓
5	GUIDE SECTION LH ?	\$ 33.00	?
6	AIR GUIDE GRILLE LH ?	\$ 95.00	?
7	RADIATOR GRILLE ?	\$ 573.00	?
8	WHEEL HOUSING LINER LH ?	\$ 151.00	?
9	WHEEL HOUSING ATTACHMENT PARTS ?	\$ 77.00	?
10	HEADLIGHT LH <i>AK</i>	\$ 1,764.00	✓
11	WASHER FLUID RESERVOIR ?	\$ 177.00	?
12	LIFT CYLINDER LH <i>AK</i>	\$ 174.00	✓
13	FRONT NO PLATE ?	S/N \$ 25.00	?
14	SUNDRIES ?	\$ 300.00	?
TOTAL SPARE PARTS CHARGE		\$ 5,689.00	
TOTAL LABOUR CHARGES		\$ 3,152.00	
GRAND TOTAL		\$ 8,841.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2323 Fax: 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 25/07/18.
Authorised Date :
Excess Cost :
Liability :
Remarks : Authorised Repairs, 03 Days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant