

趙 源 摩 哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: India International Insurance Pte Ltd

Accident Date : 20.07.2018

Not Withheld
1-B-1
Presurvey B4 pain
3 day

Policy No: _____
Date: _____
Third Party
24.07.2018

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货 名 DESCRIPTION	单 价 Unit Price	银 Amount 额 \$ cts.
Estimate Cost of Repair to "Suzuki Every" Reg. No. GBB8008S Claiming Against Your Insured Veh. No. SH6533Y			
1pc	Rear Bumper	3.00	<i>Not / cm</i> 785.00 ✓
10pcs	Rear Bumper Clips		<i>nn</i> 30.00 ✓
1pc	Rear Bumper Corner Retainer LH		<i>nn</i> 30.60 ✓
1pc	Rear Bumper Side Splash Guard LH		<i>nn</i> 72.00 X
1pc	Rear Wheel Cap		<i>nn</i> 114.50 ✓
1pc	Rear Wheel Bearing		<i>nn</i> 336.00 X
1pc	Rear Shock Absorber LH		<i>nn</i> 301.00 X
			1,669.10
	Less 15%		250.37
			1,418.74
	To Conduct Electrical Check, Bore Rear Bumper Sensor Hole, Transfer Sensors, Rewiring and Testing etc		120.00 <i>500</i>
	To Dismantle / Replace Rear Wheel Bearing		<i>nn</i> 120.00 X
	To Conduct Computerize Wheel Alignment Test		80.00 <i>600</i>
	Labour Charge - Panel Beating, Repairing Of Rear Fender, Inner Panel, and Parts Replacement		400.00 <i>300</i>
	To Respray Affected Areas		500.00 <i>400</i>
	Total :		2,638.74

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: