# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd. From: LKK Auto Consultants Pte Ltd

AIG Building

51 Ubi Ave 1 #01-25 78 Shenton Way #07-16 Paya Ubi Industrial Park Singapore 079120 Singapore 408933

Attn: Loo, Tong Shing Date: 28 Sep 2018

## **Preliminary Advice**

Vehicle No : SKN6463D **Accident Date** : 23/07/2018 Make : AUDI A4 Policy No. : 2100381999 Assignment Date : 25/07/2018 **Excess** : S\$800.00 Date of Inspection : 25/07/2018 Est. Duration of Repair : 6 days

Inspection At : Premium Automobiles Pte Ltd (UBI)

55 Ubi Road 1 Singapore 408699

#### Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s body and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,981.00 (INCLUSIVE SUPPLEMENTARY)
Revised Amount	:S\$	8,535.04 (INCLUSIVE SUPPLEMENTARY)
Chack Itams (Estimated)	·Q¢	0.00

Check Items (Estimated) :S\$ 0.00 Total :S\$ 8,535.04

Lump Sum Repair :S\$

#### **Total Loss Consideration**

New for Old Value :S\$

Pre-Accident Value :S\$ 77,000.00 COE / PARF Rebate 56,813.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 20,187.00

### Remarks

( X )	The vehicle is repairable at our adjusted amount.	We have also	confirmed	excess and	policy	coverage.
	Kindly let us have your authorisation.					

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: SUPPLEMENTARY AMOUNT \$ 252.16. ( X )