

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

# **SMRT Accident Vehicle Repair Estimates**

CylA

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHD6220B

Ref. No

TAX/07/18/2099

Reg. Date

19/02/2016

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

**PRIUS** 

Name of Driver

MOHAMAD SHUKOR BIN

ISMAIL

Type of Accident

CHAIN COLLISION

Date / Time of Accident

21/07/2018 10:30:00 PM

Accident Reported Date / Time :

23/07/2018 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

Yes

Towed Back Date/Time

21/07/2018

Replacement Vehicle issued? :

Accident Repair Job Card No :

000024097166

Special Instruction to ARC, if any

TOWED \$60/SKU4301P

Prepared Date

23/07/2018 12:21:16 PM

Contract @ STERRET 6555 8888

### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - 10 be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U605767425

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC

Adjusted by Surveyor, if applicable

**Total Labout Charges** 

676.00

0.00

2,110.19

0.00

0.00

0.00

0.00

Total Spray Painting Charges

738.00

Total Material Charges

2,110.19

Other Charges

484.00

TOTAL

4,008.19

Lum Sum Total No. of Repair Days

0.00

5.00

Prepared / Adjusted By

Arc / Surveyor Sing Off Date

: 24/07/2018 07:08:44 AM

01/01/1900 12:00:00 AM

0,00 3 days - p/P

Prepared / Adjusted Date

Remarks

Prepared Date : 24/07/2018 07:08:44 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No.

Invoice No

Quotation Date

Invoice Date :

Invoice Amount :

Prepared Date:

#### Section D - Details of Repair Estimates

#### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	676.00	0.00 350
Total Labour	676.00	0.00

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00
TO RESPRAY BUMPER BEAM	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
Total Spray Painting & Panel Beating	738.00	0.00

# Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by	Surveyor, if applicable
TOWING CHARGE	84.00	0.00	? recript
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00	60
TO REPLACE SUNDRY PARTS	100.00	0.00	×
TO WASH AND VACUUM	60.00	0.00	×
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00	bo
Total Other Costs	484.00	0.00	

AX/07/18/2099

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
90467- 07211			BUMPER CLIPS	10	2.10	25.00	15.75	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace ?	No
52576- 47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace	No
52575- 47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace	No
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace 7	No
52015- 47050			ARM SUB-ASSY, RR BUMPER RH	1	139.60	25.00	104.70	Replace	Replace ?	No
52016- 47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace -	No
76891- 47020		6505619	BUMPER LIP REAR	1	228.90	25.00	171.67	Replace	Replace	No
76088- 47020		6505617	BUMPER LIP COVER RR/LH	1	72.20	25.00	54.15	Replace	Replace	No
76087- 47020		6505618	BUMPER LIP COVER RR/RH	1	118.10	25.00	88.57	Replace	Replace X	No
89997- 30070			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	10.00	141.66	Replace	Replace -	No
58307- 47060		6505522	END PANEL	1	302.10	25.00	451.57	Replace I	Replace	No
C	OMMO	4006314	SEALANT SIKAFLEX	1 :	37.00	0.00	37.00	Replace F		No
		T	OTAL MATERIALS					2,110.21 2	2.110.19	
	TOTAL MATERIALS(Discounted)							2,110.19		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price	ARC Check	Surveyor	LT Check
TOTAL SUPPLEMENTARY MATERIALS						(4)		Offeck	Check