

160 Sin Ming Drive, #05-11,

Sin Ming AutoCity

Singapore 575722

(Registration no :095744/00B)

Tel : 64533100, Fax 62669932

DATE OF ACCIDENT : 23/07/2018

YOUR INSURED

VEHICLE NO : SKN 6463D

Estimate repair cost to HONDA STREAM reg no : SLU 4498 T

1pc o/s/f fender	S\$	509.10	✓
1pc o/s/f fender inner shield		81.50	✓
1pc o/s headlamp		734.10	✓
1pc front bumper		635.60	✓
1pc front bumper retainer		16.10	✓
1pc o/s/f sport rim		1266.20	X
		3242.60	

20%

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

	3242.60
Less 20%	648.52
	2594.08

Labour & misc charges

Panel knocking	600.00	400
Spray painting	700.00	440
Computer wheel alignment	120.00	60
	4014.08	
	4014.08	

HWA SENG SPRAY PAINTING COMPANY



Not within
 1 day @ 1900
 Return After Paint
 4 days