



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SCL3060H
Chassis No : JHMRU1810GX201356
Model : HRV DX-SIN CVT YM 2016
Owner's Name : NG THIAM CHYE
Ins Policy No. :
Date of Accident : 22/7/2018

Document No. : SQT18003074
Date : 24. Jul 2018
Customer No. : WZA006
Svc Advisor :
Engine No : L15B4531356
Date | Time : 24. Jul 2018 10:34:21 AM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SCL3060H OWNER INSURER: NG THIAM CHYE ACC DATE: 22/07/2018 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE PTE LTD TP VEH: SJU7278R						
74450-T7A-003	PROTECTOR,L.RR.WHEEL ARCH	1	86.00	25	64.50	4.52	69.02
42700-T7A-J93	DISK,ALUMINIUM WHEEL	1	721.60	25	541.20	37.88	579.08
					Sum Item	605.70	42.40
							648.10
BOSUN	SUNDRIES	1	60.00		60.00	4.20	64.20
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.	1	1000.00 900		1000.00	70.00	1070.00
					Sum Labor	1060.00	74.20
							1,134.20

Survey By

Date & Time

Excess

Status

Signature

LKR Auto Consultants hence notify the Rep of the following:

- Survey before/after spray painting
- Display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total Amount 1,665.70 116.60 1,782.30

Total (Inclusive of GST) **1,782.30**

NAZ LKK
5/9/18 1145
P/P
3 DAY
AFTER REPAIR PHOTO

Printed on 24/7/2018 10:57:15 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)