

Surveyor:

Taufik

DOI:

ASSIGNMENT


27/7/18

Date / Time:

25/7/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

EN77124

Name of Insured:

LAI HAN HOON

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

27/7/18

Is driver the owner?

( YES / NO )

Nature of Accident:

If NO, Driver Name / Age:

BUNNY LAI FU HAO

Driver Tel No.:

92951511

(V/L: YES / NO)

Claim No.:

Spm 00p0e

Policy No.:

GA 33424

Make / Model:

Shinji SX 4

Place of Accident:

Pungol Myover

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

5LE6205



INSRS:

WSP:

Auto.

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

26/7

man

5LE6205-X;

EN77124 - 66/11009022/1026392; 2018/11

Received TP video.

27/7/18

Road to Riar

13/6

7/12

6/12

13/12

17/12

18/12

Pending finalised from Taufik.

To seek mandate

Pending mandate approval

offer \$8263 (Pending acceptance)

Settle @ \$8263, DV send (Pending DV in).

DV in, File pass me to close.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Taufik

Repair Cost:

US

SS 7800

(7 days)

Reduction: \$707.12 % 48

Email

Call

FINAL SETTLEMENT

Date/Time:

17/12/18

Confirm with:

Christi

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27.

If NO or B 28, Ass. Lia:

Repair Cost:

(US\$)

SS 7811.00

(LTA instruction).

Loss of Rental (LOR):

SS

( days)

Loss of Use (LOU):

SS

450.00

(\$ 50

x

9 days)

Loss of income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

Legal Cost

SS

(e.g. Tow/ Independent)

Total:

SS

2763.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

8263.00

Name 1:

Blite Automotive Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

X GIA

Taufel

REF:

AXA


13560/71wa3 (W)

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop m/s \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No: \_\_\_\_\_  
 Claims No: \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$73K  
 IDAC Accident Rpt: Consistent? : Yes or No  
 GlA / PR Seen: Consistent? : Yes or No  
 Est. Repairs: 7 days Res: Yes or No  
 Lump Sum: 20 % 3 Val: Yes or No  
 CA / REV / REP: / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_  
 Vehicle: IN / OUT

Veh No: 9LE620S Yr Regn: 2016 July  
 Type: M.Va / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or  
 Make: Honda Shuttle o.c. 1496  
 Colour: silver A/C: Insured / Std / NI / NA  
 Sp. Reading: 032649 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: GK8100 3985  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: Inorder / Jammed / Leaked / Burnt or  
 Brake: Inorder / Jammed / Leaked / Burnt or  
 Modi: Nil / S/Rim / STD A/Rim or  
 Tyre Size: F: 185/60R15  
 R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or

Front 6 mm Rear 6 mm  
 R/Bal. 6 mm L/Bal. 6 mm

D.O.A. 25/7/18 @ 445pm  
 Survey held at Elite 280 WL Ind PKE 5 #01-17  
 Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

US \$7500 (Red = \$7017.12/48%)  
eliteautomotive13@gmail.com

→ 7 repair days + 1 Saturday + 1 Sunday + 2 PPS = 11 days.

Date/Time: File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1) S + PS \$

2) Photos

3) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)

☐ : Inter/iew (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

# ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLE 620S

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81003985

Estimated Repair Cost

| S/N | Parts Description                       | Qty | List Price               |
|-----|-----------------------------------------|-----|--------------------------|
| 1   | BOOT LID                                | 1   | \$ 1193.00 <i>ht</i>     |
| 2   | BOOT LID "SHUTTLE" EMBLEM               | 1   | \$ 66.00 <i>ner</i>      |
| 3   | BOOT LID "H" LOGO                       | 1   | \$ 45.60 <i>ner</i>      |
| 4   | BOOT LID LAMP LHS & RHS                 | 2   | \$ 790.00 <i>x ner</i>   |
| 5   | BOOT LID LOCK                           | 1   | \$ 157.10 <i>del</i>     |
| 6   | BOOT LID WEATHERSTRIP                   | 1   | \$ 168.50 <i>del</i>     |
| 7   | BOOT LID CENTRE CHROME MOULDING         | 1   | \$ 383.10 <i>x ner</i>   |
| 8   | REAR SCREEN INNER SEAL                  | 1   | \$ 120.00 <i>ner</i>     |
| 9   | TAILLAMP (LHS & RHS)                    | 2   | \$ 1041.00 <i>x ner</i>  |
| 10  | BOOT LID INNER TRIM BOARD               | 1   | \$ 320.00 <i>x ner</i>   |
| 11  | BOOT LID INNER TRIM BOARD CLIPS         | 10  | \$ 50.00 <i>x ner 20</i> |
| 12  | TAILLAMP LOWER BRACKET (LHS & RHS)      | 2   | \$ 97.40 <i>? del</i>    |
| 13  | REAR BUMPER                             | 1   | \$ 1150.60 <i>del</i>    |
| 14  | REAR BUMPER RETAINER (LHS & RHS)        | 2   | \$ 53.00 <i>? del</i>    |
| 15  | REAR BUMPER CLIPS                       | 10  | \$ 50.00 <i>ner</i>      |
| 16  | REAR BUMPER REFLECTOR (LHS & RHS)       | 2   | \$ 100.00 <i>x ner</i>   |
| 17  | REAR BUMPER REFLECTOR COVER (LHS & RHS) | 2   | \$ 90.00 <i>x ner</i>    |
| 18  | END PANEL                               | 1   | \$ 560.80 <i>ht</i>      |
| 19  | TOWING CAP                              | 1   | \$ 16.50 <i>del</i>      |
| 20  | END PANEL UPPER GARNISH                 | 1   | \$ 155.50 <i>del</i>     |
| 21  | BOOT LID ABSORBER (LHS & RHS)           | 2   | \$ 330.00 <i>x ner</i>   |
| 22  | SPARE TYRE BOARD                        | 1   | \$ 585.50 <i>x ner</i>   |
| 23  | BOOT LID WIPER                          | 1   | \$ 66.50 <i>x ner</i>    |
| 24  | BOOT LID WIPER MOTOR                    | 1   | \$ 490.00 <i>x ner</i>   |
| 25  | FENDER INNER TRIM (LH & RH)             | 2   | \$ 979.20 <i>? ner</i>   |
| 26  | SPARE TYRE TANK                         | 1   | \$ 1980.00 <i>Rx</i>     |
| 27  | REAR NUMBER PLATE LIGHT                 | 2   | \$ 77.00 <i>x ner</i>    |
| 28  | BOOT LID HANDLE COVER                   | 1   | \$ 19.60 <i>del</i>      |
| 29  | EXHAUST SILENCER                        | 1   | \$ 745.00 <i>x Rx bt</i> |
| 30  | EXHAUST MOUNTING                        | 2   | \$ 33.00 <i>x ner</i>    |
| 31  | SPARE TYRE TOOL BOX                     | 1   | \$ 245.00 <i>del</i>     |
|     |                                         |     | 12158.90                 |

Supplementary

\* Corner panel (LH & RH) @ 250 each

3500  
bt

Discount Less 20% \$ 2431.78  
List Prices Total \$ 9,727.12

8083.80 + 500 = 8583.80  
20% - 6868.84

# ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLE620S

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81003985

| S/N | Labour Descriptions                                                                                                                                                                                    | Charges                |
|-----|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------|
| 1   | LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD REAR END PANEL, TO STRAIGHTEN & REPAIR REAR FLOOR PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE. | \$ 2000.00 1000        |
| 2   | TO SPRAY PAINTING ON BOOT LID (INNER & OUTER), END PANEL, REAR FLOOR PANEL, REAR BUMPER, FENDER LH & RH                                                                                                | \$ 1800.00 1000<br>900 |
| 3   | TO REMOVE & INSTALL REAR CARPETING, TRIMMINGS.                                                                                                                                                         | \$ 150.00 60           |
| 4   | TO DRILL HOLES AND REPLACE REVERSE SENSOR & TEST FUNCTIONS.                                                                                                                                            | \$ 80.00 30            |
| 5   | TO CHECK WIRINGS & REAR LIGHT FUNCTIONS.                                                                                                                                                               | \$ 50.00 30            |
| 6   | TO CHECK & RESET E.C.U UNIT SYSTEM AND REMOVE FAULT CODES AFTER ACCIDENT NECESSARY REPAIRS.                                                                                                            | \$ 180.00 100          |
| 7   | WHEEL ALIGNMENT.                                                                                                                                                                                       | \$ 120.00 X nn         |

Labour Total \$ 4380.00 2320

Parts & Labour Total \$ 14517.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749 14/17/12  
WP 23/7/18 @ 445pm  
Kumpsum  
Resurvey after repair.  
sure@lkkauto.com  
7 days

# ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

| S/N                      | Special Nett Items:           | Qty |    |          |                       |
|--------------------------|-------------------------------|-----|----|----------|-----------------------|
| 1                        | REAR NUMBER PLATE WITH HOLDER | 1   | \$ | 60.00    | 45 bt ✓               |
| 2                        | REVERSE SENSOR                | 2   | \$ | 350.00   | 200 <del>8</del> nw ✓ |
| Special Nett Total       |                               |     | \$ | 410.00   | 245                   |
| Spare Part's Total Price |                               |     | \$ | 10137.12 |                       |

280 Woodlands Industrial Park E5, #01-17,  
Harvest @ Woodlands Singapore 757322  
Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLE 620S  
Vehicle Model : HONDA SHUTTLE  
Chassis Number : GK81003985

68418625

Estimated Repair Cost

| N  | Parts Description                         | Qty | List Price              |
|----|-------------------------------------------|-----|-------------------------|
| 1  | BOOT LID                                  | 1   | \$ 1193.00 <i>ht</i>    |
| 2  | BOOT LID "SHUTTLE" EMBLEM                 | 1   | \$ 66.00 <i>har</i>     |
| 3  | BOOT LID "H" LOGO                         | 1   | \$ 45.60 <i>na</i>      |
| 4  | BOOT LID LAMP LHS & RHS                   | 2   | \$ 790.00 <i>x</i>      |
| 5  | BOOT LID LOCK                             | 1   | \$ 157.10 <i>del</i>    |
| 6  | BOOT LID WEATHERSTRIP                     | 1   | \$ 168.50 <i>del</i>    |
| 7  | BOOT LID CENTRE CHROME MOULDING           | 1   | \$ 383.10 <i>x crn</i>  |
| 8  | REAR SCREEN INNER SEAL                    | 1   | \$ 120.00 <i>del</i>    |
| 9  | TAILLAMP (LHS & RHS) ✓                    | 2   | \$ 1041.00 <i>x crn</i> |
| 10 | BOOT LID INNER TRIM BOARD                 | 1   | \$ 320.00 <i>x del</i>  |
| 11 | BOOT LID INNER TRIM BOARD CLIPS           | 10  | \$ 50.00 <i>x rec w</i> |
| 12 | TAILLAMP LOWER BRACKET (LHS & RHS) ✓      | 2   | \$ 97.40 <i>x rec</i>   |
| 13 | REAR BUMPER                               | 1   | \$ 1150.60 <i>del</i>   |
| 14 | REAR BUMPER RETAINER (LHS & RHS)          | 2   | \$ 53.00 <i>R</i>       |
| 15 | REAR BUMPER CLIPS                         | 10  | \$ 50.00 <i>na</i>      |
| 16 | REAR BUMPER REFLECTOR (LHS & RHS)         | 2   | \$ 100.00 <i>x</i>      |
| 17 | REAR BUMPER REFLECTOR COVER (LHS & RHS) ✓ | 2   | \$ 90.00 <i>x crn</i>   |
| 18 | END PANEL                                 | 1   | \$ 560.80 <i>del</i>    |
| 19 | TOWING CAP                                | 1   | \$ 16.50 <i>del</i>     |
| 20 | END PANEL UPPER GARNISH                   | 1   | \$ 155.50 <i>del</i>    |
| 21 | BOOT LID ABSORBER (LHS & RHS)             | 2   | \$ 330.00 <i>x</i>      |
| 22 | SPARE TYRE BOARD                          | 1   | \$ 585.50 <i>x</i>      |
| 23 | BOOT LID WIPER                            | 1   | \$ 66.50 <i>x</i>       |
| 24 | BOOT LID WIPER MOTOR                      | 1   | \$ 490.00 <i>x</i>      |
| 25 | FENDER INNER TRIM (LH & RH) ✓             | 2   | \$ 979.20 <i>R</i>      |
| 26 | SPARE TYRE TANK                           | 1   | \$ 1980.00 <i>R</i>     |
| 27 | REAR NUMBER PLATE LIGHT                   | 2   | \$ 77.00 <i>x</i>       |
| 28 | BOOT LID HANDLE COVER                     | 1   | \$ 19.60 <i>del</i>     |
| 29 | EXHAUST SILENCER                          | 1   | \$ 745.00 <i>x bt</i>   |
| 30 | EXHAUST MOUNTING                          | 2   | \$ 33.00 <i>x</i>       |
| 31 | SPARE TYRE TOOL BOX                       | 1   | \$ 245.00 <i>del</i>    |
|    |                                           |     | 12158.90                |

7706.90

supplementary

corner panel (LH & RH)

Discount Less 20%  
List Prices Total

*bt* ✓ \$750 x 2

= \$500

\$ 2431.78  
\$ 9,727.12

6165.52

7676.90

## ◀ Service Request Details

Claim

S8M00POE

Reference

None ✎

Christy veh in

Loss Date

July 23, 2018

25/7/2018 @ 10-51am

Request Date

July 25, 2018

Tunkh

Due Date

August 1, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

### Actions

Next Step

Agree to perform service

Decline Work

Accept Work

### Vehicle Information

Incident Vehicle Registration #

SLE620S

Make

TPVD HONDA

Model

SHUTTLE 1.5G CVT Exact Purpose

Service Address

...

Primary Contact/Insured

LAI WAI HOONG

254 COMPASSVALE ROAD, #14-710, 540254, Singapore

92951511

WAIHOONGLAI@HOTMAIL.COM

Claim Handler

CHAN Kian Chuan

6568804269

kianchuan.chan@axa.com.sg

Additional Instructions

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

New Message



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

## Immediate Advice

To : AXA Insurance Pte Ltd

Date: 6/12/2019

### Survey Details:

|                     |                          |
|---------------------|--------------------------|
| Date of loss        | 23-Jul-18                |
| Date of appointment | 25-Jul-18                |
| Date of survey      | 25-Jul-18                |
| Location of survey  | Elite Automotive Pte Ltd |

### Vehicle Details:

|                      |                                 |
|----------------------|---------------------------------|
| Claim Type:          | THIRD PARTY CLAIM               |
| Vehicle number       | SLE 620S                        |
| Make and Model       | HONDA SHUTTLE 1.5G CVT - 1496cc |
| Date of registration | 5-Jul-16                        |
| Excess               |                                 |
| Market Value         | \$ 73,000.00                    |
| Parf Rebate          | \$ 48,331.00                    |
| Nett Loss            | \$ 24,669.00                    |

### Repair details:

|                  |           |
|------------------|-----------|
| Initial Estimate | 10,137.12 |
|------------------|-----------|

### Proposed/Revised repair cost:

|                                |                    |
|--------------------------------|--------------------|
| Parts                          | \$ 7,112.04        |
| Check items (estimate)         | \$ -               |
| Labour                         | \$ 2,320.00        |
| <b>Total</b>                   | <b>\$ 9,432.04</b> |
| <b>Lump Sum(if applicable)</b> | <b>\$ 7,500.00</b> |

|                           |               |
|---------------------------|---------------|
| Number of days for repair | <u>7 days</u> |
|---------------------------|---------------|



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

**Remarks:**

07 RECOMMENDED REPAIR DAYS + 1 SATURDAY + 1 SUNDAY + 2 PRS  
= 11 DAYS

**Mandate:**

| Liability(TP)        |    | 100%     |                  |
|----------------------|----|----------|------------------|
| Proposed repair cost | \$ | 8,025.00 | W/GST            |
| Loss of use          | \$ | 660.00   | 11days x \$60.00 |
| Loss of rental       | \$ | -        |                  |
| Loss of income       | \$ | -        |                  |
| LTA search fees      | \$ | 2.00     |                  |
| Others               |    | -        |                  |
| Proposed Total       |    | 8,687.00 |                  |



## <MANDATE IA> - S8M00POE {ACCIDENT INVOLVING EN 2712H & SLE 620S ON 23/02/2018}

Type

🔗 Question

Message

LIABILITY: 100% BOLA S27 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8,687.00 (CLAIMING LOU). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply



**Re:<MANDATE IA> - S8M00POE {ACCIDENT  
INVOLVING EN 2712H & SLE 620S ON 23/02/2018}**

Type

🔗 Question

Message

PLS PROCEED AS FOLLOWS: COR \$7,811 W/GST LOU: \$450.00 LTA: \$2.00 TOTAL: \$8,263.00

Reply

## ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17 Harvest @ Woodlands (S) 757322

Tel : 63397378/ 86606722 Fax: 63397475

Reg No: 201700196D GST Reg No: 201700196D

Date : 03/12/2019

OUR REF : TP/SLE 620S/19

M/S : AXA INSURANCE PTE LTD  
8 SHENTON WAY  
#27-01  
SINGAPORE 068811

Statement Of Claim On Veh No : SLE 620S  
MODEL : HONDA SHUTTLE

LUMP SUM OF REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

|                                |       |                   |
|--------------------------------|-------|-------------------|
| PANEL BEATING & SPRAY PAINTING |       | \$7,500.00        |
|                                | 7%GST | \$525.00          |
|                                |       | <u>\$8,025.00</u> |
| LOSS OF USE (\$120 X 14DAYS)   |       | \$1,680.00        |
| *PRE-REPAIR INSPECTION         |       |                   |
| *INCLU WEEKEND                 |       |                   |
| *POST REPAIR                   |       |                   |
| LTA SEARCH                     |       | \$2.00            |
|                                |       | <u>\$9,707.00</u> |



# Elite Automotive Pte Ltd

23HRS SERVICES

Co.Regn No: 201700196D

GST.Reg.No: 201700196D

280 Woodlands Industrial Park E5 #01-17 Harvest@Woodlands (S) 757322

Hotline: 8660 6722 Tel: 6339 7378 Fax: 6339 7475 Email: elite.automotive13@gmail.com

TAX INVOICE NO : EA1912-616

Messrs : AXA INSURANCE PTE LTD

Date : 17/12/2019

Address : 8 SHENTON WAY, #27-01  
SINGAPORE 068811

E mail : \_\_\_\_\_ Mobile : \_\_\_\_\_ Home/Office Tel : \_\_\_\_\_

| No    | Description                                                | Qty    | Amount      |
|-------|------------------------------------------------------------|--------|-------------|
|       | <u>OUR REF : TP/SLE 620S/19</u>                            |        |             |
|       | <u>ACCIDENT INVOLVING SLE 620S AND EN 2712H ON 23/7/18</u> |        |             |
|       | <u>VEHICLE NO: SLE 620S (HONDA SHUTTLE)</u>                |        |             |
|       |                                                            |        |             |
| 1     | COST OF REPAIR                                             | 1      | \$ 7,300.00 |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        |             |
|       |                                                            |        | \$ 7,300.00 |
|       |                                                            | GST 7% | \$ 511.00   |
| Total |                                                            |        | \$ 7,811.00 |



*Christy*

Elite Automotive Pte Ltd

Customer Signature & Company Stamp



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013560/T1ga3s2

8 SHENTON WAY #24-01  
AXA TOWERS SINGAPORE 068811

Date : 27-12-2019



ATTN: KIAN CHUAN

Code : ASM

## 1. Policy Particulars :- THIRD PARTY CLAIM

|              |            |                |            |
|--------------|------------|----------------|------------|
| Insured Veh. | EN 2712H   | Veh. Inspected | SLE 620S   |
| Policy No.   | GA334224   | Coverage (\$)  | 0.00       |
| Claim No.    | S8M00POE   | Excess (\$)    | 0.00       |
| Assign From  | KIAN CHUAN | Assign Date    | 25/07/2018 |

## 2. Vehicle Particulars & Condition

|              |               |              |            |
|--------------|---------------|--------------|------------|
| Make & Model | HONDA SHUTTLE | c.c          | 1496       |
| Engine No.   | HIDDEN        | Year of Reg. | 2016       |
| Chassis No.  | GK81003985    | Colour       | SILVER     |
| Odometer     | 031649        | Steering     | IN ORDER   |
| Brakes       | IN ORDER      | Modification | SPORTS RIM |
| General      | GOOD          |              |            |

## 3. Conditions of Tyres

|                | Size       | Make     | Balance |
|----------------|------------|----------|---------|
| R/H Front Tyre | 185/60 R15 | YOKOHAMA | 6 mm    |
| L/H Front Tyre | 185/60 R15 | YOKOHAMA | 6 mm    |
| R/H Rear Tyre  | 185/60 R15 | YOKOHAMA | 6 mm    |
| L/H Rear Tyre  | 185/60 R15 | YOKOHAMA | 6 mm    |

## 4. Description of Damages

|                                                                            |
|----------------------------------------------------------------------------|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.<br>DAMAGES SEE DETAILS. |
|----------------------------------------------------------------------------|

## 5. General Information

|                |                                                                                                           |                 |            |
|----------------|-----------------------------------------------------------------------------------------------------------|-----------------|------------|
| Accident Date  | 23/07/2018                                                                                                | Inspection Date | 25/07/2018 |
| Survey held at | ELITE AUTOMOTIVE PTE LTD<br>280 WOODLANDS INDUSTRIAL PARK E5 #01-17 HARVEST@WOODLANDS<br>SINGAPORE 757322 |                 |            |

## 5a. Remarks

|                                                                                                                                           |
|-------------------------------------------------------------------------------------------------------------------------------------------|
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|-------------------------------------------------------------------------------------------------------------------------------------------|

## 5b. Estimate Days of Repair

|                                     |                |
|-------------------------------------|----------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 7 Working Days |
|-------------------------------------|----------------|



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLE 620S

| Qty                         | Description of Parts                                 | Condition            | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|------------------------------------------------------|----------------------|---------------------------|-------------------|
| <b>REPLACEMENT OF PARTS</b> |                                                      |                      |                           |                   |
| 1                           | BOOT LID (CONSISTENT)                                | BENT                 | 1,193.00                  | 1,193.00          |
| 1                           | BOOT LID "SHUTTLE" EMBLEM (CONSISTENT)               | NECESSARY            | 66.00                     | 66.00             |
| 1                           | BOOT LID "H" LOGO (CONSISTENT)                       | NECESSARY            | 45.60                     | 45.60             |
| 2                           | BOOT LID LAMP LHS & RHS (CONSISTENT)                 | CRACKED              | 790.00                    | 790.00            |
| 1                           | BOOT LID LOCK (CONSISTENT)                           | DENTED               | 157.10                    | 157.10            |
| 1                           | BOOT LID WEATHERSTRIP (CONSISTENT)                   | TWISTED              | 168.50                    | 168.50            |
| 1                           | BOOT LID CENTRE CHROME MOULDING (CONSISTENT)         | NOT NECESSARY        | 383.10                    | -                 |
| 1                           | REAR SCREEN INNER SEAL (CONSISTENT)                  | NECESSARY            | 120.00                    | 120.00            |
| 2                           | TAILLAMP (LHS & RHS) (CONSISTENT)                    | CRACKED              | 1,041.00                  | 1,041.00          |
| 1                           | BOOT LID INNER TRIM BOARD (CONSISTENT)               | CRACKED              | 320.00                    | 320.00            |
| 10                          | BOOT LID INNER TRIM BOARD CLIPS (CONSISTENT)         | NECESSARY            | 50.00                     | 20.00             |
| 2                           | TAILLAMP LOWER BRACKET (LHS & RHS) (CONSISTENT)      | DISTORTED            | 97.40                     | 97.40             |
| 1                           | REAR BUMPER (CONSISTENT)                             | DEFORMED             | 1,150.60                  | 1,150.60          |
| 2                           | REAR BUMPER RETAINER (LHS & RHS) (CONSISTENT)        | DISTORTED            | 53.00                     | 53.00             |
| 10                          | REAR BUMPER CLIPS (CONSISTENT)                       | NECESSARY            | 50.00                     | 50.00             |
| 2                           | REAR BUMPER REFLECTOR (LHS & RHS) (CONSISTENT)       | NOT NECESSARY        | 100.00                    | -                 |
| 2                           | REAR BUMPER REFLECTOR COVER (LHS & RHS) (CONSISTENT) | CRACKED              | 90.00                     | 90.00             |
| 1                           | END PANEL (CONSISTENT)                               | BENT                 | 560.80                    | 560.80            |
| 1                           | TOWING CAP (CONSISTENT)                              | DEFORMED             | 16.50                     | 16.50             |
| 1                           | END PANEL UPPER GARNISH (CONSISTENT)                 | DEFORMED             | 155.50                    | 155.50            |
| 2                           | BOOT LID ABSORBER (LHS & RHS) (CONSISTENT)           | NOT NECESSARY        | 330.00                    | -                 |
| 1                           | SPARE TYRE BOARD (CONSISTENT)                        | NOT NECESSARY        | 585.50                    | -                 |
| 1                           | BOOT LID WIPER (CONSISTENT)                          | NOT NECESSARY        | 66.50                     | -                 |
| 1                           | BOOT LID WIPER MOTOR (CONSISTENT)                    | NOT NECESSARY        | 490.00                    | -                 |
| 2                           | FENDER INNER TRIM (LH & RH) (CONSISTENT)             | CRACKED              | 979.20                    | 979.20            |
| 1                           | SPARE TYRE TANK (CONSISTENT)                         | TO REPAIR SEE LABOUR | 1,980.00                  | -                 |
| 2                           | REAR NUMBER PLATE LIGHT (CONSISTENT)                 | NOT NECESSARY        | 77.00                     | -                 |
| 1                           | BOOT LID HANDLE COVER (CONSISTENT)                   | DEFORMED             | 19.60                     | 19.60             |
| 1                           | EXHAUST SILENCER (CONSISTENT)                        | BENT                 | 745.00                    | 745.00            |

Report Ref No. CC4/ASM18013560/T1ga3s2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

| Qty                                                                         | Description of Parts                                                                                                                                                                                                                               | Condition     | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------------|-------------------|
| 2                                                                           | EXHAUST MOUNTING (CONSISTENT)                                                                                                                                                                                                                      | NOT NECESSARY | 33.00                     | -                 |
| 1                                                                           | SPARE TYRE TOOL BOX (CONSISTENT)                                                                                                                                                                                                                   | DEFORMED      | 245.00                    | 245.00            |
| 2                                                                           | CORNER PANEL (LH & RH) @ \$250.00 (CONSISTENT)                                                                                                                                                                                                     | BENT          | 500.00                    | 500.00            |
|                                                                             | LESS 20% DISCOUNT                                                                                                                                                                                                                                  |               | -2,531.78                 | -1,716.76         |
|                                                                             |                                                                                                                                                                                                                                                    |               | 10,127.12                 | 6,867.04          |
|                                                                             | <b><u>SPECIAL NETT ITEMS</u></b>                                                                                                                                                                                                                   |               |                           |                   |
| 1                                                                           | REAR NUMBER PLATE WITH HOLDER (SN) (CONSISTENT) (ADDITIONAL)                                                                                                                                                                                       | BENT          | 60.00                     | 45.00             |
| 2                                                                           | REVERSE SENSOR (SN) (CONSISTENT) (ADDITIONAL)                                                                                                                                                                                                      | NOT WORKING   | 350.00                    | 200.00            |
|                                                                             |                                                                                                                                                                                                                                                    |               | 410.00                    | 245.00            |
|                                                                             | <b><u>LABOUR</u></b>                                                                                                                                                                                                                               |               |                           |                   |
|                                                                             | LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD REAR END PANEL, TO STRAIGHTEN & REPAIR REAR FLOOR PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE. INCLUSIVE OF THE REPAIR OF SPARE TYRE TANK. |               | 2,000.00                  | 1,100.00          |
|                                                                             | TO SPRAY PAINTING ON BOOT LID (INNER & OUTER), END PANEL, REAR FLOOR PANEL, REAR BUMPER, FENDER LH & RH.                                                                                                                                           |               | 1,800.00                  | 1,000.00          |
|                                                                             | TO REMOVE & INSTALL REAR CARPETING, TRIMMINGS.                                                                                                                                                                                                     |               | 150.00                    | 60.00             |
|                                                                             | TO DRILL HOLES AND REPLACE REVERSE SENSOR & TEST FUNCTIONS.                                                                                                                                                                                        |               | 80.00                     | 30.00             |
|                                                                             | TO CHECK WIRINGS & REAR LIGHT FUNCTIONS.                                                                                                                                                                                                           |               | 50.00                     | 30.00             |
|                                                                             | TO CHECK & RESET E.C.U UNIT SYSTEM AND REMOVE FAULT CODES AFTER ACCIDENT NECESSARY REPAIRS.                                                                                                                                                        |               | 180.00                    | 100.00            |
|                                                                             | WHEEL ALIGNMENT.                                                                                                                                                                                                                                   | NOT NECESSARY | 120.00                    | -                 |
|                                                                             |                                                                                                                                                                                                                                                    |               | 4,380.00                  | 2,320.00          |
| <b>GRAND TOTAL</b>                                                          |                                                                                                                                                                                                                                                    |               | <b>14,917.12</b>          | <b>9,432.04</b>   |
| <b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b> |                                                                                                                                                                                                                                                    |               |                           | <b>7,500.00</b>   |

Report Ref No. CC4/ASM18013560/T1ga3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.