

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLE 620S

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81003985

Estimated Repair Cost

S/N	Parts Description	Qty		List Price
1	BOOT LID	1	\$	1193.00 <i>by</i>
2	BOOT LID "SHUTTLE" EMBLEM	1	\$	66.00 <i>wa</i>
3	BOOT LID "H" LOGO	1	\$	45.60 <i>wa</i>
4	BOOT LID LAMP LHS & RHS	2	\$	790.00 <i>x</i>
5	BOOT LID LOCK	1	\$	157.10 <i>de</i>
6	BOOT LID WEATHERSTRIP	1	\$	168.50 <i>wi</i>
7	BOOT LID CENTRE CHROME MOULDING	1	\$	383.10 <i>x</i>
8	REAR SCREEN INNER SEAL	1	\$	120.00 <i>wa</i>
9	TAILLAMP (LHS & RHS)	2	\$	1041.00 <i>x</i>
10	BOOT LID INNER TRIM BOARD	1	\$	320.00 <i>x</i>
11	BOOT LID INNER TRIM BOARD CLIPS	10	\$	50.00 <i>x</i>
12	TAILLAMP LOWER BRACKET (LHS & RHS)	2	\$	97.40 <i>?</i>
13	REAR BUMPER	1	\$	1150.60 <i>de</i>
14	REAR BUMPER RETAINER (LHS & RHS)	2	\$	53.00 <i>?</i>
15	REAR BUMPER CLIPS	10	\$	50.00 <i>wa</i>
16	REAR BUMPER REFLECTOR (LHS & RHS)	2	\$	100.00 <i>x</i>
17	REAR BUMPER REFLECTOR COVER (LHS & RHS)	2	\$	90.00 <i>x</i>
18	END PANEL	1	\$	560.80 <i>by</i>
19	TOWING CAP	1	\$	16.50 <i>de</i>
20	END PANEL UPPER GARNISH	1	\$	155.50 <i>de</i>
21	BOOT LID ABSORBER (LHS & RHS)	2	\$	330.00 <i>x</i>
22	SPARE TYRE BOARD	1	\$	585.50 <i>x</i>
23	BOOT LID WIPER	1	\$	66.50 <i>x</i>
24	BOOT LID WIPER MOTOR	1	\$	490.00 <i>x</i>
25	FENDER INNER TRIM (LH & RH)	2	\$	979.20 <i>?</i>
26	SPARE TYRE TANK	1	\$	1980.00 <i>Ry</i>
27	REAR NUMBER PLATE LIGHT	2	\$	77.00 <i>x</i>
28	BOOT LID HANDLE COVER	1	\$	19.60 <i>de</i>
29	EXHAUST SILENCER	1	\$	745.00 <i>x</i>
30	EXHAUST MOUNTING	2	\$	33.00 <i>x</i>
31	SPARE TYRE TOOL BOX	1	\$	245.00 <i>de</i>
				<u>12158.90</u>

Discount Less	20%	\$	2431.78
List Prices Total		\$	<u>9,727.12</u>

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

S/N	Special Nett Items:	Qty			
1	REAR NUMBER PLATE WITH HOLDER	1	\$	60.00	45 bt ✓
2	REVERSE SENSOR	2	\$	350.00	200?
Special Nett Total			\$	410.00	
Spare Part's Total Price			\$	10137.12	

ELITE AUTOMOTIVE PTE LTD

280 Woodlands Industrial Park E5, #01-17,

Harvest @ Woodlands Singapore 757322

Tel: 6339 7378 Fax: 6339 7475

Vehicle Number : SLE620S

Vehicle Model : HONDA SHUTTLE

Chassis Number : GK81003985

S/N	Labour Descriptions	Charges
1	LABOUR CHARGES TO REMOVE & INSTALL REAR END ATTACHMENTS & FITTINGS TO ENABLE REPAIRS; TO CUT & WELD REAR END PANEL, TO STRAIGHTEN & REPAIR REAR FLOOR PANEL, TO REPLACE DAMAGED PARTS AS LISTED ABOVE.	\$ 2000.00 1600
2	TO SPRAY PAINTING ON BOOT LID (INNER & OUTER), END PANEL, REAR FLOOR PANEL, REAR BUMPER, FENDER LH & RH	\$ 1800.00 1000 900
3	TO REMOVE & INSTALL REAR CARPETING, TRIMMINGS.	\$ 150.00 60
4	TO DRILL HOLES AND REPLACE REVERSE SENSOR & TEST FUNCTIONS.	\$ 80.00 30
5	TO CHECK WIRINGS & REAR LIGHT FUNCTIONS.	\$ 50.00 30
6	TO CHECK & RESET E.C.U UNIT SYSTEM AND REMOVE FAULT CODES AFTER ACCIDENT NECESSARY REPAIRS.	\$ 180.00 100
7	WHEEL ALIGNMENT.	\$ 120.00 X

Labour Total \$ 4380.00

Parts & Labour Total \$ 14517.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jiah 97495749
WP 23/7/18 @ 445pm
Lumpsum
Resurvey after repair.
sure@lkkauto.com
7 days