

Jhs (in)

CC 4, Asm 180

13569,

Kua3%

LKK
DAC

59337

Surveyor:

cc 6

DOI:

ASSIGNMENT

23/7/18

Date / Time:

24/7/18

Registered in Merimen:

Pre-assign / CCU / FTE

XE1694E "VIP" car



Insured Vehicle No.:

Name of Insured:

SH1 Global Pte

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

19/7/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Woon Chai Sen

Driver Tel No.:

88589884

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

S8 moupaw

m-BMW 333Hc

top of H.

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability:

Final ? Yes / No

SLR 6736J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Esteem Pte



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

23/7
TH

SLR 6736J - X

XE1694E - ES3/Fc1 1700 1584/M19 h3m2

08/12/17

OID Reversed collided onto TP.

19/6/19

Seek mandate via SMART.

19/10/19

Mandate approve via SMART

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

fmr

Sent By:

26/7

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

11/7/19

Confirm with:

fmr

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

NIL.

If NO or B 28, Ass. Lia:

Repair Cost:

S\$ 2623.93

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$ 200.00

(S

50 x 4 days)

Loss of Income (LOI):

S\$

(S

x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ 7.45

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$ 2901.38

Global Sum S\$:

2900.00

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 2900.00

Name 1:

Esteem Performance Pte Ltd

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF:

ASMA(A)

SYNOPSIS

ASSIGNMENT

From:

Date:

25/7/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SLR 6736J

at Workshop n/a

Eskum Performance

of

385 Sin Ming Dr

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

'Virtual'

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

870k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR. Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res: Yes or No

Lum Sum:

2.8.2

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle IN / OUT

Veh No:

SLR 6736J

Yr Regn:

08 17

Type: ☒ M.Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /

Truck / Trailer or

Make:

Toy vic

CC:

1496

Colour:

White

A/C:

Insured / Std / NI / NA

Sp. Reading:

28812

T/Radio: Insured / Std / NI / NA

Eng No:

C/No:

MHF-B29F-3702013264

Gen. Cond: ☒ Good / ☐ Fair / ☐ Poor / ☐ BurntSteering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt orBrake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: Yoko

195/50R16

R: B.S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

3

mm

L/Bal.

4

mm

L/Bal.

3

mm

D.O.A.

19/7/18

D.O.L.

25/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rec

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

26/7

File pass to Coroner

10/7/19

Confirm 2.B.2 \$257.70 with 4 working days

(200) = \$2970.38
54.1.)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

Report Format:

Lump Sum / I.B.I: (\$)

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

TOTAL



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLR 6736 J

Parts	(a) Cost / List Price Items	\$	3,920.10
	Plus/Less 25%	\$	980.03
	Total of Cost / List	\$	2,940.08
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
Total Parts Cost		\$	2,940.08
Labour		\$	2,550.00
Total		\$	5,490.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor

Company

Survey conducted on

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor

Date: 25/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg


Spare Parts

Vehicle No. :	SLR 6736 J	Submit By :	Carmen Lim
Make & Model :	TOYOTA VIOS	Year Manufacture :	2017
Chassis No. :	MHFB29F3702013264	Engine No. :	

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door <i>Rh</i>	1	\$1,198.70		✓
2	RH rear door hinge top	1	\$78.20		✗
3	RH rear door hinge bottom <i>hw</i>	1	\$78.20		✗
4	RH rear door lock	1	\$418.70		✗
5	RH rear door checker <i>h</i>	1	\$155.75		✗
6	RH rear door weatherstip <i>hw</i>	1	\$158.40		✗
7	RHR door outer handle <i>h, r</i>	1	\$79.80		✓
8	RHR door outer handle side cover <i>h</i>	1	\$62.70		✗
9	RHR door glass outer moulding <i>h</i>	1	\$101.79		✓
10	RHR power window motor <i>h</i>	1	\$511.67		✓
11	RHR power window regulator <i>h</i>	1	\$198.30		✓
12	RH rear door trim <i>hw</i>	1	\$827.80		✗
13	RH rear door trim clip	10	\$50.00		✗
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



Vehicle No. : SLR 6736 J Submit By : Carmen Lim
Make & Model : TOYOTA VIOS Year of Manufacture : 2017

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Your Ref : XE 1694 E
Our Ref : SLR 6736 J

Date : 10-09-18

AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811RE : ACCIDENT INVOLVING **SLR6736J & XE1694E**
ACCIDENT DATE **19/072018**
ACCIDENT ALONG **EAST COST CARPARK H**

We are the workshop for the owner of motor vehicle no : **SLR 6736 J** which was involved in the captioned accident. The vehicle was surveyed by an independent appraiser and the claims below are based on its recommendation sum being for the repair cost and the period of repair (Strictly on a Without Prejudice Basis)

As the accident was caused by the negligent act of your insured **XE 1694 E** we are submitting these claims for your consideration.

1	Cost of repair	S \$	2,693.93
2	Loss of use <u>7</u> days @ \$ <u>120.00</u> / day	S \$	840.00
3	Surveyor Fee	S \$	0.00
4	GIA report fees (S\$ 15.00 for search fee & S\$ 14.00 for each report fee)	S \$	0.00
5	LTA Fee	S \$	7.45
		S \$	3,541.38

We enclosed herewith the following documents to support the claims:-

- a) Authorization letter
- b) Final repair bill(s)
- c) LTA search
- d) GIA report(s) / result
- e) Insurance certificate, etc.....

Kindly look into the matter and let us hear from you on the settlement of our client's claim as soon as possible. Thank you.

Yours faithfully

Carmen Lim
Claims Executive
Email : carmen@esteempref.com.sg



Re:TP MANDATE IA-S8M00PKW

Type

 Question

Message

please offer 4 days @\$50 per day and may proceed with COR.

Reply

LETTER OF AUTHORITY

To Whom It May Concern:

ACCIDENT INVOLVING SLR 6736 J & XE1694 E along East Coast
Carpark H on 19-07-2018 @ 15:00.

I, Goldbell Car Rental Pte Ltd Nric No. 200710651 D
Of 10 Raeburn Park #02-10 Singapore 088702 Owner
of motor vehicle no. SLR 6736 J. do hereby appoint M/S
ESTEEM PERFORMANCE PTE LTD as my authorized representation and
KSCGP JURIS LLP as my solicitors to write, to negotiate and settle my claim against the
other party/parties involved in the above mentioned accident. M/S ESTEEM
PERFORMANCE PTE LTD shall have absolute discretion to settle the matter at the best
terms.

I also confirm and instruct that any agreed settlement sum in respect of my claim be paid to
M/S ESTEEM PERFORMANCE PTE LTD and such payment will constitute a full and final
discharge of my claims.

I further authorize M/S ESTEEM PERFORMANCE PTE LTD to execute the discharge
voucher on my behalf.

Signature of Owner



Handwritten signature



AXA THIRD PARTY DIRECT SETTLEMENT

Vehicle No:	XE 1894E (Insd veh)	Model: Toyota Vios - 1496 cc
Date of Accident/ Time:	SLR 6736J (TP veh) 19 July 2018	

Repair Estimate	: \$	5,874.51	
Final Repair Cost	: \$	2,693.93	
Loss of Use	: \$	200.00	04 days at \$ 50.00 per day
Rental (if any)	: \$		days at \$ per day
LTA / GIA Search Fee	: \$	7.45	
Others:	: \$		
Final Settlement Sum (GLOBAL SUM)	: \$	2,900.00	
Payee Name: Esteem Performance Pte Ltd			
Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability: _____ (%)	
B)	For GIA Registered Workshop:	BOLA Applicable: Yes / No BOLA Scenario No: <u>N/L</u>	
	BOLA Liability: <u>100</u> (%)	Assessed Liability (*): _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks:			

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are not received within 7 days of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of our client to act for and on their behalf in this accident.

Signature of workshop representative / Workshop stamp:  Signature of Witness / Workshop stamp (if applicable): 

Name of Representative: Carmen Lim Name of Witness:

Date: 11.07.19 Date: 11.07.19

Signature of AXA's surveyor/representative: 

Name of AXA's surveyor /Representative:

Date: 12/07/19



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg
GST Registration No: 20-0005485-N CO Registration: 200005485N

M/S : AXA INSURANCE SINGAPORE PTE LTD
8 Shenton Way
#27-01 AXA Tower
Singapore 068811

ATTN: Motor Claim Department
Your Ref No: XE1694E
Claim Type: Third Party
Accident Date: 19/07/2018
TP Veh Reg No: XE1694E

Claim No: CER1301016
Final No: CIV1301292
Date: 31 Aug 2018
Policy No: SD18V00034/VPZ/R03
Veh Reg No: SLR6736J
Make/Model: TOYOTA VIOS 1.5E CVT
Chassis No: MHFB29F3702013264
Engine No: 2NRX166874
Reg. Date: 24/08/2017

Tax Invoice to Vehicle No :SLR6736J

Description	Quantity	List Price	Amount
		S\$	S\$
Others			
1 COST OF REPAIR	1 PCS	2,517.69	
		2,517.69	2,517.69
Total			S\$ 2,517.69
Add GST @ 7%			176.24
Total Amount Payable			S\$ 2,693.93

TOTAL: SINGAPORE DOLLAR TWO THOUSAND SIX HUNDRED NINETY THREE AND CENTS NINETY THREE ONLY

The above vehicle was surveyed by KENNETH on 25/07/2018

E. & O. E.

For Esteem Performance Pte Ltd


AUTHORISED SIGNATURE

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 23 Jul 2018 / 16:11:53

Receipt Date/Time : 23 Jul 2018 / 16:11:53

Tax Invoice/Receipt

Receipt No. : ITNET-00000-180723-001633

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - XE1694E				
As at 19 Jul 2018/15:00:00				
Insurance Co: AXA INSURANCE PTE LTD				
1	Insurance Enquiry - XE1694E Enquiry Fee 20180723161112318297	7.00	0.49	7.49
Sub-Total		7.00	0.49	7.49
Total Before Rounding		7.00	0.49	7.49
Rounding Difference				0.04
Total Amount Payable				7.45
Paid By				
	20180723161120906	Direct Debit: eNETS Debit (Internet Banking)		7.45
Total				7.45
Cash Change				0.00
Tendered Amount				7.45
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18013569/Kwa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:JAS TAN

Date : 25-07-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 1694E	Veh. Inspected	SLR 6736J
Policy No.	CN845193	Coverage (\$)	0.00
Claim No.	S8M00PKW	Excess (\$)	0.00
Assign From		Assign Date	24/07/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA VIOS (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	MHFB29F3702013264	Colour	WHITE
Odometer	28812	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/50 R16	YOKOHAMA	4 mm
L/H Front Tyre	195/50 R16	YOKOHAMA	4 mm
R/H Rear Tyre	195/50 R16	BRIDGESTONE	3 mm
L/H Rear Tyre	195/50 R16	BRIDGESTONE	3 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	19/07/2018	Inspection Date	25/07/2018
Survey held at	385 SIN MING DRIVE		
Repairer	ESTEEM PERFORMANCE PTE LTD		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 6736J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	RH REAR DOOR (CONSISTENT)	BENT	1,198.70	1,198.70
1	RH REAR DOOR HINGE TOP (CONSISTENT)	NOT NECESSARY	78.20	-
1	RH REAR DOOR HINGE BOTTOM (CONSISTENT)	NOT NECESSARY	78.20	-
1	RH REAR DOOR LOCK (CONSISTENT)	NOT NECESSARY	418.70	-
1	RH REAR DOOR CHECKER (CONSISTENT)	TO REPAIR SEE LABOUR	155.75	-
1	RH REAR DOOR WEATHERSTRIP (CONSISTENT)	NOT NECESSARY	158.40	-
1	RHR DOOR OUTER HANDLE (CONSISTENT)	DISTORTED	79.80	79.80
1	RHR DOOR OUTER HANDLE SIDE COVER (CONSISTENT)	SERVICEABLE	62.70	-
1	RHR DOOR GLASS OUTER MOULDING (CONSISTENT)	BUCKLED	101.79	101.79
1	RHR POWER WINDOW MOTOR (CONSISTENT)	BENT	511.67	511.67
1	RHR POWER WINDOW REGULATOR (CONSISTENT)	JAMMED	198.30	198.30
1	RH REAR DOOR TRIM (CONSISTENT)	NOT NECESSARY	827.80	-
10	RH REAR DOOR TRIM CLIP (CONSISTENT)	NOT NECESSARY	50.00	-
	LESS 25% DISCOUNT		-980.00	-522.58
			2,940.01	1,567.70
LABOUR				
	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (RHF DOOR ,RHR DOOR ,RHR FENDER).INCLUSIVE OF THE REPAIR OF RH REAR DOOR CHECKER.		800.00	400.00
	TO PUTTY,RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA.(RHF DOOR ,RHR DOOR ,RHR FENDER).		1,000.00	440.00
	TO CHECK WIRING.		50.00	20.00
	TO REMOVE & REFIT DOOR TRIM ,DOOR GLASS ,WINDOW REGULATOR, DOOR LOCK TO ASSIST WORK LOAD.		120.00	60.00
	TO TUFF COAT.		100.00	30.00
	TO DO ART WORK.	NOT NECESSARY	480.00	-
			2,550.00	950.00
GRAND TOTAL			5,490.01	2,517.70

Report Ref No. CC4/ASM18013569/Kwa3q2



RECOMMENDED COST OF REPAIRS			2,517.70
-----------------------------	--	--	----------

Report Ref No. CC4/ASM18013569/Kwa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report in whole or in part, does so at his or her own risk.

NAME	TYPE	SUB TYPE	AUTHOR	DATE UPLOADED
LTA SEARCH.pdf	Forms / Claims Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
LK Inspection (4).pdf	Forms / Claims Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
LK Adjustment 1a (4).pdf	Forms / Claims Documents	Others	LK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf	Forms / Claims Documents	Satisfaction / Discharge Voucher	LK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
AUTHORISATION TO ACT FORM.pdf	Forms / Claims Documents	POA / Authority Letter	LK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
WORKSHOP INVOICE.pdf	Invoice	Repairer	LK AUTO CONSULTANTS PTE LTD (TP)	31 July 2019
TP MANDATE (A-SLR 6736).pdf	Reports & Statement	Others	LK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
TP LOD.pdf	Reports & Statement	Others	LK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LK Inspection Photos.pdf	Reports & Statement	Others	LK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
MARKED ESTIMATE.pdf	Reports & Statement	Others	LK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
LK Reinspection Photos.pdf	Reports & Statement	Others	LK AUTO CONSULTANTS PTE LTD (TP)	19 June 2019
TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LK AUTO CONSULTANTS PTE LTD (TP)	27 July 2018
XEL694E INSD GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	24 July 2018
SLR6736J TP GIA REPORT.PDF	Reports & Statement	GIA Report	DHAKAL Raghav	24 July 2018
TP ESTEEM-PRI FROM WORKSHOP.mng	Letters and Correspondence	Workshop	DHAKAL Raghav	24 July 2018

