



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLR 6736 J

Parts	(a) Cost / List Price Items	\$	3,920.10
	Plus/Less 25%	\$	980.03
	Total of Cost / List	\$	2,940.08
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items		
	Total Parts Cost	\$	2,940.08
	Labour	\$	2,550.00
	Total	\$	5,490.08

Not Authorized
Resurvey B6 painting

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenneth
Company : LKK
Survey conducted on : 25/7/18 at

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 04 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$

(e) Signature of surveyor : *Ac* Date: 25/7/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLR 6736 J**
Make & Model : **TOYOTA VIOS**
Chassis No : **MHFB29F3702013264**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	RH rear door <i>Rh</i>	1	\$1,198.70		✓
2	RH rear door hinge top	1	\$78.20		?
3	RH rear door hinge bottom	1	\$78.20		?
4	RH rear door lock	1	\$418.70		?
5	RH rear door checker <i>Rh</i>	1	\$155.75		X
6	RH rear door weatherstip	1	\$158.40		?
7	RHR door outer handle <i>Rh</i>	1	\$79.80		✓
8	RHR door outer handle side cover <i>Rh</i>	1	\$62.70		X
9	RHR door glass outer moulding <i>Rh</i>	1	\$101.79		✓
10	RHR power window motor <i>Rh</i>	1	\$511.67		✓
11	RHR power window regulator <i>Rh</i>	1	\$198.30		✓
12	RH rear door trim	1	\$827.80		?
13	RH rear door trim clip	10	\$50.00		?
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Labour