

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019872
Chern Mei Ying Linda

Page 1 of 2
Your ref. TP-SGN 5161D AXA
Job No. 69687
Our ref. 18.07.41
Payment
Date 24/7/2018

Attn

Vehicle No SJW 338L
Vehicle Model : Lexus GS300
Accident on ... 23/7/2018

Not Authorized

U1 Lp @?

Measuring After Pa.ry 5 days

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Front bumper	888.00	10.00	799.20
1.00	Pc	Front number plate garnish	135.59	10.00	122.03
1.00	Pc	Front bumper sponge	128.40	10.00	115.56
8.00	Pcs	Front radiator top cover clips	3.50	10.00	25.20
1.00	Pc	Rear bumper	884.00	10.00	795.60
1.00	Pc	Rear bumper tow hook cover RH	27.20	10.00	24.48
1.00	Pc	Rear bumper reinforcement	507.96	10.00	457.16
1.00	Pc	Rear bumper sponge	146.70	10.00	132.03
1.00	Pc	Rear GS300 emblem	74.20	10.00	66.78
1.00	Pc	Rear Lexus emblem	75.25	10.00	67.73
Special nett item:					
1.00	Pc	Front number plate	35.00		35.00
1.00	Set	Rear reversing sensor with installation	200.00		200.00
Labour & Misc:					

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及零件快速准确的测量方式和大快修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明记) 摩哆有限公司 LAI HUAT (MENG KEE) MOTOR PTE LTD

Sector A, Block 21, Sin Ming Industrial Estate #01-56/58/60 Singapore 575679, Tel: 6453 8110 Fax: 6459 6267
RCB No: 199407592C

ESTIMATE

EST. No EST0019872
Chern Mei Ying Linda

Page 2 of 2
Your ref. TP-SGN 5161D AXA
Job No. 69687
Our ref 18.07.41
Payment
Date 24/7/2018

Attn

Vehicle No ... : SJW 338L
Vehicle Model : Lexus GS300
Accident on ... : 23/7/2018

Quantity	Unit	Description	Unit price	Disc. pct.	Amount	
1.00		To remove front driver's headrest + repair, etc	80.00		80.00	✓
1.00		To erase airbag fault code + check, etc	60.00		60.00	✓
1.00		To dismantle + renew front bumper, etc	200.00		200.00	✓
1.00		To straighten rear body, to knock dents on rear end panel, rear boot lid and renew of parts	500.00		500.00	450.00
1.00		To spray paint (front only)	250.00		250.00	✓
1.00		To spray paint (rear portion - including number plate garnish)	700.00		700.00	650.00

Sub-Total 4,630.77
GST 7.00% 324.15
Total S\$ 4,954.92

本公司拥有最先进的 CAROLINER MARK IV 机械，可提供给多种款式的车身及给于快速与准确的测量方式和大铁修理。除外，还有先进的 SAICO Deluxe 喷漆烘炉。

"Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support dolly system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."