

ASS. REC. BY

ASS. VENDOR

REF: CS/LPC18013574/T1rd36

Special Instruction:

ASSIGNMENT (Office)

From (Person):

Tunhih
Ong Li Li

of

LPC

Date/Time:

24/7/18 @ 1:41pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

SKZ 4774G

Insured:

at Workshop m/s:

Weemee Automotive

Tel:

9818 7217

of

249 Alexandra Rd

Policy No:

Claim No:

18/18/18/VPO5/020770

Sum Insured:

Excess:

\$500.00

Make of Veh:

(Client's Record)

D.O.A.

19/07/2018

CA / REV

REF. / REV 24 HRS

Insp: 45 long kee rd

H.O.D. Endorsement:

Date/Time:

2:06pm @ 24/7/18

Person Contacted:

Derek

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction

☒

Estimate

SKZ 4774G - CC1/LPC18013364/T1h3

DOA: 19/7/18

26/7/18

Revert thru email.

30/7/18

Derek inform \$45K to repair the vehicle; Inform Li Li; pending
authorise

31/7/18

Inform Derek to proceed repair

9176

6543

(08/11/13) wef

ASS. REC. DY

REF:

LPC CS/LPC18013574/T1rd3

ASSIGNMENT

From:

Date: 26/7/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKZ 4774G

at Workshop m/s

Wearnes Automotive

of

45 Leng Kee Rd

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

\$500.00

(Client's Record)


Make of Veh:

Mowing
Dereck @ 9818 7217

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.



Bal. or Market Value:

\$112K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKZ 4774G Yr Regn: 2016 Jan

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Infiniti Q50

c.c

1991

Colour:

white

A/C: Insured / Std / NI / NA

Sp. Reading

54911

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SN1BSCAV 57 2 0480 503

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

6

mm

Rear

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

1

mm

D.O.A.

D.O.I.

26/7/18 @ 1430

Survey held at

Wearnes

Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Confirm with Richmond \$43,817.40 @ 46 days
(Red. \$20,136.40, 31%).

under transfer
photo

RECEIVED 20 NOV 2018

Date/Time, File Pass to?

1)

topist

Date/Time, File Return to?

2)

☐

: Preli. Report

☒

: Final Report

Days Of Repair:

16

Resurvey No. of Trip:

1

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

50 x 15 = \$10

1704 810

50

50

221

1301

Report Format :

OD

Lump Sum / I.B.I. (\$

43817.40



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS/LPC18013574/T1rd3	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 26-07-2018	
			Code : LPC2	
1. Policy Particulars :- OWN DAMAGE				
Insured Veh.	Veh. Inspected		SKZ 4774G	
Policy No.	Coverage (\$)		0.00	
Claim No. 18/18/18/VP05/020770	Excess (\$)		500.00	
Assign From ONG LI LI	Assign Date		26/07/2018	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date 19/07/2018	Inspection Date		26/07/2018	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE MARKET VALUE IS S\$----- (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

Nivitha (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, 24 July 2018 1:41 PM
To: 'SUR' (sur@lkkauto.com); assignments@lkkauto.com
Cc: MT_Claim_SG; derek.oh@wearnes.com
Subject: FW: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770
Attachments: 4153_001.pdf

Importance: High

Dear LKK

Please attend to the OD survey (non-Merimen case).

Excess :\$500.00

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Derek Oh Siong Wee [mailto:derek.oh@wearnes.com]
Sent: Tuesday, 24 July, 2018 1:11 PM
To: GERALD POH WEE BIN; mt_claims@lonpac.com
Cc: Richmond Ho
Subject: OD CLAIM FOR SKZ4774G
Importance: High

Hi,

Please refer to the above attachment, car in.

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6378 9336 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: 18/18/18/VP05/020770

Date: 26 July 2018

Our Ref: CS/LPC18013574/T1rd3

The Motor Claims Department
LONPAC Insurance Berhad

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. SKZ 4774G .

We thank you for the instruction on 24/07/2018


Please be informed that we had conducted the inspection of the abovementioned vehicle 26/07/2018 at the premises of m/s: WEARNES AUTOMOTIVE PTE LTD and have the following to report:-

Repairer's Estimate (Gross)	: <u>S\$ 56,759.20</u> .
Revised Estimate Amount	: <u>S\$ 30,258.70</u> .
"Check" Items (Estimated)	: <u>S\$ 15,045.00</u> .
Total Repair cost	: <u>S\$ 45,303.70</u> .
Market Value	: <u>S\$ 112,000.00</u> .
COE/PARF value	: <u>S\$ 66,649.00</u> .
Nett Value	: <u>S\$ 45,351.00</u> .

Description of Damage:

The vehicle sustained damages
at the front portion, o/s and n/s body.

The undercarriage and chassis frame affected
due to collision.



Comments:

We have not authorize repair.

16 repairs days

Yours faithfully

TAUFIKH

Automotive Assessor

Janice Lee (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Friday, July 27, 2018 8:52 AM
To: Janice Lee (LKKAUTO); SUR
Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAUTO)
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Hi Janice

What is the surveyor's recommendation? To authorise or not?

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Thursday, 26 July, 2018 6:56 PM
To: ONG LI LI; SUR
Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAUTO)
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

Enclosed preliminary revised for **SKZ 4774G**.

16 repair days.

We have not authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Thursday, July 26, 2018 5:32 PM
To: Admin-D (LKKAUTO) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Janice

Janice Lee (LKKAuto)

From: Derek Oh Siong Wee <derek.oh@wearnes.com>
Sent: Friday, July 27, 2018 3:47 PM
To: Janice Lee (LKKAuto)
Cc: SUR; Richmond Ho
Subject: RE: SKZ 4774G LPC OD

Importance: High

Dear Janice,

We propose \$48K excluding GST and EXCESS.

Kindly revert with your approval.

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6378 9336 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Friday, 27 July, 2018 3:37 PM
To: Derek Oh Siong Wee
Cc: SUR
Subject: RE: SKZ 4774G LPC OD

Hi Derek,

Kindly advice whether the vehicle can be repair within \$45,000.00 ?

Thank you.

Best Regards,
Jannice Lee (Ms) | Case Handler
LKK Auto Consultants Pte Ltd
Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)
Sent: Friday, July 27, 2018 9:17 AM
To: derek.oh@wearnes.com
Cc: SUR <sur@lkkauto.com>
Subject: SKZ 4774G LPC OD

Hi Derek,

Kindly advice whether the vehicle can be repair within \$44,000.00 ?

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAuto)

From: Derek Oh Siong Wee <derek.oh@wearnes.com>
Sent: Monday, July 30, 2018 2:43 PM
To: Janice Lee (LKKAuto)
Cc: SUR; Richmond Ho
Subject: RE: SKZ 4774G LPC OD

Importance: High

Noted, \$45K before Excess & GST.

Can we proceed with the repair?

Best Regards,

Derek Oh
Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6378 9336 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*

From: Janice Lee (LKKAuto) [mailto:JaniceLee@lkkauto.com]
Sent: Friday, 27 July, 2018 3:37 PM
To: Derek Oh Siong Wee
Cc: SUR
Subject: RE: SKZ 4774G LPC OD

Hi Derek,

Kindly advice whether the vehicle can be repair within \$45,000.00 ?

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Monday, July 30, 2018 3:12 PM
To: ONG LI LI; SUR
Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAUTO)
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

Our surveyor had further negotiate with the repairer. The repairer agree to undertake to repair the vehicle at repair cost not more than \$45k(before excess and GST).

Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, July 30, 2018 9:44 AM
To: ONG LI LI <long@lonpac.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAUTO) <olivialau@lkkauto.com>
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

We will check and revert.

Dear Jannice,

Kindly follow up.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI <long@lonpac.com>

Sent: Monday, 30 July 2018 9:29 AM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Hi Veron

Based on your surveyor's preliminary advice, the revised estimate amount plus check items totalling up to \$45,303.70 only.

Why did the repairer request for \$48K now? What are the additional supplementary items?

Also, please state surveyor's recommendation before waiting for our instruction.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Veron Chen (LKKAuto) [<mailto:veronchen@lkkauto.com>]

Sent: Friday, 27 July, 2018 5:39 PM

To: Janice Lee (LKKAuto); ONG LI LI; SUR

Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAuto)

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

Repairer request for repair cost \$48K inclusive of supplementary items, which is exceeding the nett value.

Awaiting for your further instruction.

Best Regards,

Veron Chen | Case Handler on behalf of Jannice Lee

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAuto)

Sent: Friday, 27 July 2018 4:07 PM

To: ONG LI LI <long@lonpac.com>; SUR <sur@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto)

<olivialau@lkkauto.com>

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

As spoken, we are still pending repair cost from repairer.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]

Sent: Friday, July 27, 2018 8:52 AM

To: Janice Lee (LKKAuto) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Hi Janice

What is the surveyor's recommendation? To authorise or not?

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Janice Lee (LKKAuto) [<mailto:JaniceLee@lkkauto.com>]

Sent: Thursday, 26 July, 2018 6:56 PM

To: ONG LI LI; SUR

Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAuto)

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

Enclosed preliminary revised for **SKZ 4774G**.

16 repair days.

We have not authorize repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:lilong@lonpac.com>]

Sent: Thursday, July 26, 2018 5:32 PM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; SUR <sur@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Janice

Please let us have your preliminary advice.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]

Sent: Thursday, 26 July, 2018 9:07 AM

To: ONG LI LI; sur@lkkauto.com

Cc: MT_Claim_SG; ASSIGNMENTS@LKKAUTO.COM

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

Thank you for the email.

Dear Janice,

Kindly assist.

FYNA Our Ref : CS/LPC18013574/R1rd3

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:lilong@lonpac.com>]

Sent: Thursday, 26 July 2018 8:51 AM

To: Nivitha (LKK Auto) <admin-d@lkkauto.com>; ASSIGNMENTS@LKKAUTO.COM

Cc: MT_Claim_SG <mt_claim@lonpac.com>; sur@lkkauto.com

Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Importance: High

Hi Nivitha

Please provide update on this OD claim.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Tuesday, 24 July, 2018 2:12 PM
To: ONG LI LI; ASSIGNMENTS@LKKAUTO.COM
Cc: MT_Claim_SG; sur@lkkauto.com
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,
G.Nivitha | Admin
LKK Auto Consultants Pte Ltd
Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [<mailto:llong@lonpac.com>]
Sent: Tuesday, 24 July 2018 1:41 PM
To: 'SUR' (sur@lkkauto.com) <sur@lkkauto.com>; assignments@lkkauto.com
Cc: MT_Claim_SG <mt_claim@lonpac.com>; derek.oh@wearnes.com
Subject: FW: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770
Importance: High

Dear LKK

Please attend to the OD survey (non-Merimen case).

Excess :\$500.00

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Derek Oh Siong Wee [<mailto:derek.oh@wearnes.com>]
Sent: Tuesday, 24 July, 2018 1:11 PM
To: GERALD POH WEE BIN; mt_claims@lonpac.com
Cc: Richmond Ho
Subject: OD CLAIM FOR SKZ4774G
Importance: High

Hi,

Please refer to the above attachment, car in.

Best Regards,


Derek Oh

Service Consultant
Bodyshop & Paint



Wearnes Automotive Pte Ltd
249 Alexandra Road Singapore 159935
D (65) 6378 9336 M (65) 9818 7217
www.wearnes.com derek.oh@wearnes.com

*This email, including any attachment, is confidential and may also be privileged.
If you have received it in error, please notify us immediately by reply email and then delete this message from your system.
Please do not copy it or use it for any purpose, or disclose its contents or any attachment to any other person. Thank you.*



This email has been checked for viruses by AVG antivirus software.
www.avg.com

Janice Lee (LKKAUTO)

From: ONG LI LI <llong@lonpac.com>
Sent: Tuesday, July 31, 2018 12:02 PM
To: Janice Lee (LKKAUTO); SUR
Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAUTO)
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Janice

Please proceed to authorise OD repairs as per your surveyor's adjustment if the damages are consistent & within repair limit.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Janice Lee (LKKAUTO) [mailto:JaniceLee@lkkauto.com]
Sent: Monday, 30 July, 2018 3:12 PM
To: ONG LI LI; SUR
Cc: MT_Claim_SG; assignments; Olivia Lau (LKKAUTO)
Subject: RE: OD CLAIM FOR SKZ4774G Our Ref: 18/18/18/VP05/020770

Dear Li Li,

Our surveyor had further negotiate with the repairer. The repairer agree to undertake to repair the vehicle at repair cost not more than \$45k(before excess and GST).

Kindly let us have your approval.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: jannicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Monday, July 30, 2018 9:44 AM
To: ONG LI LI <llong@lonpac.com>; Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>; SUR <sur@lkkauto.com>
Cc: MT_Claim_SG <mt_claim@lonpac.com>; assignments <assignments@lkkauto.com>; Olivia Lau (LKKAUTO)

Janice Lee (LKKAuto)

From: Janice Lee (LKKAuto)
Sent: Tuesday, July 31, 2018 12:58 PM
To: Derek Oh Siong Wee
Cc: SUR; Richmond Ho
Subject: SKZ 4774G LPC OD

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SKZ 4774G (excess \$500/-)**. Please note that the vehicle repair at repair cost not more than **\$45,000.00**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their right not to pay if there is no valid approval obtained before repair.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	9844J
Vehicle Details	
Vehicle No.:	SKZ4774G
Vehicle to be Exported:	No
Intended De-registration Date:	26 Jul 2018
Vehicle Make:	INFINITI
Vehicle Model:	Q50 2.0T A/T (R18)
Primary Colour:	White
Manufacturing Year:	2015
Engine No.:	274AE024270A
Chassis No.:	JN1BCAV37Z0480583
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$29,932.00
Original Registration Date:	25 Jan 2016
First Registration Date:	25 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$33,905.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	24 Jan 2026
PARF Rebate Amount:	\$25,428.00
Intended COE Rebate Details	
COE Expiry Date:	24 Jan 2026
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$55,001.00
COE Rebate Amount:	\$41,221.00
Total Rebate Amount:	\$66,649.00

The information contained herein is correct as at 26 Jul 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	20/07/2018 13:44
Date Of Accident	19/07/2018 16:55
Exact Location Of Accident	INFRONT OF NO.2 TANJONG PENJURU
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ4774G
Insured/Policyholder	
Name Of Registered Owner	NG MING HUI (HUANG MINGHUI)
NRIC No	S8129844J
Email Address	MINGHUIIDEN@GMAIL.COM
Mobile Phone No	(LOCAL) +65-96630637
Alternative Phone No	OTHERS-96630637

Vehicle Particulars

Manufacturer	INFINITI
Model	Q50-2.0 T PREMIUM (A)
Exact Purpose for which vehicle was being used at time of accident	TRAVELLING FOR MEETING
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	

Vehicle Category	PRIVATE CAR
------------------	-------------

Insurance Company

Name of Insurance Company	LONPAC INSURANCE BHD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	Z18VP05017170
Cover Note Number	

Driver

Name of Driver	NG MING HUI (HUANG MINGHUI)
NRIC No	S8129844J
Date Of Birth	12/10/1981
Occupation	INDOOR
Date Of Driving Pass	06/05/2004
Driving Experience	14 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96630637
Fax Number	
Contact Number	OTHERS-96630637
Email Address	MINGHUIIDEN@GMAIL.COM

Address	BLK 433 JURONG WEST STREET 42 #07-522
Postcode	640433
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: NO. 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-8729999 - FAX NO: 67748639
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH AND POLICE REPORT D/20180720/7007

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLD5585H
Vehicle Make/Model/Colour	MERCEDES BENZ C180
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TANG JOO KIM
NRIC/Passport Number	S1633132E
Contact Number	82885585
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	

No. Of Passenger (Including Driver)

1

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you heretofore consent to the archiving of this report at the centre and to copies of the report being made available therefrom.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purpose.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that exist in evaluating, investigating, controlling or managing fraud regulators, law enforcement and government agencies as reasonable required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time 26/07/2018

C1445

Driver's Signature

(If driver is not the policyholder)

Date & Time

Reporting Centre Personnel's Signature

Name

NRIC/IN No.

Accident Sketch Plan

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Vehicle SKZ 4774 is making a turn without checking blind spot, vehicle SLD 5585 H was unable to stop in time and collide at the side of vehicle SKZ 4774. Vehicle SKZ 4774 lost control and go over the roadside drain.

POLICE REPORT D20180720/1007

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time: 20/07/2018
10:05

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name: [Signature]
Title: [Signature]

POLICE REPORT



**SINGAPORE
POLICE FORCE**



D/20180720/7007

1 of 1

POLICE REPORT (NP299)

Report No. D/20180720/7007

Police Station Of Origin
Clementi Police Divisional HQ
20 Clementi Avenue 5 SINGAPORE 129858
Tel No 1800-7740000

Date/Time Report Made 20/07/2018 12:56	Vide Report No.	Station Diary No.
Name Of Informant NG MING HUI	Address APT BLK 3A GEYLANG SERAI #07-55 SINGAPORE 402003	
ID Type / ID No. NRIC NO / S8129844J	Contact No. Home/Office	Mobile: 96630637
Nationality SINGAPORE CITIZEN	Email Address minghuiiden@gmail.com	
Occupation Interior designer	Sex Male	Age 36
Institution/School Name	Date of Birth 08/10/1981	Race Chinese
	Language English	
Date/Time Of Incident 19/07/2018 16:55 - 19/07/2018 16:55	Location Of Incident TANJONG PENJURU	

Brief details

I met a car accident along Tanjong Penjuru on Thursday, 19 July 2018, around 4:57pm. I was the driver of a White Infiniti (SKZ4774G), and was trying to make a turn at 2 Tanjong Penjuru. Failing to check the blind spot when I turn, a Mercedes Benz C180 (SLD5585H) driving along Tanjong Penjuru collide onto the side of my car, as the driver was unable to stop in time. I lost control of my car and drove over the pedestrian path way and collide onto 2 numbers of Road side drain Railing. No one was hurt or injured during the accident.

Signature Of Officer Recording The Report Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required
Signature Of Interpreter: Not applicable	Date/Time 20/07/2018 12:56
Officer In-Charge Of Case:	Classification Of Case
Authentication Stamp	

ACCIDENT STATEMENT

ACCIDENT DATE: 19/07/2018 (DD/MM/YYYY), TIME: 16:57 (HH:MM)

LOCATION: In front of 2. Tanjong Pagar

1. DETAILS OF VEHICLE

- a) VEHICLE NUMBER: SK24774G
- b) INSURANCE COMPANY: LONPAC INSURANCE BHD
- c) POLICY NUMBER: ZIRVF05017170
- d) POLICY TYPE: (COMPREHENSIVE / THIRD PARTY / THIRD PARTY FIRE & THEFT)
- e) MAKE & MODEL: INFINITI Q50 T PREMIUM 2.0
- f) TYPE: (SALOON / COUPE / MPV / VAN / LORRY / MOTORCYCLE / OTHERS)
- g) VEHICLE CATEGORY: (PRIVATE / COMMERCIAL / MOTORCYCLE)
- h) PURPOSE OF USING AT ACCIDENT TIME: Travelling for Meeting
- i) ARE YOU CLAIMING UNDER YOUR OWN INSURANCE (YES/NO)
IF NO, PLEASE STATE (THIRD PARTY CLAIM / REPORTING ONLY)

2. INSURED / POLICY HOLDER

- A) NAME: NG Ming Hui (MALE / FEMALE)
- b) NRIC/FIN/PASSPORT: S8129844 J CONTACT: 96630637
- c) ADDRESS: BLK 433 JIRONG WEST ST42 #07-522 S(640433)

* CONTINUE TO 3.d IF DRIVER ALSO POLICY HOLDER

DRIVER

- a) NAME: _____ (MALE / FEMALE)
- b) NRIC/FIN/PASSPORT: _____ CONTACT: _____
- c) ADDRESS: _____

*d) DATE OF BIRTH: 12/10/1981 (DD/MM/YYYY)

e) OCCUPATION: (INDOOR / OUTDOOR)
f) DATE OF DRIVING PASS: 06/05/2004

4. WAS DRIVER AN EMPLOYEE OF THE INSURED'S COMPANY? (YES / NO)
IF NO, RELATIONSHIP OF THE DRIVER WITH INSURED: OWNER

5. a) WEATHER CONDITION: (CLEAR / RAINING / OTHERS)
b) ROAD SURFACE: (DRY / WET / OTHERS)

6. WAS ANYBODY INJURED (YES / NO)

7. a) REPORTED TO POLICE (YES / NO)
IF YES, PLEASE STATE WHICH POLICE STATION: _____

8. THIRD PARTY VEHICLE

- a) VEHICLE NUMBER: SLD 5585H MODEL: Mercedes Benz C-180
- b) DRIVER'S NAME: TANG JOO KIM
- c) NRIC/FIN/PASSPORT: S1633132E CONTACT: 8288 5585

9. THIRD PARTY VEHICLE

- d) VEHICLE NUMBER: _____ MODEL: _____
- e) DRIVER'S NAME: _____
- f) NRIC/FIN/PASSPORT: _____ CONTACT: _____

email = minghuide@.gmail.com

VIDE0=

*No of passengers
(including driver)
(1)

*No of passengers
(including driver)
(1)

*No of passengers
(including driver)
(1)

**LONPAC INSURANCE BHD (S98FC5635C)**

(Incorporated in Malaysia)

Singapore Office: 300, Beach Road #17-04/07, The Concourse, Singapore 199555

Tel: (65) 6250 7388 Fax: (65) 6296 3767 Website: www.lonpac.com.sg

GST Reg No.: P0-0005635-C

MX1

CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CAP 189) REPUBLIC OF SINGAPORE.
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES 1960 (REPUBLIC OF SINGAPORE).
ROAD TRANSPORT ACT 1987 (MALAYSIA).
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1959 (MALAYSIA).

Certificate No. : Z18VP05017170

Type of Cover : COMPREHENSIVE

1. Index Mark and Vehicle Registration Number

INFINITI Q50 T PREMIUM 2.0
- SKZ4774G

2. Name of Policy Holder

NG MING HUI

3. Effective Date of the Commencement of Insurance
for the purpose of the Act

25/01/2018

4. Date of Expiry of the Insurance

24/01/2019

5. Persons or Classes of Persons entitled to drive

(A) THE POLICYHOLDER (B) ANY OTHER PERSON WHO IS DRIVING ON THE POLICYHOLDER'S ORDER OR WITH HIS/HER PERMISSION

Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

6. Limitations as to use

USE ONLY FOR SOCIAL, DOMESTIC AND PLEASURE PURPOSES AND FOR THE POLICYHOLDER'S BUSINESS. THE POLICY DOES NOT COVER USE FOR HIRE OR REWARD, RACING, PACE-MAKING, RELIABILITY TRIAL, SPEED-TESTING OR THE CARRIAGE OF GOODS (OTHER THAN SAMPLES) IN CONNECTION WITH ANY TRADE OR BUSINESS OR USED FOR ANY PURPOSE IN CONNECTION WITH THE MOTOR TRADE.

Excess

: S\$ 500.00 (SECTION 1) INSURED / NAMED DRIVERS

S\$ 1,500.00 (SECTION 1) UNNAMED DRIVERS

S\$ 3,000.00 (SECTION 1) ADDITIONAL EXCESS FOR ELDERLY OR YOUNG AND/OR INEXPERIENCED DRIVERS

S\$ 100.00 WINDSCREEN EXCESS

LONPAC'S AUTHORISED WORKSHOPS

Condition : ACCIDENT REPAIRS AT LONPAC'S AUTHORISED WORKSHOPS OR DISTRIBUTOR-OWNED MOTOR WORKSHOP

* Limitations rendered inoperative by Section 95 of the Road Transport Act 1987 (Malaysia) or Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189) Republic of Singapore are not included under heading.

I/WE hereby certify that this covering Note is issued in accordance with the provisions of Part IV of the Road Transport Act 1987 (Malaysia) and Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) Republic of Singapore.

H.P. Owner : OVERSEA-CHINESE BANKING CORPORATION LIMITED

CHIEF EXECUTIVE
(Singapore Branch)

User ID: FA2130

REPUBLIC OF SINGAPORE DRIVING LICENCE

Portrait photo of a man with short dark hair and glasses.

License Number: S8129844J

Name: NG MING HUI (HUANG MINGHUI)

Date of Birth: 12 Oct 1981

Issue Date: 06 May 2004

Barcode: NP12129844

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S8129844J

Portrait photo of a man with short dark hair.

Name: NG MING HUI (HUANG MINGHUI)

Chinese Name: 黃明輝

Race: CHINESE

Date of Birth: 12-10-1981

Sex: M

Country of Birth: SINGAPORE

Barcode: S8129844J

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES:

Class 3 Motor Cars and Motor Tractors the weight of which (including the maximum 2000 kilograms)

Valid Until: 06 May 2004

NP 428A

Barcode: License No. S8129844J

Barcode: 4287631

Barcode: S8129844J

Portrait photo of a man with short dark hair.

Date of Issue: 10-11-2011

APT BLK 3A GEYLANG SERAI #07-55 SINGAPORE 402003

NRIC No: S8129844J

Date: 05/03/2018

SERVICE ESTIMATE

84370 - C00001
Mr Ng Ming Hui
3a Geylang Serai
#07-55

SL: SERVICE SALES - PC

Singapore 402003

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Mr Ng Ming Hui

GST Reg.No: M28920628X
Inv.No. . : B&P 0 Page 1
Inv.date. : 24/07/2018
WIP No. . : 17774
Veh.In/Out: 20/07/2018
*Tel.No. . : Mobile: 96630637
Reg.No. . : SKZ4774G
Reg.date . : 25/01/2016
Mileage ... : 0
Chassis No: JN1BCAV37Z0480583

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

802 TO REPLACE FRONT BUMPER,FRT
BRACKET,FRT GRILL,FRT LOWER
GRILL,FRT BEAM,FRT RH HEADLAMP,
FRT RH FENDER,FRT RH DOOR,REAR
RH DOOR,REAR RH FENDER,REAR
BUMPER,LH ROCKER PANEL,ETC

0 10800.00 0 10,800.00 S

9000/

800 TO PUTTY SPRAY PAINT ON FRT
BUMPER,FRT LH & RH FENDER,
FRT BONNET,FRT RH DOOR,REAR
RH DOOR,REAR RH FENDER,REAR
BUMPER,RH ROCKER PANEL,LH
ROCKER PANEL,ETC

0 9600.00 0 9,600.00 S

8000/

802 TO VACCUH & TOP UP A/C GAS
287 TO REPLACE FRONT LH & RH

0 600.00 0 600.00 S

0 5200.00 0 5,200.00 S

4160 ? / plus to.

UNDERCARRIAGE PARTS

0031 TO REPLACE 03 RIMS

0 150.00 0 150.00 S

419 COMPUTERISED WHEEL ALIGNMENT

0 280.00 0 280.00 S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tan Jikun 97495749

Not Authorised

26/7/18 @ 1430

*Resurvey check items
& before paint

Ex \$500

sur@lkkauto.com.

16 days.

To Check repair limit.

SERVICE ESTIMATE

84370 - C00001
 Mr Ng Ming Hui
 3a Geylang Serai
 #07-55

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 2

Inv.date : 24/07/2018

WIP No. : 17774

Veh.In/Out: 20/07/2018

*Tel.No. : Mobile: 96630637

Reg.No. : SK24774G

Reg.date : 25/01/2016

Mileage : 0

Chassis No: JN1BCAV37Z0480583

Singapore 402003

Closed by : Derek Oh Siong Wee

Svc Consultant :

Remarks : Mr Ng Ming Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
280	TO FOCUS HEADLAMP	0	130.00	0		130.00 S	//
280	TO CHECK WIRING INCLUDE	0	390.00	0		390.00 S	//
RESETTING OF ALL ELECTRICAL MODULES							
R06	TO INSTALL FRONT NUMBER PLATE	0	60.00	0		60.00 S	bt //
INCLUDE HOLDER							
R16	TOWING CHARGES	0	450.00	0		450.00 S	/
	/ BUMPER FRT Q50 PREH	1.0 EA	685.80			685.80 S	de / 617.12
	BUMPER FRT BASE SPOI	1.0 EA	112.00			112.00 S	de / 100.80
	TOW COVER BUMPER FRT	1.0 EA	19.90			19.90 S	aut / 17.91
	BUMPER LOWER GRILLE-	1.0 EA	198.30			198.30 S	de / 178.47
	ENERGY ABSORBER FOAM	1.0 EA	168.60			168.60 S	de / 151.74
	BRACKET-BUMPER CENTE	1.0 EA	70.00			70.00 S	? 61.00 de
	REINFORCEMENT-BUMPER	1.0 EA	481.40			481.40 S	? 423.26 btv
	REINFORCEMENT SUPPOR	1.0 EA	115.50			115.50 S	? 2nn
	REINFORCEMENT SUPPOR	1.0 EA	115.50			115.50 S	? 2nn
	BRACKET-BUMPER FRT R	1.0 EA	19.60			19.60 S	au / 17.64

SERVICE ESTIMATE

84370 - C00001
 Mr Ng Ming Hui
 3a Geylang Serai
 #07-55

SL: SERVICE SALES - PC

Singapore 402003

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Ng Ming Hui

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 3
 Inv.date. : 24/07/2018
 WIP No. . : 17774
 Veh.In/Out: 20/07/2018
 *Tel.No. . : Mobile: 96630637
 Reg.No. . : SKZ4774G
 Reg.date. : 25/01/2016
 Mileage . : 0
 Chassis No: JN1BCAV37Z0480583

Op.No	Description	Mech Qty	Price Disc% Pkg	Amount G
	BRACKET-BUMPER FRT L	1.0 EA	19.60	19.60 S <i>nei 17.64</i>
	FOG LAMP OUTER TRIM	1.0 EA	77.10	77.10 S <i>? 69.39 nei</i>
	FOG LAMP OUTER TRIM	1.0 EA	77.10	77.10 S <i>? x 17</i>
	BRKT LICENS PLA	1.0 EA	117.50	117.50 S <i>nei 105.75</i>
	BRACKET CTER LH BUMP	1.0 EA	50.40	50.40 S <i>? x 17</i>
	BRACKET-BUMPER FRT L	1.0 EA	14.00	14.00 S <i>nei 12.60</i>
	BUMPER FRT RETAINER	1.0 EA	56.00	56.00 S <i>nei 52.40</i>
	BRACKET CTER RH BUMP	1.0 EA	50.40	50.40 S <i>? 45.36 nei</i>
	BUMPER FRT RETAINER	1.0 EA	56.00	56.00 S <i>nei x 17</i>
	BRACKET-BUMPER FRT R	1.0 EA	14.00	14.00 S <i>nei 12.60</i>
	GRILLE-RADIATOR Q50	1.0 EA	522.00	522.00 S <i>nei 469.80</i>
	I625014GA0A/BUMPER I	1.0 EA	589.10	589.10 S <i>? 530.19 nei</i>
	SUPPORT-RADIATO	1.0 EA	50.40	50.40 S <i>? x 17</i>
	BRACKET LOWER FENDER	1.0 EA	77.10	77.10 S <i>? 69.39 nei</i>
	BRACKET LOWER FENDER	1.0 EA	77.10	77.10 S <i>? x 17</i>
	RET-FR BUMPER	1.0 EA	93.90	93.90 S <i>? x 17</i>
	BRACE ASSY-R/CO	1.0 EA	110.40	110.40 S <i>? 101.20 hf 0</i>

SERVICE ESTIMATE

84370 - C00001
 Mr Ng Ming Hui
 3a Geylang Serai
 #07-55

SL: SERVICE SALES - PC

Singapore 402003

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Ng Ming Hui

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 4
 Inv.date. : 24/07/2018
 WIP No. . : 17774
 Veh.In/Out: 20/07/2018
 *Tel.No. . : Mobile: 96630637
 Reg.No. . : SKZ4774G
 Reg.date. : 25/01/2016
 Mileage . : 0
 Chassis No: JN1BCAV37Z0480583

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

FENDER SIDE BRACKET LH	1.0 EA	112.00			112.00 S	x AN	
FENDER SIDE BRACKET RH	1.0 EA	112.00			112.00 S	bt 100.80	
IF31004GAMA/FENDER-F LH	1.0 EA	706.70			706.70 S	A x AN	
IF31014GAMA/FENDER-F RH	1.0 EA	706.70			706.70 S	bt 636.03	
WHEEL ARCH OUTER FRT LH	1.0 EA	43.50			43.50 S	x AN	
WHEEL ARCH OUTER FRT RH	1.0 EA	43.50			43.50 S	? 39.15 de	
WHEEL ARCH INNER FRT LH	1.0 EA	40.90			40.90 S	x AN	
WHEEL ARCH OUTER FRT RH	1.0 EA	40.90			40.90 S	? 36.81 de	
EMBLEM	2.0 EA	47.90			95.80 S	an 86.22	
HEADLAMP ASSY-LH Q50	1.0 EA	3344.70			3,344.70 S	x AN	
HEADLAMP ASSY-RH Q50	1.0 EA	3344.70			3,344.70 S	cm 3010.23	
DAY LIGHT FRT LH Q50	1.0 EA	98.30			98.30 S	? } x AN	
DAY LIGHT FRT RH Q50	1.0 EA	98.30			98.30 S	? }	
FOG LAMP RH FRT Q50	1.0 EA	436.80			436.80 S	? }	
I261554GA0A/LAMP FOG	1.0 EA	436.80			436.80 S	? }	
DOOR-FRONT RH Q50	1.0 EA	1045.80			1,045.80 S	bt 941.22	
WSTRIP ASSY-FR	1.0 EA	165.20			165.20 S	all 149.68	

SERVICE ESTIMATE

84370 - C00001
Mr Ng Ming Hui
3a Geylang Serai
#07-55

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 5
Inv.date. : 24/07/2018
WIP No. : 17774
Veh.In/Out: 20/07/2018
*Tel.No. : Mobile: 96630637
Reg.No. : SKZ47748
Reg.date. : 25/01/2016
Mileage : 0
Chassis No: JN1BCAV37Z0480583

Singapore 402003

Closed by : Derek Oh Siong Wee
Svc Consultant :
Remarks : Mr Ng Ming Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	SEAL-REAR DOOR	1.0 EA	14.00			14.00	S 12.60
	FRAME-FRONT DOO	1.0 EA	98.90			98.90	S 89.01
	COVER-SASH INNE	1.0 EA	140.00			140.00	S 127
	WINDOW OUTER HLDG ST	1.0 EA	168.80			168.80	S 151.42
	WINDOW SEAL STRAP IN	1.0 EA	89.20			89.20	S 80.28
	DOOR-REAR RH Q50	1.0 EA	1045.80			1,045.80	S 941.22
	W/STRIP-RR DOOR	1.0 EA	165.20			165.20	S 148.68
	A SASH RR DOOR	1.0 EA	54.00			54.00	S 48.60
	SCREEN-SEALING	1.0 EA	22.20			22.20	S 20.77
	S MOUL SASH RR	1.0 EA	149.30			149.30	S 134.37
	COVER-SASH INNE	1.0 EA	97.10			97.10	S 87.39
	1828384GA0A/DOOR SEA	1.0 EA	40.40			40.40	S 36.77
	DOOR SEAL RH B PILLA	1.0 EA	40.40			40.40	S 36.77
	WHEEL-ROAD AL	1.0 EA	1825.90			1,825.90	S 1642.31
	FENDER-REAR RH	1.0 EA	966.30			966.30	S 877
	IG271689900/WINDSCRE	1.0 EA	33.80			33.80	S 30.42
	WINDSCREEN RR Q50 2.	1.0 EA	1650.00			1,650.00	S 1485

SERVICE ESTIMATE

84370 - C00001
 Mr Ng Ming Hui
 3a Geylang Serai
 #07-55

SL: SERVICE SALES - PC

Singapore 402003

Closed by : Derek Oh Siong Wee
 Svc Consultant :
 Remarks : Mr Ng Ming Hui

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 6
 Inv.date : 24/07/2018
 WIP No. : 17774
 Veh.In/Out: 20/07/2018
 *Tel.No. : Mobile: 96630637
 Reg.No. : SK24774G
 Reg.date : 25/01/2016
 Mileage : 0
 Chassis No: JN1BCAV3720480583

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER REAR Q50 2.0	1.0 EA	800.10			800.10	S
	JC2D7026/SEALANT WIN	2.0 EA	159.70			319.40	S
	D PRIMER GLASS & P	1.0 EA	37.40			37.40	S
	SPDL-KNUCKLE,RH	1.0 EA	694.90			694.90	S
	HUB ASSY-ROAD WHEEL	1.0 EA	454.00			454.00	S
	I545004GE0A/LINK COM	1.0 EA	386.70			386.70	S
	ABSORBER-SHOCK	1.0 EA	328.40			328.40	S
	GEAR A-P/STRG	1.0 EA	1804.00			1,804.00	S
	COVER-FR,UNDER	1.0 EA	140.00			140.00	S
	COVER-FR UNDER	1.0 EA	42.00			42.00	S
	COVER-FR UNDER	1.0 EA	42.00			42.00	S
	TUBE EXHAUST FR	1.0 EA	674.80			674.80	S
	BODY PANEL SEALANT X	1.0 EA	937.50			937.50	S
	ADHESIVE SEALER FL2	1.0 EA	425.40			425.40	S
	NOISE DEADENING PAD	1.0 EA	500.00			500.00	S

Gross Total. 56,759.20 63 953.80
 Net..... 56,759.20
 GST @ 7.0% 3,973.14
 Total..... 60,732.35
 Paid..... 0.00
 Please Pay.. 60,732.35

Labour Total 27,660.00
 Parts Total 29,099.20
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

60732.35

SERVICE ESTIMATE

0 - L00002 SL: LONPAC INSURANCE BHD LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555	GST Reg.No:M28920628X Inv.No. : B&P 0 Page 1 Inv.date. : 18/09/2018 WIP No. : 17774 Veh.In/Out: 20/07/2018 12/09/2018 *Tel.No. : 62507388 Reg.No. : SKZ4774G Reg.date : 25/01/2016 Mileage : 54,912 Chassis No: JN1BCAV37Z0480583
Closed by : Richmond Ho Svc Consultant : ACC Remarks : Mr Ng Ming Hui	

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
-------	-------------	----------	-------	-------	-----	--------	---

CROSSBAR ASSY-F	1.0 EA	700.00	10	630.00	S	h/	✓
ROD A-CONNECTNG	1.0 EA	34.90	10	31.41	S	bt	✓
ROD-STABILIZER	1.0 EA	34.90	10	31.41	S	bt	✓
STABILIZER ASSY	1.0 EA	380.80	10	342.72	S	bt	✓
BUSHING-STABI	1.0 EA	9.10	10	8.19	S	bt	✓
BUZAER ASSY	1.0 EA	58.80	10	52.92	S	bt	✓
STAY ASSY	1.0 EA	42.00	10	37.80	S	bt	✓
COVER-FLOOR,LH	1.0 EA	140.00	10	126.00	S	cut	✓
COVER-ENGINE,RE	1.0 EA	263.50	10	237.15	S	de	✓
COVER-FLOOR RH	1.0 EA	140.00	10	126.00	S	tn	✓
NUT-SPRING	10.0 EA	5.60	10	50.40	S	re	✓
BUMPER CLIP FX50	10.0 EA	1.30	10	11.70	S	re	✓
AIR GUIDE	1.0 EA	33.60	10	30.24	S	de	✓
SEAL-CONDENSER,	1.0 EA	49.30	10	44.37	S	re	✓
AIR GUIDE	1.0 EA	67.20	10	60.48	S	de	✓
SEAL-CONDENSER,	1.0 EA	49.30	10	44.37	S	re	✓
MOUNTING RUBBER	2.0 EA	8.40	10	15.12	S	re	✓

SERVICE ESTIMATE

0 - L00002	SL: LONPAC INSURANCE BHD	GST Reg.No:M28920628X
LONPAC INSURANCE BHD		Inv.No. : B&P 0 Page 2
300 BEACH ROAD		Inv.date. : 18/09/2018
#17-04/07 THE CONCOURSE		WIP No. : 17774
SINGAPORE 199555		Veh.In/Out: 20/07/2018 12/09/2018
		*Tel.No. : 62507388
		Reg.No. : SK24774G
Closed by : Richmond Ho		Reg.date. : 25/01/2016
Svc Consultant : ACC		Mileage : 54,912
Remarks : Mr Ng Ming Hui		Chassis No: JN1BCAV37Z0480583

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COOLER ASSY-INT	1.0 EA	2013.80	10		1,812.42	S de ✓
	HOSE-AIR INLET	1.0 EA	108.70	10		97.83	S de ✓
	CLAMP-HOSE	3.0 EA	23.20	10		62.64	S de ✓
	PROTECTOR-BODY	1.0 EA	588.00	10		529.20	S de ✓
	COVER ASSY-SILL	1.0 EA	588.00	10		529.20	S de ✓
	CLIP	8.0 EA	1.60	10		11.52	S de ✓
	WHEEL-ROAD AL	1.0 EA	1825.90	10		1,643.31	S de ✓
	RIVET-CHROME Q50	10.0 EA	2.80	10		25.20	S de ✓
	COVER	1.0 EA	140.00	10		126.00	S de ✓
	SCREEN-SEALING	1.0 EA	22.20	10		19.98	S de ✓
	FENDER PLUG FX50	1.0 EA	1.00	10		0.90	S de ✓
	RIVET-CHROME Q50	10.0 EA	2.80	10		25.20	S de ✓
	WATER PIPE TOP Q50	1.0 EA	42.00	10		37.80	S de ✓
	FOG LAMP RH FRT Q50	1.0 EA	436.80	10		393.12	S de ✓

Gross Total. 7,194.60

Labour Total 0.00
 Parts Total 7,194.60
 Package Total 0.00

Net..... 7,194.60
 GST @ 7.0% 503.62
 Total..... 7,698.22
 Paid..... 0.00
 Please Pay.. 7,698.22

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated

SERVICE ESTIMATE

0 - L00002 SL: LONPAC INSURANCE BHD
 LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 1
 Inv.date. : 18/09/2018
 WIP No. : 17774
 Veh.In/Out: 20/07/2018 12/09/2018
 *Tel.No. : 62507388
 Reg.No. : SKZ4774G
 Reg.date : 25/01/2016
 Mileage : 54,912
 Chassis No: JN1BCAV37Z0480583

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Ng Ming Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE FRONT BUMPER,FRT BRACKET,FRT GRILL,FRT LOWER GRILL,FRT BEAM,FRT RH HEADLAMP, FRT RH FENDER,FRT RH DOOR,REAR RH DOOR,REAR RH FENDER,REAR BUMPER,LH ROCKER PANEL,ETC	0	9000.00	0		9,000.00	S
800	TO PUTTY SPRAY PAINT ON FRT BUMPER,FRT LH & RH FENDER, FRT BONNET,FRT RH DOOR,REAR RH DOOR,REAR RH FENDER,REAR BUMPER,RH ROCKER PANEL,LH ROCKER PANEL,ETC	0	8000.00	0		8,000.00	S
802	TO VACCUM & TOP UP A/C GAS	0	600.00	0		600.00	S
287	TO REPLACE FRONT LH & RH UNDERCARRIAGE PARTS	0	4160.00	0		4,160.00	S
0031	TO REPLACE 03 RIMS	0	150.00	0		150.00	S
419	COMPUTERISED WHEEL ALIGNMENT	0	280.00	0		280.00	S

Wearnes Automotive Pte. Ltd.

45 Leng Kee Road, Singapore 159103 T +65 6430 4930 www.wearnesauto.com

Co reg no. 199501400R / GST reg no. M28920628X

SERVICE ESTIMATE

O - L00002 SL: LONPAC INSURANCE BHD
 LONPAC INSURANCE BHD GST Reg.No:M28920628X
 300 BEACH ROAD Inv.No. : B&P 0 Page 2
 #17-04/07 THE CONCOURSE Inv.date. : 18/09/2018
 SINGAPORE 199555 WIP No. : 17774
 Veh.In/Out: 20/07/2018 12/09/2018
 *Tel.No. : 62507388
 Reg.No. : SKZ4774G
 Closed by : Richmond Ho Reg.date. : 25/01/2016
 Svc Consultant : ACC Mileage : 54,912
 Remarks : Mr Ng Ming Hui Chassis No: JN1BCAV37Z0480583

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
280	TO FOCUS HEADLAMP	0	130.00	0		130.00	S
280	TO CHECK WIRING INCLUDE	0	390.00	0		390.00	S
RESETTING OF ALL ELECTRICAL MODULES							
R06	TO INSTALL FRONT NUMBER PLATE	0	60.00	0		60.00	S
INCLUDE HOLDER							
R16	TOWING CHARGES	0	450.00	0		450.00	S
EXC	Excess cost	0	500.00	0		500.00	S
	BUMPER FRT BASE SPOI ②	1.0 EA	112.00	10		100.80	S
	TOW COVER BUMPER FRT ③	1.0 EA	19.90	10		17.91	S
	BUMPER LOWER GRILLE- ④	1.0 EA	198.30	10		178.47	S
	BRACKET-BUMPER FRT R ⑩	1.0 EA	19.60	10		17.64	S
	BRACKET-BUMPER FRT L ⑪	1.0 EA	19.60	10		17.64	S
	BRKT LICENS PLA ⑭	1.0 EA	117.50	10		105.75	S
	BRACKET-BUMPER FRT ⑮	1.0 EA	14.00	10		12.60	S
	BRACKET CTER RH BUMP ⑬	1.0 EA	50.40	10		45.36	S
	BRACKET-BUMPER FRT R ⑯	1.0 EA	14.00	10		12.60	S

SERVICE ESTIMATE

Q - L00002 SL: LONPAC INSURANCE BHD
 LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

GST Reg.No:M28920628X
 Inv.No. : B&P 0 Page 3
 Inv.date. : 18/09/2018
 WIP No. : 17774
 Veh.In/Out: 20/07/2018 12/09/2018
 *Tel.No. : 62507388
 Reg.No. : SKZ4774G
 Reg.date. : 25/01/2016
 Mileage : 54,912
 Chassis No: JN1BCAV37Z0480583

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Ng Ming Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	GRILLE-RADIATOR Q50 (2)	1.0 EA	522.00	10		469.80	S
	EMBLEM (2)	2.0 EA	47.90	10		86.22	S
	HEADLAMP ASSY-RH Q50 (2)	1.0 EA	3344.70	10		3,010.23	S
	DOOR-FRONT RH Q50 (B)	1.0 EA	1045.80	10		941.22	S
	WSTRIP ASSY-FR (A)	1.0 EA	165.20	10		148.68	S
	SEAL-REAR DOOR (B)	1.0 EA	14.00	10		12.60	S
	FRAME-FRONT DOO (46)	1.0 EA	98.90	10		89.01	S
	WINDOW SEAL STRAP IN (F1)	1.0 EA	89.20	10		80.28	S
	DOOR-REAR RH Q50 (50)	1.0 EA	1045.80	10		941.22	S
	W/STRIP-RR DOOR (S1)	1.0 EA	165.20	10		148.68	S
	A SASH RR DOOR (S2)	1.0 EA	54.00	10		48.60	S
	S MOUL SASH RR (V)	1.0 EA	149.30	10		134.37	S
	COVER-SASH INNE (S3)	1.0 EA	97.10	10		87.39	S
	DOOR SEAL RH B PILLA (S7)	2.0 EA	40.40	10		72.72	S
	SPDL-KNUCKLE,RH (S)	1.0 EA	694.90	10		625.41	S
	ABSORBER-SHOCK (S)	1.0 EA	328.40	10		295.56	S
	COVER-FR UNDER (S1)	1.0 EA	42.00	10		37.80	S

SERVICE ESTIMATE

0 - L00002 SL: LONPAC INSURANCE BHD
 LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

GST Reg.No:M28920628X
 Inv.No. . : B&P 0 Page 4
 Inv.date. : 18/09/2018
 WIP No. . : 17774
 Veh.In/Out: 20/07/2018 12/09/2018
 *Tel.No. . : 62507388
 Reg.No. . : SKZ47746
 Reg.date. : 25/01/2016
 Mileage . : 54,912
 Chassis No: JN1BCAV37Z0480583

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Ng Ming Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COVER-FR UNDER (72)	1.0 EA	42.00	10		37.80	S
	CROSSBAR ASSY-F SUPP	1.0 EA	700.00	10		630.00	S
	I545004GE0A/LINK COM (6)	1.0 EA	386.70	10		348.03	S
	ROD A-CONNECTNG	1.0 EA	34.90	10		31.41	S
	ROD-STABILIZER	1.0 EA	34.90	10		31.41	S
	STABILIZER ASSY } SUPP	1.0 EA	380.80	10		342.72	S
	BUSHING-STABI	1.0 EA	9.10	10		8.19	S
	BUZAER ASSY	1.0 EA	58.80	10		52.92	S
	HUB ASSY-ROAD WHEEL (6)	1.0 EA	454.00	10		408.60	S
	BRACKET ASSY-AP SUPP	1.0 EA	84.00	10		75.60	S
	REINFORCEMENT-BUMPER (7)	1.0 EA	481.40	10		433.26	S
	BRACKET ASSY-AP SUPP	1.0 EA	84.00	10		75.60	S
	*ENERGY ABSORBER FOAM (5)	1.0 EA	168.60	10		151.74	S
	*BRACKET-BUMPER CENTE (6)	1.0 EA	70.00	10		63.00	S
	-BRACKET LOWER FENDER (6)	1.0 EA	77.10	10		69.39	S
	*I625014GA0A/BUMPER I (6)	1.0 EA	589.10	10		530.19	S
	STAY ASSY SUPP	1.0 EA	42.00	10		37.80	S

SERVICE ESTIMATE

0 - L00002	SL: LONPAC INSURANCE BHD	GST Reg.No:M28920628X
LONPAC INSURANCE BHD		Inv.No. . : B&P 0 Page 5
300 BEACH ROAD		Inv.date. : 18/09/2018
#17-04/07 THE CONCOURSE		WIP No. . : 17774
SINGAPORE 199555		Veh.In/Out: 20/07/2018 12/09/2018
		*Tel.No. . : 62507388
		Reg.No. . : SK24774G
Closed by : Richmond Ho		Reg.date. : 25/01/2016
Svc Consultant : ACC		Mileage . : 54,912
Remarks : Mr Ng Ming Hui		Chassis No: JN1BCAV37Z0480583

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COVER-FLOOR,LH } <i>Supp</i>	1.0 EA	140.00	10		126.00	S
	COVER-ENGINE,RE } <i>Supp</i>	1.0 EA	263.50	10		237.15	S
	COVER-FLOOR RH	1.0 EA	140.00	10		126.00	S
	COVER-FR,UNDER (F)	1.0 EA	140.00	10		126.00	S
	NUT-SPRING	10.0 EA	5.60	10		50.40	S
	BUMPER CLIP FX50	10.0 EA	1.30	10		11.70	S
	AIR GUIDE	1.0 EA	33.60	10		30.24	S
	SEAL-CONDENSER, } <i>Supp</i>	1.0 EA	49.30	10		44.37	S
	AIR GUIDE	1.0 EA	67.20	10		60.48	S
	SEAL-CONDENSER,	1.0 EA	49.30	10		44.37	S
	MOUNTING RUBBER	2.0 EA	8.40	10		15.12	S
	COOLER ASSY-INT	1.0 EA	2013.80	10		1,812.42	S
	HOSE-AIR INLET	1.0 EA	108.70	10		97.83	S
	CLAMP-HOSE	3.0 EA	23.20	10		62.64	S
	FENDER SIDE BRACKET (F)	1.0 EA	112.00	10		100.80	S
	FENDER-FRONT RH Q50 (F)	1.0 EA	706.70	10		636.03	S
	PROTECTOR-BODY <i>Supp</i>	1.0 EA	588.00	10		529.20	S

SERVICE ESTIMATE

0 - L00002
 LONPAC INSURANCE BHD
 300 BEACH ROAD
 #17-04/07 THE CONCOURSE
 SINGAPORE 199555

SL: LONPAC INSURANCE BHD

GST Reg.No:M28920628X

Inv.No. : B&P 0 Page 6
 Inv.date. : 18/09/2018
 WIP No. : 17774
 Veh.In/Out: 20/07/2018 12/09/2018
 *Tel.No. : 62507388
 Reg.No. : SKZ4774G
 Reg.date. : 25/01/2016
 Mileage : 54,912
 Chassis No: JN1BCAV37Z0480583

Closed by : Richmond Ho
 Svc Consultant : ACC
 Remarks : Mr Ng Ming Hui

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	COVER ASSY-SILL ^{sup}	1.0 EA	588.00	10		529.20	S
	BUMPER FRT RETAINER ⁽¹⁷⁾	1.0 EA	56.00	10		50.40	S
	FOG LAMP OUTER TRIM ⁽¹²⁾	1.0 EA	77.10	10		69.39	S
	CLIP ^{sup}	8.0 EA	1.60	10		11.52	S
	ROAD WHEEL 18" ⁽¹⁸⁾	1.0 EA	1825.90	10		1,643.31	S
	WHEEL-ROAD AL ^{sup}	1.0 EA	1825.90	10		1,643.31	S
	BUMPER FRT Q50 PREM ⁽¹⁾	1.0 EA	685.80	10		617.22	S
	WINDOW OUTER MLDG ST ⁽¹⁵⁾	1.0 EA	168.80	10		151.92	S
	RIVET-CHROME Q50 ^{sup}	10.0 EA	2.80	10		25.20	S
	COVER	1.0 EA	140.00	10		126.00	S
	SCREEN-SEALING ^{sup}	1.0 EA	22.20	10		19.98	S
	FENDER PLUG FX50 ^{sup}	1.0 EA	1.00	10		0.90	S
	RIVET-CHROME Q50 ^{sup}	10.0 EA	2.80	10		25.20	S
	WHEEL ARCH OUTER FRT ⁽²³⁾	1.0 EA	43.50	10		39.15	S
	WHEEL ARCH INNER FRT ⁽²⁴⁾	1.0 EA	40.90	10		36.81	S
	WATER PIPE TOP Q50 ^{sup}	1.0 EA	42.00	10		37.80	S
	FOG LAMP RH FRT Q50 ^{sup}	1.0 EA	436.80	10		393.12	S

Gross Total. 43,817.40
 Less..... 500.00
 Net..... 43,317.40
 GST @ 7.0% 3,032.22
 Total..... 46,349.62
 Paid..... 0.00
 Please Pay.. 46,349.62

Labour Total 23,220.00
 Parts Total 20,597.40
 Package Total 0.00

GST: S=StdRated; O=OutOfScope; Z=ZeroRated

Janice Lee (LKKAUTO)

From: Janice Lee (LKKAUTO)
Sent: Tuesday, November 20, 2018 3:30 PM
To: 'Richmond Ho'
Cc: 'Derek Oh Siong Wee'; Taufikh (LKKAUTO)
Subject: RE: SKZ 4774G LPC OD

Dear Richmond,

Confirm \$43,817.40 @ 16 days

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Janice Lee (LKKAUTO)
Sent: Wednesday, November 07, 2018 2:33 PM
To: Richmond Ho <richmond.ho@wearnes.com>
Cc: Derek Oh Siong Wee <derek.oh@wearnes.com>
Subject: RE: SKZ 4774G LPC OD

Hi,

The final figure get back to you once Taufikh review.

Thank you.

Best Regards,

Jannice Lee (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: janicelee@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Richmond Ho [<mailto:richmond.ho@wearnes.com>]
Sent: Wednesday, November 07, 2018 9:40 AM
To: Janice Lee (LKKAUTO) <JaniceLee@lkkauto.com>
Cc: Derek Oh Siong Wee <derek.oh@wearnes.com>
Subject: RE: SKZ 4774G LPC OD

fya



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS/LPC18013574/T1rd3e2	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 14-12-2018	
			Code : LPC2	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.	Veh. Inspected	SKZ 4774G	
	Policy No. Z18VP05017170	Coverage (\$)	0.00	
	Claim No. 18/18/18/VP05/020770	Excess (\$)	500.00	
	Assign From ONG LI LI	Assign Date	24/07/2018	
2. Vehicle Particulars & Condition				
	Make & Model INFINITI Q50	c.c	1991	
	Engine No. HIDDEN	Year of Reg.	2016	
	Chassis No. JN1BCAV37Z0480583	Colour	WHITE	
	Odometer 54911	Steering	IN ORDER	
	Brakes IN ORDER	Modification	SPORTS RIM	
	General GOOD			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
	L/H Front Tyre	225/50 R18	BRIDGESTONE	6 mm
	R/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
	L/H Rear Tyre	225/50 R18	BRIDGESTONE	6 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY, FRONT AND UNDERCARRIAGE PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date 19/07/2018	Inspection Date	26/07/2018	
	Survey held at WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A)THE MARKET VALUE IS S\$112,000.00(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607196R GST Reg. No. 19-9607196-R

Page No.:1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKZ 4774G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER FRT Q50 PREM (SN)	DEFORMED	685.80	617.22
1	BUMPER FRT BASE SPOI (SN)	DEFORMED	112.00	100.80
1	TOW COVER BUMPER FRT (SN)	CUT	19.90	17.91
1	BUMPER LOWER GRILLE - (SN)	DEFORMED	198.30	178.47
1	ENERGY ABSORBER FOAM (SN)	DEFORMED	168.60	151.74
1	BRACKET-BUMPER CENTE (SN)	DEFORMED	70.00	63.00
1	REINFORCEMENT-BUMPER (SN)	BENT	481.40	433.26
1	REINFORCEMENT SUPPOR (SN)	NOT NECESSARY	115.50	-
1	REINFORCEMENT SUPPOR (SN)	NOT NECESSARY	115.50	-
1	BRACKET-BUMPER FRT R (SN)	NECESSARY	19.60	17.64
1	BRACKET-BUMPER FRT L (SN)	NECESSARY	19.60	17.64
1	FOG LAMP OUTER TRIM (SN)	DEFORMED	77.10	69.39
1	FOG LAMP OUTER TRIM (SN)	NOT NECESSARY	77.10	-
1	BRKT LICENS PLA (SN)	CRACKED	117.50	105.75
1	BRACKET CTER LH BUMP (SN)	NOT NECESSARY	50.40	-
1	BRACKET-BUMPER FRT L (SN)	NECESSARY	14.00	12.60
1	BUMPER FRT RETAINER (SN)	NECESSARY	56.00	50.40
1	BRACKET CTER RH BUMP (SN)	NECESSARY	50.40	45.36
1	BUMPER FRT RETAINER (SN)	NOT NECESSARY	56.00	-
1	BRACKET-BUMPER FRT R (SN)	NECESSARY	14.00	12.60
1	GRILLE-RADIATOR Q50 (SN)	CRACKED	522.00	469.80
1	I625014GA0A/BUMPER I (SN)	DEFORMED	589.10	530.19
1	SUPPORT-RADIATO (SN)	NOT NECESSARY	50.40	-
1	BRACKET LOWER FENDER (SN)	DENTED	77.10	69.39
1	BRACKET LOWER FENDER (SN)	NOT NECESSARY	77.10	-
1	RET-FR BUMPER (SN)	NOT NECESSARY	93.90	-
1	BRACE ASSY-R/CO (SN)	BENT	151.20	151.20
1	FENDER SIDE BRACKET LH (SN)	NOT NECESSARY	112.00	-
1	FENDER SIDE BRACKET RH (SN)	BENT	112.00	100.80
1	IF31004GAMA/FENDER-F LH (SN)	NOT NECESSARY	706.70	-
1	IF31014GAMA/FENDER-F RH (SN)	BENT	706.70	636.03
1	WHEEL ARCH OUTER FRT LH (SN)	NOT NECESSARY	43.50	-
1	WHEEL ARCH OUTER FRT RH (SN)	DEFORMED	43.50	39.15
1	WHEEL ARCH INNER FRT LH (SN)	NOT NECESSARY	40.90	-

Report Ref No. CS/LPC18013574/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	WHEEL ARCH OUTER FRT RH (SN)	DEFORMED	40.90	36.81
2	EMBLEM (SN)	NECESSARY	95.80	86.22
1	HEADLAMP ASSY-LH Q50 (SN)	NOT NECESSARY	3,344.70	-
1	HEADLAMP ASSY-RH Q50 (SN)	CRACKED	3,344.70	3,010.23
1	DAY LIGHT FRT LH Q50 (SN)	NOT NECESSARY	98.30	-
1	DAY LIGHT FRT RH Q50 (SN)	NOT NECESSARY	98.30	-
1	FOG LAMP RH FRT Q50 (SN)	NOT NECESSARY	436.80	-
1	I261554GA0A/LAMP FOG (SN)	NOT NECESSARY	436.80	-
1	DOOR-FRONT RH Q50 (SN)	BENT	1,045.80	941.22
1	WSTRIP ASSY-FR (SN)	NECESSARY	165.20	148.68
1	SEAL-REAR DOOR (SN)	NECESSARY	14.00	12.60
1	FRAME-FRONT DOO (SN)	NECESSARY	98.90	89.01
1	COVER-SASH INNE (SN)	NOT NECESSARY	140.00	-
1	WINDOW OUTER MLDG ST (SN)	NECESSARY	168.80	151.92
1	WINDOW SEAL STRAP IN (SN)	NECESSARY	89.20	80.28
1	DOOR-REAR RH Q50 (SN)	BENT	1,045.80	941.22
1	WSTRIP-RR DOOR (SN)	NECESSARY	165.20	148.68
1	A SASH RR DOOR (SN)	NECESSARY	54.00	48.60
1	SCREEN-SEALING (SN)	NOT NECESSARY	22.20	-
1	S MOUL SASH RR (SN)	NECESSARY	149.30	134.37
1	COVER-SASH INNE (SN)	NECESSARY	97.10	87.39
1	I828384GA0A/DOOR SEA (SN)	NOT NECESSARY	40.40	-
1	DOOR SEAL RH B PILLA (SN)	NECESSARY	72.72	72.72
1	WHEEL-ROAD AL (SN)	CUT	1,825.90	1,643.31
1	FENDER-REAR RH (SN)	NOT NECESSARY	966.30	-
1	IG271689900/WINDSCRE (SN)	NOT NECESSARY	33.80	-
1	WINDSCREEN RR Q50 2. (SN)	NOT NECESSARY	1,650.00	-
1	BUMPER REAR Q50 2.0 (SN)	NOT NECESSARY	800.10	-
2	JC2D7026/SEALANT WIN (SN)	NOT NECESSARY	319.40	-
1	*D* PRIMER GLASS & P (SN)	NOT NECESSARY	37.40	-
1	SPDL-KNUCKLE, RH (SN)	BENT	694.90	625.41
1	HUB ASSY-ROAD WHEEL (SN)	BENT	454.00	408.60
1	I545004GE0A/LINK COM (SN)	BENT	386.70	348.03
1	ABSORBER-SHOCK (SN)	BENT	328.40	295.56
1	GEAR A-P/STRG (SN)	NOT NECESSARY	1,804.00	-
1	COVER-FR, UNDER (SN)	CUT	140.00	126.00

Report Ref No. CS/LPC18013574/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	COVER-FR UNDER (SN)	CUT	42.00	37.80
1	COVER-FR UNDER (SN)	CUT	42.00	37.80
1	TUBE EXHAUST FR (SN)	NOT NECESSARY	674.80	-
1	BODY PANEL SEALANT X (SN)	NOT NECESSARY	937.50	-
1	ADHESIVE SEALER FL2 (SN)	NOT NECESSARY	425.40	-
1	NOISE DEADENING PAD (SN)	NOT NECESSARY	500.00	-
1	CROSSBAR ASSY-F (SN) (ADDITIONAL)	BENT	630.00	630.00
1	ROD A-CONNECTING (SN) (ADDITIONAL)	BENT	31.41	31.41
1	ROD-STABILIZER (SN) (ADDITIONAL)	BENT	31.41	31.41
1	STABILIZER ASSY (SN) (ADDITIONAL)	BENT	342.72	342.72
1	BUSHING-STABI (SN) (ADDITIONAL)	BENT	8.19	8.19
1	BUZAER ASSY (SN) (ADDITIONAL)	DISTORTED	52.92	52.92
1	STAY ASSY (SN) (ADDITIONAL)	BENT	37.80	37.80
1	COVER-FLOOR, LH (SN) (ADDITIONAL)	CUT	126.00	126.00
1	COVER-ENGINE, RE (SN) (ADDITIONAL)	DEFORMED	237.15	237.15
1	COVER-FLOOR RH (SN) (ADDITIONAL)	TORN	126.00	126.00
10	NUT-SPRING (SN) (ADDITIONAL)	NECESSARY	50.40	50.40
10	BUMPER CLIP FX50 (SN) (ADDITIONAL)	NECESSARY	11.70	11.70
1	AIR GUIDE (SN) (ADDITIONAL)	DEFORMED	30.24	30.24
1	SEAL-CONDENSER (SN) (ADDITIONAL)	NECESSARY	44.37	44.37
1	AIR GUIDE (SN) (ADDITIONAL)	DEFORMED	60.48	60.48
1	SEAL-CONDENSER (SN) (ADDITIONAL)	NECESSARY	44.37	44.37
2	MOUNTING RUBBER (SN) (ADDITIONAL)	NECESSARY	15.12	15.12
1	COOLER ASSY-INT (SN) (ADDITIONAL)	DENTED	1,812.42	1,812.42
1	HOSE-AIR INLET (SN) (ADDITIONAL)	DEFORMED	97.83	97.83
3	CLAMP-HOSE (SN) (ADDITIONAL)	DEFORMED	62.64	62.64
1	PROTECTOR-BODY (SN) (ADDITIONAL)	DISTORTED	529.20	529.20
1	COVER ASSY-SILL (SN) (ADDITIONAL)	CRACKED	529.20	529.20
8	CLIP (SN) (ADDITIONAL)	NECESSARY	11.52	11.52
1	WHEEL-ROAD AL (SN) (ADDITIONAL)	CUT	1,643.31	1,643.31
10	RIVET-CHROME Q50 (SN) (ADDITIONAL)	NECESSARY	25.20	25.20
1	COVER (SN) (ADDITIONAL)	DEFORMED	126.00	126.00
1	SCREEN-SEALING (SN) (ADDITIONAL)	NECESSARY	19.98	19.98
1	FENDER PLUG FX50 (SN) (ADDITIONAL)	NECESSARY	0.90	0.90
10	RIVET-CHROME Q50 (SN) (ADDITIONAL)	NECESSARY	25.20	25.20
1	WATER PIPE TOP Q50 (SN) (ADDITIONAL)	DISTORTED	37.80	37.80

Report Ref No. CS/LPC18013574/T1rd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FOG LAMP RH FRT Q50 (SN) (ADDITIONAL)	CRACKED	393.12	393.12
			36,366.92	20,597.40
	LABOUR			
	TO REPLACE FRONT BUMPER, FRT BRACKET, FRT GRILL, FRT LOWER GRILL, FRT BEAM, FRT RH HEADLAMP, FRT RH FENDER, FRT RH DOOR, REAR RH DOOR, REAR RH FENDER, REAR BUMPER, LH ROCKER PANEL, ETC.		10,800.00	9,000.00
	TO PUTTY SPRAY PAINT ON FRT BUMPER, FRT LH & RH FENDER, FRT BONNET, FRT RH DOOR, REAR RH DOOR, REAR RH FENDER, REAR BUMPER, RH ROCKER PANEL, LH ROCKER PANEL, ETC.		9,600.00	8,000.00
	TO VACUUM & TOP UP A/C GAS.		600.00	600.00
	TO REPLACE FRONT LH & RH UNDERCARRIAGE PARTS.		5,200.00	4,160.00
	TO REPLACE 03 RIMS.		150.00	150.00
	COMPUTERISED WHEEL ALIGNMENT.		280.00	280.00
	TO FOCUS HEADLAMP.		130.00	130.00
	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES.		390.00	390.00
	TO INSTALL FRONT NUMBER PLATE INCLUDE HOLDER.		60.00	60.00
	TOWING CHARGES.		450.00	450.00
			27,660.00	23,220.00
GRAND TOTAL			64,026.92	43,817.40
RECOMMENDED COST OF REPAIRS				43,817.40
LESS EXCESS				-500.00
NETT LIABILITY				43,317.40

Report Ref No. CS/LPC18013574/T1rd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.