



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-		Ref : CS/TP18013581/Ktbn2		
PRELIM CONSTRUCTION PL 81 TAGORE LANE #01-21 TAG A SINGAPORE 787502- -		Date : 30-08-2018		
		Code : -		
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	Veh. Inspected	GBB 4610D	
	Policy No.	Coverage (\$)	0.00	
	Claim No.	Excess (\$)	0.00	
	Assign From	Assign Date	25/07/2018	
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA DYNA	c.c	2982
	Engine No.	HIDDEN	Year of Reg.	2009
	Chassis No.	JTFAT35Y60K200436	Colour	BLUE
	Odometer	422820	Steering	IN ORDER
	Brakes	IN ORDER	Modification	NIL
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	195 R15X8	BRIDGESTONE	2 mm
	L/H Front Tyre	195 R15X8	BRIDGESTONE	2 mm
	R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	7/7 mm
	L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	7/7 mm
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
	Accident Date	14/07/2018	Inspection Date	25/07/2018
	Survey held at	AH LIM MOTOR CO NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047		
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	