

REF: INC NG/INC18013592/Gipbe2

### ASSIGNMENT

<p>From: _____ Date: _____</p> <p>Estimated Cost: _____</p> <p>OD: <input checked="" type="checkbox"/> TP / WS / TP RES / OD RES / EVA / INV / MV</p> <p>To Inspect Vehicle No: _____</p> <p>at Workshop m/s: <b>SMRT</b></p> <p>of: _____</p> <p>Insured: <b>SLH 4069S</b></p> <p>Policy No: <b>5101635059 270618-31-10-19</b></p> <p>Claims No: <b>MT/1004014-02</b></p> <p>Sum Insured: _____ Excess: _____</p> <p>(Client's Record)</p> <p>Make of Veh: _____</p> <p>(Policy Condition)</p> <p>Remark: <b>The veh had commenced its repair at the time of inspection.</b></p> <p>Bal. or Market Value: _____</p> <p>IDAC Accident Rpt.: _____ Consistent? : Yes or No</p> <p>GIA / PR Seen: _____ Consistent? : Yes or No</p> <p>Est. Repairs: <b>4</b> days Res: Yes or No</p> <p>Lum Sum: _____ % 3 Val: Yes or No</p> <p>CA / REV / REP. / 24 HRS</p> <p>Date: _____ Person Contacted: _____</p> <p>Vehicle: IN / OUT</p>	<p>Veh No: <b>SHB 5192R</b> Yr Regd: <b>19 Jan 2017</b></p> <p>Type: M.Car / M.Cycle / Bus / Van / Lorry / <input checked="" type="checkbox"/> Taxi / Prime Mover /</p> <p>Truck / Trailer or</p> <p>Make: <b>Toyota Prius</b> C.C. <b>1798</b></p> <p>Colour: <b>Brown Maroon</b> Insured / Std / NI / NA</p> <p>Sp. Reading: <b>163926</b> T/Radio: Insured / Std / NI / NA</p> <p>Eng/No: _____</p> <p>C/No: <b>ITDKN 364 2057 68720</b></p> <p>Gen. Cond: Good / Fair / Poor / Burnt</p> <p>Steering: <input checked="" type="checkbox"/> In order / Jammed / Leaked / Burnt or</p> <p>Brake: <input checked="" type="checkbox"/> In order / Jammed / Leaked / Burnt or</p> <p>Mod: <input checked="" type="checkbox"/> Nil / <input checked="" type="checkbox"/> STD A/Rim or</p> <p>Tyre Size: F: <b>195/65 R15</b></p> <p style="margin-left: 400px;">R: <b>11</b></p> <p>BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /</p> <p>TOYO / YOKO or <b>FALKEN</b></p> <p>Front: _____ Rear: _____</p> <p>R/Bal: <b>6</b> mm R/Bal: <b>6</b> mm</p> <p>L/Bal: <b>6</b> mm L/Bal: <b>6</b> mm</p> <p>D.O.A. _____ D.O.I. <b>23-07-18</b></p> <p>Survey held at: <b>W/S</b> <b>5pm</b></p> <p>Des. of Damages: Frt / Rear / <input checked="" type="checkbox"/> O/S / N/S / U/C / Rooftop or</p> <p>The U/C / Chassis frame / Body Structure affected due to collision</p>
--	--

Date / Time	Action / Instruction
	<b>SHB 5192R - 03/NOV 2018 / R/Hdz1</b>
	<b>SLH 4069S - X</b>
	<b>07/11/18 @ 3.12pm XGR finalised with Peh Sumi Anal fig \$2446.10, 4 days.</b>
	<b>(Red \$10483.28, 81%)</b>

RECEIVED 08 NOV 2018

<p>Date/Time: File Pass to? <b>08/11/18</b></p> <p>Date/Time: File Return to? _____</p> <p>Report Format: _____</p> <p>Lump Sum / I.B.L: (\$ _____)</p>	<p>Days Of Repair: <b>4</b></p> <p>Resurvey No. of Trip: <b>1</b></p> <p>Add Fee: <input type="checkbox"/> Site Insp (\$ _____)</p> <p><input type="checkbox"/> Interview (\$ _____)</p> <p><input type="checkbox"/> Tech. Invs (\$ _____)</p> <p><input type="checkbox"/> Weekend (\$ _____)</p>	<p>Survey Fee: <b>160</b></p> <p>Transportation: _____</p> <p>Other: _____</p> <p>TOTAL: <b>160</b></p>
---	---	---



## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013592/Gqb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 26-07-2018

189556



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLH 4069S	Veh. Inspected	SHB 5192R
Policy No.	5101635059	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	23/07/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	21/07/2018	Inspection Date	23/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Shiau Chan (LKKAUTO)

**From:** mtreg <mtreg@income.com.sg>  
**Sent:** Thursday, 8 November 2018 8:14 AM  
**To:** Shiau Chan (LKKAUTO)  
**Subject:** FW: REQUEST CLAIM NUMBER

Hi,

Claim created.

With Regards

**Samsia**  
Senior Admin Assistant,  
Motor Insurance  
[www.income.com.sg](http://www.income.com.sg)



At Income, we are 'In with You' on Performance, Growth, Innovation and Impact. These attributes reflect what we promise as an employer and what we want our people to exemplify.  
Find out more at [Income.com.sg/careers](http://Income.com.sg/careers)

**in** with you

*'With effect from 1 Oct 2018, we will be discontinuing our fax number 6338 1504.*

*Please forward all motor claims related correspondences to [mtcl@income.com.sg](mailto:mtcl@income.com.sg) so that we can attend to it accordingly.'*

**From:** Shiau Chan (LKKAUTO) [mailto:[siewsc@lkkauto.com](mailto:siewsc@lkkauto.com)]  
**Sent:** Wednesday, November 07, 2018 4:55 PM  
**To:** mtreg <mtreg@income.com.sg>  
**Subject:** REQUEST CLAIM NUMBER

Dear Sir/Madam,

Please refer to the below:

### TP Claims against NTUC Income: Follow-Through Survey

Date : 07/11/2018

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	
1	MT/1004014-002	SMRT TAXIS PTE LTD	SHB 5192R	SLH 4069S	

Best Regards,

**Shiau Chan (Ms)** | Case Handler  
**LKK Auto Consultants Pte Ltd**

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No. (For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input checked="" type="radio"/>	5101635059	EZI LIMOS	S3346381E	GPC	drive CLASSIC	SLH40695	SLH40695	27/06/2018	31/10/2019

## Shiau Chan (LKKAUTO)

---

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
<YeoPohsuan@smrt.com.sg>  
**Sent:** Friday, 2 November 2018 4:12 PM  
**To:** Guo Qiang (LKKAUTO)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'; Shiau Chan (LKKAUTO)  
**Subject:** RE: SHB5192R

Hi,

Amount confirmed as per your recommendation, thanks.

Regards  
Poh Suan

-----Original Message-----

**From:** Guo Qiang (LKKAUTO) [mailto:GuoQiang@lkkauto.com]  
**Sent:** Friday, 2 November 2018 3:12 PM  
**To:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'; Shiau Chan (LKKAUTO)  
**Subject:** RE: SHB5192R

Hi,

Confirmed COR \$2446.1 before GST @ 4 working days.

Regards,  
Guo Qiang

-----Original Message-----

**From:** Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex)) [mailto:YeoPohsuan@smrt.com.sg]  
**Sent:** Friday, 2 November, 2018 1:43 PM  
**To:** Guo Qiang (LKKAUTO)  
**Cc:** SUR; CS A Team; 'Leong Chee kwong'  
**Subject:** SHB5192R

Hi Guo Qiang,

Attached herewith the repair estimate of SHB 5192R having Case No: TAX/07/18/2091.

There is no change to the approved amount of \$2,446.11 @ 4 working days under part by part repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Aside Kwong,

Please provide the before / after paint photos as per surveyor's request.

Thanks & Regards  
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Sent: Friday, 2 November 2018 1:45 PM

To: Yeo Poh Suan (Auto Svcs/Ext Biz Svcs/AR & SC/ARC (Tx&Ex)/ARC (Tx&Ex))

Subject: Scan Data from FX-D421D6

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5369K
Vehicle Details	
Vehicle No.:	SHB5192R
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Nov 2018
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR6612831
Chassis No.:	JTDKN36U205768720
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	19 Jan 2017
First Registration Date:	19 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	18 Jan 2025
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	18 Jan 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$40,516.00
COE Rebate Amount:	\$31,367.00
<b>Total Rebate Amount:</b>	<b>\$35,117.00</b>
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 08 Nov 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	21/07/2018 11:04
Date Of Accident	21/07/2018 08:40
Exact Location Of Accident	ANG MO KIO AVE 5 SLIP ROAD TO ANG MO KIO AVE 6
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB5192R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	MS FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-18090213MFSH
Cover Note Number	

### Driver

Name of Driver	ONG TEK WEE
NRIC No	S7504425I
Date Of Birth	22/01/1975
Occupation	OUTDOOR
Date Of Driving Pass	29/09/1993
Driving Experience	24 YEARS AND 9 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-800000000
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	987
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (including Driver)	2
Passenger 1	
	NAME: : UNKNOWN
	GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	ANG MO KIO NORTH NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 51 ANG MO KIO AVE 9 , POSTCODE: 569784 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4849999 - FAX NO: 52181399
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO POLICE REPORT - T/20180721/2024 On 21/07/2018 at about 0840hrs, I was driving my taxi plate number SHB5192R along AMK Ave 5 with one female passenger on board. While I was turning left at the slip road to AMK Ave 6, I came to a stopped to check for traffic. After I checked that the traffic is clear, I slowly drove off my vehicle however there was a car making U-turn at the x-junction. As such I stopped my vehicle before the dotted line to let the car drive past first. All of a sudden, I got hit by a car plate number SLH4069S. The head of the car hit the back of my taxi. There were dents at the right back of my taxi and damages on his front car. After the collision, I went to exchange particulars with the driver and my passenger informed that her neck was pain. There was no police and no ambulance attended at the scene.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	FILE TOO LARGE
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH4069S
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR

Name of Driver	JUSTIN JUNWEI CHARLES
NRIC/Passport Number	S8912475A
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

#### DETAILS OF INJURED PERSON 1

Name	LARA
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB5192R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

#### DETAILS OF INJURED PERSON 2

Name	ONG TEK WEE
Approximate Age	
Injuries Sustain	
Injured person in which vehicle?	SHB5192R
Were seat belts worn?	
Was this injured conveyed to hospital by ambulance?	NO
Address	
Postcode	

SKETCH PLANIMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.




Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 21/7/2018  
11:5am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT - 1/20180721/2224



Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time: 21/7/2018  
11:5am

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:



**SINGAPORE  
POLICE FORCE**



T/20180721/2024

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

1 of 4

Report No. T/20180721/2024

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 21/07/2018 10:20		Vide Report No.:	Station Diary No.: 41
<b>Informant's Particulars</b>			
Name of Informant: ONG TEK WEE		Address: APT BLK 987C BUANGKOK GREEN #09-55 SINGAPORE 533987	
ID Type / ID No.: NRIC NO / S75044251		Contact No.: Home/Office: Mobile: 93694824	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 43	Date of Birth: 22/01/1975	Type of Informant: Driver
Race: Chinese		Language:	Institution / School Name:
Occupation: Taxi driver		Driving Licence Information: Class: Date of Expiry:	

**General Information of the Accident**

Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 21/07/2018 08:40	Type of Location: SLIP ROAD
Location: Along Road 1 Traveling Toward Road 2 ANG MO KIO AVENUE 5 ANG MO KIO AVENUE 6 SLIP ROAD LEFT TURN TO AVE 6				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow:		Traffic Control:	Traffic Volume:	
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No. of Passenger
SHB5192R	TAXI				Slightly Damaged	1
SLH4069S	Car				Slightly Damaged	0

**Details of Person Involved**

Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



**SINGAPORE  
POLICE FORCE**



T/20180721/2024

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

2 of 4

Report No. T/20180721/2024

## CONTINUATION OF REPORT

<b>Passenger</b>			
Name	LARA	ID No.	-
Related Vehicle	SHB5192R (TAXI)	Contact No.	93870575
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	Slight
<b>Driver</b>			
Name	ONG TEK WEE	ID No.	S7504425I
Related Vehicle	SHB5192R (TAXI)	Contact No.	93694824
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	JUSTIN JUNWEI CHARLES	ID No.	S8912475A
Related Vehicle	SLH4069S (Car)	Contact No.	88628298
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL

**Brief Details.**

On 21/07/2018 at about 0840hrs, I was driving my taxi plate number SHB5192R along ANG MO KIO AVE 5 with one female passenger on board. While I was turning left at the slipped road to ANG MO KIO AVE 6, I came to a stopped to check for traffic. After I checked that the traffic is clear, I slowly drove off my vehicle however there was a car making U-turn at the x-junction. As such I stopped my vehicle before the dotted line to let the car drive past first. All of a sudden, I got hit by a car plate number SLH4069S. The head of the car hit the back of my taxi. There were dents at the right back of my taxi and damages on his front car.

After the collision, I went to exchange particulars with the driver and my passenger informed that her neck was pain.



**SINGAPORE  
POLICE FORCE**



T/20180721/2024

Police Station Of Origin;  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999

3 of 4

Report No. T/20180721/2024

CONTINUATION OF REPORT

There was no police and no ambulance attended at the scene.



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Ang Mo Kio North N.P.C  
51 Ang Mo Kio Avenue 9 SINGAPORE  
569784  
Tel No: 1800-4849999



T/20180721/2024

4 of 4

Report No. T/20180721/2024

## CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: F / Sgt 2 KOH JIA JUN	Signature Of Informant:
Signature Of Interpreter: Not applicable	Date/Time: 21/07/2018 10:20
Officer In Charge Of Case: TP / AEIT / Sr Staff Sgt ONG YONG HOCK Contact No.: 65476438	Classification Of Case:
Authentication Stamp NP168	Signature: Singapore Police Force



## SMRT Accident Vehicle Repair Estimates

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5192R  
 Ref. No : TAX/07/18/2091  
 Reg. Date : 19/01/2017  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : ONG TEK WEE  
 Type of Accident : HEAD TO REAR  
 Date / Time of Accident : 21/07/2018 08:40:00 AM  
 Accident Reported Date / Time : 21/07/2018 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024097148  
 Special Instruction to ARC, if any :  
 SLH4069S - NTUC - LKK  
 Prepared Date : 21/07/2018 11:43:53 AM



4 Days.

Case Q:amp - 82880282

23/7/18

part by part.

before paint photos.

*[Signature]*  
26/7/18

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36U205768720

Mileage : 0

Work Shop :

Repair Completed Date / Time :

### Summary of Repair Estimates

#### Quotation from ARC

#### Adjusted by Surveyor, if applicable

Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,674.00	0.00
Total Material Charges	: 6,601.82	6,601.82
Other Charges	: 1,721.88	0.00
<b>TOTAL</b>	<b>: 11,011.70</b>	<b>0.00</b>
<b>Lum Sum Total</b>	<b>: 0.00</b>	<b>0.00</b>
No. of Repair Days	: 6.00	0.00
Prepared / Adjusted By	:	
Arc / Surveyor Sign Off Date	: 23/07/2018 01:17:10 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 23/07/2018 01:14:54 PM

### Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/23/2018 1:15:32 PM

**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	1,014.00	0.00
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b> 400

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	0.00 X X N/A
TO RESPRAY TAIL GATE	378.00	0.00 200
TO RESPRAY REAR PANEL	180.00	0.00 150
TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00 X
TO RESPRAY REAR FENDER RH	378.00	0.00 X } NN
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,674.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 X NN
TO REMOVE / REFIT SEAT	120.00	0.00 X
TO REMOVE & REFIT EXHAUST	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X } NN
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 X
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	0.00 X X NN
TO REMOVE AND REFIX REAR WINDSCREEN	240.00	0.00 X NN
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 40
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 X } NN
TO WASH AND VACUUM	60.00	0.00 X
<b>Total Other Costs</b>	<b>1,721.88</b>	<b>0.00</b>

1020 12919-38

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
52159-47905		6505548	BUMPER REAR <i>ll</i>	1	458.60	25.00	343.95	Replace	Replace	No
52161-16010			BUMPER CLIPS <i>ll</i>	10	1.61	25.00	12.07 <i>17.03</i>	Replace	Replace	No
76087-47020		6505618	BUMPER LIP COVER RR/RH <i>ll</i>	1	118.10	25.00	88.57	Replace	Replace	No
76891-47020		6505619	BUMPER LIP REAR <i>X ll</i>	1	228.90	25.00	171.67 <i>X 171.67</i>	Replace	Replace	No
52023-12240		6505547	BUMPER REINFORCEMENT REAR <i>X ll</i>	1	205.70	25.00	154.27 <i>134.27</i>	Replace	Replace	No
52016-47030			ARM SUB-ASSY, RR BUMPER LH <i>X ll</i>	1	139.60	25.00	104.70 <i>nm</i>	Replace	Replace	No
52015-47050			ARM SUB-ASSY, RR BUMPER RH <i>X ll</i>	1	139.60	25.00	104.70 <i>BT</i>	Replace	Replace	No
			SENSOR REVERSE <i>X nm</i>	1	180.00	0.00	180.00 <i>X</i>	Replace	Replace	No
			PIXEL STICKER <i>ll</i>	2	60.00	0.00	120.00	Replace	Replace	No
52591-47021			BUMPER SEAL, RR RH <i>X nm</i>	1	65.70	25.00	49.27 <i>X</i>	Replace	Replace	No
52576-47020		6505550	BUMPER SIDE RETAINER RR/LH <i>X nm</i>	1	94.80	25.00	71.10 <i>X</i>	Replace	Replace	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH <i>ll</i>	1	94.80	25.00	71.10	Replace	Replace	No
58308-47011			UNDER COVER SUB-ASSY, RR FLOOR <i>X nm</i>	1	514.50	25.00	385.87 <i>X</i>	Replace	Replace	No
67005-47241			TAILGATE ASY <i>X Repair</i>	1	1,007.90	25.00	755.92 <i>X</i>	Replace	Replace	No
75574-47020			TAIL GATE DOOR GLASS MOULDING, LH <i>X</i>	1	29.40	25.00	22.05 <i>X</i>	Replace	Replace	No
75573-47080			TAIL GATE DOOR GLASS MOULDING, RH <i>X</i>	1	29.40	25.00	22.05 <i>X</i>	Replace	Replace	No
75575-47030			MOULDING BACK WINDOW, LOWER NO.1 <i>X nm</i>	1	29.40	25.00	22.05 <i>X</i>	Replace	Replace	No
	COMMON		SEALANT W/SCREEN <i>X</i>	3	37.00	0.00	111.00 <i>X</i>	Replace	Replace	No
75374-47051			NAME PLATE (HYBRID) <i>X</i>	1	51.90	25.00	38.92 <i>X</i>	Replace	Replace	No
57881-47022			TAILGATE DOOR WEATHER STRIP <i>X</i>	1	353.40	25.00	265.05 <i>X</i>	Replace	Replace	No
39350-47030			TAILGATE DOOR LOCK <i>X</i>	1	444.10	25.00	333.07 <i>X</i>	Replace	Replace	No
58307-17060		6505522	END PANEL <i>X Repair</i>	1	602.10	25.00	451.57 <i>X</i>	Replace	Replace	No
34718-17031B0			END PANEL COVER, DECK TRIM HOLE <i>X</i>	1	46.10	25.00	34.57 <i>X</i>	Replace	Replace	No
34716-17031B0			END PANEL COVER, DECK TRIM, RR <i>X nm</i>	1	121.10	25.00	90.82 <i>X</i>	Replace	Replace	No
	COMMON	4006314	SEALANT SIKAFLEX <i>X</i>	1	37.00	0.00	37.00 <i>X</i>	Replace	Replace	No
2562-7010			TAIL LAMP BRACKET, RH <i>X nm</i>	1	30.70	25.00	23.02 <i>X</i>	Replace	Replace	No
1551-7180		6505462	TAIL LAMP RH <i>ll</i>	1	557.80	10.00	502.02	Replace	Replace	No
1621-7030			TROUGH, BACK DOOR <i>X nm</i>	1	110.90	25.00	83.17 <i>X</i>	Replace	Replace	No

Number			(\$)	(%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
61604-47090		FENDER RR/RH	X NN 1 766.80	25.00	575.10 X	Replace	Replace	No
	COMMON	SMRT LOGO	/ MCC 1 7.80	0.00	7.80 ✓	Replace	Replace	No
		STICKER DECAL 6555 8888	/ MCC 1 21.60	0.00	21.60 ✓	Replace	Replace	No
62940-16060		DUCT ASSY QUARTER	X NN 1 70.40	25.00	52.80 X	Replace	Replace	No
62710-47130		QUARTER GLASS RR/RH	X NN 1 846.50	25.00	634.87 X	Replace	Replace	No
	COMMON	SEALANT W/SCREEN	X NN 37.00	0.00	37.00 X	Replace	Replace	No
58327-47020		EXHAUST HEAT SHIELD, REAR	X 1 107.40	25.00	80.55 X	Replace	Replace	No
17430-37380		EXHAUST TAIL PIPE	X 1 656.20	25.00	492.15 X	Replace	Replace	No
17565-22030		SUPPORT, EXHAUST REAR	NN 2 33.60	25.00	50.40 X	Replace	Replace	No
TOTAL MATERIALS						6,601.90	6,601.82	
TOTAL MATERIALS(Discounted)						5519.50	6,601.82	6,601.82
Added Spare Parts / Material Usage After Surveyor Signed off								

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

1426.1

~~1620.1 - 1590.9~~

~~249.1 - 1193.03~~

1342.43

84917768 Ggb

Contractor:	WEGA ENGINEERING PTE LTD		
Accident Case Number	20X/07/18/2091	Date of Collection	24/7/18
Vehicle No	SHB 5192 R	Date of Request	25/7/18
Vehicle Model	TOYOTA PRINS	Number of Days to Extend	

REQUEST FOR SUPPLYMENT PARTS

S/N	Number photos	Part Description	Quantity	Unit Price
1	9956, 51, 58,	Rear Bumper Reinforcement	BT	\$205.70
2	9961, 62, 63, 64 65, 166	Arm Sub Assy RR Bumper RH	BT	\$139.60
3	9959, 60	Bumper Lip Cover RR RH	<del>6</del> 22	\$118.10
4				
5				
6				
7				
8				

&lt;&lt;&lt;Please submit photographs for damaged parts&gt;&gt;&gt;

I, (Name) CHIA

(Position) ADVISOR

Do solemnly and sincerely declare that: - Supplementary Parts are raised for replacement for the aforesaid vehicle.

Chia

Signature of person making this declaration

[To be signed in front of an authorised witness]


I acknowledge that this declaration is true and correct, and I make it with the understanding and belief that a person who makes a false declaration is liable to the damages of perjury.

Acknowledge By	ARC Executive / Supervisor / SA	<u>[Signature]</u>
Approval By	Surveyor / In-house Staff	<u>Gus Ong</u>
Parts Ordering	SMRT Store / Contractor Supply / Form 22 / WOC	Form 22 / PO / WOC / Reservation / Number
Photo Submitted		Date of submission

For SMRT Staff



## Section A - Accident Details

Registration Number	SHB5192R
Case Reference Number	TAX/07/18/2091
Registration Date	19/01/17
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	ONG TEK WEE
Type of Accident	HEAD TO REAR
Accident Date and Time	21/07/18 8:40 AM
Accident Reported Date and Time	21/07/18 11:00 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	000024097148
Special Instruction to ARC, if any	SLH4068S - NTUC - LKK BEFORE PAINT PHOTO ,FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR quociang (LKK) & Email :quociang@lkkauto.com HP:82880282
Prepared Date and Time	21/07/2018 11:43 AM
Chassis Number	JTDKN36U205768720
Mileage	
Work Shop	
Repair Completion Date and Time	



## Section B - Summary of Repair Estimates

## Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,014.00	\$400.00
Total Spray Cost	\$1,674.00	\$550.00
Total Spare Part Cost	\$2,001.18	\$1,426.11
Total Other Cost	\$1,721.88	\$70.00
<b>TOTAL COST</b>	<b>\$5,411.06</b>	<b>\$2,446.11 (P/P)</b>
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	6.0	4.0
Prepared / Adjusted By	Taxi Estimator Team	GUO QIANG (LKK) / NTUC
ARC / Surveyor Sign Off Date	23/07/2018 1:17 PM	23/07/2018 4:57 PM
Signature		
Remarks		

## Section C - Quotation and Accident Invoice Details

Quotation Number	QN-1811-0016	Invoice Number	
Quotation Date	02.11.2018	Invoice Date	
Invoice Amount		Prepared Date	

## Section D - Details of Repair Estimates

## Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH REAR PORTION	\$1,014.00	\$400.00
<b>Total Labour</b>	<b>\$1,014.00</b>	<b>\$400.00</b>



**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
TO RESPRAY TAIL GATE	\$378.00	\$200.00
TO RESPRAY REAR PANEL	\$180.00	\$150.00
TO RESPRAY TROUGH BACK DOOR RH	\$180.00	\$0.00
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,674.00</b>	<b>\$550.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$30.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO REMOVE / REFIT SEAT	\$120.00	\$0.00
TO REMOVE & REFIT EXHAUST	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	\$125.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO TRANSFER REAR TAILGATE MECHANISM	\$120.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$0.00
TO REMOVE AND REFIX REAR WINDSCREEN	\$240.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$40.00
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
<b>Total Other Costs</b>	<b>\$1,721.88</b>	<b>\$70.00</b>

**Part 4 - Spare Parts / Material Usage**

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6505548		52159-47905	BUMPER REAR	1.00	\$458.80	25.00	\$343.95	Replace	Replace ✓
		52161-16010	BUMPER CLIPS	10.00	\$1.61	25.00	\$12.08	Replace	Replace ✓
6505619		76891-47020	BUMPER LIP REAR	0.00	\$228.90	25.00	\$0.00	Replace	Not Given X
		52016-47030	ARM SUB-ASSY, RR BUMPER LH	0.00	\$139.60	25.00	\$0.00	Replace	Not Given X
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given X

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd  
80 Woodlands Industrial Park 2A, Singapore  
FAX Number : 63601062  
Estimate Telephone Number : 63602023  
Accident Reporting Number : 68667672

Date : 02/11/2018  
User ID : Pukhuan

			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	✓
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	25.00	\$0.00	Replace	Not Given	✓
6505550		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	25.00	\$0.00	Replace	Not Given	✓
6505549		52575-47020	BUMPER SIDE RETAINER RR/RH	1.00	\$94.80	25.00	\$71.10	Replace	Replace	✓
		58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	25.00	\$0.00	Replace	Not Given	✓
		87005-47241	TAILGATE ASY	1.00	\$1,007.90	100.00	\$0.00	Replace	Repair	✓
		75574-47020	TAIL GATE DOOR GLASS MOULDING, LH	0.00	\$29.40	25.00	\$0.00	Replace	Not Given	✓
		75573-47080	TAIL GATE DOOR GLASS MOULDING, RH	0.00	\$29.40	25.00	\$0.00	Replace	Not Given	✓
		75575-47030	MOULDING BACK WINDOW, LOWER NO.1	0.00	\$29.40	25.00	\$0.00	Replace	Not Given	✓
	COMMON		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	✓
		75374-47051	NAME PLATE (HYBRID)	0.00	\$51.90	25.00	\$0.00	Replace	Not Given	✓
		67881-47022	TAILGATE DOOR WEATHER STRIP	0.00	\$353.40	25.00	\$0.00	Replace	Not Given	✓
		69350-47030	TAILGATE DOOR LOCK	0.00	\$444.10	25.00	\$0.00	Replace	Not Given	✓
6505522		58307-47060	END PANEL	1.00	\$602.10	100.00	\$0.00	Replace	Repair	✓
		64718-47031B0	END PANEL COVER, DECK TRIM HOLE	0.00	\$46.10	25.00	\$0.00	Replace	Not Given	✓
		64716-47031B0	END PANEL COVER, DECK TRIM, RR	0.00	\$121.10	25.00	\$0.00	Replace	Not Given	✓
4006314	COMMON		SEALANT SIKAFLEX	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	✓
		52562-47010	TAIL LAMP BRACKET, RH	0.00	\$30.70	25.00	\$0.00	Replace	Not Given	✓
6505462		61551-47180	TAIL LAMP RH	1.00	\$557.80	10.00	\$502.02	Replace	Replace	✓
		61621-47030	TROUGH, BACK DOOR	0.00	\$110.90	25.00	\$0.00	Replace	Not Given	✓
		61804-47090	FENDER RR/RH	0.00	\$766.80	25.00	\$0.00	Replace	Check	✓
	COMMON		SMRT LOGO	1.00	\$7.80	0.00	\$7.80	Replace	Replace	✓
			STICKER DECAL 6555 8888	1.00	\$21.60	0.00	\$21.60	Replace	Replace	✓
		62940-16060	DUCT ASSY, QUARTER	0.00	\$70.40	25.00	\$0.00	Replace	Not Given	✓
		62710-47130	QUARTER GLASS RR/RH	0.00	\$646.50	25.00	\$0.00	Replace	Not Given	✓
	COMMON		SEALANT W/SCREEN	0.00	\$37.00	0.00	\$0.00	Replace	Not Given	✓
		58327-47020	EXHAUST HEAT SHIELD, REAR	0.00	\$107.40	25.00	\$0.00	Replace	Not Given	✓
		17430-37380	EXHAUST TAIL PIPE	0.00	\$656.20	25.00	\$0.00	Replace	Not Given	✓
		17565-22030	SUPPORT, EXHAUST REAR	0.00	\$33.60	25.00	\$0.00	Replace	Not Given	✓
<b>Total</b>					<b>\$7,874.01</b>		<b>\$1,078.55</b>			



## SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
63 Woodlands Industrial Park E4, Singapore
FAX Number: 63955592
Estimate Telephone Number: 68982823
Accident Reporting Number: 68982872

Date: 02/11/2018  
User ID: Puh Guan

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
6505618		76087-47020	BUMPER LIP COVER RR/RH	1.00	\$118.10	25.00	\$88.58	Replace	Replace ✓
6505547		52023-12240	BUMPER REINFORCEMENT REAR	1.00	\$205.70	25.00	\$154.28	Replace	Replace ✓
		52015-47050	ARM SUB-ASSY, RR BUMPER RH	1.00	\$139.60	25.00	\$104.70	Replace	Replace ✓
Total					463.40		347.56		

\$1426.11  
+ \$400.00  
+ \$620.00  
-----  
\$2446.11

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC18013592/Gqbe2			
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556		Date: 07-12-2018	
		Code: INC4	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>			
Insured Veh.	SLH 4069S	Veh. Inspected	SHB 5192R
Policy No.	5101635059	Coverage (\$)	0.00
Claim No.	MT/1004014-002	Excess (\$)	0.00
Assign From		Assign Date	23/07/2018
<b>2. Vehicle Particulars &amp; Condition</b>			
Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTDKN36U205768720	Colour	MAROON
Odometer	163926	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
<b>3. Conditions of Tyres</b>			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm
<b>4. Description of Damages</b>			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>			
Accident Date	21/07/2018	Inspection Date	23/07/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
<b>5a. Remarks</b>			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No: 20-0405911-H



Page No.:1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 5192R**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	BUMPER REAR (DISC 25%)	NECESSARY	458.60	343.95
10	BUMPER CLIPS @\$1.61 (DISC 25%)	NECESSARY	16.10	12.08
1	BUMPER LIP COVER RR/RH (DISC 25%)	DEFORMED	118.10	88.57
1	BUMPER REINFORCEMENT REAR (DISC 25%)	BENT	205.70	154.28
1	ARM SUB-ASSY, RR BUMPER RH (DISC 25%)	BENT	139.60	104.70
1	BUMPER SIDE RETAINER RR/RH (DISC 25%)	NECESSARY	94.80	71.10
1	TAIL LAMP RH (DISC 10%)	SCRATCHED	557.80	502.02
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	SMRT LOGO (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 6555 8888 (SN)	NECESSARY	21.60	21.60
1	BUMPER LIP REAR	NOT NECESSARY	228.90	-
1	ARM SUB-ASSY, RR BUMPER LH	NOT NECESSARY	139.60	-
1	SENSOR REVERSE	NOT NECESSARY	180.00	-
1	BUMPER SEAL, RR RH	NOT NECESSARY	65.70	-
1	BUMPER SIDE RETAINER RR/LH	NOT NECESSARY	94.80	-
1	UNDER COVER SUB-ASSY, RR FLOOR	NOT NECESSARY	514.50	-
1	TAIL GATE DOOR GLASS MOULDING, LH	NOT NECESSARY	29.40	-
1	TAIL GATE DOOR GLASS MOULDING, RH	NOT NECESSARY	29.40	-
1	MOULDING BACK WINDOW, LOWER NO.1	NOT NECESSARY	29.40	-
3	SEALANT W/SCREEN @\$37.00	NOT NECESSARY	111.00	-
1	NAME PLATE (HYBRID)	NOT NECESSARY	51.90	-
1	TAILGATE DOOR WEATHER STRIP	NOT NECESSARY	353.40	-
1	TAILGATE DOOR LOCK	NOT NECESSARY	444.10	-
1	END PANEL COVER, DECK TRIM HOLE	NOT NECESSARY	46.10	-
1	END PANEL COVER, DECK TRIM, RR	NOT NECESSARY	121.10	-
1	SEALANT SIKAFLEX	NOT NECESSARY	37.00	-
1	TAIL LAMP BRACKET, RH	NOT NECESSARY	30.70	-
1	TROUGH, BACK DOOR	NOT NECESSARY	110.90	-
1	FENDER RR/RH	NOT NECESSARY	766.80	-
1	DUCT ASSY QUARTER	NOT NECESSARY	70.40	-

Report Ref No. NS/INC18013592/Gqbe2

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	QUARTER GLASS RR/RH	NOT NECESSARY	846.50	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	EXHAUST HEAT SHIELD, REAR	NOT NECESSARY	107.40	-
1	EXHAUST TAIL PIPE	NOT NECESSARY	656.20	-
2	SUPPORT, EXHAUST REAR @\$33.60	NOT NECESSARY	67.20	-
1	TAILGATE ASY	TO REPAIR SEE LABOUR	1,007.90	-
1	END PANEL	TO REPAIR SEE LABOUR	602.10	-
			8,519.50	1,426.10
	<b>LABOUR</b>			
	PANEL BEATING & BODY WORK. INCLUSIVE OF THE REPAIR OF TAILGATE ASY AND END PANEL.		1,014.00	400.00
	SPRAY PAINT.		1,674.00	550.00
	TO CHECK WIRING AND SYSTEM FUNCTION.		80.00	30.00
	TTO APPLY RUST-PROOFING ON AFFECTED AREA.	NOT NECESSARY	100.00	-
	TO REMOVE / REFIT SEAT.	NOT NECESSARY	120.00	-
	TO REMOVE & REFIT EXHAUST.	NOT NECESSARY	120.00	-
	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM.	NOT NECESSARY	125.00	-
	TO REMOVE & REFIT REAR QUARTER GLASS RH.	NOT NECESSARY	120.00	-
	TO TRANSFER REAR TAILGATE MECHANISM.	NOT NECESSARY	120.00	-
	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER.	NOT NECESSARY	296.88	-
	TO REMOVE AND REFIX REAR WINDSCREEN.	NOT NECESSARY	240.00	-
	TO TEST AND REFIX REVERSE SENSOR SYSTEM.		120.00	40.00
	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	NOT NECESSARY	120.00	-
	TO REPLACE SUNDRY PARTS.	NOT NECESSARY	100.00	-
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			-	-
			-	-
			4,409.88	1,020.00
	<b>GRAND TOTAL</b>		<b>12,929.38</b>	<b>2,446.10</b>

Report Ref No. NS/INC18013592/Gqbe2

RECOMMENDED COST OF REPAIRS (CONFIRMED)			2,446.10
---	--	--	----------

Report Ref No. NS/INC18013592/Gqbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.