

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5095H**AAD1807-206***Not Authored
L1 Imp 8330d*

Vehicle No.:
Chassis No.:
Vehicle Make:
Vehicle Model:
Date of Accident :
Third Party Insurer :

SHC 5095H
VF1ABL15AUC276052
RENAULT
LATITUDE
21.7.2018
III

PART		LIST	
1	BUMPER COVER FRT	\$	<i>Ru</i> 1,259.42 ✓
1	BUMPER SPOILER FRT	\$	<i>Sn</i> 181.75 X
1	BUMPER ABSORBER FRT	\$	<i>Sn</i> 394.68 X
1	BUMPER RETAINER FRT RH	\$	<i>Diy</i> 150.77 ✓
1	BUMPER SUPPORT FRT	\$	<i>Sn</i> 123.88 X
1	BUMPER UNDERTRAY FRT	\$	<i>Sn</i> 472.83 X
1	BUMPER GRILLE LOWER FRT	\$	<i>Sn</i> 266.80 X
1	BUMPER FOG LAMP GRILLE RH	\$	<i>Sn</i> 207.21 X
1	BUMPER BEAM FRT	\$	<i>R</i> 914.08 X
1	HEADLAMP RH	\$	<i>mgmt</i> 1,184.43 ✓
1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15 X
1	FENDER PANEL FRT RH	\$	<i>Ru</i> 783.83 ✓
1	WHEELARCH FRT RH	\$	<i>Sn</i> 278.84
1	FENDER BRACKET LOWER RH	\$	<i>Sn</i> 15.79
1	FENDER INSULATOR RH	\$	<i>Sn</i> 130.84
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	RADIATOR GRILLE	\$	<i>Sn</i> 1,707.78
1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>ru</i> 225.36
1	RADIATOR GRILLE FRAME	\$	<i>Sn</i> 1,353.75
1	RADIATOR FAN COWLING	\$	<i>Sn</i> 820.54
1	RADIATOR FAN MOTOR LH	\$	<i>Sn</i> 967.36
1	RADIATOR FAN MOTOR RH	\$	<i>Sn</i> 1,479.46
1	FRAME FULL SUPPORT PANEL	\$	<i>Sn</i> 615.90
1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79
1	DOOR MIRROR ASSY RH	\$	<i>Sn</i> 1,483.40
1	DOOR PANEL FRT RH	\$	<i>R</i> 2,844.66
1	BONNET	\$	<i>R</i> 1,941.63
1	BONNET INSULATOR	\$	<i>Sn</i> 405.73
1	BONNET STRUT LH	\$	<i>Sn</i> 88.61
1	BONNET STRUT RH	\$	<i>Sn</i> 88.61

Trans-cab Auto Services Pte Ltd

AAD1807-206

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5095H

1	BONNET HINGE LH	\$	<i>R</i> 348.31	}
1	BONNET HINGE RH	\$	<i>R</i> 348.31	
1	BONNET LOCK	\$	<i>R</i> 305.48	
1	BONNET CABLE	\$	<i>S</i> 119.19	
1	BONNET CABLE COVER	\$	<i>S</i> 161.03	
1	BONNET SEAL OUTER	\$	<i>S</i> 92.36	
1	BONNET SEAL INNER	\$	<i>S</i> 157.28	
1	SUBFRAME OUTER FRT	\$	<i>S</i> 2,652.45	
1	SUBFRAME BRACKET OUTER LH	\$	<i>R</i> 92.36	
1	SUBFRAME BRACKET OUTER RH	\$	<i>R</i> 92.36	
1	ENGINE UNDERTRAY	\$	<i>S</i> 564.98	
1	A/C CONDENSER	\$	<i>S</i> 2,020.37	
1	A/C CONDENSER GARNISH LH UPPER	\$	<i>S</i> 39.67	
1	A/C CONDENSER GARNISH RH UPPER	\$	<i>S</i> 39.67	
1	A/C CONDENSER GARNISH LH	\$	<i>S</i> 58.81	
1	A/C CONDENSER GARNISH RH	\$	<i>S</i> 59.60	
1	LOWER ARM RH	\$	<i>S</i> 685.76	
1	KUNCKLE ARM RH	\$	<i>S</i> 846.98	
1	ABSORBER FRT RH	\$	<i>S</i> 360.54	
1	STABILIZER BAR FRT	\$	<i>S</i> 604.65	
1	DRIVESHAFT RH	\$	<i>R</i> 1,747.45	
1	WIPER RESERVOIR	\$	<i>S</i> 348.25	}
1	WIPER RESERVOIR NECK	\$	<i>S</i> 136.11	
1	WIPER RESERVOIR MOTOR	\$	<i>S</i> 270.06	

TOTAL	\$	35,626.53
10%	\$	3,562.65
	\$	32,063.87

Specical Nett

1SET	BUMPER CLIP FRT	\$	<i>R</i> 66.00 ✓
1	BUMPER BRACKET CLIP FRT RH	\$	<i>R</i> 12.00 X
1	BUMPER SUPPORT CLIP FRT RH	\$	<i>R</i> 10.50 X
1SET	BUMPER GRILLE LOWER CLIP	\$	<i>R</i> 69.00 X
1SET	FRAME FULL SUPPORT PANEL CLIP	\$	<i>R</i> 70.00 X
2	FRAME FULL SUPPORT PANEL NUT	\$	<i>R</i> 20.00 X
2	FRAME FULL SUPPORT PANEL STUD	\$	<i>R</i> 30.00 X

Trans-cab Auto Services Pte Ltd

AAD1807-206

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5095H

1SET	WHEELARCH CLIP FRT RH	\$	nn	30.50	} X
6	BONNET INSULATOR CLIP L70Y	\$	nn	7.30	
2	BONNET STRUT L70Y	\$	nn	88.61	
2	BONNET CABLE CLIP L70Y	\$	nn	6.31	
2	BONNET CABLE COVER SCREW L70Y	\$	nn	10.85	
1	WINDSCREEN SEALANT	\$	nn	253.80	
1	FRONT WINDSCREEN MOULDING	\$	nn	120.00	
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	nn	100.00	
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	nn	80.00	
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	nn	50.00	
1	FRONT RIGHT TYRE	\$	nn	330.00	} 1501m
1	FRONT RIGHT TYRE RIM	\$	nn	380.00	
1	FRONT RIGHT FENDER ADVERTISEMENT	\$	nn	300.00	
1	FRONT RIGHT DOOR ADVERTISEMENT	\$	nn	300.00	X

TOTAL	\$	2,334.88
--------------	-----------	-----------------

TOTAL PARTS	\$	34,398.75
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	4001
Putty and spray painting of the affected portion.	\$	4,000.00	4401
To rust-proofing of the affected areas.	\$	170.00	301
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	nn	380.00 X
To check steering geometry and computer wheel alignment	\$	nn	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	nn	170.00 X
To Check Electrical Lighting Concerned.	\$	170.00	201

Trans-cab Auto Services Pte Ltd**AAD1807-206**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5095H

To transfer of front fender fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To transfer of bonnet fittings, attachment and perform water seepage test.	\$	<i>na</i> 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	<i>na</i> 380.00 X
To replace, refix and top up coolant for radiator	\$	<i>na</i> 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>na</i> 170.00 X
To transfer of front windscreen fittings and conduct water seepage test	\$	<i>na</i> 170.00 X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	45,488.75
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS***2 1/2 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: