

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5575P**AAD1807-184***Not Authored
1/1/2018*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC 5575P

VF1ABL15AUC279337

RENAULT

LATITUDE

18.7.2018

III**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bal/cm</i> 1,108.46	✓
2	1 BUMPER LOWER REAR	\$	<i>Dis/cm</i> 768.84	✓
3	1 BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>CM</i> 135.97	✓
5	1 BUMEP R RETAINER RH REAR	\$	<i>cm</i> 44.99	✓
6	1 BUMPER REFLECTOR RH	\$	<i>Ru</i> 43.61	✓
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sn</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	X
10	1 BUMPER BEAM REAR	\$	<i>Ry</i> 777.52	✓
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	X
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	X
13	1 BOOT REAR	\$	<i>Ry</i> 2,872.68	✓
14	1 BOOT FINISHER	\$	<i>Sn</i> 470.06	X
15	1 BOOT WHEATERSTRIP	\$	<i>Dis 1mm</i> 323.05	<i>50% Sn</i>
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	X
17	1 BOOT REFLECTOR LAMP RH	\$	<i>CM</i> 493.35	✓
18	1 BOOT BADGE 'RENAULT'	\$	<i>Ru</i> 225.36	✓
19	1 BOOT BADGE	\$	<i>Ru</i> 225.36	✓
20	1 BOOT STRUT LH	\$	<i>Sn</i> 276.08	X
21	1 BOOT STRUT RH	\$	<i>Sn</i> 276.08	X
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	X
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	X
24	1 BOOT INNER TRIM	\$	<i>CM</i> 586.45	✓
25	1 BOOT SWITCH	\$	<i>Sn</i> 168.13	X
26	1 BOOT LOCK	\$	<i>R</i> 202.67	X
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	X
28	2 LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	✓
29	2 BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	X

Trans-cab Auto Services Pte Ltd**AAD1807-184**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5575P

30	1 FENDER PANEL REAR LH	\$	R	3,299.13	X
31	1 WHEELARCH REAR LH	\$	Sn	543.47	X
32	1 FENDER PANEL INNER TRIM REAR RH	\$	R	671.45	X
33	1 FENDER PANEL REAR RH	\$	Bu	3,299.13	✓
34	1 WHEELARCH REAR RH	\$	CM	543.47	—
35	1 TAILLAMP RH	\$	Bu	552.55	—
36	1 TAILLAMP PANEL RH	\$	R	986.70	—
37	1 OUTER PANEL REAR (End Panel)	\$	R	1,471.77	—
38	1 OUTER PANEL REAR (End Panel)TRIM	\$	CM	404.56	—
39	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	X
40	1 SPARE WHEEL PANEL TRIM	\$	Sn	612.21	X
41	1 EXHAUST REAR	\$	R	7,489.05	—
42	1 EXHAUST CAP REAR	\$	Net	230.49	—
43	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	X
44	1 KUCKLE ARM REAR RH L70Y	\$	Sn	736.67	X
45	1 BRAKE DISC REAR L70Y	\$	Sn	525.91	X
46	1 WHEEL HUB NUT L70Y	\$	Sn	51.11	X
47	1 WHEEL HUB CAP L70Y	\$	R	57.82	X
48	1 ABS SENSOR REAR RH L70Y	\$	Sn	255.75	X
49	1 REAR AXLE L70Y	\$	R	4,167.03	→
50	1 AXLE ARM RH L70Y	\$	Sn	117.22	X
51	1 LOWER ARM REAR RH L70Y	\$	Sn	905.99	X
52	1 ABSORBER REAR	\$	Sn	389.75	X
53	1 STABILIZER BAR REAR RH	\$	Sn	604.65	X
54	1 BRAKE CALIPER REAR RH	\$	Sn	1,300.67	X
55	1 WHEEL HOUSING PANEL REAR RH	\$	R	4,682.09	X
56	1 CHASSIS PANEL REAR RH	\$	R	3,766.43	X
TOTAL		\$		54,985.76	
10%		\$		5,498.58	
		\$		49,487.19	

Special Nett

1	1SET PARKING AID	\$	Shan	700.00	600.00
2	1SET REAR BUMPER CLIP	\$	na	66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	na	33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	na	10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	na	20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	na	10.00	X

Trans-cab Auto Services Pte Ltd**AAD1807-184**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5575P

7 1SET BUMPR RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1 EXHAUST MOUNTING REAR	\$	na	17.82	X
11 1SET BOOT FINISHER CLIP	\$	na	24.20	X
12 1 BOOT STICKER "Trans-cab"	\$	na	30.00	✓
13 1 BOOT STICKER "6555-3333"	\$	na	30.00	✓
14 1 BOOT INNER TRIM CLIP	\$	na	45.00	X
15 1SET FENDER WHEELARCH REAR RH CLIP	\$	na	35.00	X
16 1SET FENDER WHEELARCH REAR LH CLIP	\$	na	35.00	X
17 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
18 1 FENDER INNER TRIM CLIP LH	\$	na	28.00	X
19 1 TAILLAMP CLIP RH	\$	na	5.00	✓
20 1 TAILLAMP CLIP LH	\$	na	5.00	X
21 2 REAR WINDSCREEN SELANT	\$	na	80.00	40sm
22 1 WINDSCREEN MOULDING	\$	na	100.00	✓
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	na	100.00	30sm
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	na	385.00	X
25 1 SPARE TYRE	\$	na	330.00	X
26 1 RIGHT REAR TYRE	\$	na	330.00	80sm
27 1 RIGHT REAR TYRE RIM	\$	na	380.00	✓

TOTAL \$ 2,935.02**TOTAL PARTS \$ 52,422.21¹⁹****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	1100l
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	1400l
To Rust-Proofing Of The Affected Areas.	\$	170.00	80l
To reinstall rear bumper parking sensor.	\$	170.00	60l

Trans-cab Auto Services Pte Ltd

AAD1807-184

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5575P

To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	601
To repair and realign rear exhaust pipe.	\$	170.00	} 801
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	} 1001
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	170.00	
To supply and re-do rear luggage floor panel insulation padding.	\$	na 380.00	X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	170.00	1201
To check steering geometry and computer wheel alignment	\$	220.00	601
To transfer of rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X

TOTAL \$ 12,540.00

Over All Total \$ 64,962.21

(LUMP SUM)

Repair Days

20 DAYS

17 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

7/20/2018

PARF/COE Rebate Enquiry

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHC5575P
Vehicle to be Exported:	Yes
Intended De-registration Date:	20 Jul 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2014
Engine No.:	M9R8839C001982
Chassis No.:	VF1ABL15AUC279337
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	15 Sep 2014
First Registration Date:	15 Sep 2014
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	14 Sep 2022
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	14 Sep 2022
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$50,704.00
COE Rebate Amount:	\$26,314.00
Total Rebate Amount:	\$35,687.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 20 Jul 2018

OK