

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLS 5743P
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG

Claim Type: Third Party

Accident Date: 17/07/2018

TP Veh Reg No: SLH8653D

Estimate No: ES1891008/YISHUN

Date: 03 Sep 2018

Policy No: 1700054680

Veh Reg No: SLS5743P

Make/Model: MITSUBISHI ATTRAGE
1.2 CVT

Chassis No: MMBSTA13AJH000385

Engine No: 3A92UGJ2263

Reg. Date: 28/09/2017

Estimate Repair Cost to Vehicle No :SLS5743P

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Net Price				
1 FRONT BUMPER	666.00	1 PC	666.00	
2 FRONT BUMPER REINFORCEMENT	135.00	1 PC	135.00	
3 FRONT BUMPER CLIPS	3.50	6 PCS	21.00	
4 FRONT GRILLE	525.00	1 PC	525.00	
5 FRONT GRILLE CLIPS	3.50	4 PCS	14.00	
6 HEADLAMP LH	544.00	1 PC	544.00	
			1,905.00	
		Less 10%	190.50	1,714.50
Labour				
7 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,KNOCK & REPAIR FRT SUPPORT PANEL,FRT LH FENDER & REALIGN THE SAME	500.00	1 LA	500.00	
8 PUTTY & RESPRAY ON FRT BUMPER,FRT LH REINFORCEMENT,FRT LH FENDER	600.00	1 LA	600.00	
			1,100.00	1,100.00
			Total	S\$ 2,814.50
			Add GST @ 7%	197.02
			Total Amount Payable	S\$ 3,011.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE