

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

EL351P
TP/MG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

Estimate No: ES1891012/YISHUN
Date: 04 Sep 2018
Policy No: 5075829029-02
Veh Reg No: EL351P
Make/Model: TOYOTA COROLLA
AXIO 1.5G CVT
Chassis No: NRE1610005245
Engine No: 2NR8480837
Reg. Date: 24/11/2015

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 22/07/2018
TP Veh Reg No: EZ1998T

Not Authorized
Repairing By painting

3-5 days

Estimate Repair Cost to Vehicle No :EL351P

PAGE:1/1

Description	U/Price	Quantity	List Price S\$	Amount S\$
List Price				
1 REAR BUMPER	590.20	1 PC	<i>Am</i> 590.20	—
2 REAR BUMPER LH SIDE RETAINER	98.10	1 PC	<i>DPH</i> 98.10	—
3 REAR BUMPER CLIPS	3.50	6 PCS	<i>m</i> 21.00	—
4 REAR BUMPER LH REFLECTOR	92.80	1 PC	<i>m</i> 92.80	?
5 TAILLAMP LH	548.40	1 PC	<i>m</i> 548.40	?
6 REAR BOOT LOGO	42.10	1 PC	<i>m</i> 42.10	—
7 REAR BOOT EMBLEM (AXIO)	44.17	1 PC	<i>m</i> 44.17	—
8 REAR BOOT EMBLEM (COROLLA)	59.10	1 PC	<i>m</i> 59.10	—
9 REAR BOOT EMBLEM (G)	47.50	1 PC	<i>m</i> 47.50	—
10 REAR BOOT INNER LOCK	451.80	1 PC	<i>m</i> 451.80	?
11 REAR BOOT INNER RUBBER	198.50	1 PC	<i>m</i> 198.50	?
12 REAR PANEL	580.70	1 PC	<i>m</i> 580.70	?
13 REAR PANEL INNER GARNISH	278.10	1 PC	<i>m</i> 278.10	?
			3,052.47	
		Less 25%	763.12	2,289.35
Special Net				
14 REVERSE SENSOR	<i>Shat</i> 200.00	1 SET	200.00	200.00
Labour				
15 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, KNOCK & REPAIR REAR BOOT, CUT, WELD & RENEW REAR PANEL & REALIGN THE	700.00	1 LA	700.00	?
16 PUTTY & RESPRAY ON REAR BOOT, REAR PANEL, REAR BUMPER, REAR LH FENDER (PEARL WHITE)	800.00	1 LA	800.00	<i>660</i>
17 RUSTPROOFING	30.00	1 LA	30.00	?
			1,530.00	1,530.00

Total S\$ 4,019.35

Add GST @ 7% 281.35

Total Amount Payable S\$ 4,300.70

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s), must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE