

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S0270629F
FOO CHENG THENG
NO 10 TOH AVENUE

SINGAPORE 508036
TEL : FAX :
PH : 96812846
ATTN :

ESTIMATE BILL

Number : EB00004909
Date : 25/07/2018
Case No : AD00009870
Vehicle No : SJG7490S
Chassis : JTDER12W503000450
Year of Mfr : 2008
Policy No :
Model : TOYOTA WISH 1.8 A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	FRONT BUMPER	1.0	557.60	25	418.20
2	FRONT BUMPER RETAINER LH	1.0	75.48	25	56.61
3	FRONT FENDER SHIELD LH	1.0	188.40	25	141.30
List Price - Parts Sub Total					616.11
4	FRONT BUMPER SPOILER	1.0	680.00	0	680.00
5	FRONT FENDER LH - REPAIR	1.0			
Special Nett Price - Parts Sub Total					680.00
Parts Total					1,296.11
6	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	600.00	0	600.00
7	SPRAY PAINT ON THE AFFECTED AREAS	1.0	500.00	0	500.00
8	ANTI-RUST COATING	1.0	150.00	0	150.00
Labour 1 Sub Total					1,250.00
SINGAPORE DOLLARS : TWO THOUSAND SEVEN HUNDRED TWENTY-FOUR AND CENTS THIRTY FOUR ONLY					
Less Excess					0.00
SUBTOTAL					2,546.11
GST 7.00%					178.23
TOTAL					2,724.34

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

Date of accident : 24/07/2018 12:35 PM. Place : BLK415 TAMPINES STREET 44 MSCP

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE