

Allswell Motor Traders

25 Defu Lane 9, Singapore 539266
Tel : +65 6679 1146 email: ben@allswellmotor.com.sg

- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate repaired by Repairer

Vehicle No.: SLT8749Z
Make & Model: Honda Vezel
Chassis No.: Hyundai

Date of survey :

Submitted by : Bun
COE expiry : 14-11-2027
Engine No. :

3 Days.
Guarantee
25/7/18

AG Insured SLT6563Z
part by part
before paint photos.

S/No	Part Description	Qty	Unit Price	Price	Disposition by
01	Rear bumper / CR2	01	\$1,119.0	936.6	
02	RH Rear Fender arc	01	\$220.90		
03	Rear tailgate X repair	01	\$1,315.1	X	* repair
04	Rear RH fender panel X repair	01	\$245.3	/	
				1402.8	
				20%: 1122.24	
	Special Mett				
01	Clips for bumper @ \$4.50 x 02	01	\$9.00	/	
	Labour description				
01.	Dismantle/Assembly of damaged parts	01	\$260	50	
02.	Panel beating of end panel	01	\$360.0	150	200
03.	Make good of tailgate & RH rear top panel	01	\$460.0	X	NN
04.	Spray painting of all affected parts including anti-rust, polish & wash	01	\$1,100.0	500	1801.24

Note: If any of the quoted parts are recommended to be repaired, then an additional labour cost will be charged accordingly under supplementary.