

## REPAIR ESTIMATE\*

DATE 24/7/2018 10:08

**MODEL : HYUNDAI i40**

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper <i>cut</i> ?			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) <i>X</i> <i>mc</i>		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket <i>X</i>			\$ 49.00
	Rear Bumper Clips <i>1/2 mc</i>			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover <i>cut</i>			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>
	<b>LESS 20%</b>			<b>\$ 381.47</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70
	Rear Bumper Rubber Mat <i>/</i>			\$ 50.00
	Rear Bumper Advertisement Logo <i>/</i>			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) <i>✓</i> <i>mc</i>		\$ 100.00	\$ 200.00
				<b>\$ 435.70</b>
	<b>Labour Charge</b>			
	Panel Beating			\$ 350.00
	Spray Painting Charge			\$ 250.00
	Wiring Charge			\$ 50.00
	R/Refix Reverse Sensor			\$ 120.00
	<b>TOTAL LABOUR</b>			<b>\$ 770.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,731.58</b>
	<i>2 days</i> <i>lump sum repair</i> <i>After repair photos.</i> <i>Guo Qial - 8-880282</i> <i>24/7/18 4pm</i>			

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer  
Signature: \_\_\_\_\_  
Date: \_\_\_\_\_

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.