

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 713A****AAD1807-216***Not Authorised  
L1 Smg 8/6001**257711P*

|                       |                   |
|-----------------------|-------------------|
| Vehicle No.:          | <b>SHF 713A</b>   |
| Chassis No.:          | VF1ABL15AUC281215 |
| Vehicle Make:         | RENAULT           |
| Vehicle Model:        | LATITUDE          |
| Date of Accident :    | 21.7.2018         |
| Third Party Insurer : | <b>AIG</b>        |

| PART |                                 | LIST |                         |
|------|---------------------------------|------|-------------------------|
| 1    | BUMPER COVER FRT                | \$   | <i>Bu/na</i> 1,259.42 ✓ |
| 1    | BUMPER SPOILER FRT              | \$   | <i>Sm</i> 181.75 X      |
| 1    | BUMPER ABSORBER FRT             | \$   | <i>Sm</i> 394.68 X      |
| 1    | BUMPER RETAINER FRT RH          | \$   | <i>Sm</i> 150.77 X      |
| 1    | BUMPER SUPPORT FRT              | \$   | <i>Sm</i> 123.88 X      |
| 1    | BUMPER UNDERTRAY FRT            | \$   | <i>Sm</i> 472.83 X      |
| 1    | BUMPER GRILLE LOWER FRT         | \$   | <i>Sm</i> 266.80 X      |
| 1    | BUMPER FOG LAMP GRILLE RH       | \$   | <i>na</i> 207.21 ✓      |
| 1    | BUMPER BEAM FRT                 | \$   | <i>na</i> 914.08        |
| 1    | HEADLAMP RH                     | \$   | <i>Sm</i> 1,184.43      |
| 1    | HEADLAMP PANEL FRT RH           | \$   | <i>na</i> 152.15        |
| 1    | FENDER PANEL FRT RH             | \$   | <i>na</i> 783.83        |
| 1    | WHEELARCH FRT RH                | \$   | <i>Sm</i> 278.84        |
| 1    | FENDER BRACKET LOWER RH         | \$   | <i>Sm</i> 15.79         |
| 1    | FENDER INSULATOR RH             | \$   | <i>Sm</i> 130.84        |
| 1    | DOOR PANEL FRT RH               | \$   | <i>na</i> 2,844.66      |
| 1    | RADIATOR GRILLE                 | \$   | <i>Sm</i> 1,707.78      |
| 1    | RADIATOR GRILLE BADGE 'RENAULT' | \$   | <i>na</i> 225.36        |
| 1    | RADIATOR GRILLE FRAME           | \$   | <i>Sm</i> 1,353.75      |
| 1    | RADIATOR FAN COWLING            | \$   | <i>Sm</i> 820.54        |
| 1    | RADIATOR FAN MOTOR LH           | \$   | <i>Sm</i> 967.36        |
| 1    | RADIATOR FAN MOTOR RH           | \$   | <i>Sm</i> 1,479.46      |
| 1    | FRAME FULL SUPPORT PANEL        | \$   | <i>na</i> 615.90        |
| 1    | FRAME FULL SUPPORT BRACKET      | \$   | <i>na</i> 89.79         |
| 1    | DOOR MIRROR ASSY RH             | \$   | <i>Sm</i> 1,483.40      |
| 1    | DOOR PANEL FRT RH               | \$   | <i>na</i> 2,844.66      |
| 1    | BONNET                          | \$   | <i>na</i> 1,941.63      |
| 1    | BONNET INSULATOR                | \$   | <i>Sm</i> 405.73        |
| 1    | BONNET STRUT LH                 | \$   | <i>Sm</i> 88.61         |
| 1    | BONNET STRUT RH                 | \$   | <i>Sm</i> 88.61         |

**Trans-cab Auto Services Pte Ltd****AAD1807-216**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 713A**

|   |                                |    |          |   |   |
|---|--------------------------------|----|----------|---|---|
| 1 | BONNET HINGE LH                | \$ | 348.31   | } | X |
| 1 | BONNET HINGE RH                | \$ | 348.31   |   |   |
| 1 | BONNET LOCK                    | \$ | 305.48   |   |   |
| 1 | BONNET CABLE                   | \$ | 119.19   |   |   |
| 1 | BONNET CABLE COVER             | \$ | 161.03   |   |   |
| 1 | BONNET SEAL OUTER              | \$ | 92.36    |   |   |
| 1 | BONNET SEAL INNER              | \$ | 157.28   |   |   |
| 1 | SUBFRAME OUTER FRT             | \$ | 2,652.45 |   |   |
| 1 | SUBFRAME BRACKET OUTER LH      | \$ | 92.36    |   |   |
| 1 | SUBFRAME BRACKET OUTER RH      | \$ | 92.36    |   |   |
| 1 | ENGINE UNDERTRAY               | \$ | 564.98   |   |   |
| 1 | A/C CONDENSER                  | \$ | 2,020.37 |   |   |
| 1 | A/C CONDENSER GARNISH LH UPPER | \$ | 39.67    |   |   |
| 1 | A/C CONDENSER GARNISH RH UPPER | \$ | 39.67    |   |   |
| 1 | A/C CONDENSER GARNISH LH       | \$ | 58.81    |   |   |
| 1 | A/C CONDENSER GARNISH RH       | \$ | 59.60    |   |   |
| 1 | LOWER ARM RH                   | \$ | 685.76   |   |   |
| 1 | KUNCKLE ARM RH                 | \$ | 846.98   |   |   |
| 1 | ABSORBER FRT RH                | \$ | 360.54   |   |   |
| 1 | STABILIZER BAR FRT             | \$ | 604.65   |   |   |
| 1 | DRIVESHAFT RH                  | \$ | 1,747.45 |   |   |
| 1 | WIPER RESERVOIR                | \$ | 348.25   |   |   |
| 1 | WIPER RESERVOIR NECK           | \$ | 136.11   |   |   |
| 1 | WIPER RESERVOIR MOTOR          | \$ | 270.06   |   |   |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>35,626.53</b> |
| <b>10%</b>   | <b>\$</b> | <b>3,562.65</b>  |
|              | <b>\$</b> | <b>32,063.87</b> |

**Specical Nett**

|      |                               |    |       |   |
|------|-------------------------------|----|-------|---|
| 1SET | BUMPER CLIP FRT               | \$ | 66.00 | ✓ |
| 1    | BUMPER BRACKET CLIP FRT RH    | \$ | 12.00 | X |
| 1    | BUMPER SUPPORT CLIP FRT RH    | \$ | 10.50 | X |
| 1SET | BUMPER GRILLE LOWER CLIP      | \$ | 69.00 | X |
| 1SET | FRAME FULL SUPPORT PANEL CLIP | \$ | 70.00 | X |
| 2    | FRAME FULL SUPPORT PANEL NUT  | \$ | 20.00 | X |
| 2    | FRAME FULL SUPPORT PANEL STUD | \$ | 30.00 | X |

**Trans-cab Auto Services Pte Ltd**

AAD1807-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 713A**

|       |                                      |    |    |          |   |   |
|-------|--------------------------------------|----|----|----------|---|---|
| 1SET  | WHEELARCH CLIP FRT RH                | \$ | na | 30.50    | } | X |
| 6     | BONNET INSULATOR CLIP L70Y           | \$ | na | 7.30     |   |   |
| 2     | BONNET STRUT L70Y                    | \$ | Sh | 88.61    |   |   |
| 2     | BONNET CABLE CLIP L70Y               | \$ | na | 6.31     |   |   |
| 2     | BONNET CABLE COVER SCREW L70Y        | \$ | Sh | 10.85    |   |   |
| 1     | WINDSCREEN SEALANT                   | \$ | na | 253.80   |   |   |
| 1     | FRONT WINDSCREEN MOULDING            | \$ | na | 120.00   |   |   |
| 1     | FRONT WINDSCREEN INNER SPONGE SEAL   | \$ | na | 100.00   |   |   |
| 1     | FRONT RIGHT DOOR STICKER 'TRANS-CAB' | \$ | na | 80.00    |   |   |
| 1     | FRONT RIGHT DOOR STICKER '6555-3333' | \$ | na | 50.00    |   |   |
| 1     | FRONT RIGHT TYRE                     | \$ | Sh | 330.00   | } |   |
| 1     | FRONT RIGHT TYRE RIM                 | \$ | Sh | 380.00   |   |   |
| TOTAL |                                      | \$ |    | 1,734.88 |   |   |

|                    |           |                  |
|--------------------|-----------|------------------|
| <b>TOTAL PARTS</b> | <b>\$</b> | <b>33,798.75</b> |
|--------------------|-----------|------------------|

**LABOUR**

|                                                                                                                           |    |          |          |
|---------------------------------------------------------------------------------------------------------------------------|----|----------|----------|
| Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same | \$ | 4,500.00 | 20d      |
| Putty and spray painting of the affected portion.                                                                         | \$ | 4,000.00 | 44d      |
| To rust-proofing of the affected areas.                                                                                   | \$ | na       | 170.00 X |
| To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.                           | \$ | na       | 380.00 X |
| To check steering geometry and computer wheel alignment                                                                   | \$ | na       | 220.00 X |
| To transfer of tire, rim and on wheel balancing.                                                                          | \$ | na       | 170.00 X |
| To Check Electrical Lighting Concerned.                                                                                   | \$ | na       | 170.00 X |
| To transfer of front fender fittings, attachment and perform water seepage test.                                          | \$ | na       | 380.00 X |

**Trans-cab Auto Services Pte Ltd****AAD1807-216**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHF 713A**

|                                                                            |    |             |
|----------------------------------------------------------------------------|----|-------------|
| To transfer of bonnet fittings, attachment and perform water seepage test. | \$ | nn 380.00 X |
| To vacuum, replace, refix and recharge air condenser                       | \$ | h 380.00 X  |
| To replace, refix and top up coolant for radiator                          | \$ | h 170.00 X  |
| To vacuum, replace, refix and recharge Air Intercooler                     | \$ | h 170.00 X  |
| To transfer of front windscreen fittings and conduct water seepage test    | \$ | h 170.00 X  |

|              |           |                  |
|--------------|-----------|------------------|
| <b>TOTAL</b> | <b>\$</b> | <b>11,090.00</b> |
|--------------|-----------|------------------|

|                       |           |                  |
|-----------------------|-----------|------------------|
| <b>Over All Total</b> | <b>\$</b> | <b>44,888.75</b> |
|-----------------------|-----------|------------------|

**LUMP SUM (REPAIR DAY)****15 DAYS***2 day*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: