

Trans-cab Auto Services Pte Ltd

AAD1807-216

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 713A

1SET	WHEELARCH CLIP FRT RH	\$	na	30.50	}	X
6	BONNET INSULATOR CLIP L70Y	\$	na	7.30		
2	BONNET STRUT L70Y	\$	Sh	88.61		
2	BONNET CABLE CLIP L70Y	\$	na	6.31		
2	BONNET CABLE COVER SCREW L70Y	\$	Sh	10.85		
1	WINDSCREEN SEALANT	\$	na	253.80		
1	FRONT WINDSCREEN MOULDING	\$	na	120.00		
1	FRONT WINDSCREEN INNER SPONGE SEAL	\$	na	100.00		
1	FRONT RIGHT DOOR STICKER 'TRANS-CAB'	\$	na	80.00		
1	FRONT RIGHT DOOR STICKER '6555-3333'	\$	na	50.00		
1	FRONT RIGHT TYRE	\$	Sh	330.00	}	
1	FRONT RIGHT TYRE RIM	\$	Sh	380.00		
TOTAL		\$		1,734.88		

TOTAL PARTS	\$	33,798.75
--------------------	-----------	------------------

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	4,500.00	200d
Putty and spray painting of the affected portion.	\$	4,000.00	640d
To rust-proofing of the affected areas.	\$	na	170.00 X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	na	380.00 X
To check steering geometry and computer wheel alignment	\$	na	220.00 X
To transfer of tire, rim and on wheel balancing.	\$	na	170.00 X
To Check Electrical Lighting Concerned.	\$	na	170.00 X
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na	380.00 X

Trans-cab Auto Services Pte Ltd**AAD1807-216**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF 713A

To transfer of bonnet fittings, attachment and perform water seepage test.	\$	na 380.00 X
To vacuum, replace, refix and recharge air condenser	\$	4 380.00 X
To replace, refix and top up coolant for radiator	\$	4 170.00 X
To vacuum, replace, refix and recharge Air Intercooler	\$	4 170.00 X
To transfer of front windscreen fittings and conduct water seepage test	\$	4 170.00 X

TOTAL	\$	11,090.00
--------------	-----------	------------------

Over All Total	\$	44,888.75
-----------------------	-----------	------------------

LUMP SUM (REPAIR DAY)**15 DAYS**

45,058.78#

2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: