

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7920T**AAD1807-147**

Not Authorised
61 Sy @ 2950/

Vehicle No.:
 Chassis No.:
 Vehicle Make:
 Vehicle Model:
 Date of Accident :
 Third Party Insurer :

SHB 7920T
 KL1LA69RJBB109972
 CHEVROLET
 EPICA 2.0
 21.7.2018
AIG

PART			LIST		
1	1	Rear Bumper	\$	<i>B</i> 1,202.00	—
2	1	Rear Bumper Beam	\$	<i>B</i> 239.94	—
3	1	Rear Bumper Centre Absorber	\$	<i>cnt</i> 260.00	—
4	1	Rear Bumper Side Retainer RH	\$	<i>D, r</i> 68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Ln</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>Bro</i> 119.74	—
7	1	Rear Bumper Reflectors LH	\$	<i>Ln</i> 119.74	X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Ln</i> 93.00	X
9	1	Rear End Panel Outer	\$	<i>B</i> <i>Boat</i> 623.76	✓
10	1	Rear End Panel Inner Trim	\$	<i>Ln</i> 263.84	} X
11	1	Rear Luggage Floor Panel	\$	<i>n</i> 973.00	
12	1	Rear Luggage Floor Panel Insulator	\$	<i>Ln</i> 63.50	
13	1	Rear Luggage Floor Panel Trim Board	\$	<i>Ln</i> 378.00	
14	1	Bootlid	\$	<i>n</i> 973.00	
15	1	Bootlid inner trim board	\$	<i>Ln</i> 400.00	
16	1	Bootlid Weatherstrip	\$	<i>Ln</i> 344.28	
17	1	Bootlid Lock - Top	\$	<i>n</i> 466.56	
18	1	Bootlid 'CHEVROLET' Badge	\$	<i>nn</i> 120.62	
19	1	Bootlid Logo	\$	<i>nn</i> 138.84	
20	1	Bootlid 'EPICA LT' Badge	\$	<i>nn</i> 119.84	
21	1	Bootlid Reflector Centre	\$	<i>Ln</i> 217.97	}
22	1	Bootlid Reflector RH	\$	<i>Ln</i> 128.40	
23	1	Bootlid Reflector LH	\$	<i>Ln</i> 128.40	
24	1	Rear Tail Lamp RH	\$	<i>Ln</i> 479.30	
25	1	Rear Tail Lamp LH	\$	<i>Ln</i> 479.30	
26	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>n</i> 1,110.00	
27	1	Rear Fender RH	\$	<i>n</i> 1,145.00	
28	1	Rear Fender Inner Trim RH	\$	<i>Ln</i> 418.44	
29	1	Rear Fender LH	\$	<i>n</i> 1,145.00	

Trans-cab Auto Services Pte Ltd**AAD1807-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7920T

30	1	Rear Fender Inner Trim LH	\$	<i>Sn</i> 418.44 <i>X</i>
----	---	---------------------------	----	---------------------------

TOTAL	\$	12,707.43
10%	\$	1,270.74
	\$	11,436.69

Special Nett

1	1Set	Bootlid inner trim board Clip	\$	<i>na</i> 40.00 <i>X</i>
2	1Set	Rear Bumper Parking Sensor	\$	<i>Not</i> 300.00 <i>✓</i>
3	1Set	Rear Bumper Fastener Clip	\$	<i>na</i> 44.00 <i>✓</i>
4	1Set	Rear Fender Inner Trim Clip LH	\$	<i>na</i> 30.00 <i>X</i>
5	1Set	Rear Bumper End Dust Cover Clip	\$	<i>na</i> 30.00 <i>X</i>
6	1	Rear Exhaust Mounting	\$	<i>Sn</i> 300.00 <i>X</i>
7	2	Rear Windscreen Sealant	\$	<i>Sn</i> 80.00 <i>X</i>
8	1	Rear Windscreen Inner Sponge Seal	\$	<i>na</i> 100.00 <i>X</i>
9	1	Spare Tyre	\$	<i>Sn</i> 180.00 <i>X</i>
10	1	Spare Wheel Rim	\$	<i>Sn</i> 126.74 <i>X</i>

TOTAL	\$	1,230.74
--------------	-----------	-----------------

TOTAL PARTS	\$	12,667.43
--------------------	-----------	------------------

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$	3,500.00	<i>600</i>
----	----------	------------

To Check Electrical Lighting Concerned.

\$	170.00	<i>150</i>
----	--------	------------

To Rust-Proofing Of The Affected Areas.

\$	170.00	<i>300</i>
----	--------	------------

Putty And Spray Painting Of The Affected
Portion.

\$	3,200.00	<i>800</i>
----	----------	------------

To reinstall rear bumper parking sensor.

\$	170.00	<i>600</i>
----	--------	------------

Trans-cab Auto Services Pte Ltd**AAD1807-147**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB 7920T

To transfer of end panel fittings and conduct water seepage test.	\$	170.00	601
To transfer of boot fittings and conduct water seepage test.	\$	170.00	X
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	X
To check steering geometry and computer wheel alignment	\$	220.00	X
	\$	8,150.00	
TOTAL	\$	20,817.43	

Repair Days (LUMP SUM)~~10 Days~~

4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: