

SMRT Accident Vehicle Repair Estimates

G/17

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4747S
 Ref. No : TAX/07/18/2112
 Reg. Date : 19/02/2016
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS
 Name of Driver : MOHAMED AMANULLAH BIN PEER MOHAMED
 Type of Accident : SIDE SWIPE
 Date / Time of Accident : 23/07/2018 02:55:00 PM
 Accident Reported Date / Time : 24/07/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024097197
 Special Instruction to ARC, if any :
 SFB555J - AIG - LKK
 Prepared Date : 24/07/2018 02:25:31 PM



Tauhin 97495749
- WP

25/7/18 @ 4:10 pm

sur@lkkauto.com.

6 days

Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Chassis No : JTDKN36UX05767444

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,183.00	0.00
Total Spray Painting Charges :	2,052.00	0.00
Total Material Charges :	9,213.42	9,213.42
Other Charges :	1,305.00	0.00
TOTAL :	13,753.42	0.00
Lum Sum Total :	0.00	0.00
No. of Repair Days :	7.00	0.00
Prepared / Adjusted By :		
Arc / Surveyor Sign Off Date :	24/07/2018 06:46:58 PM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 24/07/2018 06:40:17 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	Invoice No :
Quotation Date :	Invoice Date :
Invoice Amount : 0.00	Prepared Date : 7/24/2018 6:47:34 PM

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	1,183.00	0.00
Total Labour	1,183.00	0.00 800

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY FRONT DOOR RH	378.00	0.00 200
TO RESPRAY ROCKER PANEL MOULDING	180.00	0.00 100
TO RESPRAY CENTRE PILLAR RH	180.00	0.00 X
TO RESPRAY REAR DOOR RH	378.00	0.00 200
TO RESPRAY REAR FENDER RH	378.00	0.00 200
TO RESPRAY RIM	180.00	0.00 100
TO REPSRAY REAR BUMPER	378.00	0.00 200
Total Spray Painting & Panel Beating	2,052.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 40
TO DO WHEEL ALIGNMENT / TYRE BALANCING	120.00	0.00 80
TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	120.00	0.00 30
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO TRANSFER DOOR MECHANISM	240.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
TO REMOVE & REFIT REAR QUARTER GLASS RH	120.00	0.00 X
TO REPLACE SUNDRY PARTS	100.00	0.00 30
TO WASH AND VACUUM	60.00	0.00 X
TO REMOVE / REFIT SEAT	120.00	0.00 X
Total Other Costs	1,305.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67001-47070		6505528	DOOR FRT/RH	1	894.40	25.00	670.80	Replace	Replace <i>Ry</i>	No
			STICKER DECAL SMRT (DOOR)	1	60.00	0.00	60.00	Replace	Replace <i>ry</i>	No
68730-12120			HINGE LOWER RHF, DOOR	1	90.10	25.00	67.57	Replace	Replace <i>ry</i>	No
68710-12151			HINGE UPPER RHF, DOOR	1	80.50	25.00	60.37	Replace	Replace <i>Ry</i>	No
68610-47021			CHECK ASSY, FR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>Ry</i>	No
69030-47070			DOOR LOCK FRT/RH	1	575.80	25.00	431.85	Replace	Replace <i>X</i>	No
69410-33010			DOOR LOCK STRIKER	1	40.50	25.00	30.37	Replace	Replace <i>X</i>	No
69210-74030			DOOR OUTER HANDLE FRT/RH	1	370.80	25.00	278.10	Replace	Replace <i>Ry</i>	No
75710-47021			DOOR BELT FRT/RH	1	69.20	25.00	51.90	Replace	Replace <i>?</i>	No
85710-47120F			DOOR REGULATOR MOTOR FRONT RH	1	947.80	10.00	853.02	Replace	Replace <i>X</i>	No
69801-52070			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	25.00	168.60	Replace	Replace <i>X</i>	No
75851-47900			MOULDING BODY, RH	1	673.60	25.00	505.20	Replace	Replace <i>X</i>	No
35631-47041			SILL MEMBER PLATE RR/RH	1	57.50	25.00	43.12	Replace	Replace <i>X</i>	No
31311-47030			PILLAR, CTR BODY	1	307.70	25.00	230.77	Replace	Replace <i>X</i>	No
37003-47080		6505486	DOOR RR/RH	1	954.50	25.00	715.87	Replace	Replace <i>bl</i>	No
38750-20121			HINGE UPPER RHR, DOOR	1	81.70	25.00	61.27	Replace	Replace <i>Ry</i>	No
38770-2031			HINGE LOWER RHR, DOOR	1	52.00	25.00	39.00	Replace	Replace <i>Ry</i>	No
38630-47031			CHECK ASSY, RR DOOR,	1	150.30	25.00	112.72	Replace	Replace <i>Ry</i>	No
35730-47021			DOOR BELT RR/RH	1	69.20	25.00	51.90	Replace	Replace <i>X</i>	No
39050-47080			DOOR LOCK RR/RH	1	709.30	25.00	531.97	Replace	Replace <i>X</i>	No
39410-3010			DOOR LOCK STRIKER	1	40.50	25.00	30.37	Replace	Replace <i>X</i>	No
5710-7120			DOOR REGULATOR MOTOR REAR RH	1	947.80	10.00	853.02	Replace	Replace <i>?</i>	No
9801-2070			DOOR REGULATOR SUB-ASSY, FRT/REAR RH	1	224.80	25.00	168.60	Replace	Replace <i>?</i>	No
1604-7090			FENDER RR/RH	1	766.80	25.00	575.10	Replace	Replace <i>Ry</i>	No
	COMMO N		SMRT LOGO	1	7.80	0.00	7.80	Replace	Replace <i>ry</i>	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace <i>ry</i>	No
2710-7130			QUARTER GLASS RR/RH	1	846.50	25.00	634.87	Replace	Replace <i>X</i>	No
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace <i>X</i>	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
65637-47021		6505480	FENDER LINER RR/RH	1	141.30	25.00	105.97	Replace	Replace <i>X</i>	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace <i>de</i>	No
52591-47021			BUMPER SEAL, RR RH	1	65.70	25.00	49.27	Replace	Replace <i>no</i>	No
52575-47020		6505549	BUMPER SIDE RETAINER RR/RH	1	94.80	25.00	71.10	Replace	Replace <i>de</i>	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace <i>de</i>	No
42611-47140		6505658	WHEEL, DISC	1	1,490.20	25.00	1,117.65	Replace	Replace <i>Ry</i>	No
TOTAL MATERIALS								9,213.49	9,213.42	
TOTAL MATERIALS(Discounted)								9,213.42	9,213.42	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									