

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ECICS Limited
7 Temasek Boulevard
#10-01 Suntec Tower One
Singapore 038987

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 27 Jul 2018

Preliminary Advice

Insured Vehicle No : SKW6175M

TP Vehicle No : SHA9171E

Make : HYUNDAI I40

Date of Inspection : 26/07/2018

Inspection At : DING AUTO PTE LTD

Accident Date : 23/07/2018

Assignment Date : 26/07/2018

Est. Duration of Repair : 4/Days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages ...Rear O/S.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,718.43
Revised Amount	:S\$	3,667.56
Check Items (Estimated)	:S\$	200.00
Total	:S\$	3,867.56

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments :We have not authorized repairs.