

ASS. REC. BY:

REF:

CS/CTI18013624/

Yrd3

Special Instruction:

Surveyor  
menhen

Marius

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

26/7/18 @ 2:04pm

Estimated Cost:

Bill to:

OD TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLK 4777R

Insured:

SKB 9325M

at Workshop m/s

Kah Motor

Tel:

81006303

of

15 Ubi Rd 4

Policy No:

DMPCSN 3008491800

Claim No:

SNM18D 03609C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

21/07/2018

CA / REV / REP. / REV 24 HRS

(up)

30/07/18 @ 11am

H.O.D. Endorsement:

Date/Time:

3:45pm @ 26/7/18

Person Contacted:

Mr. Lim

Vehicle IN

OUT

Date/Time

Action/Instruction

(✓)

Estimate

SLK 4777R-x

SKB 9325M-x

(08/11/13) wef

REF: CTI

ASS. REC. BY:

## ASSIGNMENT

From: Date: 30/07/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLK 4777R

at Workshop m/s Kah Motor

of 15 Ubi Road 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

I am @ owner

Make of Veh:

waiting

Mr Lim @ 81006303

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLK4777R Regn: 1117

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA /

Make: Honda HR-V c.c. 1496

Colour: s. hue A/C: Insured / Std / NI / NA

Sp. Reading: 19911 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRU18106X201491

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NI / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 21/7/18 D.O.I. 30/7/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body.

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/8/18 confirmed final fig @ 7172.81 with Mr Lim.

Red: \$ 3244.68, 31%.

RECEIVED 31 AUG 2018

Date/Time, File Pass to?

☐ : Preli. Report

1) typist

☒ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 6

Resurvey No. of Trip: 1

Report Format: TP

Lump Sum / I.B.I.: (\$ 7172.81)

Add Fee: ☐ : Site Insp (\$ )☐ : Interview (\$ )☐ : Tech. Invs (\$ )☐ : Weekend (\$ )

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2018		26 Jul 2018 14:04 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

**CLAIM SUBFOLDER DETAILS** [Created by insurer]

Insured:	MARTIN JOHN HILL, ID: G6437661L		
Main Claimant:	SUNIL NAIR, ID: S8130611G		
Vehicle Reg. No.:	SLK4777R	Date of Loss:	21/07/2018 16:00 - :59
Claim Type:	TP / SNM18D03609C02	Policy/Cover Note No.:	DMPCSN3008491800 (Comprehensive)
Vehicle Reg. No. (Insured):	SKB9325M	Policy No. (Claimant):	
		Excess:	S\$0.00
Repairer:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4, 408610 Ubi - Tel: 68465671		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 06/08/2018]		
Adj Asg. Remarks:	EST \$11,146.70, CASE WITH SJE.		

**ASSOCIATED MAIL RECEIVED** [View All](#) [Compose Case Mail](#)

There are no mail for this case.

**ALL ASSOCIATED TASKS** [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CTI18013624/Urd3

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 26-07-2018



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 9325M	Veh. Inspected	SLK 4777R
Policy No.	DMPCSN3008491800	Coverage (\$)	0.00
Claim No.	SNM18D03609C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	26/07/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	21/07/2018	Inspection Date	30/07/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	23/07/2018 14:43
Date Of Accident	21/07/2018 16:20
Exact Location Of Accident	CLAYMORE HILL TOWARDS CLAYMORE ROAD
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLK4777R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SUNIL NAIR
NRIC No	S8130611G
Email Address	SUN_NAIR81@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98531890
Alternative Phone No	OFFICE-98531890

### Vehicle Particulars

Manufacturer	HONDA
Model	HR-V-1.5 DX CVT (A)
Exact Purpose for which vehicle was being used at time of accident	DRIVING TO MAIS AGENCY
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD17V01194/VPC2/R00
Cover Note Number	

### Driver

Name of Driver	SUNIL NAIR
NRIC No	S8130611G
Date Of Birth	18/09/1981
Occupation	INDOOR
Date Of Driving Pass	21/01/2004
Driving Experience	14 YEARS AND 6 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98531890
Fax Number	
Contact Number	OFFICE-98531890
EMail Address	SUN_NAIR81@YAHOO.COM.SG

Address	9 CHUAN HOE AVENUE
Postcode	549819
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHED STATEMENT - THIRD PARTY DIRECT SETTLEMENT

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKB9325M
Vehicle Make/Model/Colour	PEUGEOT / HATCHBACK / WHITE
Details Of Properties	FRONT RIGHT BUMPER SCRATCHED
Vehicle Category	PRIVATE CAR
Name of Driver	MARTIN HILL
NRIC/Passport Number	
Contact Number	81572393
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	3
Passenger 1	NAME: : UNKNOWN
	GENDER: : MALE

Passenger 2

NAME: : UNKNOWN

GENDER: : FEMALE

Vehicle No SLK 4777 R**SKETCH PLAN**

Annex D

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Nair / 23 July 2018, 9.35am

Policyholder's Signature / Date &amp; Time

Driver's Signature (If driver is not the policyholder) / Date &amp; Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**

Please continue to Annex E



Vehicle No SLK 4771R

Annex E

## Describe Circumstances of the Accident

It was Saturday afternoon on 21 July 2018 At about 4.20 pm, I was on the way to the mail agency to pick up a new mail. The weather was sunny and the road was dry.

I was driving along Claymore Hill towards Claymore Road. I wanted to make a right turn to Claymore Road from Claymore Hill.

I was moving straight on the right-most lane towards the right-turn point.

As I was entering a yellow box, I heard the sound of an impact on my left side. I then realised that there had been an impact to the left side of the car from another car in the next lane.

Both cars moved to the side to take pictures and exchange particulars. Photos were taken of damage. We agreed to get repair quotations and discuss further.

The incident was captured on my camera. It shows that I was going straight in my lane before the white encroached into my lane, thus causing the impact. Refer to scenario 14/15 of standard sketch.

## Declaration

We declare the foregoing particulars are true in every respect.

8/Var/23 July 2018, 9.35 am

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Addendum Sheet Pg. 1

GENERAL INSURANCE ASSOCIATION OF SINGAPORE  
RECORDS MANAGEMENT CENTRE

**IMPORTANT NOTE** : Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

**ADDENDUM**

**(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:**

Original Report No : MKM118094844 Vehicle Registration No : SLK 4777R

Name(as shown in NRIC): Sunil Nair

(\*Vehicle Driver / Vehicle Owner) (\*) Please delete as appropriate

NRIC/Passport No : S81306116

Address : 9 Chuan Hoe Avenue SLS49819

Contact (Tel) : \_\_\_\_\_ (H/P) : 98531890 (HP)

(Email) : Sun-Nair81@yahoo.com.sg

Date of Accident : 21/07/2018 Time of Accident : 16.20hrs

Place of Accident : Claymore Hill Towards Claymore Road

Insurance Company : Liberty Insurance

**(B) ADDITIONAL INFORMATION / AMENDMENTS:**

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

I Would like to amend from Report Purpose only  
To Third Party Direct Settlement

Sunil  
Signature of Vehicle Owner / Driver

Date: 24 July 2018

10 Anson Road #06-16 International Plaza Singapore 079903 Phone : + 65 6224 0010 Fax : +65 6224 0030  
Operating Hours : Monday to Friday 9am to 5pm

## CERTIFICATE OF INSURANCE

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)  
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) RULES, 1960  
ROAD TRANSPORT ACT, 1987 (MALAYSIA)  
MOTOR VEHICLES (THIRD-PARTY RISKS) RULES, 1959 (MALAYSIA)

<b>Certificate No</b>	SD17V01194 /VPC2 /R00
<b>Form</b>	MX1
<b>Date of Issue</b>	19-JAN-2017
<b>1.Index Mark and Registration No. of Vehicle:</b>	SLK4777R
<b>2.Chassis number of Vehicle:</b>	JHMRU1810GX201491
<b>3.Name of Policyholder:</b>	SUNIL NAIR
<b>4.Effective date of Commencement of Insurance for the purposes of the Act:</b>	18-JAN-2017 00:00 AM
<b>5.Date of Expiry of Insurance:</b>	17-JAN-2019 23:59 PM
<b>6.Persons or Classes of Persons entitled to drive*:</b>	
A) The Policyholder.	
B) Any other person who is driving on the Policyholder's order or with his permission.	
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.	
And provided further that the Motor Vehicle is registered under the Road Traffic Act and its registration under the Road Traffic Act has not been cancelled at the time of the accident loss or damage.	
<b>7.Limitations as to use*:</b>	
Use only for social, domestic and pleasure purposes and for the Policyholder's business.	
<b>8.The Policy does not cover:</b>	
A) Use for hire or reward.	
B) Use for racing, pace-making, reliability trials or speed-testing.	
C) Use for the carriage of goods (other than samples) in connection with any trade or business.	
D) Use for any purpose in connection with the Motor Trade.	
*Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia) are not to be included under these headings.	
I/We hereby certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).	
For and on behalf of <b>LIBERTY INSURANCE PTE LTD</b> Approved Insurers  _____ Authorised Signature	
<b>For Information only:</b>	
<b>COVERAGE :</b>	Comprehensive, Unlimited Windscreen
<b>SUM INSURED:</b>	MARKET VALUE AT THE TIME OF LOSS
<b>EXCESS:</b>	Section I S\$600, Additional Excess For Young, Elderly & Inexperienced Drivers S\$3000, Windscreen Excess S\$100
<b>FINANCE COMPANY:</b>	-
<b>PRODUCER NAME:</b>	KAH MOTOR COMPANY SDN BERHAD

PLGT/PLGT/20-JAN-17

S1\_CI\_T1\_T3\_OE\_Template2-Ver1.

20-JAN-17

REPUBLIC OF SINGAPORE  
IDENTITY CARD NO. S8130611G



Name

SUNIL NAIR

Race

INDIAN

Date of birth

18-09-1981

Sex

M

Country of birth

SINGAPORE

S8130611G

REPUBLIC OF SINGAPORE DRIVING LICENCE



Licence Number: S8130611G

Name

SUNIL NAIR

Birth Date: 18 Sep 1981

Issue Date: 21 Jan 2004



001090546F



4054392

NRIC No: S8130611G



Date of issue

18-04-2012

9 CHUAN HOE AVENUE  
SINGAPORE 549819

NRIC No: S8130611G

Date: 15/11/2014

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of  
which unladen does not exceed 2500 kilograms

21 Jan 2004



Licence No: S8130611G

NP 428A

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	0611G
Vehicle Details	
Vehicle No.:	SLK4777R
Vehicle to be Exported:	No
Intended De-registration Date:	30 Jul 2018
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 DX CVT
Primary Colour:	Silver
Manufacturing Year:	2016
Engine No.:	L15B4531491
Chassis No.:	JHMRU1810GX201491
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,368.00
Original Registration Date:	18 Jan 2017
First Registration Date:	18 Jan 2017
Transfer Count:	0
Actual ARF Paid:	\$16,916.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Jan 2027
PARF Rebate Amount:	\$12,687.00
Intended COE Rebate Details	
COE Expiry Date:	17 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,991.00
COE Rebate Amount:	\$43,164.00
Total Rebate Amount:	\$55,851.00
Message	

The information contained herein is correct as at 30 Jul 2018

OK

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

*Kindly Help to arrange  
Surveyor to Survey this  
Vehicle*

*thanks*

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer	: CHINA TAIPING INSURANCE	Document No.	: SQT18003114	Page	1
	3 ANSON ROAD #16-00	Date	: 25. Jul 2018		
	SPRINGLEAF TOWER	Customer No.	: WZC008		
	SINGAPORE 079909	Svc Advisor	: LIM CHOU SIONG		
Registration No	: SLK4777R	Engine No	: L15B4531491		
Chassis No	: JHMRU1810GX201491	Date   Time	: 25. Jul 2018 6:34:50 PM		
Model	: HRV DX-SIN CVT YM 2016	Surveyor Name	:		
Owner's Name	: SUNIL NAIR	Survey Date	:		
Ins Policy No.	:	Authorisation Date	:		
Date of Accident	: 21/7/2018				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: SUNIL NAIR						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 21/7/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L						
	TP VEH: SKB9325M						
74157-T7B-003	PROTECTOR,L.FR.WHEEL ARCH <i>Deep cut</i>	1	150.60	25	112.95	7.91	120.86
60260-T7A-J00ZZ	PANEL COMPL.FR.FENDER <i>n</i>	1	394.90	25	296.17	20.73	316.90
74150-T7A-N00	FENDER ASSYL.FR INNER <i>n</i>	1	88.20	25	66.15	4.63	70.78
74155-T7A-000	ENCLOSURE L.FR.FENDER <i>n</i>	1	9.70	25	7.27	0.51	7.78
91501-TR0-003	CLIPINNER FENDER <i>nee</i>	18	2.30	25	31.05	2.17	33.22
91505-TM8-003	CLIPBUMPER <i>nee</i>	8	2.00	25	12.00	0.84	12.84
91514-TG1-T01	CLIPUNDER COVER <i>nee</i>	4	1.60	25	4.80	0.34	5.14
71850-T7A-J02ZD	GARNISH ASSYL.SIDE SILL <i>cut</i>	1	377.50	25	283.12	19.82	302.94
76251-T7A-J01ZM	CAP,L.SKULL <i>n</i>	1	62.20	25	46.65	3.27	49.92
76258-T7A-J02	MIRROR SET,L <i>n</i>	1	571.60	25	428.70	30.01	458.71
72364-T7A-003	SEALL.FR.DOOR <i>nee</i>	1	9.90	25	7.42	0.52	7.94
67050-T7A-300ZZ	PANEL COMPL.FR.DOOR <i>body</i>	1	817.50	25	613.12	42.92	656.04
67366-T7A-003	TAPE,L.FR.DOOR SASH <i>nee</i>	1	23.60	25	17.70	1.24	18.94
67460-T5A-003ZZ	HINGEL.FR.DOOR LOWER <i>n</i>	1	37.20	25	27.90	1.95	29.85
72380-T7A-003	CHECKER COMPL.FR.DOOR <i>n</i>	1	41.70	25	31.27	2.19	33.46
72366-T7A-J01	SEALL.FR.DOOR LOWER <i>nee</i>	1	7.70	25	5.77	0.40	6.17
72367-T7A-J01	SUB SEALL.FR.DOOR CENTER <i>nee</i>	1	45.60	25	34.20	2.39	36.59
67550-T7A-305ZZ	PANEL COMP.L.RR.DOOR <i>top/surf</i>	1	880.10	25	660.07	46.20	706.27
67865-T7A-003	TAPE L.RR.DOOR SASH <i>nee</i>	1	19.30	25	14.47	1.01	15.48
67960-T2A-H11ZZ	HINGEL.RR.DOOR LOWER <i>An</i>	1	35.80	25	26.85	1.88	28.73

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

Registration No : SLK4777R

Chassis No : JHMRU1810GX201491

Model : HRV DX-SIN CVT YM 2016

Owner's Name : SUNIL NAIR

Ins Policy No. :

Date of Accident : 21/7/2018

Document No. : SQT18003114 Page 2

Date : 25. Jul 2018

Customer No. : WZC008

Svc Advisor : LIM CHOU SIONG

Engine No : L15B4531491

Date | Time : 25. Jul 2018 6:34:50 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
72880-T7A-003	CHECKER COMPL.RR.DOOR <i>11</i>	1	41.70	25	31.27	2.19	33.46
72865-T7A-003	SUB SEALL.RR.DOOR CENTER <i>me</i>	1	19.10	25	14.32	1.00	15.32
72866-T7A-J01	SEALL.DOOR LOWER <i>me</i>	1	5.00	25	3.75	0.26	4.01
75895-T7A-003	TAPEL.RR.DOOR PROTECTION <i>me</i>	1	23.60	25	17.70	1.24	18.94
42700-T7A-J93	DISK,ALUMINIUM WHEEL <i>for car</i>	1	721.60	25	541.20	37.88	579.08
44300-T6A-J51	BEARING ASSYFR.HUB <i>11</i>	1	135.50	25	101.62	7.11	108.73
Sum Item					3437.49	240.61	3,678.10

BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00		180.00	12.60	192.60
Sum Ext. Service					180.00	12.60	192.60

BOSUN	SUNDRIES	1	50.00	<i>me 20</i>	50.00	3.50	53.50
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00		80.00	5.60	85.60
BOMISC1	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	1	320.00		320.00	22.40	342.40
BMI02D	REMOVE & INSTALL CARPET, BOTH L SEATS, COMPARTMENT	1	350.00	<i>11</i>	350.00	24.50	374.50
BKDR11R	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	1	380.00		380.00	26.60	406.60
BKDR21R	REMOVE & TRANSFER ITEMS TO NEW RR L DR ADJUST	1	380.00		380.00	26.60	406.60
BMU11R	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS.(N)1	1	640.00	<i>11</i>	640.00	44.80	684.80
BKFE11R	REPLACE FR L FENDER, L SIDE STILL GARINSH. L <i>180</i>	1	2000.00	<i>1400</i>	2000.00	140.00	2140.00
BP06R	SPRAY PAINTING ON FR L FENDER, L SIDE STILL PANEL	1	2600.00	<i>2025</i>	2600.00	182.00	2782.00
Sum Labor					6800.00	476.00	7,276.00

Survey By Morax Hahn

Date & Time 20/7/18 @ 11am.

Excess \_\_\_\_\_

Status Not Accident

Signature Take photo before party.

Total Amount 10,417.49 729.21 11,146.70

Total (Inclusive of GST) **11,146.70**

Printed on 25/7/2018 7:09:56 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

**Registration No** : SLK4777R

**Chassis No** : JHMRU1810GX201491

**Model** : HRV DX-SIN CVT YM 2016

**Owner's Name** : SUNIL NAIR

**Ins Policy No.** :

**Date of Accident** : 21/7/2018

**Document No.** : SQT18003114 **Page** 3

**Date** : 25. Jul 2018

**Customer No.** : WZC008

**Svc Advisor** : LIM CHOU SIONG

**Engine No** : L15B4531491

**Date | Time** : 25. Jul 2018 6:34:50 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
------	-------------	-----	------------	--------	--------	---------------	------------------

C S Lim  
81006303 (HP)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

Printed on 25/7/2018 7:09:56 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



**Janice Lee (LKKAUTO)**

---

**From:** Lim Chou Siong <cslim@honda.com.sg>  
**Sent:** Saturday, August 25, 2018 9:13 AM  
**To:** SUR  
**Cc:** Liew Thye Wui; Faeaz  
**Subject:** Pre-Invoice Of Vehicle No: SLK4777R For Finalising  
**Attachments:** 4329\_001.pdf

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLK4777R  
Final Repair Costs (include GST) \$7,674.89  
Repair Period\*( Working Day) 06  
\*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong  
Contact No: 81006303 HP  
KAH MOTOR CO. SDN. BHD.  
(A member of Oriental Holdings Berhad)  
Body Repair & Paint Centre  
15 Ubi Road 4 Singapore 408610  
Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

---

**From:** Lim Chou Siong  
**Sent:** Saturday, 25 August, 2018 9:10 AM  
**To:** 'Survey Admin2' <surveyadmin2@fta.com.sg>  
**Cc:** Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>  
**Subject:** Pre-Invoice Of Vehicle No: SLK4777R For Finalising

Dear,

We enclosed the total final repair costs of...

Vehicle No. SLK4777R

Final Repair Costs (include GST) \$7,674.89

Repair Period\* (Working Day) 06

\*Note: Repair period does not include Sunday And Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Lim Chou Siong

Contact No: 81006303 HP

KAH MOTOR CO. SDN. BHD.

(A member of Oriental Holdings Berhad)

Body Repair & Paint Centre

15 Ubi Road 4 Singapore 408610

Tel: +65 6841 3838 Fax: +65 6748 0770

This is a computer-generated e-mail no signature is necessary Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you

**From:** Printer Service

**Sent:** Saturday, 25 August, 2018 9:08 AM

**To:** Lim Chou Siong <[cslim@honda.com.sg](mailto:cslim@honda.com.sg)>

**Subject:** Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

**SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Attn: Marcus (L.K.K.)

6 days

Customer: WZC008 / CHINA TAIPING  
 Chassis No: JHMRU1810GX201491  
 License No: SLK4777R  
 Mileage: 20410  
 Engine No: L15B4531491

Document No: SVO18046799  
 Printed By: CSLIM  
 Order Date: 11. August 2018  
 Order Time: 8:27:47 AM  
 Service Advisor: LIM CHOU SIONG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	incd GST
	TP DIRECT SETTLEMENT (J/NO: 71018) OWNER: SUNIL NAIR OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 21/7/2018 SURVEYED BY: MARCUS (L.K.K.) DATE: 30/07/2018 @ 11:10AM REF NO: TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L TP VEH: SKB9325M						
74157-T7B-003	PROTECTOR,L.FR.WHEEL ARCH	1	150.60	25	112.95	7.91	120.86
91501-TR0-003	CLIPINNER FENDER	18	2.30	25	31.05	2.17	33.22
91505-TM8-003	CLIPBUMPER	8	2.00	25	12.00	0.84	12.84
91514-TG1-T01	CLIPUNDER COVER	4	1.80	25	4.80	0.34	5.14
72364-T7A-003	SEALL.FR.DOOR	1	9.90	25	7.42	0.52	7.94
67050-T7A-300ZZ	PANEL COMPL.FR.DOOR	1	817.50	25	613.12	42.92	656.04
67366-T7A-003	TAPE,L.FR.DOOR SASH	1	23.60	25	17.70	1.24	18.94
72366-T7A-J01	SEALL.FR.DOOR LOWER	1	7.70	25	5.77	0.40	6.17
72367-T7A-J01	SUB SEALL.FR.DOOR CENTER	1	45.60	25	34.20	2.39	36.59
67550-T7Y-T00ZZ	PANEL COMPL.RR.DOOR	1	680.10	25	560.07	45.20	706.27
67865-T7A-003	TAPEL.RR.DOOR SASH	1	19.30	25	14.47	1.01	15.48
72865-T7A-003	SUB SEALL.RR.DOOR CENTER	1	19.10	25	14.32	1.00	15.32
72866-T7A-J01	SEALL.DOOR LOWER	1	5.00	25	3.75	0.26	4.01
75895-T7A-003	TAPEL.RR.DOOR PROTECTION	1	23.60	25	17.70	1.24	18.94
42700-T7A-J93	DISK,ALUMINIUM WHEEL	1	721.60	25	541.20	37.88	579.08
71850-T7A-J02ZD	GARNISH ASSYL.SIDE SILL	1	377.50	25	283.12	19.82	302.94
71851-T7J-H01	PROTECTION TAPE,L.SILL	1	18.90	25	14.17	0.99	15.16
	<b>SUM PARTS:</b>				<b>2,387.81</b>	<b>167.13</b>	<b>2,554.94</b>
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BML01I	EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	80.00		80.00	5.60	85.60
BOMISC1	0626 RESET SMART ENTRY SYSTEM & REMOVE NECESSARY COMPONENT.(N)	1	320.00		320.00	22.40	342.40
BKDR11R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW FR L DR. ADJUST & ALIGN FR L DR.(N)	1	380.00		380.00	26.60	406.60
BKDR21R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW RR L DR. ADJUST & ALIGN RR L DR.(N)	1	380.00		380.00	26.60	406.60
BKFE11R	EXT-YJ REPLACE FR L FENDER, L SIDE STILL GARINSH, L WING MIRROR, REPAIR L SIDE STILL PANEL & OTHER DAMAGE P	1	1,400.00		1,400.00	98.00	1,498.00



# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 8741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZC008 / CHINA TAIPING  
**Chassis No:** JHMRU1810GX201491  
**License No:** SLK4777R  
**Mileage:** 20410  
**Engine No:** L15B4531491

**Document No:** SVO18046799  
**Printed By:** CSLIM  
**Order Date:** 11. August 2018  
**Order Time:** 8:27:47 AM  
**Service Advisor:** LIM CHOU SIONG

BP06R	EXT-YBH	1	2,025.00	2,025.00	141.75	2,166.75
	SPRAY PAINTING ON FR L FENDER, L SIDE STILL PANEL, L SIDE STILL GARNISH, FR L DOOR & RR L DOOR					
			<b>SUM LABOUR:</b>	<b>4,605.00</b>	<b>322.35</b>	<b>4,927.35</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT X4	1	180.00	180.00	12.60	192.60
			<b>SUM EXT SERVICE:</b>	<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
			<b>TOTAL SGD</b>	<b>7,172.61</b>	<b>502.08</b>	<b>7,674.69</b>
			<b>Total Payable (SGD)</b>			<b>7,674.89</b>

GST Amount is calculated from individual line(s)

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

**QUOTATION**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE  
3 ANSON ROAD #16-00  
SPRINGLEAF TOWER  
SINGAPORE 079909

Registration No : SLK4777R

Chassis No : JHMRU1810GX201491

Model : HRV DX-SIN CVT YM 2016

Owner's Name : SUNIL NAIR

Ins Policy No. :

Date of Accident : 21/7/2018

Document No. : SQT18003559 Page 1

Date : 25. Aug 2018

Customer No. : WZC008

Svc Advisor : LIM CHOU SIONG

Engine No : L15B4531491

Date | Time : 25. Aug 2018 8:56:33 AM

Surveyor Name : MARCUS ( L.K.K. )

Survey Date : 30/7/2018

Authorisation Date : 27/7/2018

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
	TP DIRECT SETTLEMENT (J/NO: 71018)						
	OWNER: SUNIL NAIR						
	OWNER INSURER: LIBERTY INSURANCE PTE LTD						
	ACC DATE: 21/7/2018						
	SURVEYED BY: MARCUS ( L.K.K. )						
	DATE: 30/07/2018 @ 11:10AM						
	REF NO:						
	TP INSURER: CHINA TAIPING INSURANCE (S'PORE) PTE L						
	TP VEH: SKB9325M						
	SUPPLEMENTARY LABOUR & PARTS						
71651-T7J-H01	PROTECTION TAPE, L. SILL <i>DED</i>	1 <i>ML</i>	18.90	25	14.17	0.99	15.16
				Sum Item	<u>14.17</u>	<u>0.99</u>	<u>15.16</u>

Survey By \_\_\_\_\_

Date &amp; Time \_\_\_\_\_

Excess \_\_\_\_\_

Status \_\_\_\_\_

Signature \_\_\_\_\_

Total Amount 14.17 0.99 15.16

Total (Inclusive of GST) 15.16

Printed on 25/8/2018 9:01:30 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Jul 2018		26 Jul 2018 14:04 <a href="#">Edit Adj Rpt</a>	<b>S\$7,172.81</b> <a href="#">Edit Estimates</a>	<b>S\$7,172.81</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>



























  

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	<b>MARTIN JOHN HILL</b> , ID: G6437661L								
Main Claimant:	<b>SUNIL NAIR</b> , ID: S8130611G								
Vehicle Reg. No.:	<b>SLK4777R</b>	Date of Loss:	21/07/2018 16:00 - :59 [18 Months and 3 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM18D03609C02</b>	Policy/Cover Note No.:	DMPCSN3008491800 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SK89325M</b>	Policy No. (Claimant):							
		Excess:	S\$0.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (Ubi)</b> 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 06/08/2018]								
Adj Asg. Remarks:	EST \$11,146.70, CASE WITH SJE.								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLK4777R (SNM18D03609C02)  
[SKB9325M]  
TP  
SUNIL NAIR  
Jul 21 2018 4:00PM  
[MARTIN JOHN HILL]  
Kah Motor Co Sdn Bhd

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports						1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)					Thumbnail	Print	
1	23/07/18 18:32	Accident Statement				1	Load HTM		
Photos/Images						3 per page		<input checked="" type="checkbox"/>	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)					Thumbnail	Print	
1	23/07/18 18:27	Accident Photo [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
2	23/07/18 18:27	Accident Photo [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
3	23/07/18 18:27	Accident Photo [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
4	23/07/18 18:27	Accident Photo [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
5	23/07/18 18:27	Accident Photo [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
6	23/07/18 18:27	Accident Photo [Linked Accident Report Documents]				1	Load JPG	<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
2	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
3	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
4	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
5	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
6	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
7	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
8	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
9	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
10	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
11	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
12	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
13	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
14	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
15	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
16	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
17	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
18	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
19	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
20	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
21	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
22	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
23	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
24	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	
25	30/07/18 20:10	General View				1	Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
26	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
27	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
28	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
29	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
30	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
31	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
32	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
33	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
34	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
35	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
36	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
37	30/07/18 20:10	General View	 Load JPG	<input checked="" type="checkbox"/>
38	30/07/18 20:10	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
39	30/07/18 20:10	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
40	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	31/08/18 15:06	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	26/07/18 14:03	EMAIL FM KAH MOTOR	 Load PDF	
2	26/07/18 14:03	REPAIR EST WITH TP GIA	 Load PDF	
3	26/07/18 14:04	OI GIA	 Load PDF	
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	23/07/18 18:27	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	23/07/18 18:27	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	23/07/18 18:27	Sketch Plan #3 [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/09/18 08:41	SUPPLEMENTARY PART	 Load PDF	

## Linked Accident Report Documents

View 

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	23/07/18 18:32	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	23/07/18 18:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	23/07/18 18:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	23/07/18 18:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	23/07/18 18:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>



Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
5	23/07/18 18:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	23/07/18 18:27	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	S & H Motor Pte Ltd (Sin Ming)	Thumbnail	Print
1	23/07/18 18:27	Sketch Plan	 Load TIF	
2	23/07/18 18:27	Sketch Plan #2	 Load TIF	
3	23/07/18 18:27	Sketch Plan #3	 Load TIF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>

# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118013624/URD3Q2

Date: 06/09/2018

### REFERENCE

Handling Insurer: China Taiping Insurance  
(Singapore) Pte. Ltd.

Policy No: DMPCSN3008491800

Claimant Vehicle  
No: SLK4777RInsured Vehicle  
No: SKB9325M

Date of Loss: 21/07/2018

Nature of Claim: TP

Claim  
No: SNM18D03609C02

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLK4777R**

Make &amp; Model: HONDA HR-V, 1.5 DX CVT (A)

Reg. Date: 18/01/2017 (Man. Year: 2016)

Colour: Silver

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

Engine No: L15B4531491

Chassis No: JHMRU1810GX201491

Odometer: 19911 km

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Dunlop 7 mm

Rear Left Side:

Dunlop 7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side:

Dunlop 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,501.66	2,407.81	1,093.85	31.24
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,930.00	4,765.00	2,165.00	31.24
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>10,431.66</b>	<b>7,172.81</b>	<b>3,258.85</b>	<b>31.24</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>730.22</b>	<b>502.10</b>	<b>228.12</b>	<b>31.24</b>
<b>Nett Amount (S\$)</b>	<b>11,161.88</b>	<b>7,674.91</b>	<b>3,486.97</b>	<b>31.24</b>

### INSPECTION

Date of Assignment: 26/07/2018

Date Inspected: 30/07/2018

Inspected At:

Kah Motor Co Sdn Bhd (Ubi)  
15 Ubi Road 4  
Singapore 408610

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA

Manager: Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 Sep 2018)
<b>Parts:</b> M1-SUV	HONDA HR-V 1.5 DX CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SLK4777R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PROTECTOR ,L.FR.WHEEL ARCH	Deep Cut	112.95 FS	*112.95 FS
2	1		*PANEL COMPL.FR.FENDER	Repair	296.17 FS	*- FS
3	1		*FENDER ASSYL.FR.LINER	Not Necessary	66.15 FS	*- FS
4	1		*ENCLOSUREL .FR.FENDER	Not Necessary	7.27 FS	*- FS
5	1		*CLIPINNER FENDER (18PCS)	Necessary	31.05 FS	*31.05 FS
6	8		*CLIPBUMPER	Necessary	12.00 FS	*12.00 FS
7	4		*CLIPUNDER COVER	Necessary	4.80 FS	*4.80 FS
8	1		*GARNISH ASSYL.SIDE SILL	Cut	283.12 FS	*283.12 FS
9	1		*CAP,L.SKULL	Repair	46.65 FS	*- FS
10	1		*MIRROR SET ,L	Repair	428.70 FS	*- FS
11	1		*SEALL.FR.DOOR	Necessary	7.42 FS	*7.42 FS
12	1		*PANEL COMPL .FR.DOOR	Badly Dented	613.12 FS	*613.12 FS
13	1		*TAPE,L.FR.DOOR SASH	Necessary	17.70 FS	*17.70 FS
14	1		*HINGEL.FR.DOOR LOWER	Not Necessary	27.90 FS	*- FS
15	1		*CHECKER COMPL.FR.DOOR	Not Necessary	31.27 FS	*- FS
16	1		*SEALL .FR.DOOR LOWER	Necessary	5.77 FS	*5.77 FS
17	1		*SUB SEALL .FR.DOOR CENTER	Necessary	34.20 FS	*34.20 FS
18	1		*PANEL COMP,L.RR.DOOR	Dented / Bent	660.07 FS	*660.07 FS
19	1		*TAPEL.RR.DOOR SASH	Necessary	14.47 FS	*14.47 FS
20	1		*HINGEL.RR.DOOR LOWER	Not Necessary	26.85 FS	*- FS
21	1		*CHECKER COMPL.RR.DOOR	Not Necessary	31.27 FS	*- FS
22	1		*SUB SEALL.RR.DOOR CENTER	Necessary	14.32 FS	*14.32 FS
23	1		*SEALL.DOOR LOWER	Necessary	3.75 FS	*3.75 FS
24	1		*TAPEL.RR.DOOR PROTECTION	Necessary	17.70 FS	*17.70 FS
25	1		*DISK ,ALUMINIUM WHEEL FRT	Cut	541.20 FS	*541.20 FS
26	1		*BEARING ASSYFR.HUB	Not Necessary	101.62 FS	*- FS
27	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
28	1		*PROTECTION TAPE,L.SILL	Necessary	14.17 FS	*14.17 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>3,501.66</b>	<b>2,407.81</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	80.00	80.00
2	RESET SMART ENTRY SYSTEM & REMOVE NECESSARY	New	320.00	320.00
3	REMOVE & INSTALL CARPET ,BOTH L SEATS,COMPARTMENT	New	350.00	0.00
4	REMOVE & TRANSFER ITEMS TO NEW FR L DR ADJUST	New	380.00	380.00
5	REMOVE & TRANSFER ITEMS TO NEW RR L DR ADJUST	New	380.00	380.00
6	REMOVE & REPLACE FR L UNDERCARRIAGE PARTS	New	640.00	0.00
7	REPLACE FR L FENDER ,L SIDE STILL GARNISH ,L	New	2,000.00	1,400.00
8	SPRAY PAINTING ON FR L FENDER ,L SIDE STILL PANEL	New	2,600.00	2,025.00
9	WHEEL ALIGNMENT	New	180.00	180.00
Gross Labour Cost (\$\$)			<b>6,930.00</b>	<b>4,765.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >